

Search .

Home Files News About Contact &[SERVICES_TAB]

Posted Jun 16, 2020

Add New

Follow us on Twitter

Subscribe to an RSS Feed

TP-LINK Cloud Cameras NCXXX Stack Overflow

TP-LINK Cloud Cameras NCXXX suffer from a DelMultiUser stack overflow vulnerability.

SHA-25618 ceea48329dd3d48af63a7ccdec830b47ac2bcf4bf77d8735c577b80b70e19b4 Download I Favorite I View

Top Authors In Last 30 Days

31

Red Hat 154 files Ubuntu 73 files LiquidWorm 23 files Debian 18 files malvuln 11 files nu11secur1ty 11 files Gentoo 9 files

Google Security Research 8 files

T. Weber 4 files Julien Ahrens 4 files

File Archives File Tags

December 2022 Advisory (79,754) Arbitrary (15.694) October 2022 RRS (2.859) September 2022 August 2022 CGI (1,018) July 2022 Code Execution (6.926) June 2022 Conference (673) May 2022 Cracker (840) April 2022 CSRF (3,290) March 2022 DoS (22 602) February 2022 Encryption (2,349) January 2022 Exploit (50,359) Older File Inclusion (4,165) File Upload (946) Systems Firewall (821) AIX (426) Info Disclosure (2,660) Apple (1,926) Intrusion Detection (867) BSD (370) Java (2.899) CentOS (55) JavaScript (821) Cisco (1.917) Kernel (6,291) Debian (6,634) Local (14.201) Magazine (586) FreeBSD (1,242)

Gentoo (4.272) Perl (1.418) HPUX (878) PHP (5.093) iOS (330) Proof of Concept (2,291) iPhone (108) IRIX (220) Python (1.467) Juniper (67) Remote (30,044) Linux (44,315)

Mac OS X (684) Ruby (594) Mandriva (3.105) Scanner (1.631) Security Tool (7,777) OpenBSD (479) Shell (3,103) RedHat (12 469)

Slackware (941)

Solaris (1,607)

Shellcode (1,204)

Sniffer (886)

Related Files Share This TIMAE Reddit Digg StumbleUpon Lik€ Change Mirror Download Vulnerability title: TP-LINK Cloud Cameras NCXXX DelMultiUser Stack Overflow Author: Pietro Oliva NC200 <= 2.1.11 build 200508, NC210 <= 1.0.11 build 200612, NC220 <= 1.3.2 build 200508, NC230 <= 1.3.2 build 200508, NC230 <= 1.3.2 build 200508, NC250 <= 1.3.4 build 200508, NC260 <= 1.5.4 build 200508, NC450 <= 1.5.5 build 200508 Description:
The issue is located in the httpDelMultiUserEps method of the ipcamera binary (Called when deleting multiple users via /delmultiuser.fcgi), where a comma-delimited list of usernames is passed as an input, and a list of error codes for each user deletion attempt is returned to the user via HTTP. The list of error codes returned to the user is temporary stored in a fixed-size stack specify. Since the error codes are connectmented in a loop without any boundary checks until a string terminator has been found in the user-supplied string, a stack-based buffer overflow can occur if the user provided an input string with enough commas or usernames. Impact: Attackers could exploit this vulnerability to remotely crash the ipcamera process, or remotely execute arbitrary code as root. Exploitation: An attacker would first need to authenticate to the web interface and make a request similar to the following to trigger a crash of the ipcamera process: POST /delmultiuser.fcgi HTTP/1.1 Od; /uemmutuset.rug nir//...
ser-Agent: Mozilla/5.0 (X1); Linux x86_64; rv:68.0) Gecko/20100101 Firefox/68.0 ontent-Type: application/x-www-form-urlencoded ookle: sess=xxxxx Usernames=,,,,,,,,&token=xxxxx" Evidence: The disassembly of affected code from an NC200 camera is shown below: svm.httpDelMultiUserRom-Save the pointer and return error if it is NULL

0x0047eeh0 lw gp, (arg l0h)

0x0047eeh0 lw gp, (arg usernames)

0x0047eeh0 lw v0, (arg_usernames)

0x0047eeh0 lw v0, (arg_usernames)

0x0047eeh0 pher v0, 0x47eed4

0x0047eec0 b mer v0, 0x47eed4

0x0047eec0 b 0x470bc

0x0047eec0 b w v0, (arg_46ch) the arg_usernames pointer to arg_usernames_copy 0x0047eef8 lw v0, (arg_usernames) 0x0047eefc nop 0x0047ef00 sw v0, (arg_usernames_copy) Doubter to the first occurrence of the comma character and store it

0x0047e104 lw a0, (arg_usernames_copy)

0x0047e104 lw a0, (arg_usernames_copy)

0x0047e100 lw t9, -sym.imp.strchr(gp)

0x0047e110 nop

0x0047e114 jair t9

0x0047e118 nop

0x0047e118 nop

0x0047e120 sw v0, (ptr_to_next_comma) If the pointer is NULL go and delete the last username in the list 0x0047ef24 lw v0, (ptr_to_next_comma)
0x0047ef28 nop
-< 0x0047ef2c begz v0, 0x47efc0
0x0047ef30 nop Replace the comma character with a string terminator and delete the user 0x0047ef34 lw v0, (ptr_to_next_co 0x0047ef38 nop 0x0047ef3c sb zero, (v0) 0x0047ef40 lw a0, (arg_usernames_copy) 0x0047ef44 lw t9, -sym.swUMDelUser(gp) 0x0047ef48 nop 0x0047ef4c jalr t9 0x0047ef50 nop

```
0x0047ef68 nop

0x0047ef6c addiu al, al, -0x73a4 ; '{"errorCode":&d),'

0x0047ef70 lw a2, (deluser_error_code)

0x0047ef74 lw t9, -sym.imp.sprintf(gp)

0x0047ef78 nop

0x0047ef78 jair t9

0x0047ef780 nop
 | Increase the pointer by one to the next username | | | | | 0x0047efa8 lw gp, (arg_10h) | | | | | 0x0047efa8 lw v0, (ptr_to_next_comma) | | | | | 0x0047efb0 np | | | | | 0x0047efb0 np | | | | | 0x0047efb0 addiu v0, v0, 1
; Checks if the string terminator has been found.

> 0x0047f034 lw v0, (ptr_to_next_comma)

||||| 0x0047f038 nop
 ; If yes, return the error codes to the user via HTTP
Mitigating factors:
There is very limited control over the buffer that will eventually overwrite the saved return address. The only part of the buffer that can be slightly controlled is the error code by using existing, non-existing, or invalid usernames, since error codes can change in content and length. If an attacker managed to find a way to carefully combine error codes and obtain a valid address after return address overwrite, arbitrary code execution as root could be achieved.
 Install firmware updates provided by the vendor to fix the vulnerability. The latest updates can be found at the following URLs:
https://www.tp-link.com/en/support/download/nc200/#Firmware
https://www.tp-link.com/en/support/download/nc210/#Firmware
https://www.tp-link.com/en/support/download/nc210/#Firmware
https://www.tp-link.com/en/support/download/nc230/#Firmware
https://www.tp-link.com/en/support/download/nc230/#Firmware
https://www.tp-link.com/en/support/download/nc230/#Firmware
https://www.tp-link.com/en/support/download/nc230/#Firmware
Disclosure timeline:
2nd May 2020 - Vulnerability reported to vendor.
19th May 2020 - Patched firmware provided by vendor for verification.
19th May 2020 - Confirmed the vulnerability was fixed.
15th June 2020 - Firmware updates released to the public.
15th June 2020 - Vulnerability details are made public.
```

Login or Register to add favorites

packet storm © 2022 Packet Storm. All rights reserved.

Site Links About Us History & Purpose News by Month News Tags Contact Information Files by Month Terms of Service

Privacy Statement

File Tags File Directory Copyright Information **Hosting By** Rokasec



Spoof (2,166)

TCP (2.379)

UDP (876)

Virus (662) Vulnerability (31,136) Web (9,365) Whitepaper (3,729) x86 (946) XSS (17,494)

SUSE (1,444)

UNIX (9 159) UnixWare (185)

Windows (6,511) Other

SQL Injection (16,102) Ubuntu (8,199)

