Search .

Home Files News About Contact &[SERVICES_TAB]

Add New

Moxa Command Injection / Cross Site Scripting / Vulnerable Software

Authored by T. Weber | Site sec-consult.com

Posted Sep 1, 2021

Many Moxa devices suffer from command injection, cross site scripting, and outdated software vulnerabilities.

ries | CVE-2013-1914, CVE-2013-7423, CVE-2015-0235, CVE-2015-7547, CVE-2016-1234, CVE-2021-39278, CVE-2021-39279

Share This

Like TWEE

1.18.5 06/2011

LinkedIn


Reddit Digg

StumbleUpon

Change Mirror Download SEC Consult Vulnerability Lab Security Advisory < 20210901-0 > title: Multiple vulnerabilities

product: see "Wulnerable / tested versions"
vulnerable version: see "Wulnerable / tested versions"
fixed version: see "Solution"
CVE number: CUP-2021-39278, CUE-2021-39279
impact: High
homepage: https://www.moxa.com/
found: 2020-08-31
by: T. Weber (Office Vienna)
SEC Consult Vulnerability Lab An integrated part of SEC Consult, an Atos company Europe | Asia | North America https://www.sec-consult.com endor description: "Together, We Create Change Moxa is committed to making a positive impact around the world. We put our all behind this commitment--from our employees, to our products and supply chain. In our local communities, we nurture and support the spirit of volunteering. We encourage our employees to contribute to community development, with an emphasis on ecology, education, and health. In our products, we invest in social awareness programs and environment-friendly policies at every stage of the product lifecycle. We make sure our manufacturing meets the highest standards with regards to quality, ethics, and sustainability." Source: https://www.moxa.com/en/about-us/corporate-responsibility SEC Consult recommends to immediately apply the available patches from the vendor. A thorough security review should be performed b security professionals to identify further potential security iss 1) Authenticated Command Injection (CVE-2021-39279)
An authenticated command injection vulnerability can be triggered by issuing a An authenticated command injection vulnerability can be triggered by issuing a three triggered command in the web interface. An attacker can abuse this vulnerability to compromise the operating system of the device. This issue was found by emulating the firmware of the device. 2) Reflected Cross-Site Scripting via Manipulated Config-File (CVE-2021-39278) Via a crafted config-file, a reflected cross-site scripting vulnerability can be exploited in the context of the victim's browser. This config-file can be uploaded to the device via the "Config Import Export" tab in the main menu. 3) Known GNU glibc Vulnerabilities (CVE-2015-0235) The used GNU glibc in version 2.9 is outdated and contains multiple known vulnerabilities. One of the discovered vulnerabilities (CVE-2015-0235, gethostbyname "GHOST" buffer overflow) was verified by using the MEDUSA scalable firmware runtime. Multiple Outdated Software Components Multiple outdated software components containing vulnerabilities were found by the IoT Inspector. The vulnerabilities 1), 2) and 3) were manually verified on an emulated device by using the MEDUSA scalable firmware runtime. Authenticated Command Injection (CVE-2021-39279)
 The vulnerability can be triggered by navigating in the web interface to the "Main Menu"->"Maintenance"->"Config Import Export" The "TFTF Import" menu is prone to command injection via all parameters. To exploit the vulnerability, an IP address, a configuration path and a filename must be set.

If the filename is used to trigger the exploit, the payload in the interceptor proxy would be: http://192.168.1.1/forms/web importTFTP?servIP=192.168.1.1&configPath=/&fileName=name|`ping localhost -c 100` "Main Menu"->"Maintenance"->"Config Import Export" The "Config Import" menu is prone to reflected cross-site scripting via the upload of config files. Example of malicious config file: [board] deviceName="WAC-2004_0000<script>alert(document.cookie)</script>" deviceLocation="" Uploading such a crafted file triggers cross-site scripting as the erroneous value is displayed without filtering characters. 3) Known GNU glibc Vulnerabilities (CVE-2015-0235)
GNU glibc version 2.9 contains multiple CVEs like:
CVE-2016-1234, CVE-2015-7547, CVE-2013-7423, CVE-2013-1914, and more. The gethostbyname buffer overflow vulnerability (GHOST) was checked with the help of the exploit code from https://seclists.org/oss-sec/2015/q1/274. It was compiled and executed on the emulated device to test the system 4) Multiple Outdated Software Components The IoT Inspector recognized multiple outdated software components with known vulnerabilities:



File Archive: December 2022 <



Ubuntu 76 files LiquidWorm 23 files Debian 21 files nu11secur1ty 11 files Gentoo 9 files Google Security Research 8 files Julien Ahrens 4 files T. Weber 4 files

File Tags File Archives December 2022 Advisory (79,754) Arbitrary (15.694) October 2022 RRS (2.859) September 2022 August 2022 CGI (1,018) July 2022 Code Execution (6,926) June 2022 Conference (673) May 2022 Cracker (840) April 2022 CSRF (3,290) March 2022 DoS (22 602) February 2022 Encryption (2,349) January 2022 Exploit (50,359) Older File Inclusion (4,165) File Upload (946) Systems Firewall (821) AIX (426) Info Disclosure (2,660) Apple (1,926) Intrusion Detection (867) BSD (370) CentOS (55) JavaScript (821) Cisco (1.917) Kernel (6,291) Debian (6,634) Local (14.201) Magazine (586) FreeBSD (1.242) Gentoo (4.272) Perl (1.418) PHP (5.093) iOS (330) Proof of Concept (2,291) iPhone (108) Protocol (3,435) IRIX (220) Python (1.467) Juniper (67) Remote (30.044) Linux (44,315) Mac OS X (684) Ruby (594) Mandriva (3.105) Scanner (1.631) Security Tool (7,777) OpenBSD (479) Shell (3,103) RedHat (12.469) Shellcode (1,204) Slackware (941) Sniffer (886) Solaris (1,607)

```
| Drophear SSH | 2011.54 | 11/2011 | GNU glibe | 2.9 | 02/2009 | Linux Kernel | 2.6.27 | 10/2008 | OpenSSI | 0.9.7g | 04/2005 | Only found in the program "ix director" | OpenSSL | 1.0.0 | 03/2010 |
  Vendor contact timeline:

2020-10-09: Contacting vendor through moxa.cstt@moxa.com.

2020-10-09: Contact sends PGP key for encrypted communication and asks for the detailed advisory. Sent encrypted advisory to vendor.

2020-11-06: Status update from vendor regarding technical analysis. Vendor requested more time for fixing the vulnerabilities as more products are affected.

2020-11-01: Vendor asked for next steps regarding the advisory publication.

2020-11-10: Vendor asked for next steps regarding the advisory publication.

2020-11-16: Vendor responded that the product team can give a rough feedback.

2020-11-25: Vendor responded that the investigation is not done yet.

2020-11-25: Vendor responded his to fortential affected devices and stated that full investigation may take until January 2021 due to the list of CVBs that were provided with the appended 107 Inspector report.

2020-12-21: Shifted next status update.

2020-12-25: Shifted next status update round with vendor on May 2021.

2020-12-25: Wendor provided full list of affected devices.

2020-12-20: Vendor sieved out the found issues from () manually and provided a full list of affected devices.

2021-02-05: Vendor sieved out the found issues from () manually and provided a full list of affected devices.

2021-02-10: Confirmed receive of vulnerabilities, Max 2021 hours of the part days.
  2021-02-21: Confirmed receive of vulnerabilities, next status update in May 2021-06-10: Asking for an update.
2021-06-10: Hendor stated, that the update will be provided in the next days. 2021-06-21: Wendor will give an update in the next week as Covid gets worse in Taiwan.
2021-06-21: Wendor will give an update in the next week as Covid gets worse in Taiwan.
2021-06-23: Wendor private that patches are under development. Vendor needs more transported by the control of the control o
         Solution:
      The Moxa Technical Support must be contacted for requesting the security patches.
      The corresponding security advisories for the affected devices are available on the vendor's website:

TAP-327/MC-1001/MC-2004

the part of the security advisories for the affected devices are available on the part of the security advisory of the
         once:i 634/04-11740BK-31244
https://www.moxa.com/en/support/product-support/security-advisory/oncell-g3470a-wdr-3124a-cellular-gateways-
router-vulnerabilities
      The following device models are EOL and should be replaced:
* NBC-2004
* NBC-2004
* NBC-3124A-EU
* NBC-3124A-EU-7
* NBC-3124A-U-5
* NBC-3124A-U-5-7
         Workaround:
             lone.
         Advisory URL:
      https://sec-consult.com/vulnerability-lab/
      SEC Consult Vulnerability Lab
      SEC Consult, an Atos company
Europe | Asia | North America
    About SEC Consult Vulnerability Lab
The SEC Consult Vulnerability Lab is an integrated part of SEC Consult, an
Akos company. It ensures the continued knowledge gain of SEC Consult in the
field of network and application security to stay ahead of the attacker. The
SEC Consult Vulnerability Lab supports high-quality penetration testing and
the evaluation of new offensive and defensive technologies for our customers.
Hence our customers obtain the most current information about vulnerabilities
and valid recommendation about the risk profile of new technologies.
         Interested to work with the experts of SEC Consult?
Send us your application https://sec-consult.com/career/
      Mail: research at sec-consult dot com
Web: https://www.sec-consult.com
Blog: http://blog.sec-consult.com
Twitter: https://twitter.com/sec_consult
         EOF Thomas Weber / 02021
```

Login or Register to add favorites



Site Links

News by Month

News Tags

Files by Month

File Tags

About Us

Terms of Service

Privacy Statement

History & Purpose

Hosting By Rokasec



Spoof (2,166)

TCP (2.379)

UDP (876)

Virus (662)

Vulnerability (31,136) Web (9,365) Whitepaper (3,729) x86 (946) XSS (17,494) Other

SUSE (1,444)

UNIX (9 159)

Windows (6,511)

Other

SQL Injection (16,102) Ubuntu (8,199)



