Talos Vulnerability Report

TALOS-2022-1519

InHand Networks InRouter302 console infct leftover debug code vulnerability

OCTOBER 27, 2022

CVE NUMBER

CVE-2022-30543

SUMMARY

A leftover debug code vulnerability exists in the console infct functionality of InHand Networks InRouter302 V3.5.45. A specially-crafted series of network requests can lead to execution of privileged operations. An attacker can send a sequence of requests to trigger this vulnerability.

CONFIRMED VULNERABLE VERSIONS

The versions below were either tested or verified to be vulnerable by Talos or confirmed to be vulnerable by the vendor.

InHand Networks InRouter302 V3.5.45

PRODUCT URLS

InRouter302 - https://www.inhandnetworks.com/products/inrouter300.html

CVSSV3 SCORE

4.3 - CVSS:3.0/AV:N/AC:L/PR:L/UI:N/S:U/C:N/I:L/A:N

CWE

CWE-489 - Leftover Debug Code

DETAILS

The InRouter302 is an industrial LTE router. It features remote management functionalities and several security protection mechanism, such as: VPN technologies, firewall functionalities, authorization management and several other features.

The InRouter302 offers telnet and sshd services. Both, when provided with the correct credentials, will allow access to the Router console.

Here is the prompt after the login:

```
**************
         Welcome to Router console
     Inhand
     Copyright @2001-2022, Beijing InHand Networks Co., Ltd.
     http://www.inhandnetworks.com
Model
                  : IR302-WLAN
Serial Number : RF3022141057203
Description : www.inhandnetworks.com
Current Version : V3.5.45
Current Bootloader Version: 1.1.3.r4955
get help for commands
-----
type '?' for detail help at any point
_____
 help -- get help for commands
language -- Set language
show -- show system information
             -- show system information
             -- exit current mode/console
 exit
 ping
             -- ping test
 comredirect -- COM redirector
 telnet
              -- telnet to a host
 traceroute
             -- trace route to a host
              -- turn on privileged commands
 enable
Router>
```

The Router console contains a command, called infct, that is not listed among the available functionalities. This is probably a leftover debug code. This command allows to enable or disable the access of the infactory view in the router console, leading to enabling advisory TALOS-2022-1496 again.

Exploit Proof of Concept

The command allows to enable the infactory view in the router console, specifying enable as argument:

TIMELINE

2022-05-24 - Vendor Disclosure

2022-10-25 - Vendor Patch Release

2022-10-27 - Public Release

CREDIT

Discovered by Francesco Benvenuto of Cisco Talos.

VULNERABILITY REPORTS

PREVIOUS REPORT

NEXT REPORT

TALOS-2022-1517

TALOS-2022-1518

