Talos Vulnerability Report

TALOS-2022-1499

InHand Networks InRouter302 console infactory_port OS command injection vulnerability

MAY 10, 2022

CVE NUMBER

CVE-2022-26420

Summary

An OS command injection vulnerability exists in the console infactory_port functionality of InHand Networks InRouter302 V3.5.37. A specially-crafted series of network requests can lead to remote code execution. An attacker can send a sequence of requests to trigger this vulnerability.

Tested Versions

InHand Networks InRouter302 V3.5.37

Product URLs

InRouter302 - https://www.inhandnetworks.com/products/inrouter300.html

CVSSv3 Score

9.9 - CVSS:3.0/AV:N/AC:L/PR:L/UI:N/S:C/C:H/I:H/A:H

CWE

CWE-78 - Improper Neutralization of Special Elements used in an OS Command ('OS Command Injection')

Details

The InRouter302 is an industrial LTE router. It features remote management functionalities and several security protection mechanism, such as: VPN technologies, firewall functionalities, authorization management and several other features.

The InRouter302 offers telnet and sshd services. Both, when provided with the correct credentials, will allow access to the Router console.

Here is the prompt after the login:

The infactory command allows, provided the correct password, to change some configuration and performs various tests. The factory mode view:

Router> infactory input password: Router(factory)# get help for commands type '?' for detail help at any point ----help -- get help for language exit -- get help for commands exit -- exit current mode/console reboot -- reboot system factory-model -- hardware model configure modem -- modem test
reset-key -- check the status of the reset button
com -- detecting serial ports port -- Getecting Serial points

net -- complete machine network port test

led -- LED lights test

wlan -- Wi-Fi test

mem -- check memory

hw_wdg -- check the hardware watchdog status

dio -- detect digital I/O

stategridsec -- detect stategrid security chip stategridsec -- detect stategrid security chip Router(factory)#

This mode offers several functionalities. For instance, the port functionality allows to set up or down the specified interface.

```
undefined4 port_functionality(undefined4 param_1,int command_line)
{
  [...]
  command_line_ptr[0] = command_line;
  if (command_line != 0) {
    first_arg = (char *)maybe_get_next_token(command_line_ptr);
    if (*first_arg != '\0') {
      is_equal = strncmp(first_arg, "status",6);
      if (is_equal == 0) {
        [\ldots]
      else {
        is_equal = strncmp(first_arg, "up", 2);
        if (((is_equal != 0) && (is_equal = strncmp(first_arg,"down",4), is_equal !=
0))||
           (interface name = (char *)maybe get_next_token(command_line_ptr),
*interface name == '\0'
           )) goto LAB_00411340;
        is_equal = strncmp(interface_name, "lan0", 4);
        if ((is_equal != 0) || (is_equal = strncmp(first_arg, "down",4), is_equal !=
0)) {
          snprintf(command_to_execute,0x40,"ip link set %s
%s",interface_name,first_arg);
          system(command_to_execute);
[3]
          [...]
}
```

If the first provided argument is up, then the second one, parsed at [1], will be later used at [2] to form the string ip link set <interface> up. This string will later be used at [3] as argument of the system function.

The second argument is not properly sanitized, and a command injection can occur at [3]. An attacker, able to reach the net functionality, would be able to obtain a root shell.

Exploit Proof of Concept

Provided the command port up a\$IFSa\$IFS;/bin/sh;, in the factory mode view, a root shell will be obtained:

Vendor Response

The vendor has updated their website and uploaded the latest firmware on it. https://inhandnetworks.com/product-security-advisories.html https://www.inhandnetworks.com/products/inrouter300.html#link4

https://www.inhandnetworks.com/upload/attachment/202205/10/InHand-PSA-2022-01.pdf

Timeline

2022-03-30 - Vendor Disclosure 2022-05-10 - Public Release 2022-05-10 - Vendor Patch Release

CREDIT

Discovered by Francesco Benvenuto of Cisco Talos.

VULNERABILITY REPORTS

PREVIOUS REPORT

NEXT REPORT

TALOS-2022-1500

TALOS-2022-1478

