

## GILES CHEMICAL ~ PREMIER MAGNESIA

**Company Procedure** 

Title: ARCH Sampling and Testing Number: L12-PR-100-038

Owner: Ashley Williams Revision: 4

Effective Date: 5/18/2016 Page: 1 of 2



### 1.0 Purpose

This procedure describes the method for sampling and testing for Arch loads

## 2.0 Scope

This procedure applies to all finished Arch loads. All testing is to be performed in the QA Lab.

### 3.0 Responsibility

Quality Personnel is responsible for testing Arch loads.

# 4.0 Safety Considerations

Wear the appropriate lab PPE and follow area safety rules.

Safety is a condition of employment. Employees are not authorized to work in an unsafe manner and are prohibited from harming the environment of the facility or community.

# 5.0 Materials/Equipment

- Sample bags
- Sieve machine Sieves 16,50,70, and pan
- Mass Balance accurate to 0.01g or better
- Weigh boat
- Small spatula
- Brush
- Gloves

### 6.0 Procedure

#### SAMPLING

- 1. Operator will obtain sample from top of super sacks 1, 5, 10, 15, and 20. The empty sample bags will be provided by lab and placed on operators table. The bags will have a place for the operator to record lot#, date, time and the letter designated to the specific Arch load in process. Bags are to be filled completely and sealed, then placed in the Arch box for lab pick-up.
- 2. Quality Associate will pick up samples and transport them to lab for testing.



## GILES CHEMICAL ~ PREMIER MAGNESIA

**Company Procedure** 

Title: ARCH Sampling and Testing Number: L12-PR-100-038

Owner: Ashley Williams Revision: 4

Effective Date: 5/18/2016 Page: 2 of 2



#### LAB TESTING

- 1. Record the Arch letter and the pick-up number on the *OA Arch Testing (L12-PR-100-F038)*
- 2. The lab is to weigh 50 grams of sample from the first sample bag on calibrated lab scale and add to Sieve Machine that contains sieves.
- 3. The size of sieves to be used are 16, 50 and 70 mesh as well as left over pan. In this case left over pan will reflect all sample < 70 mesh.
- 4. Ensure that the timer is set for 2 minutes on the sieve machine.
- 5. Run the Sieve Machine for 2 minutes at 50% amplitude. This applies for each sample tested.
- 6. Weigh each screen of material on balance and record weight.
- 7. Record the weights of each screen on the spreadsheet in the corresponding column.
- 8. Repeat steps 2-7 for each Sample Bag.
- 9. Column mesh size <70 cannot be >2.00%. If a sample fails this requirement, Quality Associate will take samples from the pallet before and pallet after the failed sample. If these pallets fail, the next pallets will be checked until a passing sample is obtained. If super sack fails this requirement a new sack will be produced and sample will be taken and tested. If the material meets specification after additional testing the load will be released. If whole load of ARCH fails then a new load will be produced. If material meets specification it will be released. If load fails on any sample the Director of Quality, Plant Manager and Lead Operator should be notified immediately.
- 10. Results must be emailed to ARCH before load is released. Quality Department is responsible for sending results.
- 11. Attach a copy of the analysis to the Bill of Lading and sign off approval on the front page of the BOL.

#### 7.0 Reference Documents

*QA- Arch Testing (L12-PR-100-F038)* 

### 8.0 Amendment Record

Added Amplitude Reference. Added Accuracy Reference. Updated Title of Reference document.