

Hexagon Manufacturing Intelligence Metrology House Halesfield 13, Telford

Halesfield 13, Tellord Shropshire, TF7 4PL Tel: +44(0)870 446 2667 Fax: +44(0)870 446 2668 www.hexagonmi.com Registration No 1523574 England

| Total Preventative Maintenance Plan | | | | | | |
|-------------------------------------|-----------|---|---------------------------------------|-----------------------|--|--|
| Process | Frequency | Maintenance Standard | Required Equipment | Estimated Time | | |
| Full Visual Inspection | D | Check for missing/damaged parts. Check for | Visual | < 2 Mins | | |
| | | abnormal vibrations. | | | | |
| Check Guards and Covers | D | Repair/replace damaged/missing covers. | Visual | < 2 Mins | | |
| Check Pneumatic Pressure | D | Check the regulator pressure is set to 0.46MPa. | Visual | < 2 Mins | | |
| Check Main Air Inlet Filters | D | | Visual < 2 Mins | | | |
| Clean Worktable | D | Worktable should be clear of dirt, grease, and swarf. | Lint free cloth, Handy Foam | < 5 Mins | | |
| Clean Optical Scales | D | Scale should be free of grease. | Lint free cloth Isopropanol | < 5 Mins | | |
| | | | ONLY | | | |
| Clean Bearing Ways | D | Bearing way should be clear of dirt, grease, and | Lint free cloth, Fastklean | < 10 Mins | | |
| | | swarf. | ONLY | | | |
| Check The Jogbox Cable | M | Ensure cable outer sheath is undamaged. | Visual | < 2 Mins | | |
| Clean The CMM Frame | M | Frame should be clear of dirt, grease, and swarf. | Lint free cloth, Handy Foam | < 10 Mins | | |
| Check E-Stops | M | Physically intact and in working order. | Physically depress to ensure < 2 Mins | | | |
| | | | operation | | | |
| Check Buttons and Switches | Q | Physically intact and in working order. Physically | - | < 2 Mins | | |
| | | depress to ensure operation. | | | | |
| Check Air Pipes for Leaks | Q | No leakage of positive air. | Torch | < 10 Mins | | |
| Counterbalance Wire | 5M | Carefully inspect, clean, and grease the steel wire | NLGI 1 Rated Grease, 3mm | < 15 Mins | | |
| | | counterbalancing cylinder. | Hex Key | | | |
| Check Axis Reduction & Drive Belts | 5M | Ensure there are no signs of wear or that belt is | Visual | < 15 Mins | | |
| | | loose. | | | | |

| Key | | | | | |
|-----------------------|---------------------------|-----------------------------|-----------------------------|--|--|
| D | M | Q | 5M | | |
| Daily / Every 8 Hours | Monthly / Every 165 Hours | Quarterly / Every 500 Hours | 5 Monthly / Every 850 Hours | | |