

Fire Brigade Incident Report

Claim ID	PROP-B2B-2026-0417
Insured	Nordhafen Precision Parts GmbH
Document type	Official incident report
Issued by	Hannover Fire Brigade
Document date	14 May 2026
Loss location	Hafenstrasse 18, Building B, 30179 Hannover, Germany

Incident identifiers

Field	Entry
Authority reference	BF-H-2026-05-12-1148
Call received	12 May 2026, 02:47:32 CEST
Dispatch	Station 4 and Station 7; 5 appliances; 28 personnel
Premises recorded	Hafenstrasse 18, Unit 3, industrial estate north gate
Occupancy observed	Metal-processing facility; loading bay and production hall; no residential occupancy
Injuries	None reported; one security guard treated for smoke exposure but not transported

Scene observations by officer in charge

On arrival at 02:56, smoke was issuing from the loading bay door on the east elevation. Sprinkler water was running under the door into the external yard drain. The officer reported visible flame in the south-east charging alcove near a red electric pallet truck and plastic packaging cages.

Thermal imaging showed elevated temperatures along the cable tray above the charging alcove and lower heat signatures in the adjacent maintenance room. Fire spread was limited by sprinkler activation, but smoke migrated through the CNC hall and mezzanine office.

Operational timeline

Time	Action / observation
02:47	Emergency call registered from alarm receiving centre; caller described sprinkler activation and smoke detector zone B-3.
02:56	First unit arrived; external smoke visible; east loading-bay shutter closed.
03:02	Forced entry through personnel door; sprinkler operating; small seat of fire identified.
03:18	Main flame knocked down; overhaul commenced; charger, battery pack, socket, and cable area left in place for investigation.
03:44	Sprinkler zone isolated in coordination with site keyholder; water extraction requested.
04:37	Incident handed to police/fire investigation; access restricted to loading bay and CNC hall.

Suppression and damage notes

- Approx. 17 sprinkler heads were reported active or heat-damaged; only 5 heads were confirmed flowing at handover.
- Fire damage concentrated around charging alcove, pallet truck, packaging cage, low-voltage charger, and adjacent wall cladding.
- Water damage observed in packing area, finished-goods stock racks A1-A5, floor trench, and lift pit by roller shutter.
- Smoke deposits observed across CNC hall, air-handling intake, tool storage cabinets, and mezzanine server cabinet.
- Fire brigade did not determine final cause. The report states "electrical equipment in charging alcove cannot be excluded".

Items preserved / removed

Item	Status	Comment
Pallet truck battery	Preserved	Left in place, cooled, police tape applied.
Charger unit marked HL-48V-70A	Preserved	Visible heat damage; photographed before isolation.
Multi-socket extension lead	Removed to evidence bag by police	Found under metal bench; partially melted.
Packaging cages	Moved for overhaul	Two cages disposed as fire debris after photographs.
CCTV recorder	Not located during fire brigade handover	Security guard said recorder was in mezzanine office.

Cautions

This incident report is operational only. It is not a formal origin-and-cause determination. Times reflect dispatch-system records and may differ from premises alarm logs.