

Maintenance Contractor Service Records

Claim ID	PROP-B2B-2026-0417
Insured	Nordhafen Precision Parts GmbH
Document type	Service records
Issued by	HanseLift Service GmbH
Document date	28 Jan 2026 - 05 May 2026
Loss location	Hafenstrasse 18, Building B, 30179 Hannover, Germany

Records produced by HanseLift Service GmbH

The insured provided a partial service pack from HanseLift Service GmbH. The pack covers the electric pallet truck, charger, loading-bay door motor, and a site walk-through. It does not include original charger installation documentation.

Record	Date	Technician	Relevant entry
HL-2026-0128	28 Jan 2026	S. Martens	Pallet truck battery capacity test; charger output within range; advised keeping cardboard away from charger.
HL-2026-0319	19 Mar 2026	A. Nowak	Roller shutter motor adjusted; noted water ingress near dock leveller after heavy rain.
HL-2026-0504	04 May 2026	S. Martens	Replaced charger supply cable and plug; load-tested 45 minutes; no abnormal heat.
HL-2026-0504-P	04 May 2026	S. Martens	Parts line: "Cable set charger 48V"; no serial photo attached.

Technician comments copied from work order

"Customer uses charger on bench socket because old wall-mounted isolator not live. Advised plant manager that permanent installation should be checked by electrician. Cardboard sleeves stored too close. Customer says night charging only when order volume high."

The final work order tick-box marked "safe to operate" but the comment field says "electrical installation by customer, not HanseLift scope".

Missing records

- No photograph of the replaced cable or recovered old cable was included.
- No confirmation that charger was connected to a dedicated fixed circuit.
- No evidence that the insurer charging warranty was discussed with HanseLift.
- No service certificate for sprinkler system was included in this service pack.

Sprinkler and building services notes found in same folder

Document	Date	Entry	Potential conflict
Landlord service certificate	18 Jan 2026	Annual sprinkler maintenance completed by SprinkSafe Nord.	Lease extract says landlord system current.
HanseLift site walk-through note	04 May 2026	"Sprinkler heads near loading bay dusty; no recent tag visible."	Suggests inspection tag may not have been seen by technician.
Email from plant manager	05 May 2026	"Please quote for moving charger to fixed wall point after May shipments."	Supports awareness of non-permanent setup before loss.
Landlord portal ticket	11 Apr 2026	Tenant reported slow roller shutter and wet floor after rain.	Possible unrelated water issue in same area.

Relevance to claim

The service records are relevant to both causation and subrogation. They may support an argument that the charger/plug was recently serviced, but they also show HanseLift warned the insured about combustible storage and permanent installation. The insurer should request the technician's full notes and parts photographs before taking a final position.