

Witness Statements Pack

Claim ID	PROP-B2B-2026-0417
Insured	Nordhafen Precision Parts GmbH
Document type	Witness statements
Issued by	Baltic Loss Adjusting GmbH
Document date	13-14 May 2026
Loss location	Hafenstrasse 18, Building B, 30179 Hannover, Germany

Statement 1 - night security guard

Field	Entry
Witness	Tobias Lenz, contracted security guard, NordWacht Security GmbH
Statement date	13 May 2026, 16:20
Shift	11 May 2026 22:00 to 12 May 2026 06:00

Mr Lenz stated that he was in the gatehouse when the alarm panel showed "sprinkler flow B-3" at approximately 02:13. He walked toward Building B and smelled plastic smoke before seeing haze through the loading-bay window. He called the alarm centre rather than the fire brigade directly because the site instruction card said the alarm centre would dispatch emergency services.

He said the east loading-bay door was closed. He did not see open flame until firefighters forced entry. He remembered that the red pallet truck was connected to a charger when he made his 23:45 patrol. He said he had previously seen a blue extension lead on the charging bench but could not confirm it was used that night.

Statement 2 - production shift lead

Field	Entry
Witness	Yara Demir, shift lead CNC line 2
Statement date	14 May 2026, 09:10
Last on premises	11 May 2026, left loading bay at about 20:35

Ms Demir stated that the pallet truck was usually charged only after late shifts. She connected the charger at about 20:20 using the wall socket behind the bench. She did not use an extension lead and did not see cardboard directly against the charger. She said a HanseLift technician had repaired the charger cable the previous week and told her it was safe.

Ms Demir also said the charger isolator on the wall had been "dead for months" and that maintenance had discussed moving the charger after the Volta Pumps order. She recalled a faint hot-plastic smell near the bench during the prior week but attributed it to shrink-wrap equipment.

Statement 3 - plant manager phone note

Field	Entry
Person	Erik Schulte, plant manager
Taken by	Leonie Brandt, adjuster
Date/time	13 May 2026, 12:15

Mr Schulte said the first call he received was at approximately 02:38 from the security guard. He arrived at the site around 03:25 and saw firefighters working in the loading bay. He believed the source was "probably the charging station" but also noted that a maintenance room behind the bay held cleaning aerosols and shrink-wrap tools.

He admitted that the charger was not on a dedicated fixed charging circuit after an old isolator failed. He stated that management intended to install a permanent point in June 2026. He denied knowing that this could affect insurance cover.

Witness conflict summary

Topic	Security guard	Shift lead	Plant manager
First alarm / call	Alarm panel at about 02:13; alarm centre called	Not present	Call received at about 02:38
Extension lead	Seen before, not confirmed on loss night	Denies using extension lead	Aware charger was not on dedicated circuit
Combustibles near charger	Packaging often near bench	No cardboard directly against charger	High order volume caused crowded bay
Prior warning signs	No specific warning	Hot-plastic smell prior week	Old isolator dead for months
Cause opinion	Did not see flame before fire brigade entry	No opinion; cable repaired recently	Charging station probable but maintenance room also possible

Use of statements

The statements are unverified and should be tested against CCTV, alarm logs, service records, and laboratory analysis. They are deliberately useful for conflicting-fact extraction: alarm timing, charger connection method, awareness of risk, and combustible storage differ materially.