

License Number

CBD1800257

Customer

Harman International (China) Holdings Co., Ltd.
Package: MSR_Vector_SLP4 - MSR project license
"Head Unit" for BAIC

Maintenance Expiry Date

2019-06-01

SIP Version

21.06.09

SLP

MSR_Vector_SLP4

Delivery Number

D01

Report Creation Date

2018-11-27

Contact

In case of questions or the need for an update of the basic software delivery, please contact Support@vector.com or your Vector contact person.

Table of Contents

1. [Introduction](#)
 - [1.1 Resolving Issues](#)
 - [1.2 Issue Classification](#)
2. [New Issues](#)
 - [2.1 Safety Relevant Issues: 8](#)
 - [2.2 Runtime Issues without Workaround: 9](#)
 - [2.3 Runtime Issues with Workaround: 12](#)
 - [2.4 Not Released Functionality: 9](#)
 - [2.5 Apparent Issues: 80](#)
 - [2.6 Compiler Warnings: 29](#)
3. [New Issues for Information: 0](#)
4. [Report Legend](#)
5. [3rd Party Software Issues](#)
6. [Quality Management Contact](#)

1. Introduction

1.1 Resolving Issues

Reported issues are not automatically fixed with the next update delivery.

If a reported issue shall be fixed, please contact Vector agree on the issues that can be fixed with upcoming deliveries.

Please note that Vector may fix issues without explicit request.

1.2 Issue Classification

This Issue Report provides issues that have been detected since the last report. The issues have been classified to facilitate the assessment of their impact:

The chapter 'New Issues' lists issues that have been detected since the last report and which could not be excluded based on the use-case defined in the questionnaire. The issues are classified as follows:

- **Safety Related Issues:** Safety related issues have impact on the functional safety of the software module. If this issue interferes with the functional safety concept of the ECU, this module (or module configuration) must not be used for serial production in a safety-related project. The effect of the issue to the ECU functionality and functional safety has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.
- **Runtime Issues without Workaround:** Runtime issues without a workaround require an update of the software delivery in case the issue affects the ECU overall functionality. The effect of an issue to the ECU functionality has to be analyzed by the customer as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.
- **Runtime Issues with Workaround:** It is not recommended to update a delivery due to a runtime issue with a documented workaround. The effect of an issue to the ECU functionality has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.
- **Not Released Functionality:** Not released functionalities (BETA) are either complete software modules or features in the software module that have not yet passed a complete development cycle (they are e.g. not or only partly tested). If a BETA issue ticket affects a complete software module, the software module must not be used for serial production. If a BETA issue ticket affects a feature in the software module, the user has to ensure that all BETA features are disabled as indicated for the serial production release of the ECU.
- **Apparent Issues:** Apparent issues are detected immediately when using the software module. If an issue does not show up while working with the software module, the ECU project is not affected by the issue. Apparent issues may or may not have workarounds.
- **Compiler Warnings:** As a service we also provide the known compiler warnings. The occurrence of a compiler warning may depend on the used software module configuration and compiler settings.

The chapter 'New Issues for Information' lists issues that are not relevant for the use-case that has been documented in the questionnaire provided to Vector. The issues may, however, be relevant for other use-cases. Additionally, issues that have been accepted or are tolerated by the OEM (as defined in the questionnaire) are reported here.

2. New Issues

2.1 Safety Relevant Issues

Safety related issues have impact on the functional safety of the software module. If this issue interferes with the functional safety concept of the ECU, this module (or module configuration) must not be used for serial production in a safety-related project.

The effect of the issue to the ECU functionality and functional safety has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.

Index

ESCAN00097497	BETA version - the BSW module has a feature with BETA state (FEAT-3197: GCC support for ARM platform) Os_PlatformArmCortexMGen7@Implementation
ESCAN00097518	CRC32 calculations deliver wrong results MemService_AsrNvM@Implementation
ESCAN00098617	Shutdown / Reset of a multicore ECU is not performed as expected SysService_Asr4EcuM@Implementation
ESCAN00100398	Schedule table expiry point actions are not fully executed on an expiry point with more than 255 actions configured. Os_CoreGen7@Implementation
ESCAN00100861	COM call with non typesafe parameters configuration feedback does not list all Com_ReceiveSignal calls Rte_Analyzer@Application
ESCAN00100968	MICROSAR OS does support only 1023 different task priorities. Os_CoreGen7@Implementation
ESCAN00101272	ProtectionHook() call in StartOS() on S32K Os_PlatformArmCortexMGen7@GenTool_GeneratorMsr
ESCAN00101305	Reception via LdCom TP fails Rte_Core@Implementation

ESCAN00097497	BETA version - the BSW module has a feature with BETA state (FEAT-3197: GCC support for ARM platform)
Component@Subcomponent:	Os_PlatformArmCortexMGen7@Implementation
First affected version:	2.09.00
Fixed in versions:	
Problem Description:	
What is the impact of BETA software:	

BETA software	
- must not be used in productive projects as they may result in unpredictable ECU behavior - may not provide all features intended for the productive project - is not or only partly tested and not all quality measures have taken place	
Which functionality is BETA:	

The following feature/function is in BETA state.	
- GCC support for SC3/SC4	
To ensure that only productive code is used verify that:	
- the scalability class must not be set to SC3 or SC4	
Resolution Description:	

ESCAN00097518 CRC32 calculations deliver wrong results**Component@Subcomponent:** MemService_AsrNvM@Implementation**First affected version:** 5.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

CRC32s calculated internally by NVM are not as specified by AUTOSAR, i.e. the results may differ, depending on number of single CRC library calls done per NVM block. Calculated values are still CRCs, but they don't match the results from using corresponding standardized CRC32 calculations

Since CRC handling is done internally, this is usually not visible to users.

The issue becomes visible, if NVM's configuration changed between a write and a read request (see below): Data may become unreadable due to failed CRC check.

When does this happen:

It happens at run-time during CRC calculation. However this behavior is symmetric, i.e. calculated CRC during writes match the CRC calculated during reads. Data can be written and read back as expected.

In which configuration does this happen:

It happens for all blocks having CRC (NvMBlockUseCrc) enabled, and CRC type (NvMBlockCrcType) was set to CRC32 .
If (in a running project), the number of "Bytes per MainFunction" (NvMCrcNumOfBytes) was changed, existing data become unreadable, because same data result in different CRC.

Resolution Description:

Workaround:

In a running project's configuration don't change the number of "Bytes per MainFunction" (NvMCrcNumOfBytes).

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00098617 Shutdown / Reset of a multicore ECU is not performed as expected	
Component@Subcomponent:	SysService_Asr4EcuM@Implementation
First affected version:	5.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

A requested shutdown / reset may not be finished completely by the EcuM.	
When does this happen:	

If a shutdown / reset is requested.	
In which configuration does this happen:	

This can only happen on multicore devices that execute the EcuM on multiple cores with different levels of diagnostic coverage (e.g. a system with a core with lock-step and a core without lock-step).	
Resolution Description:	
Workaround:	

No workaround is available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100398 Schedule table expiry point actions are not fully executed on an expiry point with more than 255 actions configured.

Component@Subcomponent: Os_CoreGen7@Implementation

First affected version: 1.00.00

Fixed in versions: 2.25.00

Problem Description:

What happens (symptoms):

On execution of a schedule table expiry point, not all configured actions are performed.

Mind that an earlier symptom is a compiler warning about integer truncation at one of these places in file Os_ScheduleTable_Lcfg.c:

```
(1) Line containing: /* .EventCount = */
OS_CFG_NUM_EXPO_<ScheduleTableName>_<ExpiryPointIdx>_EVENTS
(2) Line containing: /* .TaskCount = */
OS_CFG_NUM_EXPO_<ScheduleTableName>_<ExpiryPointIdx>_TASKS
```

When does this happen:

This happens always and immediately when a specific schedule table expiry point is executed without a chance of recovery from that malfunction. The only condition for the occurrence of the malfunction is in the configuration as described below.

In which configuration does this happen:

This may happen in any of the two cases below:

(1) when the number of event settings (container /MICROSAR/Os/OsScheduleTable/OsScheduleTableExpiryPoint/OsScheduleTableEventSetting) configured for the expiry point exceeds the limit of 255.

In this case the malfunction only occurs if the type uint8_least is configured to be an 8 bit data type

(2) when the number of task activations (container /MICROSAR/Os/OsScheduleTable/OsScheduleTableExpiryPoint/OsScheduleTableTaskActivation) configured for the expiry point exceeds the limit of 255.

In this case the malfunction only occurs if both conditions below are met:

- less than 256 tasks have been configured (so some of them will be multiply activated by the expiry point) and
- the compiler has chosen to use an 8 bit data type to represent the enumeration data type: 'TaskType'.

Resolution Description:

Workaround:

No workaround available.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100861	COM call with non typesafe parameters configuration feedback does not list all Com_ReceiveSignal calls
Component@Subcomponent:	Rte_Analyzer@Application
First affected version:	0.09.00
Fixed in versions:	1.03.00
Problem Description:	
What happens (symptoms):	

The configuration feedback misses entries of category "COM call with non typesafe parameters (SMI-684)"	
The customer might miss to check the COM signal sizes if he does the checks purely on the listed configuration feedback entries.	
When COM runs in the ASIL partition and COM writes more bytes than expected by the RTE because of different signal size assumptions, memory corruption can occur.	
When does this happen:	

During analysis.	
In which configuration does this happen:	

This happens in two cases	
- when the signals are 8-Bit COM signals (the calls are not listed at all in this case)	
- when Com_ReceiveSignal is called directly in Rte_Read macros (then the calls are listed in the wrong category Call with non typesafe parameters (SMI-2072))	
Resolution Description:	
Workaround:	

Search for Com_Receive in the RTE sources in order to determine the relevant COM signals.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100968 MICROSAR OS does support only 1023 different task priorities.	
Component@Subcomponent:	Os_CoreGen7@Implementation
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Task scheduling does not work as expected.	
Tasks with a calculated priority higher then 1023 are not scheduled correctly.	
When does this happen:	

This happens always during system runtime.	
In which configuration does this happen:	

This happens in configurations where more then 1023 tasks are configured with different priorities. (/MICROSAR/Os/OsTask/OsTaskPriority)	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00101272 ProtectionHook() call in StartOS() on S32K	
Component@Subcomponent:	Os_PlatformArmCortexMGen7@GenTool_GeneratorMsr
First affected version:	2.01.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

A memory protection violation occurs in StartOS() in the very first function call after the MPU access right have been switched.	
When does this happen:	

Always and immediately at the start of the very first task or ISR.	
In which configuration does this happen:	

If ((OsScalabilityClass==SC3) && (#GlobalMPURegion + #ApplicationRegion + #ThreadApplicationRegion >= HardwareAvailableRegions -1))	
Resolution Description:	
Workaround:	

Configure less than 7 among (global, application, thread regions).	
Resolution:	

Create a validator for the corner case.	

ESCAN00101305 Reception via LdCom TP fails	
Component@Subcomponent:	Rte_Core@Implementation
First affected version:	1.19.00
Fixed in versions:	1.20.00
Problem Description:	
What happens (symptoms):	

If Rte_LdComCbKStartOfReception is called with SduLength=0, the reception buffer is not locked although BUFREQ_OK is returned.	
If another SDU is to be received, the corresponding Rte_LdComCbKCopyRxData function returns BUFREQ_E_NOT_OK.	
Thus the reception via LdCom TP fails.	
When does this happen:	

During runtime whenever data is received via LdCom TP callbacks.	
In which configuration does this happen:	

This happens when the configuration uses the LdCom TP API.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

2.2 Runtime Issues without Workaround

Runtime issues without a workaround require an update of the software delivery in case the issue affects the ECU overall functionality. The effect of an issue to the ECU functionality has to be analyzed by the customer as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.

Index

ESCAN00096102	Main function tick time resolution smaller than 1 ms is not supported Ccl_Asr4SmCan@GenTool_GeneratorMsr
ESCAN00098581	Init Action Lists on multiple partitions are not working correct SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00099928	Communication Interface Queued Rx API forwarding routing path do not work with regular PduR queue Gw_AsrPduRCfg5@Implementation
ESCAN00100584	Dem doesn't return DEM_CLEAR_FAILED although all ClearEventAllowed callbacks return FALSE Diag_Asr4Dem@Implementation
ESCAN00100732	Dem_DisableDTCRecordUpdate is not processed Diag_Asr4Dem@Implementation
ESCAN00100910	No reception of Rx ComIPdus after re-activation of ComIPduGroup without initialization using deferred event cache Il_AsrComCfg5@Implementation
ESCAN00101118	Invalid monitoring of requests to other ECUs Diag_Asr4Dcm@GenTool_GeneratorMsr
ESCAN00101199	Service 0x2A: Overwritten RAM behind a DCM buffer Diag_Asr4Dcm@GenTool_GeneratorMsr
ESCAN00101202	Service 0x2A: Overwritten RAM behind a DCM buffer when using UUDT delay timer Diag_Asr4Dcm@Implementation

ESCAN00096102 Main function tick time resolution smaller than 1 ms is not supported	
Component@Subcomponent:	Ccl_Asr4SmCan@GenTool_GeneratorMsr
First affected version:	1.00.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- AUTOSAR defines a float data type to configure the main function tick time. The generator truncates the configured tick time to a millisecond. e.g. 1.5 ms tick time is configured, but the counter values generated in the code are based on a 1 ms tick time. As a result, wrong timer values are used by the module When does this happen: ----- always In which configuration does this happen: ----- If a main function tick time with a resolution smaller than 1 ms is configured	
Resolution Description: Workaround: ----- No workaround available. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00098581 Init Action Lists on multiple partitions are not working correct	
Component@Subcomponent:	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
First affected version:	13.00.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- Init Action Lists might be not executed as expected, as a consequence some modules are not initialized. When does this happen: ----- During initialization. In which configuration does this happen: ----- Only in configurations with multiple BswMConfig containers (Beta functionality) AND The BswMActionListPriority is set to the same value for init action lists configured in different BswMConfig containers.	
Resolution Description: Workaround: ----- No workaround available. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00099928 Communication Interface Queued Rx API forwarding routing path do not work with regular PduR queue**Component@Subcomponent:** Gw_AsrPduRCfg5@Implementation**First affected version:** 11.03.00**Fixed in versions:** 13.00.00**Problem Description:**

What happens (symptoms):

Communication Interface Queued Rx API Forwarding routing paths do not work correctly. The Queue will always overflow and will therefore be flushed. A DET error with API-ID PDUR_FCT_RMIF_FQ and Error code PDUR_E_PDU_INSTANCES_LOST is reported if error reporting is enabled.

After the flush the same behavior occurs again.

The Pdu which is first in the queue will be forwarded to the upper layer in context of the MainFunction. All other Pdus will remain in the queue and will not be forwarded. They will be discarded at the queue flush.

When does this happen:

Always during runtime.

In which configuration does this happen:

The routing path must satisfy all of the following conditions:

- Communication interface Pdu
- API Forwarding
- Rx direction
- Queue depth set to some value > 0

Resolution Description:

Workaround:

For Multicore routing paths use the so called 'Multicore queue'. The queueing can't be used for singlecore routing paths.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100584 Dem doesn't return DEM_CLEAR_FAILED although all ClearEventAllowed callbacks return FALSE	
Component@Subcomponent:	Diag_Asr4Dem@Implementation
First affected version:	13.00.00
Fixed in versions:	16.00.00
Problem Description: What happens (symptoms): ----- The Dem doesn't return DEM_CLEAR_FAILED and clears global statistics, although no DTC was cleared. When does this happen: ----- When a clear request for a group of DTCs is triggered and the ClearEventAllowed callbacks for all concerned events return FALSE (in case of event combination ClearEventAllowed returns FALSE for at least one event of the DTC). In which configuration does this happen: ----- When ClearEventAllowed callbacks are configured (Dem/DemConfigSet/DemEventParameter/DemCallbackClearEventAllowed)	
Resolution Description: Workaround: ----- No workaround available. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00100732 Dem_DisableDTCRecordUpdate is not processed

Component@Subcomponent: Diag_Asr4Dem@Implementation

First affected version: 14.05.00

Fixed in versions: 16.00.00

Problem Description:

What happens (symptoms):

Dem_DisableDTCRecordUpdate is not processed and returns DEM_PENDING.
After a (configurable) number of DEM_PENDING, Dcm cancels requested UDS Service and sends negative response 0x10 (generalReject)

When does this happen:

In rare cases when requesting Service \$19 (ReadDTCInformation) with subfunctions

0x04 (reportDTCsSnapshotRecordByDTCNumber)
0x06 (reportDTCExtDataRecordByDTCNumber)
0x10 (reportMirrorMemoryDTCExtDataRecordByDTCNumber)
0x18 (reportUserDefMemoryDTCsSnapshotRecordByDTCNumber)
0x19 (reportUserDefMemoryDTCExtDataRecordByDTCNumber)

via DCM.

In which configuration does this happen:

Dem/DemGeneral/DemDcmSupport == TRUE

Resolution Description:

Workaround:

No workaround available.

The problem should only occur rarely due to unlikely race condition. Repeating the UDS request will be successful.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100910 No reception of Rx ComIPdus after re-activation of ComIPduGroup without initialization using deferred event cache

Component@Subcomponent: Il_AsrComCfg5@Implementation
First affected version: 8.01.00
Fixed in versions: 13.03.04, 14.00.03, 16.01.00, 15.01.03

Problem Description:

What happens (symptoms):

Deferred Rx PDUs might not be processed after the respective ComIPduGroup is restarted without initialization if the deferred event cache is used . This situation will sustain until the deferred event cache overflows.

When does this happen:

This issue may occur at runtime, whenever the ComIPduGroup is disabled after a Com_RxIndication, but before the next Rx MainFunction call.
 If the ComIPduGroup is then restarted without re-initialization (initialize-Parameter of Com_IpduGroupControl or Com_IpduGroupStart is set to FALSE), the specific ComIPdu is not cached properly.

In which configuration does this happen:

ComDeferredEventCacheSupport == TRUE
 AND
 type of processed Rx PDU is set to DEFERRED

Resolution Description:

Workaround:

If possible, set ComDeferredEventCacheSupport to FALSE.
 or
 call Com_IpduGroupControl/ Com_IpduGroupStart with initialize==TRUE.

Otherwise no workaround is available.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00101118 Invalid monitoring of requests to other ECUs

Component@Subcomponent: Diag_Asr4Dcm@GenTool_GeneratorMsr
First affected version: 4.00.00
Fixed in versions: 10.04.01

Problem Description:

What happens (symptoms):

-
- (1) DCM terminates service processing of a request when receiving a second request of any known client.
 - OR
 - (2) DCM does not terminate service processing if client sends second request to another ECU with address 0x00.

When does this happen:

At run time when a client sends a second diagnostic request to own (1) or another (2) ECU during processing of the first request.

In which configuration does this happen:

-
- Monitoring of requests to other ECUs are supported (in Dcm_Cfg.h: #define DCM_NET_MONITOR_FOREIGN_N_TA_ENABLED == STD_ON)
 - AND
 - At least one ECU address exists with value greater than or equal to 0x80 (in DCM ECUC: /Dcm/DcmConfigSet/DcmDsl/DcmDslProtocol/DcmDslProtocolRow/DcmDslConnection/DcmDslMainConnection/DslPhysicalEcuAddress)

Resolution Description:

Workaround:

No workaround available.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00101199 Service 0x2A: Overwritten RAM behind a DCM buffer

Component@Subcomponent: Diag_Asr4Dcm@GenTool_GeneratorMsr
First affected version: 9.01.00
Fixed in versions: 10.04.01

Problem Description:

What happens (symptoms):

 The memory location behind a DCM message buffer will be corrupted.
 The amount of overwritten data depends on the difference between the largest UUDT Pdu length and the largest configured periodic DID.

After ECU reset, the normal operation should be possible.

When does this happen:

-
- During scheduling of a periodic DDDID via service 0x2A
- AND
- The definition of that periodic DDDID is extended in the meanwhile via service 0x2C so that all following conditions hold:
 - length greater than 7
 - length greater than the length of every available periodic DID
 - length smaller than the Pdu length

In which configuration does this happen:

-
- Service 0x2A is supported (in Dcm_Cfg.h: #define DCM_SVC_2A_SUPPORT_ENABLED == STD_ON)
- AND
- Service 0x2C is supported (in Dcm_Cfg.h: #define DCM_SVC_2C_SUPPORT_ENABLED == STD_ON)
- AND
- At least one DDDID in range 0xF200-0xF2FF is configured (in Dcm_Cfg.h: #define DCM_DIDMGR_PERIODICDYNDID_ENABLED == STD_ON)
- AND
- At least one "EcuC/EcucPduCollection/Pdu/PduLength" of Pdu referenced via DcmDslPeriodicConnection is greater than 7 and greater than the length of every configured periodic DID (in Dcm_Cfg.h: #define DCM_NET_PERIODIC_BUFFER_SIZE < PduLength)

Resolution Description:

Workaround:

 Configure a periodic DID with a size equal to the largest UUDT Pdu length.

Resolution:

 The described issue is corrected by modification of all affected work-products.

ESCAN00101202 Service 0x2A: Overwritten RAM behind a DCM buffer when using UUDT delay timer

Component@Subcomponent: Diag_Asr4Dcm@Implementation
First affected version: 8.04.00
Fixed in versions: 11.00.00, 10.04.01

Problem Description:

What happens (symptoms):

 The memory location behind a DCM message buffer will be corrupted.
 At most two bytes will be overwritten.

After ECU reset, the normal operation should be possible.

Note:

In SafeBSW mode (in Dcm_Cfg.h: #define DCM_DEV_RUNTIME_CHECKS == STD_ON) the memory corruption will be prevented and a DET error reported instead if configured (in Dcm_Cfg.h: #define DCM_DEV_ERROR_REPORT == STD_ON).

When does this happen:

 Each time when Dcm_TxConfirmation() is called for a transmitted UUDT message.

In which configuration does this happen:

 - Service 0x2A is supported (in Dcm_Cfg.h: #define DCM_SVC_2A_SUPPORT_ENABLED == STD_ON)
 AND
 - Periodic transmission UUDT delay timer is supported (in Dcm_Cfg.h: #define DCM_NET_UUDT_DELAYTIMER_ENABLED == STD_ON)

Resolution Description:

Workaround:

 Zero out all DCM related global RAM on startup.

Resolution:

 The described issue is corrected by modification of all affected work-products.

2.3 Runtime Issues with Workaround

It is not recommended to update a delivery due to a runtime issue with a documented workaround. The effect of an issue to the ECU functionality has to be analyzed by the user as the software usage and its configuration is not known by Vector. The risk of change has also to be taken into account.

Index

ESCAN00061207	DaVinci Configurator 5: Issue Reporting Procedure GenTool_ConfiguratorCfg5@Application
ESCAN00089164	The EcuM stays in RUN state even if EcuM_KillAllRunRequests has been called SysService_Asr4EcuM@Implementation
ESCAN00091305	EcuM with fixed state machine causes a Det error in Dem_Init because this module has been initialized two times SysService_Asr4EcuM@Implementation
ESCAN00091550	Service 0x27: Dcm allows seed/key attempt earlier than the configured security delay time Diag_Asr4Dcm@GenTool_GeneratorMsr
ESCAN00094289	[Only if no Vector CanIf is used] CAN driver does not fulfill the requirements: CAN360 DrvCan__coreAsr@Implementation
ESCAN00094333	Timeout Action Replace doesn't work for Rx SignalGroups with Array Access enabled Il_AsrComCfg5@Implementation
ESCAN00096248	Validator PDUR12501 is not shown as error for PduRDestPduRef Gw_AsrPduRCfg5@GenTool_GeneratorMsr
ESCAN00098575	Com Timeouts occur for LIN Rx signals of inactive schedules SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00099239	Enabled event memory that has no events assigned leads to wrong code generation Diag_Asr4Dem@GenTool_GeneratorMsr
ESCAN00100995	ECU returns NRC 0x7F instead of NRC 0x11 for services that are not configured in all connections Diag_Asr4Dcm@Implementation
ESCAN00101027	Stack Usage of Dem functions too high Diag_Asr4Dem@Implementation
ESCAN00101058	Service 0x2C: NRC 0x31 instead of positive response for DDDID in range 0xF200-0xF2FF Diag_Asr4Dcm@GenTool_GeneratorMsr

ESCAN00061207 DaVinci Configurator 5: Issue Reporting Procedure	
Component@Subcomponent:	GenTool_ConfiguratorCfg5@Application
First affected version:	5.00.01
Fixed in versions:	
Problem Description: This ticket describes the reporting of DaVinci Configurator Pro issues. This ticket is a general information and not an issue. ----- Issues of the DaVinci Configurator Pro tool are not part of the active issue reporting (i.e. this report). The DaVinci Configurator Pro issue list can be downloaded from our home page: DaVinci Developer OpenIssue Lists https://portal.vector.com/web/davinci/shared-folder?t=c2b431ff-5dae-4a72-83ec-b9c8ca17561c DaVinci Configurator Pro OpenIssue Lists https://portal.vector.com/web/davinci/shared-folder?t=15d156f3-65d3-4b6e-8107-ec44051aebff	
Resolution Description: Workaround: ----- This is not an issue but only a reference to the tool specific issue reporting. No changes to the delivery required.	

ESCAN00089164	The EcuM stays in RUN state even if EcuM_KillAllRunRequests has been called
Component@Subcomponent:	SysService_Asr4EcuM@Implementation
First affected version:	3.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

The ECU stays in RUN state, even if anyone has called the API EcuM_KillAllRunRequests.	
When does this happen:	

Always after EcuM_KillAllRunRequests() has been called and at least one channel is in a state unequal COMM_NO_COM_NO_PENDING_REQUEST.	
In which configuration does this happen:	

Only in configurations with ECUM_FIXED_BEHAVIOR is active (EcuM/EcuMGeneral/EcuMEnableFixBehavior).	
Resolution Description:	

ESCAN00089164 The EcuM stays in RUN state even if EcuM_KillAllRunRequests has been called

Workaround:

The following shows a possible workaround to ignore all ComM channel states in case of an active KillAllRunRequests.

Hint: EcuM_SetWakeupEvent considers wakeup events even if EcuM_KillAllRunRequests() was called. This might cause that the EcuM transits from PostRun to Run again, because of a new occurred wakeup event.

The call of the API ComM_GetState() has to be mapped to an application function in case that it is called in context of EcuM.c. This can be done by configure the following header file as a User Configuration file in the EcuM configuration (EcuM/EcuMGeneral/EcuMUserConfigurationFile):

- Example Appl_ComM_EcuM.h:

```
#if defined (ECUM_SOURCE)
extern Std_ReturnType Appl_ComM_GetState(const NetworkHandleType Channel,
ComM_StateType* State);
```

```
# define ComM_GetState Appl_ComM_GetState
#endif
```

- Example Appl_ComM_EcuM.c:

```
#include "Std_Types.h"
#include "ComM.h"
```

```
#define ECUM_PRIVATE_CFG_INCLUDE
#include "EcuM_PrivateCfg.h"
#undef ECUM_PRIVATE_CFG_INCLUDE
```

```
Std_ReturnType Appl_ComM_GetState(const NetworkHandleType Channel, ComM_StateType*
State)
{
    Std_ReturnType retVal = E_OK;
    /* Verify that EcuM_KillAllRunRequests() was not called */
    if ((EcuM_GetKillAllInProgress() & (0x01u)) == 0u)
    {
        retVal = ComM_GetState(Channel, State);
    }
    else
    {
        /* In case of an active KillAllRunRequest, set the virtual ComM State to no communication and no
        request. */
        *State = COMM_NO_COM_NO_PENDING_REQUEST;
    }

    return retVal;
}
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00091305 EcuM with fixed state machine causes a Det error in Dem_Init because this module has been initialized two times

Component@Subcomponent: SysService_Asr4EcuM@Implementation

First affected version: 3.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

In some situations the EcuM with fixed state machine calls Dem_Init() two times, this lead to a Det error thrown by the Dem with the message DEM_E_WRONG_CONDITION,

When does this happen:

During runtime of the EcuM API EcuM_StartupTwo().

In which configuration does this happen:

All of the following conditions have to be fulfilled to be affected by this issue:

- The Ecum with fixed state machine has to be active (EcuM/EcuMGeneral/EcuMEnableFixBehavior).
- The include Dem has to be active (EcuM/EcuMFixedGeneral/EcuMIncludeDem).
- At least one wakeup source has to be configured for wakeup validation (EcuM/EcuMConfiguration/EcuMCommonConfiguration/EcuMWakeupSource/EcuMValidationTimeout).
- At startup the standard wakeup source (ECUM_WKSOURCE_RESET) has to be cleared via the API EcuM_ClearWakeupEvent() to force a wakeup validation after startup and to prevent a transition to RUN state until this wakeup source is validated.

Resolution Description:

Workaround:

In case that the valid wakeup event during initialization (ECUM_WKSOURCE_RESET) is cleared in context of driver init list two or three and a wakeup event for validation is set the Dem_Init call has to be avoided.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00091550 Service 0x27: Dcm allows seed/key attempt earlier than the configured security delay time

Component@Subcomponent: Diag_Asr4Dcm@GenTool_GeneratorMsr

First affected version: 1.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

A security delay timer expires too early. Dcm accepts new seed requests before the configured delay time is expired.

When does this happen:

If after last unsuccessful attempt responded with Nrc 0x36 (exceededNumberOfAttempts) a new seed request is sent before the expected delay time.

In which configuration does this happen:

- Service 0x27 is supported

AND

- There is more than one security level configured

AND

- Any delay time is configured for any security level (in Dcm_Cfg.h:

DCM_STATE_SEC_RETRY_ENABLED == STD_ON or

DCM_STATE_SEC_DELAY_ON_BOOT_ENABLED == STD_ON)

AND

- The dividend of a configured security delay time (in milliseconds) and the task cycle (also in milliseconds) is greater than 65535

Resolution Description:

Workaround:

The equation shall become true: ($\text{<TimeParameter>} / \text{DcmTaskTime}$) < 65535.

Therefore, the following workarounds are possible:

1) Increase the DcmTaskTime parameter value.

OR

2) Reduce the timeout value in the corresponding timing parameter.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00094289 [Only if no Vector CanIf is used] CAN driver does not fulfill the requirements: CAN360

Component@Subcomponent: DrvCan__coreAsr@Implementation

First affected version: 4.00.00

Fixed in versions: 8.00.00

Problem Description:

What happens (symptoms):

The CAN driver does not return with CAN_OK, CAN_NOT_OK but with E_OK and E_NOT_OK. If the values of CAN_OK and CAN_NOT_OK defined with other values than for E_OK and E_NOT_OK the CanIf does not detect a wakeup.

When does this happen:

- always at runtime, but only if "In which configuration does this happen" applies

In which configuration does this happen:

- A CanIf is used which is not implemented by Vector
AND
- the definition (mapping to integer value) of CAN_OK != definition of E_OK (in real: CAN_OK != 0)
AND
- CAN_WAKEUP_SUPPORT == STD_ON (Please see file: Can_Cfg.h)

Please note: If you don't evaluate/use the return value of API CanIf_CheckWakeup() in your EcuM / application then you are not affected and you can ignore this issue. In fact a wakeup is confirmed by an explicit call of EcuM_SetWakeupEvent() by CanDrv and must not be determined from return value of CanIf_CheckWakeup()

Resolution Description:

Workaround:

1) If possible: Please do not use the return value of Can_CheckWakeup().
or
2) If possible: Please adapt your CanDrv and define CAN_OK to E_OK.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00094333 Timeout Action Replace doesn't work for Rx SignalGroups with Array Access enabled	
Component@Subcomponent:	Il_AsrComCfg5@Implementation
First affected version:	7.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

The timeout Replace action for rx SignalGroups with array access enabled does not replace the buffer value either with the initial value or the configured Rx Data Timeout Substitution Value.	
When does this happen:	

During call of Com_MainFunctionRx()	
In which configuration does this happen:	

In all configurations with rx SignalGroups which have a configured timeout > 0, timeout action set to Replace and array access is enabled.	
Resolution Description:	
Workaround:	

Disable Array Access for signalGroups if applicable (no use of com-based transformer)	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00096248 Validator PDUR12501 is not shown as error for PduRDestPduRef	
Component@Subcomponent:	Gw_AsrPduRCfg5@GenTool_GeneratorMsr
First affected version:	9.01.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Validator message PDUR12501 is shown on a PduRDestPduRef. It is shown as information only, but in reality shall be an error message.	
When does this happen:	

During live validation in the DaVinci Configurator 5.	
In which configuration does this happen:	

The validator message is shown if the global Pdu of PduRDestPduRef is referenced by more than one other container. This kind of 1:N routing path is not supported.	
Resolution Description:	
Workaround:	

Check if the validation message is shown for a PduRDestPduRef.	
If No, then you're not affected.	
If Yes, check if this is correctly configured. The PduR will only forward the Pdu to one of the destination container (the destination is chosen randomly while generating due to the internal Java structure). The routing to this destination container will then work as configured.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00098575 Com Timeouts occur for LIN Rx signals of inactive schedules	
Component@Subcomponent:	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
First affected version:	5.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Com Rx Timeouts occur for LIN signals which should be inactive because the corresponding LIN schedule is not active.	
When does this happen:	

Always during runtime if a LIN channel is in FULL_COMMUNICATION and the corresponding schedule is not active.	
In which configuration does this happen:	

Only for LIN channels with configured LinIf schedules (LinIf/LinIfGlobalConfig/LinIfChannel/LinIfScheduleTable) which refer the same LinIfFrame (LinIf/LinIfGlobalConfig/LinIfChannel/LinIfFrame) multiple times.	
AND	
For at least one signal of this Frame a Timeout is configured (Com/ComConfig/ComSignal/ComTimeout).	
Resolution Description:	
Workaround:	

Adapt the auto-configured rules manually, so that Pdu Groups are only enabled if the corresponding schedule is active.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00099239 Enabled event memory that has no events assigned leads to wrong code generation	
Component@Subcomponent:	Diag_Asr4Dem@GenTool_GeneratorMsr
First affected version:	1.00.00
Fixed in versions:	16.00.00
Problem Description: What happens (symptoms): ----- Generated code leads to undefined behavior in DEM. When does this happen: ----- When requesting services (e.g. ClearDTC) for an event memory. In which configuration does this happen: ----- (Dem/DemGeneral/DemMaxNumberEventEntrySecondary > 0 AND No event with Dem/DemConfigSet/DemEventParameter/DemEventClass/DemEventDestination == DEM_DTC_ORIGIN_SECONDARY_MEMORY configured) OR (Dem/DemGeneral/DemMaxNumberEventEntryPrimary > 0 AND No event with Dem/DemConfigSet/DemEventParameter/DemEventClass/DemEventDestination == DEM_DTC_ORIGIN_PRIMARY_MEMORY configured)	
Resolution Description: Workaround: ----- If no event with Dem/DemConfigSet/DemEventParameter/DemEventClass/DemEventDestination == DEM_DTC_ORIGIN_SECONDARY_MEMORY is configured, set Dem/DemGeneral/DemMaxNumberEventEntrySecondary == 0. If no event with Dem/DemConfigSet/DemEventParameter/DemEventClass/DemEventDestination == DEM_DTC_ORIGIN_PRIMARY_MEMORY is configured, set Dem/DemGeneral/DemMaxNumberEventEntryPrimary == 1 and configure dummy event with Dem/DemConfigSet/DemEventParameter/DemEventClass/DemEventDestination == DEM_DTC_ORIGIN_PRIMARY_MEMORY. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00100995 ECU returns NRC 0x7F instead of NRC 0x11 for services that are not configured in all connections	
Component@Subcomponent:	Diag_Asr4Dcm@Implementation
First affected version:	1.05.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- ECU returns an NRC 0x7F (ServiceNotSupportedInActiveSession) instead of an NRC 0x11 (ServiceNotSupported) for a request on a connection where the service is not configured. When does this happen: ----- After requesting a service that is configured in some, but not all, service tables on a connection where the service is not configured. Additionally, the configured service (in the other table) is not configured for the currently active session. In which configuration does this happen: ----- There are multiple service tables configured (in Dcm_Cfg.h: #define DCM_DIAG_MULTI_SVC_TABLE_ENABLED == STD_ON)	
Resolution Description: Workaround: ----- Implement a manufacturer request notification function (i.e. Xxx_Indication callout) to send the NRC 0x11. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00101027 Stack Usage of Dem functions too high	
Component@Subcomponent:	Diag_Asr4Dem@Implementation
First affected version:	14.03.00
Fixed in versions:	16.01.00
Problem Description:	
What happens (symptoms):	

Stack Usage of some functions too high. Especially the stack usage of following APIs:	
- Dem_GetNextFreezeFrameData	
- Dem_GetNextExtendedDataRecord	
When does this happen:	

When using inlining during compilation.	
In which configuration does this happen:	

Dem/DemGeneral/DemDcmSupport == TRUE	
Resolution Description:	
Workaround:	

define the macro DEM_LOCAL_INLINE and set the content to empty as follows:	
#define DEM_LOCAL_INLINE	
The result of the workaround depends on the used compiler and compiler options.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00101058 Service 0x2C: NRC 0x31 instead of positive response for DDDID in range 0xF200-0xF2FF

Component@Subcomponent: Diag_Asr4Dcm@GenTool_GeneratorMsr

First affected version: 7.01.00

Fixed in versions: 10.04.01

Problem Description:

What happens (symptoms):

ECU responds with NRC 0x31 instead of positive response for a service 0x2C request with a periodic dynamically defined DID (PDDID) in range 0xF200-0xF2FF.

When does this happen:

For each service 0x2C request with a PDDID, for which all following conditions hold:

- length greater than 7
- length greater than the length of every available periodic DID
- length smaller than the Pdu length

In which configuration does this happen:

- Service 0x2A is supported (in Dcm_Cfg.h: #define DCM_SVC_2A_SUPPORT_ENABLED == STD_ON)

AND

- Service 0x2C is supported (in Dcm_Cfg.h: #define DCM_SVC_2C_SUPPORT_ENABLED == STD_ON)

AND

- At least one DDDID in range 0xF200-0xF2FF is configured (in Dcm_Cfg.h: #define DCM_DIDMGR_PERIODICDYNDID_ENABLED == STD_ON)

AND

- At least one "EcuC/EcucPduCollection/Pdu/PduLength" of Pdu referenced via DcmDslPeriodicConnection is greater than 7 and greater than the length of every configured periodic DID

Resolution Description:

Workaround:

Configure a periodic DID with a size equal to the largest UUDT Pdu length.

Resolution:

The described issue is corrected by modification of all affected work-products.

2.4 Not Released Functionality

Not released functionalities (BETA) are either complete software modules or features in the software module that have not yet passed a complete development cycle (they are e.g. not or only partly tested). If a BETA issue ticket affects a complete software module, the software module must not be used for serial production. If a BETA issue ticket affects a feature in the software module, the user has to ensure that all BETA features are disabled as indicated for the serial production release of the ECU.

Index

ESCAN00088830	BETA version - the BSW module has a feature with BETA state (Memory Protection in trusted applications) <i>Os_CoreGen7@Implementation</i>
ESCAN00089701	BETA version - the BSW module has a feature with BETA state (Executing trusted applications in non privileged mode) <i>Os_CoreGen7@Implementation</i>
ESCAN00091204	BETA version - the Nm module has a feature with BETA state (FEAT-1865) <i>Nm_Asr4NmIf@Implementation</i>
ESCAN00092470	BETA version - the BSW module has a feature with BETA state (FEAT-1454) <i>SysService_Asr4BswMCfg5@GenTool_GeneratorMsr</i>
ESCAN00092471	BETA version - the BSW module has a feature with BETA state (FEAT-1454) <i>SysService_Asr4EcuM@GenTool_GeneratorMsr</i>
ESCAN00092764	BETA version - the BSW module has a feature with BETA state (FEAT-1454) <i>Ccl_Asr4ComMCfg5@Implementation</i>
ESCAN00093797	BETA version - the BSW module has a feature with BETA state (Barriers) <i>Os_CoreGen7@Implementation</i>
ESCAN00093813	BETA version - the BSW module has a feature with BETA state (Fast Trusted Functions) <i>Os_CoreGen7@Implementation</i>
ESCAN00098377	BETA version - the BSW module has a feature with BETA state (FEAT-2721) <i>SysService_Asr4BswMCfg5@GenTool_GeneratorMsr</i>

ESCAN00088830	BETA version - the BSW module has a feature with BETA state (Memory Protection in trusted applications)
Component@Subcomponent:	Os_CoreGen7@Implementation
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What is the impact of BETA software:	

BETA feature:	
- must not be used in productive projects as they may result in unpredictable ECU behavior - may not provide all features intended for the productive project - is not tested and not all quality measures have taken place	
Which functionality is BETA:	

The following feature/function is in BETA state.	
- Memory Protection in trusted applications.	
To ensure that only productive code is used verify that:	
- OsTrustedApplicationWithProtection is false for all applications.	
Resolution Description:	
Workaround:	

Do not use memory protection for trusted.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00089701 BETA version - the BSW module has a feature with BETA state (Executing trusted applications in non privileged mode)

Component@Subcomponent: Os_CoreGen7@Implementation

First affected version: 1.00.00

Fixed in versions:

Problem Description:

What is the impact of BETA software:

BETA feature:

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not tested and not all quality measures have taken place

Which functionality is BETA:

The following feature/function is in BETA state.

- Executing trusted applications in non privileged mode is implemented as a BETA feature:

To ensure that only productive code is used verify that:

- IsPrivileged is TRUE for all trusted applications

Resolution Description:

API Extensions:

No extension of the API.

API Changes:

No modification of the API.

Module handling changes:

No modification of the module handling.

For a detailed description of the API and the handling of the module refer to the Technical Reference.

ESCAN00091204 BETA version - the Nm module has a feature with BETA state (FEAT-1865)	
Component@Subcomponent:	Nm_Asr4NmIf@Implementation
First affected version:	10.00.00
Fixed in versions:	
Problem Description: What is the impact of BETA software: ----- BETA software - must not be used in productive projects as they may result in unpredictable ECU behavior - may not provide all features intended for the productive project - is not or only partly tested and not all quality measures have taken place Which functionality is BETA: ----- The following feature/function is in BETA state. The NmOsek has to support the specific coordination use cases: - Use different intervals between the Nm_SynchronizationPoint() function call and the expected NmOsek_NetworkRelease() call in dependency of the state of NmOsek - Use different shutdown times for CanNm and NmOsek on the same channel To ensure that only productive code is used verify that: - If Nm Coordination is active in Nm and NmOsek is used in the configuration, then check that in NmOsek the configuration parameter "Wait Bus Sleep Extensions" is inactive -Nm_Cfg.h contains the following line: #define NM_WAIT_BUS_SLEEP_EXTENSIONS STD_OFF	
Resolution Description:	

ESCAN00092470 BETA version - the BSW module has a feature with BETA state (FEAT-1454)

Component@Subcomponent: SysService_Asr4BswMCfg5@GenTool_GeneratorMsr

First affected version: 10.00.00

Fixed in versions:

Problem Description:

What is the impact of BETA software:

BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

The following feature/function is in BETA state.

- Configuration of Switch Ports (Mode Request Port (BswM_EthIf_PortGroupLinkStateChg))

Additonal:

Currently the BswM general switch BswMEthIfEnabled is not set via a Auto-Validation. During fixing of this BETA ESCAN a validation has to be implemented which ensures that the BswMEthIfEnabled is true if the EthIf calls this API and if the Mode Request Port is configured in BswM.

Resolution Description:

ESCAN00092471 BETA version - the BSW module has a feature with BETA state (FEAT-1454)

Component@Subcomponent: SysService_Asr4EcuM@GenTool_GeneratorMsr

First affected version: 8.00.00

Fixed in versions:

Problem Description:

What is the impact of BETA software:

BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

The following feature/function is in BETA state.

- Configuration of PNC references for WakeupSources

HINT: Only Ethernet regarding PNCs might be references by WakeupSources, other busses are not supported!

Resolution Description:

ESCAN00092764 BETA version - the BSW module has a feature with BETA state (FEAT-1454)	
Component@Subcomponent:	Ccl_Asr4ComMCfg5@Implementation
First affected version:	8.00.00
Fixed in versions:	
Problem Description:	
What is the impact of BETA software:	

BETA software	
- must not be used in productive projects as they may result in unpredictable ECU behavior - may not provide all features intended for the productive project - is not or only partly tested and not all quality measures have taken place	
Which functionality is BETA:	

The following feature/function is in BETA state.	
- FEAT-1454: Configuration of Switch Ports (switchable per PNC)	
The above feature/function has following limitations:	
- CFG5 do not provide any validations rules. A proper feature configuration has to be ensured manually. - Use case PB-L is not supported. - PNCs having at least one /MICROSAR/ComM/ComMConfigSet/ComMPnc/ComMPortGroupsPerPnc require a ComM user.	
To ensure that only productive code is used verify that:	
- /MICROSAR/ComM/ComMConfigSet/ComMPnc/ComMPortGroupsPerPnc does not exist.	
and	
- ensure that COMM_WAKEUPENABLEDOFPNC is defined to STD_OFF in ComM_Cfg.h.	
Note: otherwise MSSV fails with error message 'assertion 'COMM_WAKEUPENABLEDOFPNC: "STD_ON" == "STD_OFF" does not hold'.	
Resolution Description:	

ESCAN00093797 BETA version - the BSW module has a feature with BETA state (Barriers)**Component@Subcomponent:** Os_CoreGen7@Implementation**First affected version:** 2.00.00**Fixed in versions:****Problem Description:**

What is the impact of BETA software:

BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

The following feature/function is in BETA state.

- Using barriers to synchronize tasks is implemented as a BETA feature.

To ensure that only productive code is used verify that:

- No barriers (/MICROSAR/Os/OsBarrier) are configured in the configuration tool.

Resolution Description:

API Extensions:

No extension of the API.

API Changes:

No modification of the API.

Module handling changes:

No modification of the module handling.

For a detailed description of the API and the handling of the module refer to the Technical Reference.

ESCAN00093813 BETA version - the BSW module has a feature with BETA state (Fast Trusted Functions)

Component@Subcomponent: Os_CoreGen7@Implementation

First affected version: 2.00.00

Fixed in versions:

Problem Description:

What is the impact of BETA software:

BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

The following feature/function is in BETA state.

- Os_CallFastTrustedFunction() API

To ensure that only productive code is used verify that:

- No elements are configured in /MICROSAR/Os/OsApplication/OsApplicationFastTrustedFunction

Resolution Description:

ESCAN00098377 BETA version - the BSW module has a feature with BETA state (FEAT-2721)

Component@Subcomponent: SysService_Asr4BswMCfg5@GenTool_GeneratorMsr

First affected version: 13.00.00

Fixed in versions:

Problem Description:

What is the impact of BETA software:

BETA software

- must not be used in productive projects as they may result in unpredictable ECU behavior
- may not provide all features intended for the productive project
- is not or only partly tested and not all quality measures have taken place

Which functionality is BETA:

The following feature/function is in BETA state.

- Configuration of more than one BswMConfig container / MultiPartition Support

Resolution Description:

2.5 Apparent Issues

Apparent issues are detected immediately when using the software module. If an issue does not show up while working with the software module, the ECU project is not affected by the issue. Apparent issues may or may not have workarounds.

Index

ESCAN00072881	'Port Access' references the wrong destination EcuAb_AsrIoHwAb@Description
ESCAN00073545	Final FBL response not cancelled on protocol preemption Diag_Asr4Dcm@Implementation
ESCAN00079399	Linker error: '<Cdd>_Transmit' : undeclared identifier (or '<Cdd_RxIndication>') Cdd_AsrCddCfg5@Description
ESCAN00087264	VTT only: parameter settings from VttEcuC not used (EcuC used instead) DrvCan__base@GenTool_GeneratorMsr
ESCAN00087958	Wrong return value of GetTaskState when called from PostTaskHook Os_CoreGen7@Implementation
ESCAN00089109	Software stack monitoring for non trusted functions not supported Os_CoreGen7@Implementation
ESCAN00089770	CANbedded only: Messages are not transmitted DrvCan_ImxFlexcan3LI@Implementation
ESCAN00091118	EcuM causes a Rte Det error (RTE_E_DET_UNINIT) in the shutdown sequence while the Nvm write all is performed SysService_Asr4EcuM@Implementation
ESCAN00091322	Validation error message cannot be solved: Error at validator runtime Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator. ModelView:UnfilteredInvariantProjectModelView Nm_Asr4NmIf@GenTool_GeneratorMsr
ESCAN00092622	A change of the main function period does not lead to a rebuild of the SWC description SysService_Asr4EcuM@GenTool_GeneratorMsr
ESCAN00092892	Compiler error: function "EcuM_BswErrorHook" has no prototype SysService_Asr4EcuM@Implementation
ESCAN00092955	Compiler error: incompatible types - from 'const <MSN>_PCConfigType *' to 'const <MSN>ConfigType *const' SysService_Asr4EcuM@GenTool_GeneratorMsr
ESCAN00093405	Auto Configuration - Invalid multiplicity after manual adaptations of container BswMAvailableActions SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00094259	Auto-Configuration Communication Control shows an error in case of not available module Com SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00094298	The Ecu does not startup properly in some MultiCore configurations SysService_Asr4EcuM@GenTool_GeneratorMsr
ESCAN00094319	Auto-Configuration Communication Control: Init Mode of Lin Schedule Indication is missing SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00094355	[Error] CANIF10027 None CAN-channel has multiple BasicCAN Tx-objects. Hence the feature "CanIfMultipleBasicCANTxObjects" is not required in current configuration and must be disabled. If_AsrIfCan@GenTool_GeneratorMsr
ESCAN00094541	Auto-Configuration Communication Control: Rules without expressions are created and so validation errors are shown SysService_Asr4BswMCfg5@GenTool_GeneratorMsr

Index

ESCAN00095259	Compiler error: WdqIf uses undefined memory sections If_Asr4IfWd@GenTool_GeneratorMsr
ESCAN00095519	ConsistencyRT00002 Error at validator runtime: CanSMBorTxConfPollingValidator if CanIf is missing Ccl_Asr4SmCan@GenTool_GeneratorMsr
ESCAN00095571	EcuM causes a Rte warning about a not existing mode request type map SysService_Asr4EcuM@GenTool_GeneratorMsr
ESCAN00096007	IoHwAb - Init Values not configurable for complex data type (e.g Array, structure...) EcuAb_AsrIoHwAb@GenTool_GeneratorMsr
ESCAN00096900	Compiler error: identifier EcuM_Get<***> not declared SysService_Asr4EcuM@GenTool_GeneratorMsr
ESCAN00097063	Auto-Configuration Communication Control: Tx PDU-Groups are not assigned to a channel and can not be selected SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00097168	EcuM debug data cannot be found in the map file SysService_Asr4EcuM@GenTool_GeneratorMsr
ESCAN00097181	Incorrect description of the arrays NmOsek_TargetConfigTable and NmOsek_ConfigMaskTable Nm_AsrNmDirOsek@Doc_TechRef
ESCAN00097203	Compiler error: "conversion of data types, possible loss of data" in case of large buffers Diag_Asr4Dcm@Implementation
ESCAN00097240	CanIf debug data cannot be found in the map file If_AsrIfCan@GenTool_GeneratorMsr
ESCAN00097355	Auto-Configuration Ecu State Handling: Self run request timeout value is not shown correct in case of 0 SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00097683	A generated value is not in range of the specified datatype Il_AsrComCfg5@GenTool_GeneratorMsr
ESCAN00097828	Compiler error: 'Network' : undeclared identifier SysService_Asr4BswMCfg5@Implementation
ESCAN00097876	Generated data streams toggle with each code generation if <MSN>ReduceDataByStreaming is enabled SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00098260	Erroneous validation message "CanIfMultipleBasicCANTxObjects is not required" If_AsrIfCan@GenTool_GeneratorMsr
ESCAN00098551	Configurator 5: It is possible to add more than 1 filter to BasicCAN FD mode is used DrvCan_ImxFlexcan3Asr@GenTool_GeneratorMsr
ESCAN00098584	NvM NVM01036 validation does not clearly describe the problem MemService_AsrNvM@GenTool_GeneratorMsr
ESCAN00099057	EcuM Wakeup Source defines are generated multiple times with numerical postfix in case of variance SysService_Asr4EcuM@GenTool_GeneratorMsr
ESCAN00099156	Missing description of OS_VTH_FORCED_TERMINATION and OS_VTHP_THREAD_CLEANUP Os_CoreGen7@Doc_TechRef
ESCAN00099172	Linker Errors: Unresolved external symbol Diag_AsrSwcVDem42@Make
ESCAN00099179	Compiler error: MemMap_Common.h: Wrong pragma command / unknown memory section used Tp_Asr4TpCan@Implementation

Index

ESCAN00099186	Compiler error: Inconsistent setting for number of channels; with dynamic channel assignment, more SDUs than channels are expected Tp_Asr4TpCan@Implementation
ESCAN00099352	ConsistencyRT00002 - Error at validator runtime: CanIfTxBufferSupportValidator If_AsrIfCan@GenTool_GeneratorMsr
ESCAN00099398	Compiler error: Incorrect expansion of Com_ReceiveShadowSignal with COM_RECEIVE_SIGNAL_MACRO_API Il_AsrComCfg5@Implementation
ESCAN00099525	CanTpEnableSynchronousTransmit cannot be used with non MICROSAR Components Tp_Asr4TpCan@Doc_TechRef
ESCAN00099553	State diagram of the EcuM with fixed state machine shows call of EcuM_AL_DriverRestart in the wrong transition. SysService_Asr4EcuM@Doc_TechRef
ESCAN00099814	Wrong references to CanTp_Cfg.c exist Tp_Asr4TpCan@Doc_TechRef
ESCAN00100067	Validator: IllegalStateException occurred when DID Control Mask Size is empty for external control mask Diag_Asr4Dcm@GenTool_GeneratorMsr
ESCAN00100161	Service 0x2C: Unnecessary RAM usage Diag_Asr4Dcm@Implementation
ESCAN00100264	Tool cannot be started if a file MipConfig.xml_bak exists _3rdParty_McalIntegration_Helper@VectorIntegration
ESCAN00100267	Exception when file not found _3rdParty_McalIntegration_Helper@VectorIntegration
ESCAN00100420	Compiler error: in Os_Hal_MemoryProtection_Lcfq.c expected an expression Os_PlatformArmCortexMGen7@GenTool_GeneratorMsr
ESCAN00100457	Compiler error: Missing parameter in function Dem_DcmGetDTCOfOBDFreezeFrame Diag_Asr4Dcm@Implementation
ESCAN00100485	Sorting of EA Blocks leads to DaVinci Configurator error "modification of the data model failed" If_AsrIfEa@GenTool_GeneratorMsr
ESCAN00100613	Compiler error: Declaration of CanIf_ControllerModeIndication() is missing If_AsrIfCan@Implementation
ESCAN00100659	Template functionality can not reference items of 3rd Party MCAL implementations EcuAb_AsrIoHwAb@Description
ESCAN00100716	Compiler error: identifier ComM_UserHandleArrayType_<channel_name> is undefined Ccl_Asr4ComMCfg5@GenTool_GeneratorMsr
ESCAN00100722	Memory abstraction is missing for PduR_SchM_<Enter Exit>_PduR_PDUR_EXCLUSIVE_AREA_<X> wrapper functions Gw_AsrPduRCfg5@GenTool_GeneratorMsr
ESCAN00100736	MSSV terminates unexpectedly if header files are included multiple times Elisa_core@Application
ESCAN00100742	Compiler error: 'NmOsek_SetSleepReadyBit' : undeclared identifier Nm_AsrNmDirOsek@Implementation
ESCAN00100796	Compiler error: Invalid assignment for ModeSwitchEventMask0 Rte_Core@Implementation
ESCAN00100799	Compiler error: Memset used with float initializer in RTE Analyzer stubs Rte_Core@Implementation
ESCAN00100823	Generation Error: ArxmlToA2I01009 - Generation of A2L file failed Ccl_Asr4SmCan@GenTool_GeneratorMsr

Index

ESCAN00100828	Null pointer exception when component for a data mapping is missing Rte_Asr4@GenTool_GeneratorMsr
ESCAN00100860	RTE Analyzer also tries to extract the COM signal length of TX signals Rte_Analyzer@Application
ESCAN00100931	Null pointer exception when ISignal has no data def props Rte_Asr4@GenTool_GeneratorMsr
ESCAN00100981	Compiler error: Unknown Identifier Dcm_ExternalSetNegResponse/ Dcm_ExternalProcessingDone Diag_Asr4Dcm@GenTool_GeneratorMsr
ESCAN00100999	Invalid combination of MPU access rights for S32K derivatives Os_PlatformArmCortexMGen7@GenTool_GeneratorMsr
ESCAN00101005	Compiler error: "undeclared identifier EcuM_GlobalPBConfig_Ptr" SysService_Asr4EcuM@GenTool_GeneratorMsr
ESCAN00101074	Compiler error: Missing Rte_MemClr when LdCom TP is used Rte_Core@Implementation
ESCAN00101078	MSSV does not consider include paths not containing header files Elisa_core@Application
ESCAN00101086	IndexOutOfBoundsException during Calculation Rte_Asr4@GenTool_GeneratorMsr
ESCAN00101088	Missing ROM data sections for Globalshared ZERO_INIT sections Os_CoreGen7@GenTool_GeneratorMsr
ESCAN00101120	Dem include is independent from configuration. Dem is always included. DrvEep_coreAsr@GenTool_GeneratorMsr
ESCAN00101164	Compiler error: PduR_LoIfTxConfirmation undefined Gw_AsrPduRCfg5@Implementation
ESCAN00101183	Compiler error: Missing parentheses for Rte_IrvIRead_ and Rte_IrvIWriteRef macros Rte_Core@Implementation
ESCAN00101322	CddType missing for UserDefinedPdu GenTool_CsAsrLegacyDb2SystemDescr@Application
ESCAN00101345	Service 0x86: Consistency error due to a missing reference to DcmDsdServiceTable Diag_Asr4Dcm@GenTool_GeneratorMsr
ESCAN00101354	Service 0x86: Consistency error due to an invalid DcmDsdSidTabServiceDispatcher value Diag_Asr4Dcm@GenTool_GeneratorMsr
ESCAN00101362	Compiler error: C4305 - truncation from 'unsigned int' to <MSN>_<IndexConstArray>Type Gw_AsrPduRCfg5@GenTool_GeneratorMsr
ESCAN00101415	RTE49999: When NvBlock SWCs are used and NvM_MainFunction is missing Rte_Core@Implementation
ESCAN00101416	Warning RTE1070: Missing parameter definition when NVM configuration uses the standard definition Rte_Core@Implementation

ESCAN00072881 'Port Access' references the wrong destination	
Component@Subcomponent:	EcuAb_AsrIoHwAb@Description
First affected version:	4.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

The connection between runnables and assigned port prototypes erroneously references the whole port interface, whereas it should point to a data element inside the very port interface. As a result of this, too many unnecessary consistency checks will be applied	
When does this happen:	

This happens always and immediately.	
In which configuration does this happen:	

This happens in all configurations.	
Resolution Description:	
Workaround:	

Transfer of all data elements within one runnable call.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00073545 Final FBL response not cancelled on protocol preemption	
Component@Subcomponent:	Diag_Asr4Dcm@Implementation
First affected version:	1.05.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

The ECU will process the FBL final response even if there is higher protocol request sent.	
When does this happen:	

When immediately after reprogramming of the ECU has ended, the very first request after ECU powers on in the application is a hi-priority one (i.e. OBD).	
In which configuration does this happen:	

- Any configuration where the ECU shall be able to send a final response without request after reset.	
AND	
- Protocol prioritisation is to be supported (i.e. OBD vs. UDS).	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00079399 Linker error: '<Cdd>_Transmit' : undeclared identifier (or '<Cdd>_RxIndication')

Component@Subcomponent: Cdd_AsrCddCfg5@Description

First affected version: 2.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Linker error in PduR_Lcfg.c: '<Cdd>_Transmit' : undeclared identifier

Linker error in PduR_Lcfg.c: '<Cdd>_RxIndication' : undeclared identifier

The Cdd_AsrCddCfg5 is not derived according to the ASR 4.0.3 rules and allows a LOWER-MULTIPLICITY of 0 for the CddPduRLowerLayerRxPdu and CddPduRLowerLayerTxPdu instead of the LOWER-MULTIPLICITY of 1.

The generic ASR PduR according to the ASR 4.0.3 Specification has no information to deactivate a communication direction (e.g. a Parameter in the PduRBSwModules).

When does this happen:

The error is issued by the linker after compilation of the code in case the configuration is as described below.

In which configuration does this happen:

Rx only Cdd with a CddPduRLowerLayerContribution (just receive pathways exits)

The <CddName>.h file contains the following define:

<CddName>_LOWERLAYERCOMIF_TX is defined to STD_OFF

OR

Tx only Cdd with a CddPduRLowerLayerContribution (just transmit pathways exits)

The <CddName>.h file contains the following define:

<CddName>_LOWERLAYERCOMIF_RX is defined to STD_OFF

Resolution Description:

Workaround:

Implement the not required '<Cdd>_Transmit' API on your own in a c and h file of your choice and add the header file with a user config file to the PduR configuration that the compiler does not throw a warning.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00087264 VTT only: parameter settings from VttEcuC not used (EcuC used instead)	
Component@Subcomponent:	DrvCan__base@GenTool_GeneratorMsr
First affected version:	3.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

VTT does not use the settings given in VttEcuC modul like:	
- SafeBswChecks (SafeBsw used but should not --> more runtime consumption)	
- DummyFunction (compiler warnings)	
- DummyStatement (compiler warnings)	
- OsType (same for Hardware)	
When does this happen:	

while compile time for DummyFunction and DummyStatement	
while runtime for SafeBswChecks	
In which configuration does this happen:	

VTT used	
and	
Platform settings in EcuC modul differ from settings in VttEcuC modul	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00087958 Wrong return value of GetTaskState when called from PostTaskHook	
Component@Subcomponent:	Os_CoreGen7@Implementation
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

GetTaskState returns SUSPENDED for current task when called from PostTaskHook. Return 'RUNNING' instead.	
When does this happen:	

In PostTaskHook the task is still running.	
In which configuration does this happen:	

Configuration invariant.	
Resolution Description:	
Workaround:	

Do not use the API GetTaskState for the current task in the PostTaskHook.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00089109 Software stack monitoring for non trusted functions not supported	
Component@Subcomponent:	Os_CoreGen7@Implementation
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Stack monitoring in software is not supported for non trusted functions.	
When does this happen:	

Always	
In which configuration does this happen:	

In systems where non trusted functions and software stack checks are used:	
In configuration:	
/ActiveEcuC/Os/<Application>/OsApplicationNonTrustedFunction is used and /ActiveEcuC/Os/OsOS[OsStackMonitoring] = TRUE	
Resolution Description:	
Workaround:	

If a MPU is available, protect stacks by MPU.	
In case that no MPU is available, user has to ensure that stack overflow does not occur during execution of non trusted functions. Otherwise non trusted functions shall not be used.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00089770 CANbedded only: Messages are not transmitted

Component@Subcomponent: DrvCan_ImxFlexcan3LI@Implementation

First affected version: 1.07.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Messages are not transmitted because the mailbox stays locked after successful cancellation.

When does this happen:

At runtime after cancellation of an active transmit request that was already set for that mailbox. After call if CanInit the mailbox is free to send again until the next occurrence of hardware cancellation.

In which configuration does this happen:

CANbedded CAN driver
AND
Cancel in Hardware is enabled
(see can_cfg.h if C_ENABLE_CANCEL_IN_HW is defined)

Resolution Description:

Workaround:

- 1.) Enable feature "Tx Observation" in the generation tool
(see can_cfg.h if C_ENABLE_TX_OBSERVE is defined)
OR
2.) Enable feature "Common Confirmation Function" in the generation tool
(see can_cfg.h if C_ENABLE_CAN_TX_CONF_FCT is defined)

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00091118	EcuM causes a Rte Det error (RTE_E_DET_UNINIT) in the shutdown sequence while the Nvm write all is performed
Component@Subcomponent:	SysService_Asr4EcuM@Implementation
First affected version:	3.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

The Rte throws a Det error with the ID RTE_E_DET_UNINIT during the shutdown sequence.	
When does this happen:	

Always during the NvM_WriteAll() is performed.	
In which configuration does this happen:	

Only in configurations with all the following parameters are set to true:	
/ActiveEcuC/EcuM/EcuMGeneral/EcuMEnableFixBehavior /ActiveEcuC/EcuM/EcuMFixedGeneral/EcuMModeSwitchRteAck /ActiveEcuC/EcuM/EcuMFixedGeneral/EcuMIncludeNvramMgr /ActiveEcuC/Rte/RteGeneration/RteDevErrorDetect	
Resolution Description:	
Workaround:	

The only workaround is to filter this DET message.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00091322	Validation error message cannot be solved: Error at validator runtime Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator.ModelView:UnfilteredInvariantProjectModel
Component@Subcomponent:	Nm_Asr4NmIf@GenTool_GeneratorMsr
First affected version:	9.00.00
Fixed in versions:	
Problem Description:	

ESCAN00091322 Validation error message cannot be solved: Error at validator runtime Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator.ModelView:UnfilteredInvariantProjectModel

What happens (symptoms):

The following validation error message appears in the Validation view in DaVinci Configurator:

ConsistencyRT00002 Error at validator runtime (1 message)

ConsistencyRT00002 Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator.ModelView:UnfilteredInvariantProjectModelView

This is not a configuration problem but an internal implementation error. Please contact Vector for support.

Validator-Class:

com.vector.cfg.gen.Nm_Asr4NmIf.validation.NmGlobalCoordinatorTimeAllNmOsekInNormalValidator

Validator-Description: NmGlobalCoordinatorTimeAllNmOsekInNormalValidator validates that the setting NmGlobalCoordinatorTimeAllNmOsekInNormal is defined if it required.

Further runtime errors of this validator won't be reported in the UI.

Ex: com.vector.cfg.gen.core.moduleinterface.exceptions.ValidationFailedException: [Error]

NM01003 - A Specific Channel configuration is missing for the NmChannelConfig

- The corresponding CanNmChannelConfig is missing for this NmChannelConfig

We are sorry, but due to this internal error, code generation of /[ANY]/CanNm, /MICROSAR/NmOsek, /[ANY]/FrIf, /[ANY]/FrNm, /[ANY]/UdpNm, /[ANY]/ComM, /MICROSAR/Nm has to be blocked. As a workaround, you may try to restart DaVinci Configurator. Otherwise, please call Vector for support

/ActiveEcuC/ComM

FrIf

UdpNm

CanNm

/ActiveEcuC/Nm

FrNm

/ActiveEcuC/NmOsek

Apparently, the message cannot be resolved.

When does this happen:

During configuration with DaVinci Configurator.

In which configuration does this happen:

Any configuration with Nm where a NmChannelConfig container exists that does not have a correspondent BusNmChannelConfig container (e.g. CanNmChannelConfig, FrNmChannel, LinNmChannelConfig, UdpNmChannelConfig, J1939NmChannelConfig, NmOsekChannelConfig, ...)

AND

(
'Coordinator Support Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/
NmCoordinatorSupportEnabled) is turned OFF in the NmGlobalFeatures container in Nm in the
'Network Management General' / 'Basic Editor' in DaVinci Configurator-> Nm_Cfg.h contains
#define NM_COORDINATOR_SUPPORT_ENABLED STD_OFF)

AND/OR

('Wait Bus Sleep Extensions' (/MICROSAR/NmOsek/NmOsekGlobalConfig/
NmOsekWaitBusSleepExtensions) is turned OFF or not defined or cannot be found in the

ESCAN00091322

Validation error message cannot be solved: Error at validator runtime Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator.ModelView:UnfilteredInvariantProjectModel

NmOsekGlobalConfig container in NmOsek in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator -> NmOsek_Cfg.h does not contain #define NMOSEK_WAIT_BUS_SLEEP_EXTENSIONS)

AND/OR

('Synchronizing Network' (/MICROSAR/Nm/NmChannelConfig/NmSynchronizingNetwork) is turned OFF for at least one NmChannelConfig container in Nm in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator)

AND/OR

('Coord Cluster Index' (/MICROSAR/Nm/NmChannelConfig/NmCoordClusterIndex) is undefined or set to 255 for at least one NmChannelConfig container in Nm in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator)

)

Please note that this is an invalid configuration because either the NmChannelConfig container without a BusNmChannelConfig must be deleted or the corresponding BusNmChannelConfig container must be created.

Resolution Description:

Workaround:

In DaVinci Configurator:

1) Create the corresponding BusNmChannelConfig container and configure its parameters and sub-containers.

OR

2) Delete the NmChannelConfig container that lacks a corresponding BusNmChannelConfig container.

Afterwards (no matter whether 1) or 2) has been applied), save the configuration, close it and re-open it.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00092622 A change of the main function period does not lead to a rebuild of the SWC description	
Component@Subcomponent:	SysService_Asr4EcuM@GenTool_GeneratorMsr
First affected version:	1.00.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- The SWC description file is not updated after a change of the EcuM main function period. When does this happen: ----- After change of the parameter /MICROSAR/EcuM/EcuMGeneral/EcuMMainFunctionPeriod. In which configuration does this happen: ----- In all configurations.	
Resolution Description: Workaround: ----- Adapt another parameter which leads to a rebuild of the SWC description, e.g. rename of a sleepmode [/EcuM/EcuMConfiguration/EcuMCommonConfiguration/EcuMSleepMode]. After rebuild the name of this sleepmode can be switched back to the old name, the rename is only necessary to trigger a rebuild. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00092892	Compiler error: function "EcuM_BswErrorHook" has no prototype
Component@Subcomponent:	SysService_Asr4EcuM@Implementation
First affected version:	2.00.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- Compiler throws the following error: function "EcuM_BswErrorHook" has no prototype When does this happen: ----- The error is issued by the compiler during compilation of the code in case the configuration is as described below. In which configuration does this happen: ----- Only in configurations with any PB Modules but EcuM is not configured as PB AND The module which uses the API EcuM_BswErrorHook() includes 'EcuM.h' instead of 'EcuM_BswErrorHook.h'.	
Resolution Description: Workaround: ----- Include the file 'EcuM_Error.h' additional to the include 'EcuM.h', e.g. via a user configuration file. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00092955	Compiler error: incompatible types - from 'const <MSN>_PCConfigType *' to 'const <MSN>ConfigType *const'
Component@Subcomponent:	SysService_Asr4EcuM@GenTool_GeneratorMsr
First affected version:	4.00.00
Fixed in versions:	
Problem Description:	

ESCAN00092955 Compiler error: incompatible types - from 'const <MSN>_PCConfigType *' to 'const <MSN>ConfigType *const'

What happens (symptoms):

The compiler throws an error like the following:

```
1> EcuM_Init_Cfg.c
1>GenData/EcuM_Init_Cfg.c(86): error C4133: 'initializing' : incompatible types - from 'const CanNm_PCConfigType *' to 'const EcuM_PbConfigType *const '
1>GenData/EcuM_Init_Cfg.c(87): error C4133: 'initializing' : incompatible types - from 'const EcuM_PCConfigType *' to 'const SchM_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(88): error C4133: 'initializing' : incompatible types - from 'const SchM_ConfigType *' to 'const Can_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(89): error C4133: 'initializing' : incompatible types - from 'const Can_PCConfigType *' to 'const CanIf_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(90): error C4133: 'initializing' : incompatible types - from 'const CanIf_PCConfigType *' to 'const Com_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(91): error C4133: 'initializing' : incompatible types - from 'const Com_PCConfigType *' to 'const PduR_PBConfigType *const '
1>GenData/EcuM_Init_Cfg.c(92): error C4133: 'initializing' : incompatible types - from 'const PduR_PCConfigType *' to 'const CanSM_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(93): error C4133: 'initializing' : incompatible types - from 'const CanSM_PCConfigType *' to 'const CanNm_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(103): error C4133: 'initializing' : incompatible types - from 'const CanNm_PCConfigType *' to 'const EcuM_PbConfigType *const '
1>GenData/EcuM_Init_Cfg.c(104): error C4133: 'initializing' : incompatible types - from 'const EcuM_PCConfigType *' to 'const SchM_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(105): error C4133: 'initializing' : incompatible types - from 'const SchM_ConfigType *' to 'const Can_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(106): error C4133: 'initializing' : incompatible types - from 'const Can_PCConfigType *' to 'const CanIf_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(107): error C4133: 'initializing' : incompatible types - from 'const CanIf_PCConfigType *' to 'const Com_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(108): error C4133: 'initializing' : incompatible types - from 'const Com_PCConfigType *' to 'const PduR_PBConfigType *const '
1>GenData/EcuM_Init_Cfg.c(109): error C4133: 'initializing' : incompatible types - from 'const PduR_PCConfigType *' to 'const CanSM_ConfigType *const '
1>GenData/EcuM_Init_Cfg.c(110): error C4133: 'initializing' : incompatible types - from 'const CanSM_PCConfigType *' to 'const CanNm_ConfigType *const '
```

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

In variant configurations with modules which uses different EcuC init phases in different variants (/MICROSAR/EcuC/EcucGeneral/BswInitialization/InitFunction/InitPhase).

E.g.

VARIANT_1: InitPhase = NO_INIT

VARIANT_2: InitPhase = INIT_TWO_MCAL

Resolution Description:

ESCAN00092955 Compiler error: incompatible types - from 'const <MSN>_PCConfigType *' to 'const <MSN>ConfigType *const

Workaround:

To resolve this the content of the `CONT EcuM_GlobalConfigRoot` in `EcuM_Init_Cfg.c` has to be reordered to fit to the struct `EcuM_GlobalConfigRootType`.

e.g.

```
CONST(EcuM_GlobalConfigRootType, ECUM_CONST) EcuM_GlobalConfigRoot =
{
{
BswM_Config_CanNm_Ptr,
EcuM_Config_CanNm_Ptr,
CanNm_Config_CanNm_Ptr,
},
{
BswM_Config_ClassB_Ptr,
CanNm_Config_ClassB_Ptr, <===== Wrong position, must be the last one
EcuM_Config_ClassB_Ptr,
},
{
BswM_Config_ClassC_Ptr,
CanNm_Config_ClassC_Ptr, <===== Wrong position, must be the last one
EcuM_Config_ClassC_Ptr,
}
};
```

typedef struct

```
{
CONSTP2CONST(BswM_ConfigType, TYPEDEF, BSWM_INIT_DATA) CfgPtr_BswM_Init;
CONSTP2CONST(EcuM_PbConfigType, TYPEDEF, ECUM_INIT_DATA) CfgPtr_EcuM_Init;
CONSTP2CONST(CanNm_ConfigType, TYPEDEF, CANNM_INIT_DATA) CfgPtr_CanNm_Init;
} EcuM_GlobalPCConfigType;
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00093405 Auto Configuration - Invalid multiplicity after manual adaptations of container BswMAvailableActions

Component@Subcomponent: SysService_Asr4BswMCfg5@GenTool_GeneratorMsr

First affected version: 10.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

User-modifications about a changed BswMAvailableActions subcontainer are recognized by the Auto Configuration assistant but even if they should be kept, the assistant will re-create the original action. This leads to an invalid model because the user modification is not removed by the assistant.

Example:

- Configure Communication Control is used and Reinitialize TX is turned ON, Finish is clicked.
- the /MICROSAR/BswM/BswMConfig/BswMModeControl/BswMAAction CC_EnableDM_<I-PDU-Group> has a BswMDeadlineMonitoringControl container which is deleted within the Basic Editor
- Instead another BswMAvailableActions subcontainer is created of another type, e.g.

BswMComMMModelimitation

- Configure Communication Control is used once again and Finish is clicked. An option is offered to either keep this modification or to restore it, but independent of the choice, the original BswMDeadlineMonitoringControl is restored without removing the user modification. Because the user modification is not removed the multiplicity of the container BswMAvailableActions[0...1] is violated.

When does this happen:

During the configuration with DaVinci Configurator in the BSW Management Editor in the following sequence:

- Configure <Auto Configuration> is clicked
- Finish is clicked
- Some objects like a /MICROSAR/BswM/BswMConfig/BswMModeControl/BswMAAction/BswMAvailableActions/BswMDeadlineMonitoringControl container are deleted or changed
- Configure <Auto Configuration> is clicked once again
- Finish is clicked
- the dialog 'Manual Adaptions' does pop up
- Finish is clicked in the 'Manual Adaptions' dialog

In which configuration does this happen:

Any configuration using one of the Auto Configurations in BSW Management in DaVinci Configurator

Resolution Description:

Workaround:

Redo the previously manual changes that have been overwritten.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00094259 Auto-Configuration Communication Control shows an error in case of not available module Com	
Component@Subcomponent:	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
First affected version:	2.01.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- Auto-Configuration shows the following error: Configuration *error* Reason for *error*: Could not collect all necessary informations. Solve errors in depending Modules first! To see following errors in the Validation view execute on-demand generator validation! Container ComConfig does not exist. Element def.: /[ANY]/Com/ComConfig When does this happen: ----- Always during configuration. In which configuration does this happen: ----- In all configurations without the module Com.	
Resolution Description: Workaround: ----- No workaround available. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00094298 The Ecu does not startup properly in some MultiCore configurations

Component@Subcomponent: SysService_Asr4EcuM@GenTool_GeneratorMsr

First affected version: 2.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

The Ecu does not startup properly, e.g. communication does not start , the application is not started, the configuration variant is not detected correct etc.

When does this happen:

Always after startup of the Ecu.

In which configuration does this happen:

In MultiCore configurations with parameter "/EcuM/EcuMGeneral/EcuMBswCoreId" set to another value than to the ID of the master core

AND

The OS symbols OS_CORE_ID_<X> are provided as a enumeration and not as a preprocessor define.

Resolution Description:

Workaround:

Create a header file with the following content and add it to /MICROSAR/EcuM/EcuMGeneral/EcuMUserConfigurationFile:

```
#if defined(ECUM_CFG_H)

# undef ECUM_CORE_ID_STARTUP
# undef ECUM_CORE_ID_BSW
# define ECUM_CORE_ID_STARTUP <Core Id as Numerical Value, e.g. '0>
# define ECUM_CORE_ID_BSW <Core Id as Numerical Value, e.g. '1>

#endif
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00094319 Auto-Configuration Communication Control: Init Mode of Lin Schedule Indication is missing**Component@Subcomponent:** SysService_Asr4BswMCfg5@GenTool_GeneratorMsr**First affected version:** 10.01.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

A validator in Cfg5 reports the following warning:

BSWM01057 Init Mode of CC_LinScheduleIndication_<Schedule Name> is not known.
Set BswMBswModeInitValueMode(value=) to LinSMConf_LinSMSchedule_<NAME>
/ActiveEcuC/BswM/BswMConfig/BswMArbitration/
CC_LinScheduleIndication_LIN00_<Schedule_Name>/BswMModeInitValue/
BswMBswModeInitValue[BswMBswModeInitValueMode]
/ActiveEcuC/BswM/BswMConfig/BswMArbitration/
CC_LinScheduleIndication_LIN00_<Schedule_Name>

When does this happen:

Always after configuring the Auto-Configuration Communication Control.

In which configuration does this happen:

Only in configurations with at least one Lin channel

AND

Auto-Configuration Communication Control is configured.

Resolution Description:

Workaround:

Set the normal schedule via the provided solving action.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00094355 [Error] CANIF10027 None CAN-channel has multiple BasicCAN Tx-objects. Hence the feature "CanIfMultipleBasicCANTxObjects" is not required in current configuration and must be disabled.

Component@Subcomponent: If_AsrIfCan@GenTool_GeneratorMsr

First affected version: 4.02.00

Fixed in versions:

Problem Description:

What happens (symptoms):

One of the following validation messages always occurs during configuration:

[Error] CANIF10027 - A feature is not supported in current configuration and shall be disabled.
- None CAN-channel has multiple BasicCAN Tx-objects. Hence the feature "CanIfMultipleBasicCANTxObjects" is not required in current configuration and must be disabled.
Solving action: Disable parameter: "CanIfMultipleBasicCANTxObjects".

-> After executing of this solving action you get the following validation message within the CanDrv:

[Error] CAN02002 - An invalid value is configured
- CanMultipleBasicCANTxObjects is not active but multiple TX BasicCANs used on some controller.
Solving action: Enable parameter: "CanMultipleBasicCANTxObjects"

-> After execution of this solving action you get the validation message mentioned above

When does this happen:

During configuration

In which configuration does this happen:

In case there is at least one CAN channel with no BasicCAN Tx-hardware object (there is no "CanHardwareObject" with "CanHandleType" == BASIC and "CanObjectType" == TRANSMIT)
-> The configuration has only FullCAN-objects or no Tx-objects at all on at least one channel

Resolution Description:

Workaround:

Make sure you get [Error] CANIF10027 (i.e. solve [Error] CAN02002 if present).
Set the parameter "CanIfMultipleBasicCANTxObjects" to user defined and keep it enabled.
[Error] CANIF10027 is then demoted to a warning that can be ignored.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00094541 Auto-Configuration Communication Control: Rules without expressions are created and so validation errors are shown

Component@Subcomponent: SysService_Asr4BswMCfg5@GenTool_GeneratorMsr

First affected version: 11.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

The validation tab shows the following message:

AR-ECUC02008 Invalid multiplicity (3 messages)
AR-ECUC02008 Mandatory parameter BswMRuleExpressionRef is missing in
CC_<CHANNELNAME>_<PNCNAME>_RX
BswMRuleExpressionRef
/ActiveEcuC/BswM/BswMConfig/BswMArbitration/CC_<CHANNELNAME>_<PNCNAME>
AR-ECUC02008 Mandatory parameter BswMRuleExpressionRef is missing in
CC_<CHANNELNAME>_<PNCNAME>_RX_DM
BswMRuleExpressionRef
/ActiveEcuC/BswM/BswMConfig/BswMArbitration/CC_<CHANNELNAME>_<PNCNAME>
AR-ECUC02008 Mandatory parameter BswMRuleExpressionRef is missing in
CC_<CHANNELNAME>_<PNCNAME>_TX
BswMRuleExpressionRef
/ActiveEcuC/BswM/BswMConfig/BswMArbitration/CC_<CHANNELNAME>_<PNCNAME>

When does this happen:

Always after execution of the Communication Control assistant.

In which configuration does this happen:

In configurations with PNCs where at least one PduGroup is mapped to different PNCs

AND

Not all PNCs of a channel are configured (selected) in the Communication Control assistant.

Resolution Description:

Workaround:

Rules must be deleted manually from configuration.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00095259 Compiler error: WdgIf uses undefined memory sections

Component@Subcomponent: If_Asr4IfWd@GenTool_GeneratorMsr

First affected version: 2.01.00

Fixed in versions:

Problem Description:

What happens (symptoms):

WdgIf uses memory section which are not defined. The WdgIf assumes erroneously that Os provides these sections. This error leads to a compiler error like: #error "MemMap.h, wrong pragma command"

The sections of the WdgIf

- WDGIF_START_SEC_VAR_INIT_8BIT / WDGIF_STOP_SEC_VAR_INIT_8BIT
- WDGIF_START_SEC_VAR_INIT_16BIT / WDGIF_STOP_SEC_VAR_INIT_16BIT
- WDGIF_START_SEC_VAR_INIT_32BIT / WDGIF_STOP_SEC_VAR_INIT_32BIT

are mapped to

(Gen6)

- <ApplicationName>_START_SEC_VAR_<InitPolicy>_8BIT /
- <ApplicationName>_STOP_SEC_VAR_<InitPolicy>_8BIT
- <ApplicationName>_START_SEC_VAR_<InitPolicy>_16BIT /
- <ApplicationName>_STOP_SEC_VAR_<InitPolicy>_16BIT
- <ApplicationName>_START_SEC_VAR_<InitPolicy>_32BIT /
- <ApplicationName>_STOP_SEC_VAR_<InitPolicy>_32BIT.

(Gen7)

- OS_START_SEC_<ApplicationName>_VAR_<InitPolicy>_8BIT /
- OS_STOP_SEC_<ApplicationName>_VAR_<InitPolicy>_8BIT
- OS_START_SEC_<ApplicationName>_VAR_<InitPolicy>_16BIT /
- OS_STOP_SEC_<ApplicationName>_VAR_<InitPolicy>_16BIT
- OS_START_SEC_<ApplicationName>_VAR_<InitPolicy>_32BIT /
- OS_STOP_SEC_<ApplicationName>_VAR_<InitPolicy>_32BIT.

Os currently supports only "InitPolicy" {-, NOINIT, ZEROINIT}. The actually needed init policy is "INIT".

When does this happen:

Only if a multi core platform is used and the WdgIf is configured to use the state combiner functionality.

In which configuration does this happen:

If a container "/MICROSAR/WdgIf/WdgIfStateCombiner" is configured
AND
if /MICROSAR/WdgIf/WdgIfGeneral/WdgIfUseStateCombiner == true

Resolution Description:

Workaround:

Provide the missing memory sections and locate them in a proper memory section.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00095519 ConsistencyRT00002 Error at validator runtime: CanSMBorTxConfPollingValidator if CanIf is missing	
Component@Subcomponent:	Ccl_Asr4SmCan@GenTool_GeneratorMsr
First affected version:	3.02.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

ConsistencyRT00002 - Error at validator runtime	
When does this happen:	

If the CanIf Module is deleted or a configuration without CanIf is loaded	
In which configuration does this happen:	

If CanIf is deleted or missing	
Resolution Description:	
Workaround:	

Activate CanIf Module or remove the CanSM Module and reload the project	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00095571 EcuM causes a Rte warning about a not existing mode request type map**Component@Subcomponent:** SysService_Asr4EcuM@GenTool_GeneratorMsr**First affected version:** 3.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

During validation the Rte throws the following warning:

Mode Declaration Group <EcuM_Mode> of Component <EcuM> has no mode request type map. Each Mode Declaration Group used in the SW-C's ports has to have a unique mapping to an implementation data type. The Mode Group Data Type is set to <uint8>.

Help:

- define a mode request type map.

When does this happen:

During validation of the Rte.

In which configuration does this happen:

If /MICROSAR/EcuM/EcuMGeneral/EcuMEnableFixBehavior is set

OR

If /MICROSAR/EcuM/EcuMFlexGeneral/EcuMModeHandling is set

Resolution Description:

Workaround:

No workaround available.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00096007 IoHwAb - Init Values not configurable for complex data type (e.g Array, structure...)	
Component@Subcomponent:	EcuAb_AsrIoHwAb@GenTool_GeneratorMsr
First affected version:	6.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

No Init-Value for configured complex Data Type could be set.	
When does this happen:	

when a data type is created by the user and he wants to set a Init Value on the port prototype	
In which configuration does this happen:	

Every configuration with IoHwAb and with Data Types != from base types	
Resolution Description:	
Workaround:	

Currently, for Arrays and Records no initial values can be configured. So a user has to connect a port with a data element referencing an array or a record always with the counterpart in an application within the DaVinci Developer.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00096900 Compiler error: identifier EcuM_Get<***> not declared

Component@Subcomponent: SysService_Asr4EcuM@GenTool_GeneratorMsr

First affected version: 8.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

The compiler throws one of the following errors:

Compiler error: identifier EcuM_GetValidationTimeoutTable not declared
 Compiler error: identifier EcuM_DecValidationTimeoutTable not declared
 Compiler error: identifier EcuM_SetValidationTimeoutTable not declared
 Compiler error: identifier EcuM_GetReasonOfWakeupSourceList not declared
 Compiler error: identifier EcuM_GetChannelOfWakeupSourceList not declared

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

In variant configurations
 AND
 At least one variant don't use parameter EcuMValidationTimeout | EcuMComMChannelRef | EcuMResetReasonRef (Value = 0 or not existent)
 AND
 Another variant use parameter EcuMValidationTimeout | EcuMComMChannelRef | EcuMResetReasonRef

Resolution Description:

Workaround:

Ensure that the parameters EcuMValidationTimeout | EcuMComMChannelRef | EcuMResetReasonRef are existent in all variants OR are not existent in all variants. But the existence for each of them has to be consistent over all variants.

It is sufficient to configure a dummy wakeup source which is not used by the code to ensure this.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00097063	Auto-Configuration Communication Control: Tx PDU-Groups are not assigned to a channel and can not be selected
Component@Subcomponent:	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
First affected version:	13.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Some Tx PDU-Groups are listed at the end of the communication control view and are marked in grey as not available with the following annotation:	
"Channel of corresponding Group PDUs could not be determined"	
When does this happen:	

Always during execution of the Auto-Configuration Communication Control.	
In which configuration does this happen:	

In Configurations with at least one Tx Pdu Group, in which all of the Tx Pdus have different global Pdu References in parameters /MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/	
PduRRoutingPath/PduRDestPdu and /MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/	
PduRRoutingPath/PduRSrcPdu.	
Resolution Description:	
Workaround:	

Control of Tx PDU-Groups has to be configured with manual BswM Rules.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00097168 EcuM debug data cannot be found in the map file	
Component@Subcomponent:	SysService_Asr4EcuM@GenTool_GeneratorMsr
First affected version:	1.01.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

During A2L update several symbols of EcuM (that the EcuM generator actually registers through the CFG5 McData Service Interface) cannot be found in the map file.	
EcuM_ExpiredWakeup	
EcuM_PendingCheckWakeup	
EcuM_PendingWakeup	
When does this happen:	

After compilation when the A2L / calibration workflow is used to generate a complete A2L file with addresses of the target.	
In which configuration does this happen:	

Whenever generation of Debug Data is enabled in DaVinci Configurator and EcuM is used.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00097181	Incorrect description of the arrays NmOsek_TargetConfigTable and NmOsek_ConfigMaskTable
Component@Subcomponent:	Nm_AsrNmDirOsek@Doc_TechRef
First affected version:	7.00.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- The technical reference TechnicalReference_NmOsek.pdf claims that the arrays "NmOsek_TargetConfigTable" and "NmOsek_ConfigMaskTable" are one dimensional and shows code examples for them. They are actually two dimensional arrays. This can be found in chapter 2.10.2.3 Compare Configuration A correct example can be found under: Workaround. When does this happen: ----- When reading the Technical Reference. In which configuration does this happen: ----- Configurations in which MICROSAR/NmOsek/NmOsekGlobalConfig/NmOsekUseNmNodeList is enabled.	
Resolution Description:	

ESCAN00097181 Incorrect description of the arrays NmOsek_TargetConfigTable and NmOsek_ConfigMaskTable

Workaround:

The correct description of the variables is as follows:

```
CONST(NmOsek_NodeConfigType, NMOSEK_APPL_CONST) NmOsek_ConfigMaskTable[]
[sizeof(NmOsek_NodeConfig) / sizeof(NmOsek_NodeConfigType)];
CONST(NmOsek_NodeConfigType, NMOSEK_APPL_CONST) NmOsek_TargetConfigTable[]
[sizeof(NmOsek_NodeConfig) / sizeof(NmOsek_NodeConfigType)];
```

In which:

*The first dimension corresponds to:
The index of the table of the corresponding array

*The second dimension corresponds to:
The configuration byte

/

* Example of the ROM tables provided by the application:

```
CONST(NmOsek_NodeConfigType, NMOSEK_APPL_CONST) NmOsek_ConfigMaskTable[2]
[sizeof(NmOsek_NodeConfig) / sizeof(NmOsek_NodeConfigType)] =
```

```
{
```

```
{
```

```
0x69u,
```

```
0x00u,
```

```
0x80u,
```

```
0x80u
```

```
},
```

```
{
```

```
0x02u,
```

```
0x12u,
```

```
0x11u,
```

```
0x40u
```

```
}
```

```
};
```

```
CONST(NmOsek_NodeConfigType, NMOSEK_APPL_CONST) NmOsek_TargetConfigTable[2]
[sizeof(NmOsek_NodeConfig) / sizeof(NmOsek_NodeConfigType)] =
```

```
{
```

```
{
```

```
0xF9u,
```

```
0x00u,
```

```
0x80u,
```

```
0x80u
```

```
},
```

```
},
```

ESCAN00097181	Incorrect description of the arrays NmOsek_TargetConfigTable and NmOsek_ConfigMaskTable
{	0x0Fu, 0x12u, 0x11u, 0xC1u } };

ESCAN00097203 Compiler error: "conversion of data types, possible loss of data" in case of large buffers

Component@Subcomponent: Diag_Asr4Dcm@Implementation

First affected version: 1.03.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Following compiler errors might be reported:

Error: Dcm.c, line 36235: error C4244: '=' : conversion from 'Dcm_CfgNetBufferSizeMemType' to 'Dcm_DidMgrDidLengthType', possible loss of data

Error: Dcm.c, line 13586: error C4244: '=' : conversion from 'const Dcm_CfgDidMgrOptimizedDidLengthType' to 'uint16', possible loss of data

Error: Dcm.c, line 25946: error C4244: '=' : conversion from 'const Dcm_CfgDidMgrOptimizedDidLengthType' to 'Dcm_DidMgrDidLengthType', possible loss of data

In many cases (dependent on compiler option settings) this might be reported as warning.

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

- At least one DCM buffer is larger than 65535bytes (ECUC parameter DcmDslBufferSize > 65535)
AND

- Service 0x22 (ReadDataByIdentifier) is handled within DCM (in Dcm_Cfg.h #define DCM_SVC_22_SUPPORT_ENABLED == STD_ON)

OR

- Service 0x2A (ReadDataByPeriodicIdentifier) is handled within DCM (in Dcm_Cfg.h #define DCM_SVC_2A_SUPPORT_ENABLED == STD_ON)

OR

- Service 0x2C (DynamicallyDefineDataByIdentifier) is handled within DCM (in Dcm_Cfg.h #define DCM_SVC_2C_SUPPORT_ENABLED == STD_ON)

OR

- Service 0x2F (InputOutputControlByIdentifier) is handled within DCM (in Dcm_Cfg.h #define DCM_SVC_2F_SUPPORT_ENABLED == STD_ON)

Note: Such buffer sizes are typically used in case of Bootloader applications.

Resolution Description:

Workaround:

Ignore the warning since no DID can have size of more than 16KB, since largest DcmDspDidDataPos can accept only up to 8KB and the largest DID signal can have only up to 8KB. So the largest DID can be a DID with a signal starting at position 8191 and having 8192 bytes.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00097240 CanIf debug data cannot be found in the map file	
Component@Subcomponent:	If_AsrIfCan@GenTool_GeneratorMsr
First affected version:	3.07.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- During A2L update some symbols of CanIf (that the CanIf generator actually registers through the CFG5 McData Service Interface) cannot be found in the map file. CanIf_CtrlStates.CtrlModeOfCtrlStates CanIf_CtrlStates.PduModeOfCtrlStates When does this happen: ----- After compilation when the A2L / calibration workflow is used to generate a complete A2L file with addresses of the target. In which configuration does this happen: ----- Whenever generation of Debug Data is enabled in DaVinci Configurator and CanIf is used.	
Resolution Description: Workaround: ----- Fix the generated symbols in the A2L file manually before proceeding with the A2L workflow. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00097355	Auto-Configuration Ecu State Handling: Self run request timeout value is not shown correct in case of 0
Component@Subcomponent:	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
First affected version:	11.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	
----- The overview page of the Auto-configuration Ecu State handling does not show the correct value for the self run request timeout. Instead it shows the default value (0.1).	
When does this happen:	
----- Always if the value is set to 0.	
In which configuration does this happen:	
----- In all configurations with Auto-Configuration Ecu State Handling configured	
AND	
Value of self run request timeout is set to 0.	
Resolution Description:	
Workaround:	
----- No workaround available.	
Resolution:	
----- The described issue is corrected by modification of all affected work-products.	

ESCAN00097683 A generated value is not in range of the specified datatype	
Component@Subcomponent:	Il_AsrComCfg5@GenTool_GeneratorMsr
First affected version:	3.00.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- An error is reported in the configurator with following error message: COM90500 The value 122040 with comment () is not in the range of the specified datatype UINT_16. When does this happen: ----- During generation of COM In which configuration does this happen: ----- In configurations in which any generated table has more than 65535 entries AND /PduR/PduRBswModules/PduRTransportProtocol for COM is set to FALSE	
Resolution Description: Workaround: ----- 1) Use LdCom instead of COM for large PDUs or 2) Enable /ActiveEcuC/PduR/Com[1:PduRTransportProtocol] and configure one Dummy TP PDU or 3) set /MICROSAR/Com/ComConfig/ComIPdu/ComIPduSignalProcessing to IMMEDIATE for all PDUs which are greater than 65535. Resolution: ----- No modification of code as it would cause performance problems and use a lot of RAM, especially in Post-Build configurations.	

ESCAN00097828 Compiler error: 'Network' : undeclared identifier	
Component@Subcomponent:	SysService_Asr4BswMCfg5@Implementation
First affected version:	10.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

The compiler throws an error like the following one:	
error C2065: 'Network' : undeclared identifier	
When does this happen:	

The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

If the BswM has more than one instance of container BswMConfig (Multi Partition UseCase)	
AND	
BswMDevErrorDetect is enabled	
AND	
One of the following Mode Request ports is used:	
ComM_InitiateReset	
ComM_CurrentPNCMode	
Dcm_ApplicationUpdated	
EthIf_PortGroupLinkStateChg	
J1939DcmBroadcastStatus	
EcuM_CurrentState	
EcuM_CurrentWakeup	
EcuM_RequestedState	
Nm_StateChangeNotification	
NvM_CurrentBlockMode	
NvM_CurrentJobMode	
PduR_RxIndication	
PduR_TpRxIndication	
PduR_TpStartOfReception	
PduR_TpTxConfirmation	
PduR_Transmit	
PduR_TxConfirmation	
Sd_ClientServiceCurrentState	
Sd_ConsumedEventGroupCurrentState	
Sd_EventHandlerCurrentState	
WdgM_RequestPartitionReset	
Resolution Description:	

ESCAN00097828 Compiler error: 'Network' : undeclared identifier	
Workaround: ----- No workaround available.	
Resolution: ----- The described issue is corrected by modification of all affected work-products.	
ESCAN00097876 Generated data streams toggle with each code generation if <MSN>ReduceDataByStreaming is enabled	
Component@Subcomponent:	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
First affected version:	2.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms): ----- Generated Code has to be recompiled or added again to the Users CMS because the order in streamed CONST arrays is not deterministic and changes by chance with each code generation.	
When does this happen: ----- At generation time.	
In which configuration does this happen: ----- Any configuration where <MSN>ReduceDataByStreaming returns true.	
Resolution Description:	

ESCAN00098260 Erroneous validation message "CanIfMultipleBasicCANTxObjects is not required"	
Component@Subcomponent:	If_AsrIfCan@GenTool_GeneratorMsr
First affected version:	4.02.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- Erroneous validation message CANIF10027 (None CAN-channel has multiple BasicCAN Tx-objects. Hence the feature ""CanIfMultipleBasicCANTxObjects" is not required in current configuration and must be disabled.) shows up in CFG5 and cannot be solved. When does this happen: ----- During configuration. In which configuration does this happen: ----- Multiple CAN drivers are used AND There is at least one CAN channel with != 1 BasicCAN Tx-hardware object ("CanHardwareObject" with "CanHandleType" == BASIC and "CanObjectType" == TRANSMIT) for one of the drivers.	
Resolution Description: Workaround: ----- Set the parameter "CanIfMultipleBasicCANTxObjects" to user defined and keep it enabled. [Error] CANIF10027 is then demoted to a warning that can be ignored. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00098551 Configurator 5: It is possible to add more than 1 filter to BasicCAN FD mode is used

Component@Subcomponent: DrvCan_ImxFlexcan3Asr@GenTool_GeneratorMsr

First affected version: 3.02.00

Fixed in versions:

Problem Description:

What happens (symptoms):

It is possible to add more than 1 filter to a BasicCAN object in combination with FD mode. This will lead to a wrong configuration so that BasicCAN messages are not received.

When does this happen:

It might happen during configuration of a FlexCAN3 Controller for CAN FD.

In which configuration does this happen:

#define CAN_FD_SUPPORT CAN_BRS OR #define CAN_FD_SUPPORT CAN_FULL has been generated in Can_Cfg.h

Resolution Description:

Workaround:

Workaround:

The user must take care to assign only 1 filter to a BasicCAN object when CAN FD is used.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00098584 NvM NVM01036 validation does not clearly describe the problem**Component@Subcomponent:** MemService_AsrNvM@GenTool_GeneratorMsr**First affected version:** 4.02.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

DaVinci Cfg5 shows the NvM error NVM01036 NVM01036 "NvMCalcRamBlockCrc requires configured NvMBlockCrcType, NvMSelectBlockForReadAll, NvMRamBlockDataAddress and disabled" for NvMBlockDescriptors derived from NvBlockNeeds. Resolving the problem via provided solving action leads to other validation errors in e.g. RTE.

Since the NvMBlockDescriptor is derived from NvBlockNeeds, the error cannot be fixed within the DaVinci Cfg5.

When does this happen:

NvMBlockDescriptor derived from NvBlockNeeds. For other blocks the error shall be clear and resolvable within the Cfg5.

In which configuration does this happen:

NvBlockNeeds with calcRamBlockCrc true, reliability != NO and enabled explicit synchronization leads to NvMBlockDescriptor with NvMBlockUseCrc true, NvMBlockCrcType != NoCrc and NvMBlockUseSyncMechanism.

Resolution Description:

Workaround:

Correct the NvMBlockDescriptor preconditions directly within the DaVinci Developer -> ensure the configuration matches the preconditions described in error message NVM01036. Do not use the provided solving action!

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00099057	EcuM Wakeup Source defines are generated multiple times with numerical postfix in case of variance
Component@Subcomponent:	SysService_Asr4EcuM@GenTool_GeneratorMsr
First affected version:	8.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Wakeup Source Defines are generated multiple times with an numerical postfix, but the same value.	
#define ECUM_WKSOURCE_POWER (EcuM_WakeupSourceType)(1UL)	
#define ECUM_WKSOURCE_POWER_1 (EcuM_WakeupSourceType)(1UL)	
When does this happen:	

During generation of the code.	
In which configuration does this happen:	

Only in variant configurations.	
Resolution Description:	
Workaround:	

The defines with the numerical postfix can be just ignored.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00099156	Missing description of OS_VTH_FORCED_TERMINATION and OS_VTHP_THREAD_CLEANUP
Component@Subcomponent:	Os_CoreGen7@Doc_TechRef
First affected version:	1.00.01
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Missing description of OS_VTH_FORCED_TERMINATION and OS_VTHP_THREAD_CLEANUP	
When does this happen:	

Always	
In which configuration does this happen:	

All	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00099172 Linker Errors: Unresolved external symbol	
Component@Subcomponent:	Diag_AsrSwcVDem42@Make
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Linker throws many errors like:	
Rte.obj : error LNK2019: unresolved external symbol	
_VDem42_ERRH_Fpl_SG_msg_PMM_DemCallbackEventStatusChanged_CallbackEventUdsStatusCha	
referenced in function	
Rte_Call_DemMaster_0_CBEventUdsStatusChanged_ERRH_Fpl_SG_msg_PMM_DemCallback	
EventStatusChanged_CallbackEventUdsStatusChanged	
When does this happen:	

At compilation time.	
In which configuration does this happen:	

In all configurations using vDem42 and having at least one service port of vDem42 connected.	
Resolution Description:	
Workaround:	

Workaround 1:	
Correct vDem42 make file "vDem42_rules.mak" by removing '#' from line:	
#GENERATED_SOURCE_FILES += \$(GENDATA_DIR)\vDem42_Cfg.c.	
Workaround 2:	
Add the "\$(GENDATA_DIR)\vDem42_Cfg.c" file manually to your make support environment.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00099179 Compiler error: MemMap_Common.h: Wrong pragma command / unknown memory section used	
Component@Subcomponent:	Tp_Asr4TpCan@Implementation
First affected version:	3.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

The following error is reported during compilation: MemMap_Common.h:1763: #error "MemMap_Common.h: Wrong pragma command / unknown memory section used. Please use only valid pragma commands and known memory sections."	
When does this happen:	

The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

This happens in configurations having more than 254 Tx SDUs or more than 254 Rx SDUs.	
Resolution Description:	
Workaround:	

Add the missing memory sections (CANTP_START_SEC_VAR_NOINIT_16BIT and CANTP_STOP_SEC_VAR_NOINIT_16BIT) to the MemMap.h file.	
Resolution:	

Not yet available.	

ESCAN00099186 Compiler error: Inconsistent setting for number of channels; with dynamic channel assignment, more SDUs than channels are expected

Component@Subcomponent: Tp_Asr4TpCan@Implementation

First affected version: 2.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

The following error is issued by the preprocessor:

Inconsistent setting for number of channels; with dynamic channel assignment, more SDUs than channels are expected

When does this happen:

fatal error C1189: #error : "Inconsistent setting for number of channels; with dynamic channel assignment, more SDUs than channels are expected"

In which configuration does this happen:

This happens in configurations where all of the following conditions are fulfilled:

1. Only Rx SDUs have been configured (no CanTp/CanTpConfig/CanTpChannel/CanTpTxNSdu containers are present).
2. Dynamic Channel assignment is enabled (CanTp/CanTpGeneral/CanTpDynamicChannelAssignment is set).
3. "Postbuild-Selectable" is enabled for the module or "POST-BUILD-LOADABLE" has been selected as the module's "Implementation Variant" (In any of the two cases the macro CANTP_USE_INIT_POINTER will be defined as STD_ON in the generated file CanTp_Cfg.h).

Resolution Description:

Workaround:

Add a user config file to the CanTp with the following code:

```
#if (CANTP_USE_INIT_POINTER != STD_ON) && (CANTP_DYN_CHANNEL_ASSIGNMENT ==
STD_ON) && (CANTP_NUM_TX_SDUS == 0)
# undef CANTP_NUM_TX_CHANNELS
# define CANTP_NUM_TX_CHANNELS 0
#endif
```

Resolution:

Not yet available.

ESCAN00099352 ConsistencyRT00002 - Error at validator runtime: CanIfTxBufferSupportValidator	
Component@Subcomponent:	If_AsrIfCan@GenTool_GeneratorMsr
First affected version:	4.06.01
Fixed in versions:	
Problem Description: What happens (symptoms): ----- The following error occurs in CFG5: ConsistencyRT00002 Error at validator runtime (1 message) ConsistencyRT00002 Consistency: an exception was caught while executing onModelEvent() of a validator. Configuration inconsistencies couldn't be reported by this validator. ModelView:UnfilteredInvariantProjectModelView This is not a configuration problem but an internal implementation error. Please contact Vector for support. Validator-Class: com.vector.cfg.gen.If_AsrIfCan.validation.TxValidators.TxBufferValidators.CanIfTxBufferSupportVali Validator-Description:Setting control of features: "CanIfPublicTxBuffering, "CanIfMultipleBasicCANTxObjects" and "CanIfCtrlDrvTxCancellation". Further runtime errors of this validator won't be reported in the UI. Ex: java.lang.IllegalArgumentException: The passed instance element (/ActiveEcuC/Can/ CanConfigSet/CN_PB_9dcd9cfb_Tx (DefRef: /MICROSAR/Can_CanoeemuCanoe/Can/CanConfigSet/ CanHardwareObject)) is not unique in the ModelTraverser InstanceTree. You can only pass elements which are unique in the InstanceTree, or you have to use the selectxxxAsSubView() methods. Please enable debug log level to see more details. We are sorry, but due to this internal error, code generation of /MICROSAR/CanIf, /[ANY]/Can has to be blocked. As a workaround, you may try to restart DaVinci Configurator. Otherwise, please call Vector for support. /ActiveEcuC/Can /ActiveEcuC/CanIf	
When does this happen: ----- During configuration	
In which configuration does this happen: ----- The same Can/CanConfigSet/CanHardwareObject is referenced by multiple CanIf/CanIfInitCfg/ CanIfInitHohCfg/CanIfHthCfg/CanIfHthIdSymRef	
Resolution Description: Workaround: ----- Referencing the same CanHardwareObject from multiple CanIfHthCfgs is a mis-configuration - delete the duplicated CanIfHthCfgs and reload the configuration to avoid the exception. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00099398 Compiler error: Incorrect expansion of Com_ReceiveShadowSignal with COM_RECEIVE_SIGNAL_MACRO_API

Component@Subcomponent: IL_AsrComCfg5@Implementation

First affected version: 8.01.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Compile error occurs if Com_ReceiveShadowSignal is used having COM_RECEIVE_SIGNAL_MACRO_API enabled:

```
In file included from ...:
src/Com.h:718:54: error: pasting "Com_Get" and "(" does not give a valid preprocessing token
# define Com_ReceiveSignal(SignalId, SignalDataPtr) Com_Get##SignalId((SignalDataPtr))
^
src/Com.h:739:66: note: in expansion of macro 'Com_ReceiveSignal'
# define Com_ReceiveShadowSignal(SignalId, SignalDataPtr) (void)
Com_ReceiveSignal((SignalId), (SignalDataPtr))
^
test/test_all.c:519:3: note: in expansion of macro 'Com_ReceiveShadowSignal'
Com_ReceiveShadowSignal(GrpSig_1, someBuffer)
^
```

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

```
/MICROSAR/Com/ComGeneral/ComReceiveSignalMacroAPI is enabled
AND
Com_ReceiveShadowSignal is used
```

Resolution Description:

Workaround:

```
Use Com_ReceiveSignal API instead of deprecated Com_ReceiveShadowSignal API
OR
Disable /MICROSAR/Com/ComGeneral/ComReceiveSignalMacroAPI
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00099525 CanTpEnableSynchronousTransmit cannot be used with non MICROSAR Components	
Component@Subcomponent:	Tp_Asr4TpCan@Doc_TechRef
First affected version:	3.01.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Add a warning box to chapter 3.1.2.8 and to the integration chapter that CanTpEnableSynchronousTransmit cannot be used with non MICROSAR components.	
When does this happen:	

At runtime.	
In which configuration does this happen:	

Any configuration where CanTp/CanTpGeneral/CanTpEnableSynchronousTransmit is configured to true.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

Not yet available.	

ESCAN00099553	State diagram of the EcuM with fixed state machine shows call of EcuM_AL_DriverRestart in the wrong transition.
Component@Subcomponent:	SysService_Asr4EcuM@Doc_TechRef
First affected version:	3.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

State diagram of the EcuM with fixed state machine shows call of EcuM_AL_DriverRestart in the transition from ECUM_STATE_GO_SLEEP to ECUM_STATE_WAKEUP_VALIDATION.	
The call should be located in the transition from ECUM_STATE_SLEEP to ECUM_STATE_WAKEUP_VALIDATION.	
When does this happen:	

During reading of the TechRef.	
In which configuration does this happen:	

Only in EcuM with fixed behavior configurations (EcuM/EcuMGeneral/EcuMEnableFixBehavior == true).	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00099814 Wrong references to CanTp_Cfg.c exist	
Component@Subcomponent:	Tp_Asr4TpCan@Doc_TechRef
First affected version:	3.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

CanTp_Cfg.c is mentioned as a generated file, but the file is actually not generated.	
When does this happen:	

Always and Immediately.	
In which configuration does this happen:	

All of them.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

Not yet available.	

ESCAN00100067 Validator: IllegalStateException occurred when DID Control Mask Size is empty for external control mask

Component@Subcomponent: Diag_Asr4Dcm@GenTool_GeneratorMsr

First affected version: 9.02.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Dcm generator validation issues the following message:

[Error] ConsistencyRT00002 - Error at validator runtime

- Consistency: an exception was caught while executing onModelEvent() of a validator.

Configuration inconsistencies couldn't be reported by this validator.

ModelView:UnfilteredInvariantProjectModelView

This is not a configuration problem but an internal implementation error. Please contact Vector for support.

Validator-Class: com.vector.cfg.model.swctemplates.internal.validation.SwcValidation Validator-

Name: Dcm Swc description validator (/MICROSAR/Dcm) Validator-

Description:com.vector.cfg.model.swctemplates.internal.validation.SwcValidation

Further runtime errors of this validator won't be reported in the UI.

Ex: java.lang.IllegalStateException: Missing size of EXTERNAL control mask of IO-DID:

com.vector.cfg.gen.Diag_Asr4DcmCore.cm.didManager.did.impl.DidObjectStaticGeneric@235df359.

We are sorry, but due to this internal error, code generation of all modules has to be blocked. As a workaround, you may try to restart the tool. Otherwise, please call Vector for support.

When does this happen:

When the control mask for an IO DID (/Dcm/DcmConfigSet/DcmDsp/DcmDspDidInfo/
DcmDspDidAccess/DcmDspDidControl/DcmDspDidControlMask) is switched from

DCM_CONTROLMASK_INTERNAL to DCM_CONTROLMASK_EXTERNAL while the IO DID control
mask size (Dcm/DcmConfigSet/DcmDsp/DcmDspDidInfo/DcmDspDidAccess/DcmDspDidControl/
DcmDspDidControlMaskSize) is empty.

In which configuration does this happen:

- Service 0x2F is supported (in Dcm_Cfg.h: #define DCM_SVC_2F_SUPPORT_ENABLED ==
STD_ON)

Resolution Description:

Workaround:

Save the configuration, close the DaVinci Developer and reopen the configuration.

Hint: Set first the DID Control Mask Size to the correct value before switching the DID Control
Mask to DCM_CONTROLMASK_EXTERNAL.

ESCAN00100161 Service 0x2C: Unnecessary RAM usage	
Component@Subcomponent:	Diag_Asr4Dcm@Implementation
First affected version:	1.02.00
Fixed in versions:	11.00.00
Problem Description:	
What happens (symptoms):	

The RAM usage is significantly increased.	
When does this happen:	

Always and immediately	
In which configuration does this happen:	

- Service 0x2C is supported (in Dcm_Cfg.h: #define DCM_SVC_2C_SUPPORT_ENABLED == STD_ON) AND - Subfunction 0x01 of service 0x2C is supported (in Dcm_Cfg.h: #define DCM_SVC_2C_01_SUPPORT_ENABLED = STD_ON) AND - Subfunction 0x02 of service 0x2C is supported (in Dcm_Cfg.h: #define DCM_SVC_2C_02_SUPPORT_ENABLED = STD_ON) AND - At least one DDDID in range 0xF300 to 0xF3FF is configured	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100264 Tool cannot be started if a file MipConfig.xml_bak exists	
Component@Subcomponent:	_3rdParty_McalIntegration_Helper@VectorIntegration
First affected version:	2.03.01
Fixed in versions:	2.05.00
Problem Description:	
What happens (symptoms):	

Tool cannot be started if a file MipConfig.xml_bak exists	
When does this happen:	

When file MipConfig.xml_bak AND MipConfig.xml file exist in folder VectorIntegration	
In which configuration does this happen:	

All	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100267 Exception when file not found	
Component@Subcomponent:	_3rdParty_McalIntegration_Helper@VectorIntegration
First affected version:	2.04.01
Fixed in versions:	2.05.00
Problem Description:	
What happens (symptoms):	

Helper Tool throws an exception during preparing the MCAL.	
When does this happen:	

When a file shall be modified by Helper Tool but it does not exist or is renamed in a way that Helper Tool does not find it.	
In which configuration does this happen:	

All	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100420	Compiler error: in Os_Hal_MemoryProtection_Lcfg.c expected an expression
Component@Subcomponent:	Os_PlatformArmCortexMGen7@GenTool_GeneratorMsr
First affected version:	2.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler states:	
Os_Hal_MemoryProtection_Lcfg.c", line xxx: error #29:	
expected an expression	
/* .Word2 = */ (),	
^	
This is an example for GHS compiler but as this is a syntax error, other compilers will come up	
with similar messages.	
As a consequence, the code cannot be used.	
When does this happen:	

The error is issued by the compiler during compilation of the code in case the configuration is as	
described below.	
In which configuration does this happen:	

This happens only in configurations with memory protection when a memory region has been	
configured but no bus master for that memory region has been configured yet (/MICROSAR/Os/	
OsMemoryProtection/OsMemoryRegion/OsMemoryRegionBusMasters).	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100457 Compiler error: Missing parameter in function Dem_DcmGetDTCOfOBDFreezeFrame**Component@Subcomponent:** Diag_Asr4Dcm@Implementation**First affected version:** 7.02.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

Compilation error due to wrong prototype of DEM API "Dem_DcmGetDTCOfOBDFreezeFrame".

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

- Non-MICROSAR DEM is used

AND

- DEM APIs for AR 4.3.0 are enabled (in Dcm_Cfg.h: #define DCM_DEM_API_430_ENABLED == STD_ON)

AND

- Service 0x02 is supported (in Dcm_Cfg.h: #define DCM_SVC_02_SUPPORT_ENABLED == STD_ON)

Resolution Description:

ESCAN00100457 Compiler error: Missing parameter in function Dem_DcmGetDTCoOBDFreezeFrame

Workaround:

Use a user-configuration file to override and adapt the API to match the expected prototype.

- 1) Create a user-configuration file (e.g. dcm.cfg). Refer to the DCM technical reference on how to use such a file.
- 2) Add the following content to it:

```
/* WA_ESCAN00100457_BEGIN: */
#if defined (DCM_SOURCE)
extern Std_ReturnType Dem_DcmGetDTCoOBDFreezeFrame_Wrapper(uint8 FrameNumber,
uint32* DTC);
# define Dem_DcmGetDTCoOBDFreezeFrame Dem_DcmGetDTCoOBDFreezeFrame_Wrapper
#endif
/* WA_ESCAN00100457_END: */
```

- 3) In an application C-source file (e.g. Appl<SourceFile>.c) add following code:

```
#include "Dcm.h"

/* WA_ESCAN00100457_BEGIN: */
/**
 * (AR <= 4.2.1) to (AR >= 4.2.2) wrapper Dem_DcmGetDTCoOBDFreezeFrame_Wrapper
 */
Std_ReturnType Dem_DcmGetDTCoOBDFreezeFrame_Wrapper(uint8 FrameNumber, uint32* DTC)
{
    return DcmGetDTCoOBDFreezeFrame(FrameNumber, DTC, );
}
/* WA_ESCAN00100457_END: */
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100485 Sorting of EA Blocks leads to DaVinci Configurator error "modification of the data model failed"	
Component@Subcomponent:	If_AsrIfEa@GenTool_GeneratorMsr
First affected version:	5.02.02
Fixed in versions:	
Problem Description: What happens (symptoms): ----- Pushing the "move up" or "move down" buttons/ arrows in DaVinci Configurator for memory blocks related to a EA partition leads to the error "The modification of the data model failed. An invalid modification was detected during the execution of the UserOperation". Re-sorting of the blocks is not possible, order remains the same. Re-sorting means here that the memory layout will also change, which makes the different configurations incompatible.	
When does this happen: ----- Every time the memory blocks related to EA shall be resorted by user via DaVinci Configurator "move up" or "move down" buttons.	
In which configuration does this happen: ----- With configured memory blocks related to a EA with enabled service ports.	
Resolution Description: Workaround: ----- No workaround available.	
Resolution: ----- /The described issue is corrected by modification of all affected work-products. /	

ESCAN00100613 Compiler error: Declaration of CanIf_ControllerModeIndication() is missing	
Component@Subcomponent:	If_AsrIfCan@Implementation
First affected version:	5.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compile error "CanIf_ControllerModeIndication is not declared" occurs.	
When does this happen:	

The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

When using a Can Driver, which does not include CanIf.h.	
Doesn't occur with Vector Can Driver.	
Resolution Description:	
Workaround:	

Include CanIf.h or copy declaration from CanIf_ControllerModeIndication() into any file, which is included by the Can.c	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100659 Template functionality can not reference items of 3rd Party MCAL implementations	
Component@Subcomponent:	EcuAb_AsrIoHwAb@Description
First affected version:	4.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

IoHwAbSRUsedMcalEntity in IoHwAbSRPortPrototype can not be referenced / chosen if it is a 3rd party MCAL item	
When does this happen:	

always and immediately	
In which configuration does this happen:	

when template functionality is wanted to be used and a 3rd party MCAL item needs to be referenced	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100716	Compiler error: identifier ComM_UserHandleArrayType_<channel_name> is undefined
Component@Subcomponent:	Ccl_Asr4ComMCfg5@GenTool_GeneratorMsr
First affected version:	3.01.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- Typical compiler error explanations may be: \Appl\GenData\ComM_Lcfg.c(452) : error: identifier "ComM_UserHandleArrayType_<channel_name>" is undefined COMM_LOCAL VAR(ComM_UserHandleArrayType_<channel_name>, COMM_VAR_NOINIT) ComM_FullComRequesters_<channel_name>; \Appl\GenData\ComM_Lcfg.c(646) : error: function Rte_Write_ComM_CR_<channel_name>_fullComRequesters declared implicitly (void)Rte_Write_ComM_CR_<channel_name>_fullComRequesters(&ComM_FullComRequesters_CR_<	
When does this happen: ----- The error is issued by the compiler during compilation of the code in case the configuration is as described below. In which configuration does this happen: ----- - /MICROSAR/ComM/ComMGeneral/ComMPncSupport is enabled AND at least one ComM channel with - /MICROSAR/ComM/ComMConfigSet/ComMChannel/ComMFullCommRequestNotificationEnabled is enabled AND - all ComM users mapped to this channels are also mapped to at least one Partial Network.	
Resolution Description: Workaround: ----- 1) If optional ComM_CurrentChannelRequest functionality is not needed, disable it by setting / ComM/ComMConfigSet/ComMChannel/ComMFullCommRequestNotificationEnabled to disabled. otherwise 2) Create a new ComM user and map it to the channel that has /MICROSAR/ComM/ComMConfigSet/ComMChannel/ComMFullCommRequestNotificationEnabled enabled. Notes: - this user has to be a "channel-only" user, do not map it to any Partial Network. - ComM_CurrentChannelRequest functionality only considers "channel-only" users, refer to the Technical Reference chapter "Sender Receiver Interface" -> "ComM_CurrentChannelRequest". Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00100722	Memory abstraction is missing for PduR_SchM_<Enter Exit>_PduR_PDUR_EXCLUSIVE_AREA_<X> wrapper functions
Component@Subcomponent:	Gw_AsrPduRCfg5@GenTool_GeneratorMsr
First affected version:	14.01.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

The Memory abstraction is missing for PduR_SchM_<Enter	
Exit>_PduR_PDUR_EXCLUSIVE_AREA_<X> wrapper functions.	
The functions can't be mapped to different memory sections and will be put to the default section	
for c functions.	
This could be a problem for bootloader usecases where the functions shall be mapped to RAM.	
When does this happen:	

Always and immediately	
In which configuration does this happen:	

Every configuration.	
Resolution Description:	
Workaround:	

Manually move the start of PDUR_START_SEC_CODE above the Exclusive Area wrapper functions.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100736 MSSV terminates unexpectedly if header files are included multiple times	
Component@Subcomponent:	Elisa__core@Application
First affected version:	1.08.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

MSSV terminates unexpectedly.	
When does this happen:	

When a header file is included multiple times.	
In which configuration does this happen:	

Any Configuration where header files are included multiple times, resulting in an extremely large size of the code.	
In the configuration where the problem was found, MemMap.h included Os_MemMap.h	
Resolution Description:	
Workaround:	

Use a define (e.g. Vector_MSSV_Test) to switch off the content of MemMap.h.	
Set this define when running MSSV, so that the code is deactivated for the analysis.	

ESCAN00100742 Compiler error: 'NmOsek_SetSleepReadyBit' : undeclared identifier

Component@Subcomponent: Nm_AsrNmDirOsek@Implementation

First affected version: 2.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

A compile error similar to the following one occurs during compilation of NmOsek.c:
error C2065: 'NmOsek_SetSleepReadyBit' : undeclared identifier

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

'Coordinator Sync Support' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/
NmCoordinatorSyncSupport) is turned ON in the NmGlobalFeatures container in the 'Basic Editor' /
'Network Management General' editor in DaVinci Configurator (-> Nm_Cfg.h contains #define
NM_COORDINATOR_SYNC_SUPPORT STD_ON)

Resolution Description:

Workaround:

Create a User Config File for the Nm module with the following content:
extern Std_ReturnType NmOsek_SetSleepReadyBit(CONST(NetworkHandleType, AUTOMATIC)
nmChannelHandle, CONST(boolean, AUTOMATIC) nmSleepReadyBit);

Configure this User Config File in the 'User Config File' (/MICROSAR/Nm/NmGlobalConfig/
NmGlobalProperties/NmUserConfigFile) setting in the NmGlobalProperties container in the 'Basic
Editor' / 'Network Management General' editor in DaVinci Configurator.

Then create a stub implementation in a C File of this function:

```
Std_ReturnType NmOsek_SetSleepReadyBit( CONST( NetworkHandleType, AUTOMATIC )
nmChannelHandle,
CONST( boolean, AUTOMATIC ) nmSleepReadyBit )
{
    return E_OK;
}
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100796 Compiler error: Invalid assignment for ModeSwitchEventMask0**Component@Subcomponent:** Rte_Core@Implementation**First affected version:** 1.19.00**Fixed in versions:** 1.20.00**Problem Description:**

What happens (symptoms):

Compilation fails because Rte*.c contains following code that does not compile

ModeSwitchEventMask0 |= ;

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

This happens when all of the following conditions evaluate to true:

- the configuration contains runnables with on entry, on exit or on transition mode switch triggers
- the configuration contains multiple partitions
- the mode switch triggered runnables are mapped to a different partition than the mode provider
- no mode disablings are configured

Resolution Description:

Workaround:

Configure a runnable with mode disabling dependency.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100799 Compiler error: Memset used with float initializer in RTE Analyzer stubs	
Component@Subcomponent:	Rte_Core@Implementation
First affected version:	1.18.00
Fixed in versions:	1.20.00
Problem Description:	
What happens (symptoms):	

Analysis with RTE Analyzer fails with	
error: implicit conversion from 'float' to 'int' changes value from XXXX to 0	
When does this happen:	

The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

This happens when all of the following conditions evaluate to true:	
- the configuration contains implicit inter runnable variables - the data type is a float data type - the initializer is different from 0	
Resolution Description:	
Workaround:	

Adapt the analyzer stubs to call memset with 0 as initializer value.	
The stubs are not part of the generated code that will be executed in the ECU.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100823 Generation Error: ArxmlToA2l01009 - Generation of A2L file failed	
Component@Subcomponent:	Ccl_Asr4SmCan@GenTool_GeneratorMsr
First affected version:	3.01.00
Fixed in versions:	5.00.01
Problem Description:	
What happens (symptoms):	

DVMcDataConverter returned exit code 1. [Error] MICROSAR McDataConverter: M1001 An element with the same name "Initialized" has already been processed; McDataConverter can't be generated because of same shortname of MC-DATA-INSTANCE in internal behaviours of different modules.	
When does this happen:	

The error is issued by the generator during generation of Cfg5.	
In which configuration does this happen:	

- generate debug data is enabled - Project Settings -> Modules -> Implementation Variant of the module == Post Build Variance Support	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100828	Null pointer exception when component for a data mapping is missing
Component@Subcomponent:	Rte_Asr4@GenTool_GeneratorMsr
First affected version:	4.00.00
Fixed in versions:	4.20.00
Problem Description:	
What happens (symptoms):	

Generation fails with a null pointer exception.	
When does this happen:	

During generation.	
In which configuration does this happen:	

This happens when the configuration contains data mappings for not existing SWCs.	
Resolution Description:	
Workaround:	

Remove data mappings for all removed components.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100860 RTE Analyzer also tries to extract the COM signal length of TX signals

Component@Subcomponent: Rte_Analyzer@Application

First affected version: 0.09.00

Fixed in versions: 1.03.00

Problem Description:

What happens (symptoms):

Analysis with RTE Analyzer fails with a message similar to

"

Analysis started at 15:23:26 2018-09-20

Compiling...

Linking...

Preparing Static Code Analysis...

Running Static Code Analysis...

Compiling...

Path/ComTest.c:13231:3: error: implicit declaration of function 'Com_GetComConf_ComSignal_name' is invalid in C99

When does this happen:

During analysis of the BSW gendata.

In which configuration does this happen:

This happens when the configuration contains tx COM signals and when the COM is configured to use macro APIs.

Resolution Description:

Workaround:

Disable the analysis of the BSW gendata with the -d commandline switch and manually verify the messages

COM call with non typesafe parameters (SMI-684)
in the configuration feedback.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100931 Null pointer exception when ISignal has no data def props**Component@Subcomponent:** Rte_Asr4@GenTool_GeneratorMsr**First affected version:** 4.08.00**Fixed in versions:** 4.20.00**Problem Description:**

What happens (symptoms):

RTE generation aborts with a null pointer exception.

When does this happen:

During generation.

In which configuration does this happen:

This happens when ISignals do not reference data def props.**Resolution Description:**

Workaround:

Add empty data def props to the ISignals

```
<I-SIGNAL>
<SHORT-NAME>SG04</SHORT-NAME>
<LENGTH>32</LENGTH>
<NETWORK-REPRESENTATION-PROPS>
<SW-DATA-DEF-PROPS-VARIANTS>
<SW-DATA-DEF-PROPS-CONDITIONAL>
</SW-DATA-DEF-PROPS-CONDITIONAL>
</SW-DATA-DEF-PROPS-VARIANTS>
</NETWORK-REPRESENTATION-PROPS>
<SYSTEM-SIGNAL-REF DEST="SYSTEM-SIGNAL">/Communication/SystemSignals/SG04</
SYSTEM-SIGNAL-REF>
</I-SIGNAL>
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100981 Compiler error: Unknown Identifier Dcm_ExternalSetNegResponse/ Dcm_ExternalProcessingDone

Component@Subcomponent: Diag_Asr4Dcm@GenTool_GeneratorMsr

First affected version: 4.00.00

Fixed in versions: 11.00.00

Problem Description:

What happens (symptoms):

Compiler error: Unknown Identifier Dcm_ExternalSetNegResponse/Dcm_ExternalProcessingDone

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-
- No service is implemented externally
- AND
- One or more sub-services are implemented externally

Resolution Description:

Workaround:

Use a user-configuration file to manually change the switch
DCM_DIAG_EXTERN_SVC_HANDLING_ENABLED to STD_ON.

- 1) Create a user-configuration file (e.g. dcm.cfg). Refer to the DCM technical reference on how to use such a file.
- 2) Add the following content to it:

```
/* WA_ESCAN00100981_BEGIN: */
#if defined (DCM_DIAG_EXTERN_SVC_HANDLING_ENABLED)
# undef DCM_DIAG_EXTERN_SVC_HANDLING_ENABLED
# define DCM_DIAG_EXTERN_SVC_HANDLING_ENABLED STD_ON
#endif
/* WA_ESCAN00100981_END: */
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100999 Invalid combination of MPU access rights for S32K derivatives	
Component@Subcomponent:	Os_PlatformArmCortexMGen7@GenTool_GeneratorMsr
First affected version:	2.01.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- Selecting SUPERVISOR_RX and SUPERVISOR_RW leads the supervisor mode having the same access rights as user mode. When does this happen: ----- (1) Always and immediately In which configuration does this happen: ----- If (OsScalabilityClass==SC3 OsScalabilityClass==SC3) && (OsMemoryRegionX/OsMemoryRegionAccessRights==SUPERVISOR_RX) && (OsMemoryRegionX/OsMemoryRegionAccessRights.SUPERVISOR_RW)	
Resolution Description: Workaround: ----- Configure the dedicated SUPERVISOR_RWX access rights instead of SUPERVISOR_RX and SUPERVISOR_RW. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00101005 Compiler error: "undeclared identifier EcuM_GlobalPBConfig_Ptr"**Component@Subcomponent:** SysService_Asr4EcuM@GenTool_GeneratorMsr**First affected version:** 9.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

The compiler throws the following error:

undeclared identifier "EcuM_GlobalPBConfig_Ptr"

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

Only if EcuM is configured as PB-S

AND

an MCAL module is configured which do only support PB-L

AND

This MCAL module is initialized via an EcuM Driver Init List.

Resolution Description:

Workaround:

Don't use the parameter EcuModuleService in the container EcuMDriverInitItem. Instead use the parameter AdditionalInitCode and pass the correct configuration pointer.

e.g.

Mcu_Init(&<ConfigPtrName>)

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00101074 Compiler error: Missing Rte_MemClr when LdCom TP is used	
Component@Subcomponent:	Rte_Core@Implementation
First affected version:	1.19.00
Fixed in versions:	1.20.00
Problem Description:	
What happens (symptoms):	

Compilation fails because the RTE calls a method Rte_MemClr that does not exist.	
When does this happen:	

The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

This happens when the LDCOM TP API is configured and	
- no timeout flags	
- no update flags	
- no never received flags	
- no acknowledgement	
are configured.	
Resolution Description:	
Workaround:	

Configure any other feature that require Rte_MemClr, e.g.	
- Tx Acknowledge Handling	
- NeverReceived Handling	
- IsUpdated Handling	
- Mapped Client/Server communication	
- Queued Sender/Receiver communication	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00101078 MSSV does not consider include paths not containing header files

Component@Subcomponent: Elisa__core@Application

First affected version: 1.08.00

Fixed in versions:

Problem Description:

What happens (symptoms):

MSSV exits with a fatal error because an included file cannot be found in the include paths.

When does this happen:

When executing MSSV with included files (e.g. ".inc"-files) in directories which don't contain header files.

Resolution Description:

Workaround:

Put a dummy header file in included paths if needed.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00101086 IndexOutOfBoundsException during Calculation

Component@Subcomponent: Rte_Asr4@GenTool_GeneratorMsr

First affected version: 4.19.00

Fixed in versions: 4.20.00

Problem Description:

What happens (symptoms):

- When generating the RTE, a java.lang.IndexOutOfBoundsException: Index: 0, Size: 0 is thrown.
-> Rte cannot be generated

When does this happen:

- Generation or validation of the RTE

In which configuration does this happen:

- projects with variants

Resolution Description:

Workaround:

- Deleting RteCache files, if the current checksum != ""
- Disable RteCache

Resolution:

- fixed in RteFileCache class getChecksum, by checking the return value of reading the checksum file

ESCAN00101088 Missing ROM data sections for Globalshared ZERO_INIT sections	
Component@Subcomponent:	Os_CoreGen7@GenTool_GeneratorMsr
First affected version:	2.09.00
Fixed in versions:	2.25.00
Problem Description:	
What happens (symptoms):	

Variables which are mapped to the global shared memory region are not initialized correctly during system startup. Only variables which are mapped to a OS_GLOBALSHARED_VAR_[...]_ZERO_INIT section are affected.	
When does this happen:	

This happens during the boot process, as the init values could not be copied from ROM to RAM.	
In which configuration does this happen:	

Any configuration.	
Resolution Description:	
Workaround:	

Add corresponding ROM sections manually to the linker file.	
Example for the GreenHills compiler and the OS_GLOBALSHARED_VAR_ZERO_INIT section:	
<pre>.ROM_OS_GLOBALSHARED_VAR_ZERO_INIT ROM(OS_GLOBALSHARED_VAR_ZERO_INIT) :> . _ROM_OS_GLOBALSHARED_VAR_ZERO_INIT_START = ADDR(.ROM_OS_GLOBALSHARED_VAR_ZERO_INIT); _ROM_OS_GLOBALSHARED_VAR_ZERO_INIT_END = ENDADDR(.ROM_OS_GLOBALSHARED_VAR_ZERO_INIT);</pre>	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00101120 Dem include is independent from configuration. Dem is always included.

Component@Subcomponent: DrvEep__coreAsr@GenTool_GeneratorMsr

First affected version: 1.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Compiler throws error that "Dem.h cannot be found" and "Dem_EventIdType is not declared".

When does this happen:

During compilation.

In which configuration does this happen:

If Dem module is not part of the delivery.

Resolution Description:

Workaround:

Create a "Dem.h" file and define the "Dem_EventIdType" as integer parameter within this file.

Resolution:

The generator must check if the optional container "EepInitConfiguration -> EepDemEventParameterRefs" is configured. If not, the Dem module must not be included and all elements within the structure "ConfigType" must be pre-processed via pre-processor switch.

To prevent several code sections to be pre-processed:

e.g.

```
#if (MSN_DEM_ERROR_REPORT == STD_ON)
  Dem_ErrorReport();
#endif
```

A better solution would be to define a function macro for Dem_ErrorReport(). In case Dem is not supported, this function macro is defined as empty.

ESCAN00101164 Compiler error: PduR_LoIfTxConfirmation undefined	
Component@Subcomponent:	Gw_AsrPduRCfg5@Implementation
First affected version:	12.02.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler error "PduR_LoIfTxConfirmation undefined" occurs.	
When does this happen:	

The error is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

- only precompile configuration - At least one module which has /MICROSAR/PduR/PduRBswModules/PduRTxConfirmation activated - No communication interface routing path with /MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/PduRRoutingPath/PduRDestPdu/PduRTransmissionConfirmation activated	
Resolution Description:	
Workaround:	

Configure a dummy communication interface routing path and activate /MICROSAR/PduR/PduRRoutingTables/PduRRoutingTable/PduRRoutingPath/PduRDestPdu/PduRTransmissionConfirmation.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00101183 Compiler error: Missing parentheses for Rte_IrvIRead_ and Rte_IrvIWriteRef macros

Component@Subcomponent: Rte_Core@Implementation

First affected version: 1.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Compilation fails with an error message
"error: invalid type argument of `->'" or similar.

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

This happens when implicit inter-runnable variables of record or primitive type are configured and a Rte_IrvIWriteRef or Rte_IrvIRead_ macro is used directly in an expression:

E.g.
When one element of a record type shall be written.

```
Rte_IrvIWriteRef_a()->element = 0;
```

the compiler is not able to resolve the element because missing parentheses around the address operator let the compiler evaluate the element selection operator first.

```
#define Rte_IrvIWriteRef_a() \  
&(Rte_r)
```

Resolution Description:

Workaround:

Encapsulate the RTE API call in parentheses.
E.g.

```
(Rte_IrvIWriteRef_a())->element = 0;
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00101322 CddType missing for UserDefinedPdu	
Component@Subcomponent:	GenTool_CsAsrLegacyDb2SystemDescr@Application
First affected version:	1.08.24
Fixed in versions:	1.08.25
Problem Description:	
What happens (symptoms):	

The conversion that resulted in a UserDefinedPdu containing a <CDD-TYPE> before, creates UserDefinedPdu without CddType set.	
This leads to the creation of global PDUs, that are not associated to any component, instead of the creation of UserDefinedPdus associated to the specified CDD.	
When does this happen:	

During conversion	
In which configuration does this happen:	

For every dbc containing messages having CddType set.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00101345 Service 0x86: Consistency error due to a missing reference to DcmDsdServiceTable	
Component@Subcomponent:	Diag_Asr4Dcm@GenTool_GeneratorMsr
First affected version:	5.01.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Consistency error is issued from the DaVinci Configurator due to a thrown exception.	
When does this happen:	

Once service 0x86 (response on event) is configured in a service table (DcmDsdServiceTable).	
In which configuration does this happen:	

- Service 0x86 is configured in DcmDsdServiceTable	
AND	
- DcmDsdServiceTable is not referenced by DcmDslProtocolRow	
Resolution Description:	
Workaround:	

To prevent the appearance of the consistency error on the configurator GUI, configure DcmDslProtocolRow before configuring service 0x86 in DcmDsdServiceTable.	
Or,	
If the consistency error is already issued, configure DcmDslProtocolRow, save, close the project, and loaded again.	

ESCAN00101354 Service 0x86: Consistency error due to an invalid DcmDsdSidTabServiceDispatcher value	
Component@Subcomponent:	Diag_Asr4Dcm@GenTool_GeneratorMsr
First affected version:	10.02.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Consistency error is issued from the DaVinci Configurator due to a thrown exception.	
When does this happen:	

Once service 0x86 (response on event) is configured in a service table (DcmDsdServiceTable).	
In which configuration does this happen:	

- Service 0x86 is configured in DcmDsdServiceTable	
AND	
- 0x86 is configured as external service	
AND	
- The parameter DcmDsdSidTabServiceDispatcher is set to "false"	
Resolution Description:	
Workaround:	

If the parameter DcmDsdSidTabServiceDispatcher is set to "false", then delete it.	

ESCAN00101362 Compiler error: C4305 - truncation from 'unsigned int' to <MSN>_<IndexConstArray>Type

Component@Subcomponent: Gw_AsrPduRCfg5@GenTool_GeneratorMsr

First affected version: 14.01.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Compile error C4305: truncation from 'unsigned int' to <MSN>_<IndexConstArray>Type

When does this happen:

The error is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

-
- EModuleConfigurationVariant = VARIANT_POST_BUILD_LOADABLE
 - IndexConstArray with datatype EComStackDataTypeRep.PDUIDTYPE and invalid elements
 - PduIdType = UInt8

Resolution Description:

Workaround:

Configure EcuC/EcucPduCollection/PduIdTypeEnum to UINT16.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00101415 RTE49999: When NvBlock SWCs are used and NvM_MainFunction is missing	
Component@Subcomponent:	Rte_Core@Implementation
First affected version:	1.01.00
Fixed in versions:	1.20.00
Problem Description:	
What happens (symptoms):	

RTE generation aborts with an RTE49999 error.	
When does this happen:	

During generation.	
In which configuration does this happen:	

This happens when the configuration contains NvBlock SWCs but does not contain a NvM_MainFunction runnable.	
Resolution Description:	
Workaround:	

Configure a NvM_MainFunction runnable.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00101416 Warning RTE1070: Missing parameter definition when NVM configuration uses the standard definition	
Component@Subcomponent:	Rte_Core@Implementation
First affected version:	1.12.00
Fixed in versions:	1.20.00
Problem Description:	
What happens (symptoms):	

RTE generator issues a warning RTE1070: Missing parameter definition	
When does this happen:	

During generation.	
In which configuration does this happen:	

This happens when a 3rd party NVM is used.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

2.6 Compiler Warnings

As a service we also provide the known compiler warnings. The occurrence of a compiler warning may depend on the used software module configuration and compiler settings.

Index

ESCAN00066880	Compiler warning: function 'Appl_CanSM_BusOffBegin()' has no-used argument(CanSM_BusOffNotificationCounter). Nm_AsrNmDirOsek@Implementation
ESCAN00067159	Compiler warning: cast truncates constant value MemService_AsrNmM@Implementation
ESCAN00068434	Compiler warning: conditional expression or part of it is always true/false DrvCan__coreAsr@Implementation
ESCAN00068872	Compiler warning: the order of volatile accesses is undefined in this statement DrvCan__coreAsr@Implementation
ESCAN00074793	Compiler warning: Condition is always constant Diag_Asr4Dem@Implementation
ESCAN00081459	Compiler warning: function "ApplCanTimerLoop" was declared but never referenced DrvCan__coreAsr@Implementation
ESCAN00088061	BswM_Lcfg.c: warning: 'function' : conversion from 'const BswM_ImmediateUserStartIdxOfModeReqeustMappingType' to 'BswM_SizeOfImmediateUserType', possible loss of data SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00089543	Compiler warning: dead assignment to "errorId" eliminated Nm_Asr4NmIf@Implementation
ESCAN00089544	Compiler warning: conversion to 'uint8' from 'int' may alter its value Nm_Asr4NmIf@Implementation
ESCAN00090161	Compiler warning: condition evaluates always to true/false Ccl_Asr4ComMCfg5@Implementation
ESCAN00090831	Compiler warning: integer conversion resulted in a change of sign IL_AsrComCfg5@Implementation
ESCAN00091295	Compiler warning: dead assignment / variable set but not used Ccl_Asr4ComMCfg5@Implementation
ESCAN00091601	Compiler warning: array subscript is above array bounds Nm_AsrNmDirOsek@Implementation
ESCAN00091606	Compiler warning: array subscript is above array bounds Nm_AsrNmDirOsek@Implementation
ESCAN00091814	Compiler warning: variable defined but not used (S32) DrvCan_ImxFlexcan3LI@Implementation
ESCAN00097136	Compiler warning: "conditional expression is constant" Nm_AsrNmDirOsek@Implementation
ESCAN00097980	Compiler warning: Unreferenced formal parameter due to reduction of rom data IL_AsrComCfg5@Implementation
ESCAN00098070	Compiler warning: NmM_Cfg.c: 'ServiceId' : unreferenced formal parameter MemService_AsrNmM@GenTool_GeneratorMsr
ESCAN00099190	Compiler warning: BswM_Lcfg.c(2990): warning C4100: 'handleId' : unreferenced formal parameter SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
ESCAN00100160	Compiler warning: Order of volatile access is undefined in this statement Diag_Asr4Dem@Implementation
ESCAN00100182	Compiler warning: A value that cannot be used to initialize an entity with a function pointer type Gw_AsrPduRCfg5@GenTool_GeneratorMsr

Index

ESCAN00100219	Compiler warning: Explicit Cast Discards Volatile Qualifier Diag_Asr4Dem@Implementation
ESCAN00100609	Compiler warning: Undefined compiler abstraction DrvEep_XXi2c01Asr@Implementation
ESCAN00100871	Compiler warning: Variable is possibly uninitialized Diag_Asr4Dcm@Implementation
ESCAN00100903	Compiler warning: last line of Dem_EnableCondition_Interface.h ends without a newline Diag_Asr4Dem@Implementation
ESCAN00100904	Compiler warning: last line of Dem_Cfg_Definitions.h ends without a newline Diag_Asr4Dem@Implementation
ESCAN00100905	Compiler warning: last line of Dem_MemState_Implementation.h ends without a newline Diag_Asr4Dem@Implementation
ESCAN00100939	Compiler warning: "Eep_30_XXi2c01_GetVersionInfoStd()" was declared but never referenced. DrvEep_XXi2c01Asr@Implementation
ESCAN00101035	Misra warning: "0612 - size of object exceeds 32767 bytes" Ccl_Asr4SmCan@GenTool_GeneratorMsr

ESCAN00066880 Compiler warning: function 'Appl_CanSM_BusOffBegin()' has no-used argument(CanSM_BusOffNotificationCounter).

Component@Subcomponent: Nm_AsrNmDirOsek@Implementation

First affected version: 1.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Compiler warns for an unused argument: Can be accepted - is usually because of a standardized API which doesn't respect unused parameters in special configurations

[Warning(ccom):../../external/BSW/NmOsek/NmOsek.c,line 4891] function 'NmOsek_CanSM_Actual_BusOffBegin()' has no-used argument(CanSM_BusOffNotificationCounter).

The warning occurs independent of NMOSEK_USE_DUMMY_STATEMENT = STD_ON or = STD_OFF

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

Configurations where 'Bus Off Notification Enabled' is ON in the NmOsek module settings (-> #define NMOSEK_BUSOFF_NOTIFICATION_ENABLED can be found in NmOsek_Cfg.h) OR 'Single Channel Optimization' is ON (-> #define NMOSEK_OPTIMIZE_CHANNEL_ENABLED can be found in NmOsek_Cfg.h)

Hint:

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed because there are only a few compilers that complain about an unused argument event though dummy statements are enabled.

Resolution Description:

Workaround:

Ignore the warning.

For Reneasas compilers do not use the -Wno_unused_argument command line argument.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00067159 Compiler warning: cast truncates constant value**Component@Subcomponent:** MemService_AsrNvM@Implementation**First affected version:** 3.08.01**Fixed in versions:****Problem Description:**

What happens (symptoms):

```
>..\..\bsw\nvm\nvm_crc.c(229) : warning C4310: cast truncates constant value
```

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

CANoeEmu + VS2008

It depends on definition of uint16_least: Warning occurs only if uint16_least is not of type int.

Hint:

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed, because the cast confirms and enforces this behavior (i.e. the value SHALL be truncated, if necessary).
Additionally: Why uint16_least is not (unsigned) int? -> this data type fulfills all requirements on a 16 bit unsigned value...

Resolution Description:

Workaround:

No workaround necessary.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00068434 Compiler warning: conditional expression or part of it is always true/false**Component@Subcomponent:** DrvCan__coreAsr@Implementation**First affected version:** 4.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

- Compiler warns for "condition is always true": This may happen depending on configuration, i.e. assert checks

in function Can_SetControllerMode following code is available

```
...
transitionRequest = kCanRequested;

CanMicroModeRestore();
}
if ( transitionRequest == CAN_NOT_OK ) /* PRQA S 3355,3356,3358,3359 */ /* MD_Can_13.7 */
{ /* PRQA S 3201 */ /* MD_Can_3201 */
    retval = CAN_NOT_OK;
    transitionDone = CAN_NOT_OK; /* at least one HW channel is not in new state (CAN_MSR40: poll later) */
}
..
```

this issues following compiler warning:

if (transitionRequest == CAN_NOT_OK) - warning (dcc:1606): conditional expression or part of it is always true/false

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

All configurations.

but not for all Platform implementations (hw always return OK for state transition)

Resolution Description:

Workaround:

Ignore warning

ESCAN00068872 Compiler warning: the order of volatile accesses is undefined in this statement	
Component@Subcomponent:	DrvCan__coreAsr@Implementation
First affected version:	3.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler issues warning messages like this:	
undefined behavior: the order of volatile accesses is undefined in this statement	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

Rx Queue is enabled	
Resolution Description:	
Workaround:	

Ignore Warning	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00074793 Compiler warning: Condition is always constant	
Component@Subcomponent:	Diag_Asr4Dem@Implementation
First affected version:	4.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler warning 'Condition is always constant'	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

Configurations without DTCs	
AND	
Precompile configuration	
Resolution Description:	
Workaround:	

The warning can be ignored	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00081459 Compiler warning: function "ApplCanTimerLoop" was declared but never referenced	
Component@Subcomponent:	DrvCan__coreAsr@Implementation
First affected version:	4.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

compiler warning: function "ApplCanTimerLoop" was declared but never referenced	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

In all configurations where feature SLeep/Wakeup is not enabled. And no other transition needs this hardware transition loop.	
Hint:	

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed due to compiler will remove this function so no effect in code size will occur.	
And the code complexity will increase significant to fix this problem by pre-processor switches	
Resolution Description:	
Workaround:	

Ignore Warning	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00088061	BswM_Lcfg.c: warning: 'function' : conversion from 'const BswM_ImmediateUserStartIdxOfModeReqeustMappingType' to 'BswM_SizeOfImmediateUserType', possible loss of data
Component@Subcomponent:	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
First affected version:	7.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

BswM_Lcfg.c: warning: 'function' : conversion from 'const BswM_ImmediateUserStartIdxOfModeReqeustMappingType' to 'BswM_SizeOfImmediateUserType', possible loss of data	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

All	
Resolution Description:	

ESCAN00089543 Compiler warning: dead assignment to "errorId" eliminated	
Component@Subcomponent:	Nm_Asr4NmIf@Implementation
First affected version:	7.00.00
Fixed in versions:	
Problem Description: What happens (symptoms): ----- A compiler warning similar to the following one occurs for the compilation of Nm.c: dead assignment to "errorId" eliminated When does this happen: ----- The warning is issued by the compiler during compilation of the code in case the configuration is as described below. In which configuration does this happen: ----- 'Dev Error Detect' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalProperties/NmDevErrorDetect) in the NmGlobalProperties container is turned OFF in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm_Cfg.h contains #define NM_DEV_ERROR_REPORT STD_OFF). Hint: ----- The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed due to the API pattern that Vector has decided to use: each API that may report development errors shall always have an errorId variable on the stack to which assignments are made - regardless of whether the variable is actually used or not.	
Resolution Description: Workaround: ----- Ignore the warning. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00089544 Compiler warning: conversion to 'uint8' from 'int' may alter its value

Component@Subcomponent: Nm_Asr4NmIf@Implementation

First affected version: 9.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Compiler warnings similar to the following one occur for the compilation of Nm.c:
conversion to 'uint8' from 'int' may alter its value

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

'Coordinator Support Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/
NmCoordinatorSupportEnabled) is turned ON in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm_Cfg.h contains #define NM_COORDINATOR_SUPPORT_ENABLED STD_ON)

AND

(
'Remote Sleep Ind Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/
NmRemoteSleepIndEnabled) is turned OFF in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm_Cfg.h contains #define NM_REMOTE_SLEEP_IND_ENABLED STD_OFF)

OR

all coordinated channels have 'Channel Sleep Master' (/MICROSAR/Nm/NmChannelConfig/
NmChannelSleepMaster) turned ON in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm_Cfg.h contains #define NM_OPTIMIZE_ALL_SLEEP_MASTER STD_ON)

OR

all coordinated channels have 'Synchronizing Network' (/MICROSAR/Nm/NmChannelConfig/
NmSynchronizingNetwork) turned ON in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm_Cfg.h contains #define NM_OPTIMIZE_ALL_SYNC_CHANNEL STD_ON)
)

Hint:

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed because there is no risk of an invalid conversion of value to uint8.

Resolution Description:

Workaround:

Ignore the warning.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00090161 Compiler warning: condition evaluates always to true/false

Component@Subcomponent: Ccl_Asr4ComMCfg5@Implementation

First affected version: 7.00.01

Fixed in versions:

Problem Description:

What happens (symptoms):

Compiler warns for conditional expression being constant

a) in the function ComM_Init() when checking the generated data. Compiler warns about condition being always false in the following conditions:

if (ComM_GetWakeupStateOfChannel(ComM_ChannelIndex) >= COMM_MAX_NUMBER_OF_STATES)

if (ComM_GetSizeOfChannel() != ComM_GetSizeOfChannelPb())

if (ComM_GetSizeOfPnc() != ComM_GetSizeOfPncPb())

As secondary effect compiler might warn about unreachable code/statement.

b) in the function ComM_PncProcessRxSignalEra() compiler warns about condition being always true in

if(ComM_IsSynchronizedOfPnc(pncIndex))

c) in the functions ComM_PncSetBitInSignal() and ComM_PncClearBitInSignal() when checking the generated data. Compiler warns about condition being always true in

if(signalByteIndex < ComM_GetSizeOfPncSignalValues())

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

a) occurs when COMM_DEV_ERROR_DETECT == STD_ON

b) occurs when

- 'Pnc Support' is enabled in ComM (/MICROSAR/ComM/ComMGeneral/ComMPncSupport)

AND

- 'Pnc Gateway Enabled' is enabled in ComM (/MICROSAR/ComM/ComMGeneral/ComMPncGatewayEnabled)

AND

- Only one PNC exists (COMM_ACTIVE_PNC == 1U, can be found in ComM_Cfg.h).

c) occurs when 'Pnc Support' is enabled in ComM (/MICROSAR/ComM/ComMGeneral/ComMPncSupport)

Hint:

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed because no simple remedy exist.

The warning is caused by an if-statement applied on external configuration data. Configuration data is const for the given compilation context but might be changed at post-build time.

Resolution Description:

ESCAN00090831 Compiler warning: integer conversion resulted in a change of sign	
Component@Subcomponent:	Il_AsrComCfg5@Implementation
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler warns that "integer conversion resulted in a change of sign".	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

If the compiler WindRiver Diab is used. (found with version 5.9.4.2.)	
Hint:	

The compiler warning is known and has been analyzed thoroughly for its impact on the code.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00091295 Compiler warning: dead assignment / variable set but not used	
Component@Subcomponent:	Ccl_Asr4ComMCfg5@Implementation
First affected version:	5.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler warns about an useless assignment to a local variable. Typically the warnings refer to local variables 'channel', 'errorId', 'Status' or 'User'.	
Example compiler warning strings:	
"Useless assignment to variable 'abc'. Assigned value not used."	
"Removed dead assignment"	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

EcuC Parameter 'Dummy Statement Kind' is set to 'SelfAssignment'. This can be detected in ComM_Cfg.c: #define COMM_DUMMY_STATEMENT(v) (v)=(v)	
Hint:	

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed because no simple remedy exist.	
If Dummy Statement is switched off, other compiler warnings might occur e.g. "Unused/unreferenced variable".	
Resolution Description:	

ESCAN00091601 Compiler warning: array subscript is above array bounds

Component@Subcomponent: Nm_AsrNmDirOsek@Implementation

First affected version: 2.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Compiler warnings similar to the following one occur for the compilation of NmOsek.c:

array subscript is above array bounds

in expansion of macro 'NmOsek_GetRxMessageData'

NmOsek_GetRxMessageData(NMOSEK_MESSAGE_DATA_BYTE_INDEX(NMOSEK_CHANNEL_IDX, byteIndex));

for the usage within NmOsek_GetUserData()

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

'User Data Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/NmUserDataEnabled) is turned ON in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm_Cfg.h contains #define NM_USER_DATA_ENABLED STD_ON)

AND

(
The configuration variant of NmOsek is VARIANT-POST-BUILD-LOADABLE (regardless of the Postbuild-Selectable Support) in the Project Settings, Modules view in DaVinci Configurator (-> NmOsek_Cfg.h contains #define NMOSEK_CONFIGURATION_VARIANT NMOSEK_CONFIGURATION_VARIANT_POSTBUILD_LOADABLE)
OR

The number of NmOsek channels is greater than one, i.e. the multiplicity of /MICROSAR/NmOsek/NmOsekGlobalConfig/NmOsekChannelConfig is greater than 1 in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> NmOsek_Cfg.h contains #define NMOSEK_MAX_NUMBER_OF_NMOSEK_CHANNELS <value greater than 1U>)
)

AND

'Api Optimization' (/MICROSAR/NmOsek/NmOsekGlobalConfig/NmOsekApiOptimization) is turned OFF in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> NmOsek_Cfg.h contains #define NMOSEK_API_OPTIMIZATION STD_OFF)

Resolution Description:

Workaround:

Ignore the warning.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00091606 Compiler warning: array subscript is above array bounds

Component@Subcomponent: Nm_AsrNmDirOsek@Implementation

First affected version: 2.00.00

Fixed in versions:

Problem Description:

What happens (symptoms):

Compiler warnings similar to the following one occur for the compilation of NmOsek.c:
array subscript is above array bounds

in expansion of macro 'NmOsek_SetTxMessageData'

NmOsek_GetTxMessageData(NMOSEK_MESSAGE_DATA_BYTE_INDEX(NMOSEK_CHANNEL_IDX,
byteIndex));

for the usage within NmOsek_SetUserData()

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

'User Data Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/NmUserDataEnabled) is turned ON in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm_Cfg.h contains #define NM_USER_DATA_ENABLED STD_ON)

AND

'Com User Data Support' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/NmComUserDataSupport) is turned OFF in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm_Cfg.h contains #define NM_COM_USER_DATA_SUPPORT STD_OFF)

AND

'Passive Mode Enabled' (/MICROSAR/Nm/NmGlobalConfig/NmGlobalFeatures/NmPassiveModeEnabled or /MICROSAR/Nm/NmChannelConfig/NmPassiveModeEnabled) is turned OFF in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> Nm_Cfg.h contains #define NM_PASSIVE_MODE_ENABLED STD_OFF)

AND

(
The configuration variant of NmOsek is VARIANT-POST-BUILD-LOADABLE (regardless of the Postbuild-Selectable Support) in the Project Settings, Modules view in DaVinci Configurator (-> NmOsek_Cfg.h contains #define NMOSEK_CONFIGURATION_VARIANT NMOSEK_CONFIGURATION_VARIANT_POSTBUILD_LOADABLE)

OR

The number of NmOsek channels is greater than one, i.e. the multiplicity of /MICROSAR/NmOsek/NmOsekGlobalConfig/NmOsekChannelConfig is greater than 1 in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> NmOsek_Cfg.h contains #define NMOSEK_MAX_NUMBER_OF_NMOSEK_CHANNELS <value greater than 1U>)

AND

'Api Optimization' (/MICROSAR/NmOsek/NmOsekGlobalConfig/NmOsekApiOptimization) is turned OFF in the 'Network Management General' / 'Basic Editor' in DaVinci Configurator (-> NmOsek_Cfg.h contains #define NMOSEK_API_OPTIMIZATION STD_OFF)

ESCAN00091606	Compiler warning: array subscript is above array bounds
<i>Resolution Description:</i> Workaround: ----- Ignore the warning. Resolution: ----- The described issue is corrected by modification of all affected work-products.	

ESCAN00091814 Compiler warning: variable defined but not used (S32)**Component@Subcomponent:** DrvCan_ImxFlexcan3LI@Implementation**First affected version:** 1.00.00**Fixed in versions:** 2.04.01**Problem Description:**

What happens (symptoms):

S32 derivative: compiler warning occurs (variable defined but not used)
In case of strict compiler settings might not compile

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

Running Testsuite ConfigGEN for S32 derivative (CANbedded) with test cases using
C_ENABLE_PRETRANSMIT_FCT
Also affected IMX and Vybrid when using C_ENABLE_PRETRANSMIT_FCT

Resolution Description:

Workaround:

No workaround available.

Change code from

```
# if defined( C_CPUTYPE_LITTLEENDIAN )
/* RAM CATEGORY 1 START*/
V_DEF_VAR(CAN_STATIC, tCanTxMsgBuffer, VAR_NOINIT)
canTxMsgBuffer[kCanNumberOfUsedTxCANObjects];
/* RAM CATEGORY 1 END*/
# endif
```

to

```
# if defined( C_CPUTYPE_LITTLEENDIAN ) && defined( C_ENABLE_PRETRANSMIT_FCT )
/* RAM CATEGORY 1 START*/
V_DEF_VAR(CAN_STATIC, tCanTxMsgBuffer, VAR_NOINIT)
canTxMsgBuffer[kCanNumberOfUsedTxCANObjects];
/* RAM CATEGORY 1 END*/
# endif
```

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00097136 Compiler warning: "conditional expression is constant"**Component@Subcomponent:** Nm_AsrNmDirOsek@Implementation**First affected version:** 8.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

The following or similar compiler warning occurs:

NmOsekS.c (NmOsekS.c): conditional expression or part of it is always true/false

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

NMOSEK_DEV_ERROR_DETECT == STD_ON

It is used to detect invalid generated data.

Hint:

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed due to AN-ISC-8-1184_Compiler_Warnings.pdf**Resolution Description:**

ESCAN00097980 Compiler warning: Unreferenced formal parameter due to reduction of rom data	
Component@Subcomponent:	Il_AsrComCfg5@Implementation
First affected version:	1.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler warning occurs: Unreferenced formal parameter	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

/MICROSAR/Com/ComGeneration/ComReduceConstantData2Define is enabled	
OR	
/MICROSAR/Com/ComGeneral/ComOptimizeConstArrays2Define is enabled (in older releases).	
Hint:	

The compiler warning is known and has been analyzed thoroughly for its impact on the code. Nevertheless it will not be fixed due to existence of a sufficient workaround.	
Resolution Description:	
Workaround:	

Disable	
/MICROSAR/Com/ComGeneration/ComReduceConstantData2Define (in newer releases)	
OR	
/MICROSAR/Com/ComGeneral/ComOptimizeConstArrays2Define (in older releases).	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00098070 Compiler warning: NvM_Cfg.c: 'ServiceId' : unreferenced formal parameter	
Component@Subcomponent:	MemService_AsrNvM@GenTool_GeneratorMsr
First affected version:	3.01.02
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

1> NvM_Cfg.c	
1>..\..\Appl\GenDataVtt\NvM_Cfg.c(588): warning C4100: 'ServiceId' : unreferenced formal parameter	
with Visual Studio compiler	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

Any configuration with disabled NvMMultiBlockCallback and NvMBswMMultiBlockJobStatusInformation	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00099190	Compiler warning: BswM_Lcfg.c(2990): warning C4100: 'handleId' : unreferenced formal parameter
Component@Subcomponent:	SysService_Asr4BswMCfg5@GenTool_GeneratorMsr
First affected version:	6.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler warns about C4100: 'handleId' : unreferenced formal parameter in BswM_Lcfg.c.	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

In all configurations which use actions of type BswMTimerControl.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100160 Compiler warning: Order of volatile access is undefined in this statement	
Component@Subcomponent:	Diag_Asr4Dem@Implementation
First affected version:	13.00.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

A compiler warning is shown which indicates that order of volatile accesses are undefined.	
For example in an IAR compiler for ARM 8.20: Warning[Pa082]: undefined behavior: the order of volatile accesses is undefined in this statement.	
When does this happen:	

The warning is issued by the compiler during compilation of the code.	
In which configuration does this happen:	

Happens in all configurations.	
Resolution Description:	
Workaround:	

The compiler warning can be ignored as the order of access of the respective volatile variables have no effect on the functionality.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100182 Compiler warning: A value that cannot be used to initialize an entity with a function pointer type**Component@Subcomponent:** Gw_AsrPduRCfg5@GenTool_GeneratorMsr**First affected version:** 1.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

Compiler warns for a value that cannot be used to initialize an entity with a function pointer type with MSN_CopyRxData, MSN_CopyTxData and MSN_StartOfReception.

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

Any configuration using a BSW or CDD adjacent to the PduR which has been implemented based on an AUTOSAR Specification that uses const in API parameters of MSN_CopyRxData, MSN_CopyTxData and MSN_StartOfReception.

The AUTOSAR Specifications have been changed multiple times between ASR 4.00.03 and today. There is no common solution for all versions possible and you have to accept the compile warning until all components in the system have implemented the Com-Stack API harmonization introduced with ASR 4.03.00.

Resolution Description:

Workaround:

No workaround available.

Resolution:

The described issue is corrected by modification of all affected work-products.

ESCAN00100219 Compiler warning: Explicit Cast Discards Volatile Qualifier**Component@Subcomponent:** Diag_Asr4Dem@Implementation**First affected version:** 6.02.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

The compiler states one or more of the following warnings:

In Dem_Mem_Implementation.h

line 1323: warning (dcc:1824): explicit cast from 'ptr-to-volatile Dem_Event_InternalStatusType' to 'Dem_DataPtrType' discards volatile qualifier

line 1436: warning (dcc:1824): explicit cast from 'ptr-to-volatile Dem_Cfg_MemoryCommitNumberType' to 'Dem_DataPtrType' discards volatile qualifier

In Dem_EnableCondition_Implementation.h

line 744: warning (dcc:1824): explicit cast from 'ptr-to-volatile Dem_Cfg_EnableConditionGroupStateType' to 'Dem_DataPtrType' discards volatile qualifier

When does this happen:

At compile time.

In which configuration does this happen:

All**Resolution Description:**

Workaround:

Disable Compiler Warning.

Resolution:

Warning will not be fixed.

ESCAN00100609 Compiler warning: Undefined compiler abstraction**Component@Subcomponent:** DrvEep_XXi2c01Asr@Implementation**First affected version:** 2.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

Compiler warns for an undefined compiler abstraction.

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

In every configuration.

Hint:

The compiler warning is known and has been analyzed thoroughly for its impact on the code.**Resolution Description:**

Workaround:

The missing compiler abstractions:

EEP_30_XXI2C_01_APPL_DATA and EEP_APPL_DATA may be defined manually.

Resolution:

Correct the used compiler abstractions within the implementation:

EEP_30_XXI2C_01_APPL_DATA -> EEP_30_XXI2C01_APPL_DATA

EEP_APPL_DATA -> EEP_30_XXI2C01_APPL_DATA

ESCAN00100871 Compiler warning: Variable is possibly uninitialized	
Component@Subcomponent:	Diag_Asr4Dcm@Implementation
First affected version:	7.02.00
Fixed in versions:	
Problem Description:	
What happens (symptoms):	

Compiler warns that variable is possibly uninitialized (W507 variable INrc is possibly uninitialized).	
When does this happen:	

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.	
In which configuration does this happen:	

Configuration independent.	
Resolution Description:	
Workaround:	

Ignore warning.	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100903		Compiler warning: last line of Dem_EnableCondition_Interface.h ends without a newline
Component@Subcomponent:	Diag_Asr4Dem@Implementation	
First affected version:	13.03.00	
Fixed in versions:	16.01.00	
Problem Description:		
What happens (symptoms):		

Compiler warns about missing newline:		
../../../../external/bsw/dem/Dem_EnableCondition_Interface.h:698:120: error: no newline at end of file [-Werror,-Wnewline-eof]		
When does this happen:		

The warning is issued by the compiler during compilation of the code		
In which configuration does this happen:		

all		
Resolution Description:		
Workaround:		

Ignore the warning		
Resolution:		

The described issue is corrected by modification of all affected work-products.		

ESCAN00100904 Compiler warning: last line of Dem_Cfg_Definitions.h ends without a newline	
Component@Subcomponent:	Diag_Asr4Dem@Implementation
First affected version:	15.04.00
Fixed in versions:	16.01.00
Problem Description:	
What happens (symptoms):	

Compiler warns about missing newline:	
<pre>../../../../external/bsw/dem/Dem_Cfg_Definitions.h:5251:120: error: no newline at end of file [-Werror,-Wnewline-eof]</pre>	
When does this happen:	

The warning is issued by the compiler during compilation of the code	
In which configuration does this happen:	

all	
Resolution Description:	
Workaround:	

Ignore the warning	
Resolution:	

The described issue is corrected by modification of all affected work-products.	

ESCAN00100905		Compiler warning: last line of Dem_MemState_Implementation.h ends without a newline	
Component@Subcomponent:	Diag_Asr4Dem@Implementation		
First affected version:	15.05.00		
Fixed in versions:	16.01.00		
Problem Description:			
What happens (symptoms):			

Compiler warns about missing newline:			
../../../../external/bsw/dem/Dem_MemState_Implementation.h:1085:120: error: no newline at end of file [-Werror,-Wnewline-eof]			
When does this happen:			

The warning is issued by the compiler during compilation of the code			
In which configuration does this happen:			

all			
Resolution Description:			
Workaround:			

Ignore the warning			
Resolution:			

The described issue is corrected by modification of all affected work-products.			

ESCAN00100939 **Compiler warning:**
"Eep_30_XXi2c01_GetVersionInfoStd()" was
declared but never referenced.**Component@Subcomponent:** DrvEep_XXi2c01Asr@Implementation**First affected version:** 2.00.00**Fixed in versions:****Problem Description:**

What happens (symptoms):

- Compiler warns for an unused function: Eep_30_XXi2c01_GetVersionInfoStd()

When does this happen:

The warning is issued by the compiler during compilation of the code in case the configuration is as described below.

In which configuration does this happen:

- The compiler warning appears in case the "EepVersionInfoApi" is "disabled".**Resolution Description:**

Workaround:

The GetVersionInfo API service may be enabled within the Cfg5.
There's no reason to disable this API service.

Resolution:

Add the preprocessor switch `#if (EEP_30_XXI2C01_VERSION_INFO_API == STD_ON)` to the API service declaration.

ESCAN00101035 Misra warning: "0612 - size of object exceeds 32767 bytes"	
Component@Subcomponent:	Ccl_Asr4SmCan@GenTool_GeneratorMsr
First affected version:	5.00.00
Fixed in versions:	5.00.01
Problem Description:	
What happens (symptoms):	

Big var structs and var arrays whose size exceed 32767 bytes generate the Misra warning "0612: size of object exceeds 32767 bytes"	
When does this happen:	

The warning is issued during the misra analysis.	
In which configuration does this happen:	

Any configuration with var structs and var arrays bigger than 32767 bytes.	
Resolution Description:	
Workaround:	

No workaround available.	
Resolution:	

The described issue is corrected by update the used CommonAsr_ComStackLib.	

3. New Issues for Information

Issues which should not have an effect on the usage of the license as the issues are relevant for use cases other than those defined in the questionnaire. The list contains issues that have been detected since the last report.

Issues listed in this section are not relevant for the use case that has been documented in the questionnaire provided to Vector. However, the issues may be relevant for other use cases. Also issues that have been accepted or are tolerated by the OEM (as defined in the questionnaire) are reported here.

No issue to be reported.

4. Report Legend

Issue Report	
Report Creation Date 2011-02-25	
Index	The ID number identifies the Issue
ESCAN0002257 Headline describes symptoms and consequences of the Issue in one sentence DrvCan baseAsr@GenTool_GeneratorGeny	
ESCAN0002257 Headline describes symptoms and consequences of the Issue in one sentence	
Component@Subcomponent: First affected version: Version fixed: Problem Description: What happens (symptoms):	Component@Subcomponent describes the group of workproducts which are composed of the source code, project documentation, User Manual and Generation Tool. The Subcomponent describes the certain affected work-product in which part of the Component the issue appears. e.g. inside of the source code (e.g. Implementation) or inside of the User Manual (e.g. Documentation) or inside of the concerning Generation Tool code.
// to be removed: Describe FROM CUSTOMERS NON TECHNICAL POINT OF VIEW, - which symptoms one will get if this issue occurs? - How can the issue be seen? - if it cannot be seen, how can the customer detect it? - what happens AFTER the issue occurred? - What is the consequence, the implication? Consider the following questions: If the issue is TEMPORARY: Does the issue cause the malfunction once but after that ECU continues to work and probably works correctly? In which situation (ECU reset / wakeup) does the ECU recover? If the issue is PERMANENT: ECU is blocked until Watch-Dog reset. ECU blocked forever and Watch-Dog cannot help. When does this happen: // to be removed: Describe FROM CUSTOMERS NON TECHNICAL POINT OF VIEW, which circumstances, operational situations, API function calls lead to the issue. With this information the customer wants to find out, whether he is affected by this issue or not. Consider the following questions: When (during runtime) does the issue occur and how can the customer find the issue? (1) Always and immediately (2) Only under specific circumstances (describe them) (3) Rarely, very rarely or unlikely Can the probability of occurrence of the issue be estimated? In which configuration does this happen: // to be removed: Describe FROM CUSTOMERS POINT OF VIEW, which configurations of e.g. GenTool, database (attributes), OEM, compiler, components, ... lead to the issue. Resolution Description: Workaround: No workaround available. // to be removed: If there is a workaround available, please replace the default text. Describe FROM CUSTOMERS POINT OF VIEW, what has to be done to avoid this issue. Resolution: The described issue is corrected by modification of all affected workproducts. // to be removed: technical resolution: e.g. error is resolved in file "xyz" function "opq"	The First affected Version describes in which version of the Component the Issue appears first and the Version fixed describes the corrected version of the Component in which the Issue does not appear anymore. The Problem description expresses the Issue content, eventually impact, etc. What happens: Symptoms, consequences and/or the detection way is described. When does it happen: Ignition, trigger point of the Issue In which configuration does this happen: Dependencies to a certain functionality or another component The Resolution description describes a workaround, if available and the resolution of the Issue.

5. 3rd Party Software Issues

This issue report does not include issues of 3rd party software. If 3rd party software was included in the SIP, the documentation of the issue reporting process is included in the SIP: .\Doc\DeliveryInformation\IssueHandling_<Name>.pdf. Please follow the given instructions.

6. Quality Management Contact

Quality Management
Productline Embedded Software (PES)

Vector Informatik GmbH
Ingersheimer Str. 24
D-70499 Stuttgart

Phone: +49 711 80670-3700
Fax: +49 711 80670-399
eMail: QualityPES@vector.com