Official Incident Report

Initial Incident Details			
Incident Raised By:	PCCW Global	Incident Received By:	Tola MOCH
Reported Date:	12-Sep-2026	Service Disruption:	MX1052, MX1054

Detailed Incident Information			
Incident date:	12-Sep-2026	**Report Time:**	06:39 UTC+7
Incident Number:	TCT#1966505	**Incident Category:**	SLA
Customers Impacted:	PCCW Global	**Duration of Interruption:**	05hrs 01mins

Incident Number	Report Time	Restored Time	Duration
#TCT:1966505	12-Sep-2026 06:39 UTC+7	12-Sep-2026 11:40 UTC+7	05hrs 01mins

Root Cause Analysis – Chronology of Events

Details of Incident

Incident Number:	TCT#1966505
Date and Time:	12th Sep 2026 (Cambodia local time, UTC+7)
Time of Complaint:	12th-Sep-2026 06:39 UTC+7
Issue Reported:	PCCW reported a connection issue with CID: MX1052, MX1054, which was identified as down.

Actions Taken: Acknowledgment, Investigation, Resolution & Root Cause Analysis

Date and Time: 12-Sep-2026

05:39: TELCOTECH detected link down at border CAM/VN affecting terrestrial IPLC link to Hong Kong
05:47: TELCOTECH had arranged FE to proceed to site for investigation
06:39: TELCOTECH received complaint from PCCW regarding service outage on MX1052, MX1054
06:42: TELCOTECH acknowledged complaint and initiated investigation
06:55: TELCOTECH observe circuits went down related a terrestrial IPLC link to Hong Kong
07:30: Our FE has arrived at fault location and submitted work request to TRC (Telecommunication Regulator of Cambodia)
08:20: TRC work approval obtained; our FE started laying the fiber optical cable
10:00: Due to multiple 24cores fiber optic affected from this incident, operation work took some time to complete
11:40: TELCOTECH has been fixing the issue
11:49: TELCOTECH requested PCCW verification of circuit status
12:04: PCCW confirm circuits restore

Fault Analysis & Resolution	
1st Cause of Outage:	Partner submarine maintenance to repair a shunt fault (IA Cable) – TCT#1959739
1st Fault GPS Location:	IA perform emergency maintenance related to the IA Cable Repair – SVW (Singapore)
1st Issued Time (GMT+7):	06th-Sep-2026 06:59 UTC+7
1st Resolution:	In progress (ETR: 26th Sep 2026)

Fault Analysis & Resolution	
2nd Cause of Outage:	The fiber optic cable was damaged due to an electrical explosion.
2nd Fault GPS Location:	Svay Rieng Province, Cambodia. (11.071607, 106.158259)
2nd Issued Time (GMT+7):	12th-Sep-2026 06:39 UTC+7
2nd Resolution:	Laid new fiber optic cable and re-spliced to restore the service.
2nd Permanent Fixed	Yes

Improvement and preventive plan
TELCOTECH will take the following actions:
1.Enhance customer communication during incidents through proactive and timely status updates at regular intervals.
2.Strengthen coordination and escalation with relevant network partners during emergency maintenance activities
3.Review the affected terrestrial route to identify opportunities to improve physical route resilience

Picture Reference



