

Table 4. When Replacing Camshaft Cover

Original Camshaft Cover Part No.	Model	Superseded Kit Part No.	Notes
25701104	RA1250/S	25701660	Order gaskets separately.
25701110	RH1250S	25701659	Order gaskets separately.
25701104	RH975/S	25701662	Order gaskets separately.

When replacing engine assembly complete powertrain:

- Order appropriate engine assembly complete powertrain part number.
- Install engine harness connector kit (Part No. 25701669) supplied with powertrain.

Required Dealer Action

To determine if a 2021-2023 Revolution® Max vehicle needs to be updated with the VVT Service Kit while performing a qualifying repair, identify what VVT connector is present on the engine harness:

- If it has one black 4 pin connector (Part No. 69203272), it has been updated.
- If it has two separate 2 pin connectors, one white (PN 69202627) and one black, (Part No. 69202037), it needs to be updated when performing qualifying repairs.

Table 5.

Action Required	Resolution
NO ☐	Actionable: Any vehicle, component or software related issues must be performed according to the service bulletin procedure.
YES ☒	

When installing replacement engines, engine harnesses, camshaft covers, or VVT harnesses on a 2021-2023 Revolution® Max powered vehicle, refer to Affected Part Numbers for ordering the correct kit.

Refer to Instruction sheet 94100540.

Return Parts

Hold all claimed parts for 60 days from date of credit issued for possible field inspection and/or request to return to factory. After 60 days, destroy and discard the parts.