

SERVICE BULLETIN

M1634

2024-03-21



M1634 (REV A): SWITCHBACK SEAT FOR NIGHTSTER

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2024-03-21	A	Update Claim Type.
		* Updated: Credit Procedure
2024-03-08	-	Initial release

Purpose for Service Bulletin

To inform dealers of a seat support cable issue with the initial shipment of Switchback Seats (Part No. 52000655) that will require a replacement with Seat Support Cable (Part No. 52100087).

In the initial shipment of Nightster Switchback Seats, the seat support cable used to limit the seat opening while accessing the fuel tank was installed to the seat in the incorrect location. Compared to the stock seat, this creates a reduction in available space to access the fuel tank.

Vehicles Affected

2022 and later: Nightster/S (RH975/S)

Markets Affected

All markets affected.

Part Numbers

Refer to Table 2.

Table 2. Seat Support Cable Replacement Part Number

Seat Part No.	Item Description	Cable Replacement Part No.
52000655	Switchback Seat	52100087

Required Dealer Action

Table 3.

Action Required	Resolution
NO ☐	Actionable: Any vehicle, component or software related issues must be performed according to the service bulletin procedure.
YES ☒	

1. Remove seat.

2. Follow instructions in kit.

3. Install seat. After installing the seat pull up on the seat to verify that it is secure.

Dealer Inventory Instructions

Dealers with current inventory of the Nightster Switchback Seat, purchase Seat Support Cable (Part No. 52100087) to replace the seat support cable that is currently installed.

Credit Procedure

NOTE

Enter bulletin number M1634 into Events Comments.

Submit a warranty claim per Table 4. **Do Not** include a Vehicle Identification Number (VIN) in the claim

Table 4. Seat Support Cable Kit Credit Table

ITEM	DATA
Claim Type	DFS/PAM claim – stock/PAM claim – sold
Problem Part Number	52000655
Quantity	Leave Blank
Primary Labor Code	Leave Blank
Replacement Part Number	52100087
Quantity	1
Detail Labor Code	8888
Labor Time	0.1 hours
Customer Concern Code	6812
Condition Code	1506

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

[illegible]