

Table 3. Software Version BCM Calibration Version

Current	Update
16.4.44.2	16.4.45.2

Verify that the most up-to-date software (25.3.4 or newer) is installed. Check software version using DT II.

DIGITAL TECHNICIAN II (PART NUMBER: HD-48650)

BCM Reflash Sequence

1. Connect battery tender to vehicle.
 - a. Verify battery is fully charged before proceeding.
 - b. Connect tender using supplied tender connection on the vehicle.
2. Connect Techlink 3 to vehicle.
3. Connect external power to Techlink 3 using appropriate power supply providing at least:
 - a. 12 V
 - b. 1.2 A
4. Place vehicle in Accessory mode.
 - a. Press and hold trip button for 5 seconds.
5. Open DT II program and establish communication with vehicle.
6. Proceed to reflash BCM and follow on-screen directions.

Vehicles Affected

2025: Pan America S (RA1250S), CVO Pan America (RA1250SE)

Markets Affected

All markets affected.

Part Numbers

Refer to Table 4.

Table 4. Affected Part Numbers

Old Part No.	Item Description	Notes
41001664	MODULE, BODY CONT, 2GI, 3-AXIS, 434 MHZ	Rest of world
41001655	MODULE, BODY CONT, 2GI, 3-AXIS, 315 MHZ	Japan only

Credit Procedure

NOTE

Enter bulletin number M1682 into Event Comments section of claim.

Submit a warranty claim per Table 5.

Table 5. Pan America BCM Update

ITEM	DATA
Claim Type	PRD/MC/DEM - PDI/Standard claim
Problem Part Number	41001664 or 41001665 (Japan only)
Quantity	Leave Blank
Primary Labor Code ⁽¹⁾	1762
Labor Time	0.2 hours
Customer Concern Code	9203
Condition Code	1762
<i>(1) Download may be required</i>	