

MANGALORE REFINERY AND PETROCHEMICALS LIMITED (MRPL)
EQUIPMENT MAINTENANCE REPORT & SIGN-OFF

DOCUMENT REF	MRPL/MAINT/2026/09-441	DATE	23-09-2026
UNIT LOCATION	Phase-II Crude Distillation Unit (CDU-2)	EQUIPMENT TAG	210-P-104B
EQUIPMENT	Desalter Feed Pump		

1. PARAMETER READINGS (PRE-INSPECTION)

Parameter	Reading	Reference / Status
Suction Pressure	3.2 bar	—
Discharge Pressure	28.5 bar	Normal: 32.0 bar — BELOW TARGET
Bearing Temperature	78 °C	Warning Limit: 75 °C
Vibration Level	6.8 mm/s	ISO Class II — Unsatisfactory

2. FIELD INSPECTION NOTES (HANDWRITTEN BY ENGINEER)

“Severe mechanical seal flushing line blockage observed causing dry running and temperature spike on NDE bearing. Impeller clearance opened up by 1.2 mm due to abrasive wear from crude solids.”

3. RECOMMENDED CORRECTIVE ACTIONS

Status	Corrective Action
■	Immediate flushing line clearance & seal replacement
■	Impeller re-alignment and wear ring adjustment
■	Complete pump casing replacement

ESTIMATED DOWN-TIME	14 Hours
ESTIMATED REPAIR COST	■3,25,000 INR
INSPECTING ENGINEER	K. V. Rao (Emp ID: 40182)
STATUS	Pending Senior Maintenance Manager Approval

Inspecting Engineer

Senior Maintenance Manager

K. V. Rao

Emp ID: 40182

Approval / Sign-off