



FLEET TEAM DIGEST¹

737MAX-FTD-31-23004²

Issue Title : Takeoff Alert Inhibit Option³

Airplane Model	ATA	Minor Model(s)
737MAX	3165-00	-7,-8,-9,-8200,

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
06/14/2023	08/22/2023	08/18/2023

Estimated Completion Date	Next Update Date
02/19/2024	11/14/2023

Revision Description⁵

Updated Optional Service Bulletin ECD.⁶

Applicability⁷

All 737MAX Airplanes.⁸

Description⁹

Boeing has determined that there is an issue with Option Selection Software (OSS) parameter OSS_TO_ALERT_INH_800FT.¹⁰

Background¹¹

The Takeoff Alert Inhibit is designed to inhibit the blinking for Engine Alert Messages as described in the Flight Crew Operations Manual (FCOM) Chapter 7 (Engines, APU), Section 10 (Controls and Indicators: Crew Alerts). The Inhibit feature is designed to minimize pilot distractions from 80 knots (kts) up to 400 feet (ft) Radio Altitude (RA) by disabling the OSS parameter above and inhibiting blinking up to 400 ft RA. However, it was determined that the parameter was inverted such that the Inhibit is enabled through 800 ft RA.¹²

Note:¹³

Disclaimer: This document contains **BOEING PROPRIETARY** information, Encrypted emails required for forwarding via Email. Document Generated on 09/20/2023 by Fleet Team Digest, this document is only for reference purpose, visit the application for all latest and updated revisions of this digest article.



FLEET TEAM DIGEST¹

- The Engine Alert Messages will still annunciate and parent aircraft requirements are still met; requirements do not specify either blinking or inhibiting behavior of crew alerting. ²

- This issue was determined not a safety issue. ³

Status ⁴

Boeing will publish a Flight Crew Operations Manual Bulletin (OMB) to reflect the current differences between design and actual behavior. ⁵

Applicable FCOM Volume 2 (V2) systems descriptions are also being amended to reflect these changes targeting a November 23 release. ⁶

The final fix will be available as part of the next MAX Display System (MDS) BlockPoint (BP) release, MDS BP 2. ⁷

Please see 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2 and a list Fleet Team Digest (FTD) articles that are also addressed by the MDS BP 2 release. ⁸

Interim Action ⁹

Boeing has identified two interim courses of action: ¹⁰

(1) Operators may continue to fly with the OSS parameter inversion of 800 ft RA. ¹¹

If this course of action is chosen, operators should consider proactively communicating with flight crew that blinking of engine alerts will be inhibited at a different range (up to 800 ft RA instead of up to 400 ft RA) than as described in FCOM Chapter 7.10. ¹²

Be aware that the OSS parameter OSS_TO_ALERT_INH_800FT is designed for affected aircraft to inhibit during takeoff from 80 Knots Indicated Airspeed (KIAS) to 400 ft RA as described in the FCOM, or 30 seconds after reaching 80 kts, whichever occurs first; however, the inhibit is currently active up to 800 ft RA, or 30 seconds after reaching 80 kts. ¹³

Disclaimer: This document contains **BOEING PROPRIETARY** information, Encrypted emails required for forwarding via Email. Document Generated on 09/20/2023 by Fleet Team Digest, this document is only for reference purpose, visit the application for all latest and updated revisions of this digest article.



FLEET TEAM DIGEST¹

(2) An optional Boeing Service Bulletin (SB 737-31-2108) will be available for in-service airplanes flying with MDS OPS (Operational Program Software) SW BP 1.5.1 to revert to the intended 400 ft RA inhibit configuration until the release of MDS BP 2.²

When available, please submit a Service Request via My Boeing Fleet or contact your Field Service Representative and reference PRR 3M9900-100R and/or SB 737-31-2108.³

Final Action⁴

When available, incorporate Max Displays System (MDS) BlockPoint (BP) 2 Release, MDS BP 2. This will revert the behavior to the intended 400 ft RA inhibit.⁵

Please see 737MAX-FTD-31-23002 for current status and release schedule of MDS BP2.⁶

Milestones⁷

Note: Target dates are based upon currently available status and are subject to change.⁸

Root Cause Established: Completed⁹

Solution Selected: Completed

Change Committed: PRR3M9900-100R

Production Incorporation: See 737MAX-FTD-31-23002

Optional Service Bulletin 737-31-2108 Available: ECD DEC-2023

MDS BP2 Service Bulletin 737-31-1929 Available: See 737MAX-FTD-31-23002

Related Categories¹⁰

- Flight Deck Effects and Maintenance Messages - Issue that occurs frequently and causes a flight deck effect or maintenance message¹¹
- Flight Operations - Flight Operations

Disclaimer: This document contains **BOEING PROPRIETARY** information, Encrypted emails required for forwarding via Email. Document Generated on 09/20/2023 by Fleet Team Digest, this document is only for reference purpose, visit the application for all latest and updated revisions of this digest article.