

PROPERTY DAMAGE EVIDENCE FILE

Physical Ledger, Incident Metrics & Photographic Verification Log

CASE REF: EV-2025-1118

Claim Number	CL-2025-1118-892	Policy Number	GL-334981-2025
Date & Time	11/18/2025 @ 02:45 PM CST	Incident Location	Main Server Data Core (FI 5), 1001 McKinney St, Houston TX
Responsible Party	Apex Mechanical & Plumbing Solutions LLC	Damaged Party	Sovereign Data Hosting Infrastructure Inc

1. Quantitative Incident Metrics & Cause of Loss

Forensic reconstruction of physical parameters governing the loss event. Data verified by Chief Building Engineering and Houston Fire Department extraction teams.

Source Mechanism	Pressurized structural main chilled-water supply pipeline (Floor 6 overhead installation zone).
Pipe Specifications	4-inch diameter heavy-gauge commercial copper conduit.
Hydrostatic Pressure	Continuous structural operation at 90 PSI (Pounds per Square Inch).
Flow Duration	Uncontained active escape for exactly 38 minutes prior to regional municipal valve isolation.
Estimated Effluent Volume	Approximately 3,420 US Gallons of chemically treated chilled water migrated vertically.
Failure Diagnostics	Accidental direct contact with high-temperature welding torches during line modification, causing structural thinning and catastrophic burst under pressure.

2. Physical Evidence Inventory Manifest

ITEM ID	DESCRIPTION OF PHYSICAL EVIDENCE	RECOVERY LOCATION	DAMAGE STATUS
EV-01	Ruptured 4-inch copper main pipeline segment. Exhibits extensive structural tearing, thermal deformation from welding apparatus, and jagged pressure fracture lines.	Floor 6 Plumber Overhead Welding Rig Zone	DESTROYED / CORE
EV-02	14 Enterprise Server Rack Cabinets (Serial arrays SDH-R01 to SDH-R14). Deep structural water logging, internal circuit shorting, mineral salt residual tracing.	Floor 5 Server Data Core Facility	CATASTROPHIC SHORT

4. Photographic Evidence Catalog

Visual references verified by forensic investigators on-site on 11/18/2025 and 11/19/2025.



EXHIBIT A: FAILURE ORIGIN

Exhibit A: Ruptured Supply Main (Floor 6)

Photographic detail showing the physical breach point on the 4-inch chilled-water line. Clearly demonstrates torch scorch markings and structural wall shearing under 90 PSI load.



EXHIBIT B: ENVELOPE COLLAPSE

Exhibit B: Ceiling Envelope Breach (Floor 5)

Wide-angle view of the structural main server room core ceiling grid. Heavy water saturations caused complete disintegration of acoustic panels, collapsing directly over structural server arrays.



EXHIBIT C: RACK FLOODING

Exhibit C: Server Rack Intrusion & Shorts

Detailed view of server rack enclosure No. 4 (SDH-R04) showing continuous internal vertical water flows, severe internal computational node arcing, and complete burn-out of switching motherboards.



EXHIBIT D: SUB-FLOOR ACCUMULATION

Exhibit D: Standing Sub-Floor Water Level

Inspection photograph of the raised floor plenum area showing approximately 2.5 inches of continuous standing effluent, shorting out all sub-floor primary electrical links and fiber trunks.