

# Incident Report INC002 — 2026-06-22, 13:10:00

Equipment: CMP-02 (EQ002)

Alarm Triggered: Pad Pressure Low (CMP205), Medium severity

Downtime: 18 minutes | Affected Lot: LOT1056

Repeat Occurrence: Yes (including the current incident, there have been 2 occurrences of this alarm on this equipment within the last 30 days).

## Escalation List

- **Manufacturing Supervisor (Emily Ng, ENG005, emily.ng@example.com):** Triggered by rule R005 (affected\_lot is not null).

## Root Cause Analysis

The likely root cause is a recurring hydraulic leak or a faulty pressure sensor. Sensor readings show a sharp decline in pressure from 1.049 to 0.76 between 13:00 and 13:10, which corresponds to the alarm trigger. Historical data reveals this is a chronic issue for EQ002, with five similar incidents (H082, H085, H061, H053, H088) citing hydraulic leaks and worn pressure sensors as the primary causes. Furthermore, recent calibration maintenance (PM045) on 2026-06-15 remains "Open," suggesting the tool was not fully stabilized after the last part replacement.

## Supporting Evidence

- **Sensor Readings:** Pressure dropped from 1.049 at 13:00 to 0.76 at 13:10 (INC002).
- **Past Incidents:** 5 previous occurrences of CMP205 on EQ002, most recently H082 (2026-05-27) caused by a hydraulic leak.
- **Maintenance History:** Calibration (PM045) performed on 2026-06-15 is still marked as "Open" status following a part replacement.
- **SOP (SOP004):** Points to pressure sensor failure, hydraulic line leaks, and pad wear as the primary troubleshooting targets.

## Recommended Actions

Based on SOP004:

1. **Inspect hydraulic lines** for any visible leaks or fluid level drops.

2. **Verify pressure sensor** stability and accuracy; replace the sensor if readings continue to fluctuate or fail to return to baseline.
3. **Check pad condition** to ensure no mechanical wear is contributing to pressure loss.
4. **Close out PM045** after verifying the tool's post-calibration stability.