

Service Report: 1011**Date:** July 25, 2026**Hospital / Client:** Al Tamayuz Physiotherapy Center**Device:** Longest Shockwave (LGT-2500x)**Serial Number:** EN2500X002300260**Installation Date:** July 21, 2024**Department:** Physiotherapy Dept**Issue Reported:**

Device delivering weak shockwave impact/pulse output; energy output significantly below normal, with intermittent loss of pulse during treatment (cuts out periodically).

Findings Upon Inspection:

Device found with excessive buildup of old, dried coupling gel on the applicator/transmitter area, affecting acoustic coupling and energy transmission. Applicator O-rings found worn and in need of replacement, which was contributing to inconsistent pressure/seal and the weak, intermittent shockwave output.

Action Taken:

Cleaned the applicator/transmitter area, removing all old dried gel residue.
Replaced the worn O-rings and the bullet ,Cleaned the handpiece kit.

Important Note:

Advised staff to clean the applicator/handpiece after each patient use to maintain proper hygiene and prevent gel buildup, ensuring consistent device performance.

Status:

- Resolved

Recommendation

Recommend replacement of the transmitter/applicator kit, as the pulse count has exceeded 4 million shots (beyond the manufacturer's rated service life), which may affect performance consistency going forward.

Customer Sign	Hospital B.M.E.	Orthoserv Biomedical
		Mahmoud Ghasan

© 2026 OrthoServ