

APPENDIX A – TROUBLESHOOTING

FastBack® Model 260E-G2 Technical Manual

Appendix A Troubleshooting

Use Table A-1 to help solve problems you experience with the FastBack® Model 260E-G2. If following these steps does not correct the problem, call the Heat and Control, Inc. Service Office in Lititz, PA, at (717) 519-5240 or (800) 648-5313. Have the serial number of your FastBack® available when you call. The serial number is printed on the equipment name plate (see page x).

Symptom	Possible Cause	Corrective Action
Conveyor does not run – motor does not turn	Emergency disconnect switch set to OFF position	Rotate emergency disconnect switch to ON position.
	Control wires not connected to correct terminals on inverter in the power module	<u>Yaskawa V1000</u> : Connect common signal wire to terminal SC and return wire to terminal S1. See TechPub PH009 for inverter wiring diagrams.
	No run command from control source	Troubleshoot PLC output or relay logic
Conveyor does not run – motor turns	Broken motor belt	Install new motor drive belt (see Section 5 – Maintenance)
	Broken eccentric timing belt	Replace eccentric timing belt (see Section 5 – Maintenance)
	Motor belt detached from motor sprocket	Reinstall motor drive belt (see Section 5 – Maintenance)
Pan shakes excessively	Improper tensioning of pan fasteners	Check pan installation (see Section 4 – Installation Procedures)
	Improperly installed pan	Check pan installation (see Section 4 – Installation Procedures)
	Drive arm and Remote Idler arm are not synchronized.	Adjust base of remote idler arm to ensure that it is synchronized with the drive arm
Drive unit shakes excessively	Loose locknuts on articulating feet	Tighten locknuts
	Threaded rods on articulating feet extend past 3 inches	Adjust threaded rods so that no more than 3 inches show
	Interference between pan and surrounding equipment	Adjust equipment position to remove interference
Conveyor runs rough	Misadjusted timing belt	Reinstall timing belt (see Section 5 – Maintenance)
	Motor belt jumping	Install new motor belt (see Section 5 – Maintenance)

APPENDIX A – TROUBLESHOOTING

FastBack® Model 260E-G2 Technical Manual

Symptom	Possible Cause	Corrective Action
Motor pulls excessively high current	Imbalanced motor load – resistance between motor phases (not within 5% of each other)	Rewire motor in motor junction box
		Replace motor
	One phase of the power input is not making full contact	Check that all phases of the input power is electrically secure
Conveyor runs at incorrect speed	VFD not programmed for correct speed	Check VFD parameters and reprogram if necessary
Conveyor not responding proportionately to 4-20mA signal from weigher or other source	VFD programmed incorrectly	Check VFD parameters and reprogram if necessary. See TechPub PH009 (Yaskawa) or TechPub PH015 (A-B)
Conveyor starting and stopping frequently (running between 1/3 and 2/3 of the time)	Infeed photoeye, which controls conveyor ON/OFF, is calibrated for too high a bed depth	Reduce sensing distance on photoeye by 20-50% and re-evaluate
Conveyor running 100% of the time, but weigher is starving	Infeed photoeye, which controls conveyor ON/OFF, is calibrated for too low a bed depth	Increase sensing distance on photoeye or check the gate feeding the conveyor
Product spilling on floor at pan infeed	Infeed photoeye calibrated for too high a bed depth	Reduce maximum sensing distance on photoeye.
	Photoeye “Covered Timer” value set too high	Reduce the “Covered Timer” value within the Engineering Screens for a faster response
	Pan misaligned with distribution feed point	Adjust pan (see “Final Positioning” in Section 4 – Installation Procedures)
Conveyor travel rate too low/bed depth too high	Motor running in wrong direction	Swap any two motor leads in motor junction box or at the inverter
	Conveyor inclined excessively	Reduce incline to under 1.5°
	Wrong preset speed selected	Check and correct signal wiring or jumper connections
	Incorrectly set speed reference	See TechPub PH009 (Yaskawa) or TechPub PH015 (A-B)
Product moves the opposite direction from that desired	Incorrectly installed eccentric drive sprocket on new crankshaft	Remove key under crankshaft sprocket bushing and reinstall 180° out (see Section 5 – Maintenance)
	Drive installed backwards	Re-position the drive 180 degrees

Table A-1 – Troubleshooting Guide