

6 TROUBLESHOOTING

6.1 Error Message Handling

When an error occurs, the message will appear on the display screen of the RCU.

1. Press the [EXIT] key.
2. Carry out the countermeasure recommended below.
3. Press the [START] key to restart operation.

NOTE

- The "No." in the table means the error number.

Table 6-1 Error Displays

No.	Error Indication	Cause	Measures
1	Emergency switch was pushed	Emergency switch was pushed.	Check the safety around the system and turn the emergency switch for resetting.
3	Seal checker door open	Seal checker cover was opened.	Check the safety around the system and close the seal checker cover.
5	Servo1 alarm detected	Checker servomotor is faulty or may fail.	Ask the distributor you purchased or our company for repairs.
8	Seal Checker ARC-NET error	Communication status error due to disconnection of communication line, poor contact, faulty board or noise.	Ask the distributor you purchased or our company for repairs.
9	Jam up at seal checker	Bags are jammed up at the photoelectric sensor and continuously shading the sensor. Optical axis of photoelectric sensor is out of position. Photoelectric sensor is faulty or sensor cable is broken.	Check the safety around the system and remove the jammed bags. Adjust the mounting position of photoelectric sensor. Ask the distributor you purchased or our company for repairs.
10	Jam up at Pre-Rejector		
11	Air pressure is low	Air is not supplied to specifications.	Supply normal air quantity.
22	Error stop by Leak bag	Air leak reject direction is set to STOP and air leak bag was detected.	Open the cover and remove the bag on the conveyor.
23	Error stop by Flat bag	Flat bag reject direction is set to STOP and flat bag was detected.	Open the cover and remove the bag on the conveyor.
24	Error stop by Thick bag	Thick bag reject direction is set to STOP and thick bag was detected.	Open the cover and remove the bag on the conveyor.
27	Error stop by Double bag	Double bag reject direction is set to STOP and double bag was detected.	Open the cover and remove the bag on the conveyor.
28	Error stop by Ext.1 N/G bag	Ext. 1 N/G bag reject direction is set to STOP and Ext.1 N/G bag was detected.	Open the cover and remove the bag on the conveyor.
29	Error stop by Ext.2 N/G bag	Ext. 2 N/G bag reject direction is set to STOP and Ext.2 N/G bag was detected.	Open the cover and remove the bag on the conveyor.

Table 6-1 Error Displays (Continued)

No.	Error Indication	Cause	Measures
31	Error stop by Continuous N/G	Continuous N/G reject direction is set to STOP and continuous N/G bag was detected.	Open the cover and remove the bag on the conveyor.
37	Seal Check conveyor overload	Driver for conveyor drive motor detected overload.	- If the gap between transfer belt and top plate of conveyor is stained, clean. - If timing belt and transfer belt tension is too strong, adjust it. This error also occurs if roller or bearing is damaged or motor cable is broken. If cleaning and adjustment do not still solve the problem, ask the distributor you purchased or our company for repairs.
38	Conditioner overload		
39	Infeed conveyor overload		
40	Bag stabilizer[F] overload		
41	J-Belt conveyor overload		
42	Reject conveyor overload		
43	Seal Check conveyor speed error	Conveyor speed is excessively slow.	- If the gap between transfer belt and top plate of conveyor is stained, clean. - If timing belt and transfer belt tension is too strong, adjust it. This error also occurs if roller or bearing is damaged or motor cable is broken. If cleaning and adjustment do not still solve the problem, ask the distributor you purchased or our company for repairs.
44	Conditioner speed error		
45	Infeed conveyor speed error		
46	Bag stabilizer[F] speed error		
47	J-Belt conveyor speed error		
48	Reject conveyor speed error		
49	Operation enable signal off	Error stopped due to operation enable signal OFF.	Set ON the operation enable signal.
50	Operation disable signal on	Error stopped due to operation disable signal ON.	Set OFF the operation disable signal.
51	Seal check task overflow	Because a long bag or bags were carried in the checker at too short intervals, simultaneous start maximum quantity for seal check task was exceeded.	Avoid carrying in of a long bag or bags at too short intervals.
52	Reject delay timer overflow	Reject delay timer setting was too great.	Decrease the reject delay timer setting.
53	Signal delay timer overflow	Output signal delay timer setting was too great.	Decrease the output signal delay timer setting.
54	Pre-Rej. Delay timer overflow	Pre-rejector delay timer setting was too great.	Decrease the pre-rejector delay timer setting.
55	Bag stabilizer[R] overload	Driver for conveyor drive motor detected overload.	- If the gap between transfer belt and top plate of conveyor is stained, clean. - If timing belt and transfer belt tension is too strong, adjust it. This error also occurs if roller or bearing is damaged or motor cable is broken. If cleaning and adjustment do not still solve the problem, ask the distributor you purchased or our company for repairs.

6.2 System Error / Failure

If the system shows an error without error indication, take corrective actions according to "Table 7-2 Error / Failure Table".

Table 6-2 Error / Failure Table

Status	Cause	Measures
When power switch is ON, Initial screen is not displayed on the display section.	Board in the remote control unit is faulty or poor wiring.	Ask the distributor you purchased or our company for repairs.
Initial screen is displayed on the display section, but cannot be switched to other screen.	Board in the main body is faulty or poor wiring.	Ask the distributor you purchased or our company for repairs.
Pre-rejector / N/G reject device works despite no product is running.	Optical axis of photoelectric sensor is out of position.	Adjust the position of photoelectric sensor mounting bracket.

6.3 Other Troubleshooting

Table 6-3 Troubleshooting

No.	Operation status	Phenomenon	Check item	Possible cause
1	In operation	Pre-Rejecter/Error-Rejecter operates though the bag is not fed.	Photo sensor LED lamp condition	Optical axis of the photo sensor is displaced.

6.4 TSC-RS-120 Troubleshooting (in operation)

Table 6-4 TSC-RS-120 Troubleshooting (in operation)

No.	Error Indication	Cause	Measures
1-1	Continuous bag rejection at pre-rejecter.	Photo-eye beam is blocked by object.	Remove all residual objects. Use air hose to blow or wipe it off with dust cloth. Check the frequency of rejection.
		Product infeed guide on J-Chute is adjusted too narrow. Creates product jam at guide and photo-eye sensor detect as "double bag error" by longer detect time.	Adjust the guides in 1/4" wider than horizontal seal of bags. Check the frequency of rejection.
		Product guide at brush roller unit is adjusted inward than J-chute product guide. Creates product jam.	Adjust the guides in 1/8" wider from J-chute guide. Narrow down the guides toward downstream. Guides at brush roller to after need to be adjusted in similar width as bag width and alongside to bag length. Check the product transfer from upstream guide to downstream guide. Readjust if bag jams when pass through guide to guide.
1-2	Continuous "good" bag rejection at pre-rejecter.	When bags dropped to J-chute in standing posture, photo-eye will miss detect when bags are dropped in to J-chute in standing posture. Photo-eye requires a certain length of time to sense the bag.	Clean the jaw face if bag flings out. Check the heater temperature. Adjust to proper temperature if any residue left on seal face by excessive heat. Check the condition of bag transfer.
		Photo-eye will sense as "double bag" when sensor is blocked over certain length of time. This will cause by improper guide adjustment, especially bags are not smoothly transfer from one to another.	Adjust the guide in proper width. Check the condition of bag transfer.
		Bag will flip toward front if J-chute's belt speed is faster than bag drop speed from Apex.	Adjust the J-chute's belt speed. Check the condition of bag transfer.
		Bag topples if infeed conveyor's belt speed is slower than J-chute's belt speed.	Adjust the J-chute's belt speed or infeed/conditioner's belt speed. Check the condition of bag transfer.
1-3	Continuous bag reject at error reject conveyor.	Photo-eye beam (at seal check head) is blocked by object.	Remove all residual objects. Use air hose to blow or wipe it off with dust cloth. Check the frequency of rejection.
		Have "flat" result because the Maximum Height is lower than the Standby Height.	Adjust the seal check head in proper height. Check the frequency of rejection.
		Zero is not properly adjusted because the product residue is accumulated underneath the seal check head.	Clean the seal check head area with air or dust cloth. Turn the power on and rezero it. Check the frequency of rejection.

Table 6-4 TSC-RS-120 Troubleshooting (in operation) (Continued)

No.	Error Indication	Cause	Measures
1-4	Bags orient in 90 degrees infrequently.	Rotates the bag orientation by residue objects on conveyor.	Remove all residual objects. Use air hose to blow or wipe it off with dust cloth. Check the status and the condition.
		Skews while the bags are passing through the brush roller because of narrowly adjusted product guide.	Adjust the guide in proper width. Adjust the guide width approx. 1/4" wider than bag width. Check the status and the condition.
		Not able to straighten the bag rotation because of the narrowly adjusted product guide.	Adjust the guide in proper width. Adjust the guide width approx. 1/4" wider than bag width. Check the status and the condition.
		Skews the less weighted bags by cooling fan.	Cover the blowhole of fan if bag has enough back seal strength. Check the status and the condition.
		Empty or less weighted bag is produced by product jam at bagger's former and stability of bag transfer is low.	Adjust the parameter on scale and bagger to avoid any product clog at bagger. Check the status and the condition.
1-5	Off track of conveyor belt.	Conveyor is not properly mounted.	Mount the conveyor properly. Check the belt tracking.
		Belt tracking is not properly adjusted.	Adjust the belt tracking. Check the belt tracking.
1-6	Rubber lees on timing belt cover.	Cover is scraping the belt. Cover is not mounted properly.	Insert the belt cover properly. Make sure the belt is not scraping the guard.
1-7	When turn the power on, emergency stop error occurs.	The emergency button was pushed.	Unlock the emergency button. Make sure that error message does not appear.
		The cover is open.	Close the cover. Make sure that error message does not appear.
		The emergency stop key is not set even though the cover is closed.	Set the emergency key correctly in place. Make sure that error message does not appear.
		SSC board (AS01 P-5530*) is not supplied with 34V.	Connect the harness to the switching power supply (UP02). If UP02 is not working because of a blown fuse, change the UP02. In this case, check whether it shorted out or not at the output port. Make sure that error message does not appear.

Table 6-4 TSC-RS-120 Troubleshooting (in operation) (Continued)

No.	Error Indication	Cause	Measures
1-8	Products are not down rejected.	Input signal (XJ731) is not connected when downstream machine is operated.	Connect the input signal correctly. Make sure that products are down rejected.
		The DipSW2-2 is OFF.	Turn DipSW2-2 on. Make sure that products are down rejected.
1-9	The products are down rejected even though DipSW2-2 is OFF.	It is set to AC-HORN interlock mode.	Machine Parameter> system comfit. Turn "Diverter Interlock" OFF. Make sure that products are down rejected.
		In the case of AC-HORN interlock specification, Box ready signal XT11-A4B4, A4B4are disconnected.	Connect them properly. Make sure that products are down rejected.
		In the case of AC-HORN interlock specification and preset to AC-HORN unused, AC-HORN interlock set value is left in.	Preset Parameter > Basic Setting > Crick on the General Setting Tab and set the "Divert Fill Bag" value to 0. Make sure that products are down rejected.

6.5 Error detect and checkup

Table 6-5 Error detect and checkup

No.	Error Indication	Cause	Measures
01	Emergency switch was pushed	The emergency switch was pushed.	Unlock the emergency switch.
		The harness to XJ756 and XJ740 contacts poorly or does not contact at all.	Connect the harness to the emergency switch correctly.
02	Emergency stop2 was detected	The harness to XJ756 and XJ740 contacts poorly or does not contact at all.	Connect the harness correctly.
03	Seal Checker door open	The seal checker cover was opened. The cover key is not properly set.	Close the seal checker cover. Set the key correctly.
		The harness to XJ757 and XJ742 contacts poorly or does not contact at all.	Connect the harness to the cover door switch correctly.
04	Bag stabilizer is pulled out	The bag stabilizer has been pulled out.	Put the bag stabilizer back in position.
		The harness to XJ757 and XJ743 contacts poorly or does not contact at all.	Connect the harness to the stabilizer unit correctly. Check the joint point of the up conveyor.
05	Servo1 alarm detected	The harness to XJ711 and XJ713 contacts poorly or does not contact at all.	Connect harness correctly.
		The servo driver connector contacts poorly.	Connect harness correctly.

Table 6-5 Error detect and checkup (Continued)

No.	Error Indication	Cause	Measures
		The driver or the motor is damaged.	Change the driver or the motor.
		The servomotor detected overload in inspection head operation.	Reassemble the inspection head link correctly. Clean around the drive unit link.
06	Servo2 alarm detected	Not in use for TSC-RS	Not in use for TSC-RS
07	Servo3 alarm detected	Not in use for TSC-RS	Not in use for TSC-RS
08	Seal Checker ARC-NET error	Not in use for TSC-RS	Not in use for TSC-RS
09	Jam up at Seal Checker	The line sensor at the intake is blocked.	Remove the pumper blocking the line sensor.
		The line sensor at the intake is chattering.	Attach the line sensor correctly.
		The harness to XJ744 contacts poorly or does not contact at all.	Connect the harness correctly. Check the joint connector to the sensor AS in the frame.
		The line sensor at the intake is damaged.	Change the line sensor.
10	Jam up at Pre-Rejector	Not in use for TSC-RS	Not in use for TSC-RS
11	Air pressure is low	1) The air pressure supply does not fulfill the specified air pressure value.	Supply air at the specified air pressure value.
		2) The regulator valve is closed.	Open the regulator valve.
		The harness to XJ730 contacts poorly.	Connect the harness correctly.
		The manometer setting is wrong.	Set the manometer correctly.
01-11 in common		The harness to XJ758 contacts poorly or does not contact at all.	Connect the harness correctly.
		The switching power supply UP02 is damaged.	Change the switching power supply.
12	Unknown error (12)	Not in use for TSC-RS	Not in use for TSC-RS
13	Unknown error (13)	Not in use for TSC-RS	Not in use for TSC-RS
14	Unknown error (14)	Not in use for TSC-RS	Not in use for TSC-RS
15	Unknown error (15)	Not in use for TSC-RS	Not in use for TSC-RS
16	Unknown error (16)	Not in use for TSC-RS	Not in use for TSC-RS
17	Unknown error (17)	Not in use for TSC-RS	Not in use for TSC-RS
18	Unknown error (18)	Not in use for TSC-RS	Not in use for TSC-RS
19	Unknown error (19)	Not in use for TSC-RS	Not in use for TSC-RS
20	Unknown error (20)	Not in use for TSC-RS	Not in use for TSC-RS
21	Error stop by Good bag	The good bag reject direction is set to "STOP" and a good bag was detected.	Change the setting to other than "STOP".
22	Error stop by Leak bag	The air leak bag reject direction is set to "STOP" and an air leak bag was detected.	Change the setting to other than "STOP".

Table 6-5 Error detect and checkup (Continued)

No.	Error Indication	Cause	Measures
23	Error stop by Flat bag	The flat bag reject direction is set to "STOP" and a flat bag was detected.	Change the setting to other than "STOP".
24	Error stop by Thick bag	The thick bag reject direction is set to "STOP" and a thick bag was detected.	Change the setting to other than "STOP".
25	Error stop by OK Flat bag	Not in use for TSC-RS	Not in use for TSC-RS
26	Error stop by OK Thick bag	Not in use for TSC-RS	Not in use for TSC-RS
27	Error stop by Double bag	Double bag reject direction is set to "STOP" and a double bag was detected.	Change the setting to other than "STOP".
28	Error stop by Ext.1 N/G bag	Ext.1 N/G bag reject direction is set to "STOP" and a Ext.1 N/G bag was detected.	Change the setting to other than "STOP".
29	Error stop by Ext.2 N/G bag	Ext.2 N/G bag reject direction is set to "STOP" and a Ext.2 N/G bag was detected.	Change the setting to other than "STOP".
30	Error stop by Metal bag	Not in use for TSC-RS	Not in use for TSC-RS
31	Error stop by Continuous N/G bag	Continuous N/G is set to other than '0' and continuous N/G bag reject direction is set to "STOP". A continuous N/G bag was detected.	Change the setting to '0'.
32	Error stop by Long bag	Not in use for TSC-RS	Not in use for TSC-RS
33	Error stop by Short bag	Not in use for TSC-RS	Not in use for TSC-RS
34	Error stop by Miss feed bag	Not in use for TSC-RS	Not in use for TSC-RS
35	Error stop by Down reject bag	The double bag reject direction is set to "STOP" and a double bag was detected.	Change the setting to other than "STOP".
36	Error stop by ??? bag	Not in use for TSC-RS	Not in use for TSC-RS
37	Seal check conveyor overload	The seal check conveyor drive motor detected overload.	Clean around the conveyor belt. Clean around the timing belt.
		1) The pumper such as bag is stuck between the seal check conveyor and the up conveyor or between the check conveyor and the reject conveyor.	Remove the pumper.
		The harness (connecting to connector CN2) from the DC motor driver AS11 to XJ746 contacts poorly.	Connect the harness correctly.
38	Conditioner overload	The brush drive motor detected overload.	
		1) The conditioner height is too low for the bag.	Adjust the conditioner height.
		The harness (connecting to connector CN2) from the DC motor driver AS13 to XJ747 contacts poorly.	Connect the harness correctly.
39	Infeed conveyor overload	The infeed conveyor drive motor (up conveyor) detected overload.	

Table 6-5 Error detect and checkup (Continued)

No.	Error Indication	Cause	Measures
		1) A pumper such as a bag is stuck between the J-belt chute and the infeed conveyor or between the infeed conveyor and the check conveyor.	Remove the pumper.
		The harness (connecting to connector CN2) from the DC motor driver AS12 to XJ748 contacts poorly.	Connect the harness correctly.
40	Bag stabilizer [F] overload	The bag stabilizer brush (the front side, the downstream side, TSC-R side) driving motor detected overload.	
		1) The gap between the bag stabilizer brushes is too narrow for the bag thickness.	Adjust the bag stabilizer brush width correctly. (Auto adjustment function "OPTION" set up : Set the width adjustment parameter correctly.)
		2) The infeed conveyor height is too low for the bag length.	Adjust the bag stabilizer brush width correctly. (Auto adjustment function "OPTION" set up : Set the bag length correctly.)
		The harness (connecting to connector CN2) from the DC motor driver AS14 to XJ749 contacts poorly.	Connect the harness correctly.
41	J-Belt conveyor overload	J-belt conveyor detected overload.	
		1) A pumper such as a bag is stuck between the J-belt conveyor and the infeed conveyor.	Remove the pumper.
		The harness (connecting to connector CN2) from the DC motor driver AS15 to XJ750 contacts poorly.	Connect the harness correctly.
42	Reject conveyor overload	The reject conveyor drive motor detected overload.	
		1) The pumper such as bag is stuck between the reject conveyor and the seal check conveyor.	Remove the pumper.
		2) The downstream machine of TSC contacts with the reject conveyor.	Move the machine contacting TSC-R.
		The harness (connecting to connector CN2) from the DC motor driver AS61 (or the driver in the reject conveyor unit) to XJ751 contacts poorly.	Connect the harness correctly.
43	Seal check conveyor speed error	Toggle switch SS11 is on. (it has been moved up.)	Turn it off.
44	Conditioner speed error	Toggle switch SS13 is on. (it has been moved up.)	Turn it off.
45	Infeed conveyor speed error	Toggle switch SS12 is on. (it has been moved up.)	Turn it off.

Table 6-5 Error detect and checkup (Continued)

No.	Error Indication	Cause	Measures
46	Bag stabilizer [F] speed error	Toggle switch SS14 is on. (it has been moved up.)	Turn it off.
47	J-Belt conveyor speed error	Toggle switch SS15 is on. (it has been moved up.)	Turn it off.
48	Reject conveyor speed error	Toggle switch SS61 is on. (it has been moved up.)	Turn it off.
37-48 in common		Toggle switch SS10 is on. (it has been moved up.)	Turn it off.
		The product etc. is stuck between the belts and conveyors.	Remove something stuck.
		The power supply harness (connecting to connector CN1) of the DC motor driver AS** (other than AS21) contacts poorly.	Connect the power supply harness of the drive correctly.
		The switching power supply UP3, UP4, UP5 is damaged.	Change the switching power supply.
		The harness (connecting to connector CN3) from the DC motor driver AS** to the motor contacts poorly.	Connect the harness correctly. Check if the joint connectors are connected correctly in the up conveyor, frame, J-belt unit, and stabilizer unit.
		The motor or driver is damaged.	Change the motor or driver.
49	Operation enable signal off	When it is associated with the downstream machine : the downstream has been stopped.	Put the downstream machine into operation.
		When it is not associated with the downstream machine : the open-circuit A1 and B1 of XT11	Short-circuit A1 and B1 of XT11.
50	Operation disable signal on	When it is associated with the downstream machine : the downstream has been stopped.	Put the downstream machine into operation.
		When it is associated with the downstream machine : A1 and B1 of XT11 are short-circuited.	Open-circuit A1 and B1 of XT11.
51	Seal check task overflow	Each delay time is set to the value run over the maximum delay time.	Conduct the auto calculation again by reset the product length. Basic Setting > Mode / Speed Setting tab > Checking time > Auto calculation Decrease each delay timer setting.
52	Reject delay timer overflow		
53	Signal delay timer overflow	The delay time runs over.	Decrease the delay time setting.
54	Pre-Re. delay time overflow	The delay time runs over.	Conduct the auto calculation again by reset the product length. PRESET > Advance Setting > Pre-Reject Auto Timing (Select ON) Reset product length. Decrease the delay timer pre-reject relating setting.

Table 6-5 Error detect and checkup (Continued)

No.	Error Indication	Cause	Measures
55	Bag stabilizer [R] overload	The bag stabilizer brush (the rear side, the upstream side, ATLAS side) driving motor detected overload.	Clean around the brushes. Clean around the timing belt.
		1) The gap between the bag stabilizer brushes is too narrow for the bag thickness.	Adjust the bag stabilizer brush width correctly. (Auto adjustment function "OPTION" equipped : Set the width adjustment parameter correctly.)
		2) The infeed conveyor height is too low for the bag length.	Adjust the bag stabilizer brush width correctly. (Auto adjustment function "OPTION" equipped : Set the bag length correctly.)
		The harness (connecting to connector CN2) from the DC motor driver AS21 to J714 contacts poorly.	Connect the harness correctly.
56	Bag stabilizer [R] speed error	Toggle switch SS21 is on. the level has been moved up).	Turn it off.
55-56 in common		Toggle switch SS10 is on. the level has been moved up).	Turn it off.
		The product etc. is stuck between the belts and conveyors.	Remove the stuck object.
		The power supply harness (connecting to connector CN1) of the DC motor driver AS21 contacts poorly.	Connect the power supply harness of the drive correctly.
		The switching power supply UP5 is damaged.	Change the switching power supply.
		The harness (connecting to connector CN3) from the DC motor driver AS21 to the motor contacts poorly.	Connect the harness correctly. Check if the joint connectors are connected correctly in the up conveyor, frame, J-belt unit, and stabilizer unit.
		The motor or driver is damaged.	Change the motor or driver.
57	Emergency switch was pushed	The harness to XJ756 and XJ757 contacts poorly or does not contact at all.	Connect the harness correctly.
		The harness to XJ758 contacts poorly.	Connect the harness correctly.
		The switching power supply UP02 is damaged.	Change the switching power supply.
58	Automated adjustment unit error	Error occurred in the automated adjustment unit.	Stop emergently and restart.
59	Downstream equipment stopped.	When it is associated with the downstream machine: the downstream has been stopped.	Turn the downstream machine into operation.
		When it is not associated with the downstream machine : DipSw2-2 is OFF and DipSW2-3 is ON. XJ731 is open-circuited.	Turn DipSw2-2 and DipSW2-3 OFF. Short-circuit XJ731.
60	Upper sensor detected.		

Table 6-5 Error detect and checkup (Continued)

No.	Error Indication	Cause	Measures
61	Lower sensor detected.		
62	Up motion error.		
63	Down motion error.		
60/62 in common		The limit sensor is not placed correctly.	Adjust the limit sensor position. Parameter of the limit sensor position : When the infeed conveyor height is set to minimum value, the limit sensor does not detect the infeed conveyor. The sensor detects the conveyor before the mechanical limit
61/63 in common		The limit sensor is not placed correctly.	Adjust the limit sensor position. Parameter of the limit sensor position : When the infeed conveyor height is set to maximum value, the limit sensor does not detect the infeed conveyor. The sensor detects the conveyor before the mechanical limit. After moving back to home position, the infeed conveyor moves to the height of the maximum value.
62-63 in common		The harness relating to motor power supply of the infeed conveyor height automated adjustment unit contacts poorly or is disconnected. (XC302 line) from the DC motor driver AS21 to J714 contacts poorly.	Connect the harness correctly.
		The harness relating to motor power supply of the intake conveyor height automated adjustment unit contacts poorly or is disconnected. (XC303 line) from the DC motor driver AS21 to J714 contacts poorly.	Connect the harness correctly.
60-63 in common		There is something at the limit sensor side of the infeed conveyor height automated adjustment driving unit or around the limit sensor.	Clean the drive unit. Clean around the limit sensor.
64	Narrow sensor detected.		
65	Wide sensor detected.		
66	Narrow motion error.		
67	Wide motion error.		
64-66 in common		The limit sensor is not placed correctly.	Adjust the sensor position. Parameter of the limit sensor position : When the stabilizer width is set to the minimum value, the limit sensor does not detect the infeed conveyor. The sensor detects the conveyor before the mechanical limit.

Table 6-5 Error detect and checkup (Continued)

No.	Error Indication	Cause	Measures
65/67 in common		The limit sensor is not placed correctly.	Adjust the sensor position. Parameter of the limit sensor position : When the stabilizer width is set to maximum value, the limit sensor does not detect the infeed conveyor. After moving back to home position, the stabilizer moves to the width of the maximum value.
66-67 in common		The harness (XC300 line) relating to motor power supply of the stabilizer width automated adjustment unit contacts poorly or is disconnected.	Connect the harness correctly.
		The harness (XC301 line) relating to the sensors for the stabilizer width automated adjustment unit contacts poorly or is disconnected.	Connect the harness correctly.
64-67 in common		There is something at the limit sensor side of the drive unit of automated adjustment unit, or around the limit sensor.	Clean the drive unit. Clean around the limit sensor.
60-67 in common		The rotation detect sensor for drive unit motor of the automated adjustment unit is chattering or in poor detect condition.	Adjust the rotation detect sensor position of each drive unit.
68	SEAL CHECKER ERROR (68)	Not in use for TSC-RS	Not in use for TSC-RS
69	SEAL CHECKER ERROR (69)	Not in use for TSC-RS	Not in use for TSC-RS
70	SEAL CHECKER ERROR (70)	Not in use for TSC-RS	Not in use for TSC-RS
101	ARC-NET connection error \\SEAL CHECKER	Not in use for TSC-RS	Not in use for TSC-RS
102	ARC-NET map send error \\SEAL CHECKER	Not in use for TSC-RS	Not in use for TSC-RS
103	TSC communication error	Communication harness contacts poorly. (SSC side J752 / DMU side XJ379)	Connect the harness correctly.
		The harness to the main power supply X701 contacts poorly.	Connect the harness correctly.
		The switching power supply UP01 is damaged.	Change the switching power supply.
104	MASTER ACCESS FAIL	CF is not inserted in DMU.	Turn off the main power supply. Insert the CF, and restart.
		Master has not created.	Switch to the screen of the copy and initialization, and save the master.
105	PRESET DATA NO SELECT	Not in use for TSC-RS	Not in use for TSC-RS

Table 6-5 Error detect and checkup (Continued)

No.	Error Indication	Cause	Measures
106	Set error	Setting error of the dynamic check mode. The check conveyor speed / the infeed conveyor speed is too fast. The product length is too long.	Switch the timing setting to manual and set to the proper value and change to the automatic setting. Or initialize only the preset and on they copy screen.
107	Set error	Setting error of the static check mode. The static time is too short. The pause filter time is too long.	
108	Height Compensation failed	The specified compensation block was unused.	Use the specified compensation block.
		The choice of the compensation (35mm / 42.5mm) block specification is wrong.	Switch to "Maint Srvc" level > Preset > Machine Parameter > System config. Set "Height compensation block thickness" to the compensation block height which has been using.
		The choice of TSC-RS specification (80 or 120) is wrong.	Turn off the main power supply. Change the dip switch (DPSW) 2-4 to ON (in case of TSC-R-120) or OFF (in case of TSC-R-080), and restart.
109	Jam up at Infeed Conveyor.	Products are stuck at the infeed conveyor and discharge to the check unit.	Clean the infeed conveyor. Adjust the brush conditioner height.
		"IFC jam detection count" setting is too small.	It is common to set the value more than five to use the infeed jam detect function. If you do not use the function, set the value to 0.
		"Infeed conveyor length" setting is too short.	Switch to "Maintenance level". Maintenance level > Setting > Preset > Machine set > Drive unit setting. Set the infeed conveyor height to 1550.
110	Memory Initialize failed	The DMU memory is out of order.	Reinitialize the memory. If the same error occurs, turn the dip switch (DPSW) 2-6 ON, and restart and initialize the memory again.
111	SEAL CHECKER ERROR (111)	Not in use for TSC-RS	Not in use for TSC-RS
112	SEAL CHECKER ERROR (112)	Not in use for TSC-RS	Not in use for TSC-RS
113	SEAL CHECKER ERROR (113)	Not in use for TSC-RS	Not in use for TSC-RS
114	SEAL CHECKER ERROR (114)	Not in use for TSC-RS	Not in use for TSC-RS
115	SEAL CHECKER ERROR (115)	Not in use for TSC-RS	Not in use for TSC-RS

INDEX

A

AC Servo Motor 2-18
AC Servo Motor Replacement 2-18
AC Servo Parameter 2-25
AC Servo Parameter Instruction Guide 2-19
Air pressure is low 6-1
APPENDIX 5-1
Automated adjustment unit 6-11

B

Bag Stabilizer Unit (Option) 2-6
Browser Setting 3-37

C

Communication Set Menu Screen 3-38
Conditioner speed error 6-2
Conditioner overload 6-2
CONFIGURATION OF THE SYSTEM 1-1
Configuration 1-2
Control Panel Items (Maintenance Service) 3-33
Control Unit 3-4
Conveyor Belt Tension Adjustment 2-27

D

DC Motor Replacement 2-3
DC Motors 2-3
Destination ID 3-37
Destination ID Menu Screen 3-37
Device Location 1-4
Display Control Menu Screens 3-33
DMU BOARD (P-5562*) 3-22
Drive Unit Setting screen 4-2

E

E-mail Setting 3-37
ELECTRICAL CONTROL UNIT 3-1
Emergency switch 2-16
Emergency switch was pushed 6-1
Error detect and checkup 6-6

Error Message Handling 6-1
Error stop by Continuous N/G 6-2
Error stop by Double bag 6-1
Error stop by Ext.1 N/G bag 6-1
Error stop by Ext.2 N/G bag 6-1
Error stop by Flat bag 6-1
Error stop by Leak bag 6-1
Error stop by Thick bag 6-1
Example of operational timing chart 2-8
EXPERT SETTINGS 4-1

I

Infeed conveyor overload 6-2
Infeed conveyor speed error 6-2
Installation Software Start up 5-1
Installing Program Newly 5-5
Installing the Program to Existing Model 5-4

J

J-Belt conveyor overload 6-2
J-Belt conveyor speed error 6-2
Jam up at Pre-Rejector 6-1
Jam up at seal checker 6-1

L

Language Select Setting 3-35
Locations of Electrical Devices 3-1
Lower test conv. speed error 6-2
Lower test conveyor overload 6-2

M

Machine Parameter screen 4-1
Memory Inti. & Copy Screen 4-10
Monitor Mode 2-21
Motor rotation direction setting 2-15
Motor Setting Screen 4-4

O

Operating conditions 2-7
Operating the motor 2-7
Operation (HBL Series DC Motor) 2-7
Operation disable signal on 6-2
Operation enable signal off 6-2
Other Troubleshooting 6-3

P

P-5500 3-29
Password Set/Language Select Set Menu Screen 3-35
Password Setting 3-36
PID Control Setting Screen 4-3
Position of each Sensor / Motor in Infeed Conveyor Height ADJ. Unit 2-1
Position of each Sensor / Motor in New Stabilizer Unit 2-6
Pre-Rej. Delay timer overflow 6-2
Program Installation Procedure from Web-RCU 5-1
Program Number Screen 4-10
Protection functions 2-8
Protective functions 2-23

R

RCU Software Backup 5-2
RCU Software Installation 5-4
Reject conveyor overload 6-2
Reject conveyor speed error 6-2
Reject delay timer overflow 6-2
REPLACEMENT AND ADJUSTMENT 2-1

S

Seal check Conveyor Sensor 2-2
Seal test task overflow 6-2
Seal tester door open 6-1
SEAL-TESTER arc-net error 6-1
Sensor Replacement 2-1
Servo1 alarm detected 6-1
Setting 3-39
Setting the running speed (AXH Series DC Motor) 2-11
Signal delay timer overflow 6-2
Specification 1-1
SSC CONTROL BOARD (P-5530*) 3-5

System Diagnosis screen 4-5
System Diagnosis screen 1 (GPIO) 4-6
System Diagnosis screen 3 (BL-MOTOR) 4-8
System Diagnosis screen 6 (OTHER) 4-9
System Error / Failure 6-3

T

Test method of seal check conveyor alignment 2-28
Timing Belt Tension Adjustment 2-26
Touch Panel Coordinate Adjustment 3-33
TROUBLESHOOTING 6-1
Troubleshooting 2-9
TSC-RS Troubleshooting (in operation) 6-4

U

Upper test conv. speed error 6-2
Upper test conveyor overload 6-2



ISHIDA CO.,LTD.

44 SANNO-CHO, SHOGOIN, SAKYO-KU,
KYOTO, 606-8392 JAPAN
PHONE: (075)771-4141
FACSIMILE: (075)751-1634
URL: <http://www.ishidajapan.com>