

STANDARD OPERATING PROCEDURE

SOP-INSP-014 Rev.4 - Testing and Certification of Pressure Relief Valves

Document No.: SOP-INSP-014**Revision:** 4**Effective Date:** 01 Jan 2024**Next Review:** 01 Jan 2027**Custodian:** Head - Inspection and Reliability**Classification:** Internal

1. Purpose

This procedure defines the requirements for the removal, bench testing, overhaul, certification and reinstatement of pressure relief valves in process service. It applies to all spring loaded and pilot operated relief valves installed within the refinery battery limits.

2. Responsibilities

Removal of a relief valve from service shall be authorised in writing by the Shift Manager, Operations, who shall confirm that the protected equipment is either depressurised or adequately protected by a second relieving device before the valve is removed.

The Inspection Engineer is responsible for the technical adequacy of the test, for review of the test record, and for issue of the certificate. The Workshop Supervisor is responsible for the physical conduct of the test.

3. Test Medium and Equipment

Dry nitrogen shall be used as the test medium for all bench testing of relief valves in gas or vapour service. Air shall not be used where the valve has been in hydrocarbon service. Water may be used only for valves in liquid service and only with the written agreement of the Inspection Engineer.

4. Acceptance Criteria

Set Pressure Range	Pop Test Tolerance	Blowdown	Seat Tightness
Up to 70 psig	plus or minus 2 psi	Max 7 percent	API 527
Above 70 psig	plus or minus 3 percent	Max 7 percent	API 527
Above 1000 psig	plus or minus 3 percent	Max 5 percent	API 527

The seat tightness test shall be carried out at 90 percent of the set pressure, held for a minimum of one minute, with leakage measured in accordance with API 527. A valve that fails the tightness test shall be dismantled and the seat lapped before retest.

5. Test Intervals

Service Category	Description	Maximum Interval	Basis
Clean	Non fouling, non corrosive vapour	60 months	Risk assessment 2021
Normal	General hydrocarbon service	36 months	Risk assessment 2021
Severe	Fouling, coking or corrosive	24 months	Risk assessment 2021
Critical	Fired equipment protection	12 months	Statutory

6. Valve Register - Debutaniser Section

Tag No.	Location	Set Pressure	Size	Last Tested	Next Due
PSV-2101	Debutaniser reflux drum D-2101	9.8 barg	2 x 3	12 Feb 2023	12 Feb 2026
PSV-2102	Debutaniser reboiler E-2105 shell	11.0 barg	1.5 x 2.5	03 Mar 2023	03 Mar 2026
PSV-2103	Debutaniser overhead line 6-P-2104	12.5 barg	3 x 4	22 May 2023	22 May 2026
PSV-2104	Debutaniser bottoms pump P-2107 dischar	18.0 barg	1 x 2	09 Jun 2023	09 Jun 2025

Tag No.	Location	Set Pressure	Size	Last Tested	Next Due
PSV-2105	LPG treater vessel V-2110	16.4 barg	2 x 3	28 Jul 2023	28 Jul 2026
PSV-2106	Naphtha splitter overhead condenser	7.2 barg	3 x 4	14 Sep 2023	14 Sep 2026

PSV-2103 protects the debutaniser overhead line 6-P-2104 against blocked outlet on the overhead condenser. Its relieving capacity was reconfirmed against the 2022 revalidation study and found adequate.

7. Procedure Step 1

7.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

7.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

7.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

7.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

7.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

7.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

8. Procedure Step 2

8.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

8.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

8.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

8.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

8.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

8.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note

Step	Action	Responsible	Record
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

9. Procedure Step 3

9.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

9.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

9.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

9.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

9.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

9.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

10. Procedure Step 4

10.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

10.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

10.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

10.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

10.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

10.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record

Step	Action	Responsible	Record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

11. Procedure Step 5

11.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

11.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

11.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

11.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

11.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

11.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

12. Procedure Step 6

12.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

12.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

12.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

12.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

12.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

12.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record

Step	Action	Responsible	Record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

13. Procedure Step 7

13.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

13.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

13.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

13.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

13.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

13.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

14. Procedure Step 8

14.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

14.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

14.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

14.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

14.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

14.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

15. Procedure Step 9

15.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

15.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

15.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

15.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

15.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

15.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

16. Procedure Step 10

16.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

16.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

16.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

16.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

16.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

16.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

17. Procedure Step 11

17.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

17.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

17.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

17.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

17.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

17.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

18. Procedure Step 12

18.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

18.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

18.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

18.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

18.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

18.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

19. Procedure Step 13

19.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

19.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

19.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

19.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

19.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

19.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

20. Procedure Step 14

20.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

20.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

20.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

20.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

20.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

20.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

21. Procedure Step 15

21.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

21.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

21.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

21.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

21.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

21.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

22. Procedure Step 16

22.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

22.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

22.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

22.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

22.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

22.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

23. Procedure Step 17

23.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

23.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

23.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

23.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

23.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

23.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

24. Procedure Step 18

24.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

24.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

24.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

24.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

24.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

24.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

25. Procedure Step 19

25.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

25.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

25.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

25.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

25.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

25.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

26. Procedure Step 20

26.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

26.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

26.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

26.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

26.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

26.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

27. Procedure Step 21

27.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

27.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

27.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

27.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

27.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

27.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

28. Procedure Step 22

28.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

28.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

28.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

28.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

28.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

28.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

29. Procedure Step 23

29.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

29.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

29.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

29.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

29.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

29.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

30. Procedure Step 24

30.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

30.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

30.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

30.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

30.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

30.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

31. Procedure Step 25

31.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

31.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

31.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

31.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

31.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

31.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

32. Procedure Step 26

32.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

32.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

32.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

32.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

32.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

32.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

33. Procedure Step 27

33.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

33.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

33.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

33.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

33.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

33.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

34. Procedure Step 28

34.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

34.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

34.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

34.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

34.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

34.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

35. Procedure Step 29

35.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

35.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

35.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

35.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

35.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

35.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

36. Procedure Step 30

36.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

36.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

36.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

36.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

36.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

36.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

37. Procedure Step 31

37.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

37.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

37.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

37.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

37.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

37.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

38. Procedure Step 32

38.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

38.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

38.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

38.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

38.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

38.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

39. Procedure Step 33

39.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

39.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

39.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

39.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

39.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

39.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

40. Procedure Step 34

40.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

40.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

40.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

40.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

40.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

40.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

41. Procedure Step 35

41.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

41.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

41.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

41.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

41.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

41.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

42. Procedure Step 36

42.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

42.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

42.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

42.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

42.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

42.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

43. Procedure Step 37

43.1 All work shall be carried out under a valid work permit issued by the area authority. The permit shall remain displayed at the work site for the duration of the activity and shall be returned on completion.

43.2 Personnel engaged in this activity shall have completed the department competency assessment within the preceding twenty four months. Records of assessment shall be available for audit.

43.3 Any deviation from this procedure shall be recorded on the deviation register and shall be approved in writing by the Head of Inspection before work proceeds. Verbal approval is not acceptable.

43.4 Calibration certificates for all test instruments shall be current and traceable to a national standard. An instrument whose calibration has lapsed shall be withdrawn from service immediately.

43.5 On completion, the work site shall be restored, all temporary supports removed, and the area handed back to Operations against a signed clearance.

43.6 Where the results of the test fall outside the acceptance criteria stated in this procedure, the item shall be quarantined and referred to the Inspection Engineer for disposition.

Step	Action	Responsible	Record
1	Confirm isolation and depressurisation of the protected system	Operations	Permit
2	Fit blind flange and tag the removed valve with its tag number	Maintenance	Tag register
3	Transport valve to workshop in the vertical position	Maintenance	Movement note
4	Record as-received condition photographically before dismantling	Workshop	Test record
5	Carry out as-received pop test and record the lift pressure	Workshop	Test record
6	Dismantle, clean and inspect all internal components	Workshop	Inspection sheet

44. Records

The completed test record and the certificate issued against it shall be retained for a period of 10 years from the date of test. Records shall be held in the equipment history file and in the departmental document management system.

Prepared By

Reviewed By

Approved By