Troubleshooting 49

The IC Series charger is continuously monitoring itself and its environment

for unusual conditions. There are a few
indications that may require attention.

Troubleshooting 50

SPTO RECOENDED ACTION

No indicator
lights

Check AC voltage and connection to
wall power

Only blue
AC light on

Charger is connected to AC and
is waiting for a batter y to be
connected, or for CAN remote
control commands. Battery voltage
must rise over 0.1V/cell before
charging will begin. Some charging
algorithms require a higher battery
voltage to begin.

Solid red Fault/
Error/USB
Indicator

Read fault code (e.g., F-0-0-1)
number on the Charge Algorithm/
Error Display and refer to the fault
code table.

Flashing amber
Fault/Error/USB
Indicator

Read error code (e.g., E-0-0-1)
number on the Charge Algorithm/
Error Display and refer to the error
code table.

Table 4-1

Troubleshooting 51

FAULT CODE TROUBLESOOTING /

CUSTOER ACTIONS

If a unit is not functioning and an Error is not indicated
or logged, and this condition persists after cycling both
AC and DC, it should be sent back to manufacturer of
your vehicle/ machine or the distributor of the charger
for servicing.

F-0-0-1

Internal charger fault. Remove AC
and battery for minimum 30 seconds
and retry charger. If the fault
persists, contact the manufacturer
of your vehicle/ machine or the
distributor of the charger for
servicing

F-0-0-2

F-0-0-3

F-0-0-4

F-0-0-5

F-0-0-6

Table 4-2

Troubleshooting 54

ERROR

CODE DESC. TROUBLESOOTING /

CUSTOER ACTIONS

E-0-0-1

E-0-2-1High

Battery

Voltage
Error

Batter y Voltage is too high

to charge. Check the battery
voltage and cable connections.
Check battery size and condition

(could be too full to charge). This
error automatically clears once

the condition has been corrected.

E-0-0-2

E-0-2-2Low

Battery
Voltage

Battery Voltage is too low to

charge. Check the batter y
voltage and cable connections.

Check battery size and condition.
This error automatically clears
once the condition has been

corrected.

E-0-0-3 Charge

Timeout

Charge Timeout caused by battery
pack not reaching required

voltage within safe time limit.
Charger output reduced due to

high temperatures. Possible
causes include poor battery
health, very deeply discharged

batter y, poorly connected
battery, or extra loads. Possible

solutions include replacing the
battery pack, checking the DC

connections, disconnecting
parasitic loads, and operating

at lower ambient temperatures.
This error automatically clears

once the charger is reset by
cycling DC.

Table 5-1

10 OST COON ERROR CODES

Troubleshooting 55

ERROR
CODE DESC. TROUBLESOOTING /

CUSTOER ACTIONS

E-0-1-2 Reverse

Polarity

Batter y is connec ted the
wrong way around. Check the

battery connections. This error
automatically clears once the
condition has been corrected.

E-0-1-3Battery

does
not take

current

Battery voltage is detected but
the charger is unable to charge

the battery. This can be due to
an electrical device connected

between the charger and the
battery, which passes through

voltage but not current. Verify
correct set up with OEM.

Table 5-2

Troubleshooting 56

for complete list, please check our

website at

https://support.delta-q.com

ERROR
CODE DESC. TROUBLESOOTING/

CUSTOER ACTIONS

E-0-11, E-0-29,

E-0-30, E-0-32Charger is

disabled

by external
command

(e.g., CAN
bus)

Charger has been disabled by
an external controller over
the CAN bus network contact

contact the manufacturer of

your vehicle/machine or the
distributor of the charger for
assistant.

E-0-16, E-0-18,

E-0-19, E-0-26 Software

error

The software update failed.
Ensure the USB Flash Drive

is properly formatted (FAT 32
recommended) and retry the

update by reinserting the USB
Flash Drive into the charger.

If software updates continue
to fail, try a different USB
Flash Drive or contact the

manufacturer of your vehicle/
machine or the distributor of

the charger for servicing.

E-0-20, E-0-28 Algorithm

Error

The selected charging profile is
incompatible with the charger

software. Update charger
software or select a different
charging profile. Ensure default

algorithm is selected.

Table 6

SOTWARE / ALGORITH
ERRORS

Quote error code to manufacturer of your

vehicle/machine or the distributor of the

charger.

Troubleshooting 57

ERROR

CODE DESC. TROUBLESOOTING/

CUSTOER ACTIONS

E-0-14, E-0-15, E-0-24, E-0-31,

E-0-33, E-0-34, E-0-35, E-0-36

E-0-37 Configuration

Error

There is an error with
the charger’s internal

configur ation. Contac t
the manufacturer of your

vehicle/machine or the
distributor of the charger
for assistance. USB drive

update may be provided to
clear the error.

E-0-38Fan has a

locked rotor
or open circuit

(Fan-equipped models only)
Check fan connections.

Check to ensure the fan

turns freely and is not
obstructed. This error

automatically clears once
the condition has been
corrected.

Table 7

for complete list, please

check our website at

https://support.delta-q.com

CONIGURATION ERRORS

Quote error code to manufacturer of your
vehicle/machine or the distributor of the

charger.