



Aviation Investigation Final Report

Location: Kenai, Alaska Accident Number: GAA18CA469

Date & Time: August 4, 2018, 15:30 Local Registration: N8443B

Aircraft: Rans S7 Aircraft Damage: Substantial

Defining Event: Aerodynamic stall/spin **Injuries:** 1 Minor, 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot in the tailwheel-equipped airplane reported that, during the takeoff roll about 40 knots airspeed with full flaps and about 50% of the 900-ft-long runway remaining, the airplane lifted off and began to climb. The airplane climbed above the tree line but then descended into ground effect. The pilot attempted to clear the trees ahead, but the airplane stalled. The left wing dropped, and the airplane descended below the tree line and touched down on the main landing gear, collided with trees, and then came to rest inverted.

The airplane sustained substantial damage to the left wing lift struts.

The pilot reported that he could have used the additional runway surface and held the airplane on the ground to achieve a more desirable airspeed. Additionally, the Pilot's Operating Handbook stated not to use full flap application during short-field takeoffs.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's exceedance of the airplane's climb capability due to his use of full flaps during a short-field takeoff, his failure to attain a positive climb rate after takeoff, and his exceedance of the airplane's critical angle of attack, which resulted in an aerodynamic stall.

Findings

Personnel issues Aircraft control - Pilot
Personnel issues Use of equip/system - Pilot

Aircraft Climb capability - Capability exceeded

Aircraft Angle of attack - Capability exceeded

Environmental issues Tree(s) - Contributed to outcome

Page 2 of 5 GAA18CA469

Factual Information

History of Flight

| Initial climb | Aerodynamic stall/spin (Defining event) |
|---------------|---|
| Landing | Collision with terr/obj (non-CFIT) |

Pilot Information

| Certificate: | Private | Age: | 62,Male |
|---------------------------|--|---|--------------------|
| Airplane Rating(s): | Single-engine land; Single-engine sea | Seat Occupied: | Front |
| Other Aircraft Rating(s): | None | Restraint Used: | 4-point |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | Yes |
| Medical Certification: | Sport pilot Without waivers/limitations | Last FAA Medical Exam: | July 16, 2013 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | August 3, 2018 |
| Flight Time: | (Estimated) 1273 hours (Total, all air (Pilot In Command, all aircraft) | craft), 360 hours (Total, this make and | model), 1273 hours |

Passenger Information

| Certificate: | | Age: | Male |
|---------------------------|----|-----------------------------------|---------|
| Airplane Rating(s): | | Seat Occupied: | Rear |
| Other Aircraft Rating(s): | | Restraint Used: | 4-point |
| Instrument Rating(s): | | Second Pilot Present: | No |
| Instructor Rating(s): | | Toxicology Performed: | No |
| Medical Certification: | | Last FAA Medical Exam: | |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | |
| Flight Time: | | | |

Page 3 of 5 GAA18CA469

Aircraft and Owner/Operator Information

| Aircraft Make: | Rans | Registration: | N8443B |
|-------------------------------|-----------------------------|-----------------------------------|-----------------|
| Model/Series: | S7 S | Aircraft Category: | Airplane |
| Year of Manufacture: | 2006 | Amateur Built: | Yes |
| Airworthiness Certificate: | Experimental (Special) | Serial Number: | 0405398 |
| Landing Gear Type: | Tailwheel | Seats: | 2 |
| Date/Type of Last Inspection: | June 14, 2018 Condition | Certified Max Gross Wt.: | 1320 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 382 Hrs at time of accident | Engine Manufacturer: | Rotax |
| ELT: | Installed, not activated | Engine Model/Series: | 912S |
| Registered Owner: | | Rated Power: | 100 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|-------------------|
| Observation Facility, Elevation: | PALV,60 ft msl | Distance from Accident Site: | 17 Nautical Miles |
| Observation Time: | 23:44 Local | Direction from Accident Site: | 214° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 5 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 240° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 29.87 inches Hg | Temperature/Dew Point: | 21°C / 12°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Kenai, AK (PVT) | Type of Flight Plan Filed: | None |
| Destination: | Kenai, AK (PVT) | Type of Clearance: | None |
| Departure Time: | | Type of Airspace: | Class G |
| | | | |

Page 4 of 5 GAA18CA469

Airport Information

| Airport: | Private Airstrip PVT | Runway Surface Type: | Dirt |
|--------------------|----------------------|---------------------------|----------------|
| Airport Elevation: | 100 ft msl | Runway Surface Condition: | Dry;Vegetation |

Runway Used:27IFR Approach:NoneRunway Length/Width:900 ft / 100 ftVFR Approach/Landing:None

Wreckage and Impact Information

| Crew Injuries: | 1 Minor | Aircraft Damage: | Substantial |
|---------------------|-----------------|-------------------------|----------------------------|
| Passenger Injuries: | 1 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 Minor, 1 None | Latitude, Longitude: | 61.045276,-151.979721(est) |

Administrative Information

| Investigator In Charge (IIC): | Hicks, Michael |
|-----------------------------------|---|
| Additional Participating Persons: | |
| Original Publish Date: | June 10, 2019 |
| Note: | This accident report documents the factual circumstances of this accident as described to the NTSB. |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=98001 |

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA18CA469