



# **Aviation Investigation Final Report**

Location: Bozeman, Montana Accident Number: GAA18CA437

Date & Time: July 19, 2018, 11:15 Local Registration: N3224D

Aircraft: Cessna 180 Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot of the tailwheel-equipped airplane reported that, after a wheel landing, the tailwheel touched down, and it then started shaking violently. In an attempt to stop the shaking, he pushed forward on the control yoke to no avail. He then tried adding power, raised the tail, and let the tailwheel touch down again; however, the tailwheel continued to shake, and the airplane began to veer left, and he corrected by applying right rudder. Shortly after the airplane regained the runway heading, it suddenly veered right, exited the runway to the right, and ground looped.

The airplane sustained substantial damage to the left wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The pilot added that, during landing, the wind was from 010° at 4 knots. The airport's automated weather observation station reported that, about the 15 minutes before the accident, the wind was from 160° at 4 knots. The pilot landed the airplane on runway 03.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing.

# Findings

A ·	D: .: 1
Aircraft	Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Page 2 of 5 GAA18CA437

## **Factual Information**

## History of Flight

Landing-landing roll	Loss of control on ground (Defining event)	
Landing-landing roll	Attempted remediation/recovery	
Landing-landing roll	Runway excursion	

#### **Pilot Information**

Certificate:	Private	Age:	81,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	June 1, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated)		

## **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N3224D
Model/Series:	180 Undesignat	Aircraft Category:	Airplane
Year of Manufacture:	1954	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	32022
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Amateur/Experimental
ELT:		Engine Model/Series:	Unknown
Registered Owner:		Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA437

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KBZN,4427 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	16:56 Local	Direction from Accident Site:	325°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	60°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.15 inches Hg	Temperature/Dew Point:	24°C / 7°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	Bozeman, MT (BZN )	Type of Flight Plan Filed:	VFR
Destination:	Bozeman, MT (BZN )	Type of Clearance:	VFR
Departure Time:		Type of Airspace:	Class D

## **Airport Information**

Airport:	BOZEMAN YELLOWSTONE INTL BZN	Runway Surface Type:	Asphalt
Airport Elevation:	4473 ft msl	Runway Surface Condition:	Dry
Runway Used:	03	IFR Approach:	None
Runway Length/Width:	2650 ft / 75 ft	VFR Approach/Landing:	Full stop

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	45.777221,-111.150276(est)

Page 4 of 5 GAA18CA437

#### **Administrative Information**

Investigator In Charge (IIC): Nepomuceno, Eleazar

Additional Participating Persons: Robert A Radtke; FAA; Helena, MT

Original Publish Date: September 26, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=97880">https://data.ntsb.gov/Docket?ProjectID=97880</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 GAA18CA437