



# **Aviation Investigation Final Report**

Location: Hobbs, New Mexico Accident Number: CEN19CA017

Date & Time: October 27, 2018, 19:40 Local Registration: N6899C

Aircraft: Piper PA28R Aircraft Damage: Substantial

**Defining Event:** Navigation error **Injuries:** 3 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that he entered a left traffic pattern for runway 30 during night, visual meteorological conditions. Although the pilot thought he had sufficient altitude during the initial phase of the final approach based on his altimeter indication, shortly after turning to final approach, the airplane impacted terrain.

The airplane sustained substantial damage to the right wing and fuselage, and the three occupants were not injured.

Postaccident examination of the airframe and engine revealed no evidence of preaccident mechanical failures or malfunctions that would have precluded normal operation. The examination did reveal that the altimeter had an incorrect setting, which resulted in an altimeter indication error of +800 ft mean sea level. The pilot stated that he must have had the incorrect altimeter setting for the destination airport.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's incorrect altimeter setting during the night visual approach, which resulted in a controlled flight into terrain.

# **Findings**

Aircraft Instrument panel - Incorrect use/operation

Personnel issues Use of equip/system - Pilot

Aircraft Altitude - Not attained/maintained

Page 2 of 5 CEN19CA017

# **Factual Information**

# **History of Flight**

Approach	Navigation error (Defining event)
Approach-VFR pattern final	Controlled flight into terr/obj (CFIT)

#### **Pilot Information**

Certificate:	Private	Age:	56,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	January 16, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 24, 2018
Flight Time:	192 hours (Total, all aircraft), 184 hours (Total, this make and model), 97 hours (Pilot In Command, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Piper	Registration:	N6899C
Model/Series:	PA28R 201	Aircraft Category:	Airplane
Year of Manufacture:	1978	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	28R-7837176
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	November 17, 2017 Annual	Certified Max Gross Wt.:	2750 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	10-360
Registered Owner:		Rated Power:	200 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 CEN19CA017

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>		Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	260°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.12 inches Hg	Temperature/Dew Point:	19°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Carlsbad, NM (CNM)	Type of Flight Plan Filed:	None
Destination:	Hobbs, NM (HOB)	Type of Clearance:	None
Departure Time:	19:05 Local	Type of Airspace:	Class G

# **Airport Information**

Airport:	Lea County Regional Airport HOB	Runway Surface Type:	
Airport Elevation:	3660 ft msl	Runway Surface Condition:	
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Traffic pattern

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	32.68222,-103.221107(est)

Page 4 of 5 CEN19CA017

#### **Administrative Information**

Investigator In Charge (IIC): Sauer, Aaron

Additional Participating Persons: Steven R White; Federal Aviation Administration; Lubbock, TX

Original Publish Date: March 18, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=98563">https://data.ntsb.gov/Docket?ProjectID=98563</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 CEN19CA017