



Aviation Investigation Final Report

Location: Grass Valley, California Accident Number: GAA18CA271

Date & Time: May 9, 2018, 11:15 Local Registration: N210BG

Aircraft: Cessna P210 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, while en route, he noticed a loose camlock screw on the engine cowling and decided to land the airplane at the nearest airport. He added that, during the landing, he applied the brakes, but they had "minimal effect." As the airplane slowed "very slightly," he determined he could make the taxiway turn. But, he added that, "the left steering did not [a]ffect direction." The airplane exited the runway and went over the runway embankment.

The airplane sustained substantial damage to the left wing.

The pilot reported that the brakes failed to slow the airplane to a complete stop, and the nosewheel failed to turn.

A local mechanic examined the brakes following the accident and found no anomalies.

The airport manager reported that marks on the runway showed that the airplane had touched down about 1,000 to 1,500 ft beyond the approach end of the runway. Additionally, there was about a 15- ftlong skid mark showing a skidding left turn before the airplane exited the runway.

Pictures submitted by the Federal Aviation Administration inspector showed the skid marks turning left while exiting the end of the runway.

The airport supplement stated that runway 25 sloped downhill to the west.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper landing flare, which resulted in a long landing and a runway excursion.

Findings

Aircraft Landing flare - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Sloped/uneven terrain - Response/compensation

Page 2 of 5 GAA18CA271

Factual Information

History of Flight

| Landing | Landing area overshoot |
|---------|--|
| Landing | Loss of control on ground (Defining event) |
| Landing | Runway excursion |

Pilot Information

| Certificate: | Private | Age: | 68,Male |
|---------------------------|--|-----------------------------------|------------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | 3-point |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 With waivers/limitations | Last FAA Medical Exam: | May 10, 2017 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | October 17, 2017 |
| Flight Time: | (Estimated) 1460 hours (Total, all aircraft), 460 hours (Total, this make and model), 1460 hours (Pilot In Command, all aircraft), 6.4 hours (Last 90 days, all aircraft), 0.8 hours (Last 30 days, all aircraft), 0.8 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | Cessna | Registration: | N210BG |
|-------------------------------|--------------------------------|-----------------------------------|-----------------|
| Model/Series: | P210 N | Aircraft Category: | Airplane |
| Year of Manufacture: | 1978 | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | P21000025 |
| Landing Gear Type: | Retractable - Tricycle | Seats: | 6 |
| Date/Type of Last Inspection: | April 3, 2018 Annual | Certified Max Gross Wt.: | 4000 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 3482 Hrs as of last inspection | Engine Manufacturer: | CONT MOTOR |
| ELT: | Installed, not activated | Engine Model/Series: | TSI0-520-P |
| Registered Owner: | | Rated Power: | 310 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |

Page 3 of 5 GAA18CA271

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|---|------------------|
| Observation Facility, Elevation: | KG00,3153 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 18:15 Local | Direction from Accident Site: | 62° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 7 knots / | Turbulence Type Forecast/Actual: | None / None |
| Wind Direction: | 180° | Turbulence Severity Forecast/Actual: | N/A / N/A |
| Altimeter Setting: | 30.05 inches Hg | Temperature/Dew Point: | 21°C / 9°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Beckwourth, CA (002) | Type of Flight Plan Filed: | None |
| Destination: | Grass Valley, CA (GOO) | Type of Clearance: | None |
| Departure Time: | 10:37 Local | Type of Airspace: | Class G |
| | | | |

Airport Information

| Airport: | NEVADA COUNTY GOO | Runway Surface Type: | Asphalt |
|----------------------|-------------------|----------------------------------|---------------------------|
| Airport Elevation: | 3157 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 25 | IFR Approach: | None |
| Runway Length/Width: | 4657 ft / 75 ft | VFR Approach/Landing: | Full stop;Traffic pattern |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|---------------------|--------|-------------------------|----------------------------|
| Passenger Injuries: | 1 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 39.223056,-121.005279(est) |

Page 4 of 5 GAA18CA271

Administrative Information

Investigator In Charge (IIC): Swenson, Eric

Additional Participating Persons: Joseph C Mitchell; FAA; Sacramento, CA

Original Publish Date: October 24, 2018

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=97228

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA18CA271