

INCIDENT REPORT

Report ID: INC-2023-089

Date: 8 November 2023

Facility: Visakhapatnam Industrial Complex, Unit 3

Equipment: Boiler-3

Investigated by: Rajesh Kumar (Senior Maintenance Engineer)

Severity: Moderate (No injuries, unplanned shutdown)

INCIDENT DESCRIPTION:

Boiler-3 experienced unexpected bearing failure on feed water pump assembly, resulting in 6-hour unplanned shutdown. Root cause investigation revealed early warning signs (elevated vibration) were logged 12 days prior but not escalated for corrective action.

ROOT CAUSE:

Vibration threshold breach (recorded 6.8 mm/s against limit of 4.5 mm/s) was noted in routine logs but did not trigger a maintenance work order due to manual handoff gap between monitoring team and maintenance team.

CORRECTIVE ACTIONS:

1. Immediate bearing replacement completed
2. Recommend automated alert system for vibration threshold breaches
3. Cross-reference with Safety Procedure SP-45 for escalation protocol review

REFERENCE DOCUMENTS:

- Safety Procedure SP-45
- Regulatory Guideline OISD-105

LESSONS LEARNED:

This incident pattern (vibration anomaly preceding bearing failure) should be treated as a leading indicator across all rotating equipment in the facility, including feed pumps such as Pump-101 and Pump-104.

Status: Closed - Corrective Actions Implemented