

INSITE

Inspection Report

Field Safety Inspection Record

Riverside Bridge Deck Project

Riverside Deck — Full Multi-Area Compliance Walk-Down

Inspection date: August 18, 2026

Inspector: Riley Okafor

Findings documented: 13

Report generated: August 18, 2026

Executive Summary

13

FINDINGS

8

CRITICAL / HIGH

13

OPEN ACTIONS

Completed

STATUS

RISK DISTRIBUTION

Critical		2
High		6
Moderate		5
Low		0

INSPECTION RECORD

SITE / FACILITY

Riverside Bridge Deck Project

INSPECTION

Riverside Deck — Full Multi-Area Compliance Wal...

INSPECTION DATE

August 18, 2026

INSPECTOR

Riley Okafor

REGULATORY CONTEXT

OSHA - Construction (29 CFR 1926)

ASSESSMENT

This inspection documented 13 findings: 2 Critical, 6 High, 5 Moderate. 8 findings rated Critical or High require prioritized corrective action and should be assigned an owner and a closure date without delay. 13 corrective actions were logged for this inspection, of which 13 remain open.

BASIS AND LIMITATIONS

Regulatory context: OSHA - Construction (29 CFR 1926) — set for this inspection. HazLenz AI output is advisory and requires qualified human review; this report reflects findings as reviewed at the time of generation.

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Electrical	High	Finalized	Open
2	Hazard Communication	Critical	Finalized	Open
3	Fall Protection	Critical	Finalized	Open
4	Excavation Trenching	High	Finalized	Open
5	Excavation Trenching	High	Finalized	Open
6	Excavation	Moderate	Finalized	Open
7	Pressure	Moderate	Finalized	Open
8	Excavation Trenching	High	Finalized	Open
9	Excavation Trenching	High	Finalized	Open
10	Noise	Moderate	Finalized	Open
11	Walking Working Surfaces	Moderate	Finalized	Open
12	Fall Protection	High	Finalized	Open
13	Egress	Moderate	Finalized	Open

Detailed Findings

Finding 1 — Electrical

WHAT WAS OBSERVED

the extension cord powering the chop saw at the deck level has exposed copper conductors

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

During the morning walk-down of the north bridge deck the perimeter guardrail was removed for a concrete pour and never reinstalled, leaving roughly forty feet of open edge at a fall height of about twenty-six feet with laborers working within two feet of the edge and no personal fall arrest anchored anywhere on that span; at the same location the scaffold erected against the pier had no guardrail on the open side of the platform above ten feet and the planking was not fully decked, and the extension cord powering the chop saw at the deck level has exposed copper conductors and remains energized while laborers are working around it, and a five gallon container of solvent in the paint room adjacent to the deck has no label identifying its contents or hazards.

Risk:

High

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

29 CFR 1926.416(a)(1) — Electrical safety-related work practices - General requirements: protection of employees from contact with electric power circuits

HazLenz standard summary: No employer may permit an employee to work in such proximity to any part of an electric power circuit that the employee could contact the circuit in the course of work, unless the employee is protected against electric shock by deenergizing the circuit and grounding it, or by guarding it effectively by insulation or other means (29 CFR 1926.416(a)(1)). HazLenz basis: Supported by submitted evidence for OSHA Construction electric power circuit contact protection; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 1

Immediate: Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.

Permanent: Repair or replace the electrical component with appropriately rated equipment and verify the installation.

Verification: Have a qualified person document the electrical inspection before returning the equipment to service.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 2 — Hazard Communication

WHAT WAS OBSERVED

during the morning walk-down of the north bridge deck the perimeter guardrail was removed for a concrete pour and never reinstalled, leaving roughly forty feet of open edge at a fall height of about twenty-six feet with laborers working within two feet of the edge and no personal fall arrest anchored anywhere on that span; at the same location the scaffold erected against the pier had no guardrail on the open side of the platform above ten feet and the planking was not fully decked, and the extension cord powering the chop saw at the deck level has exposed copper conductors and remains energized while laborers are working around it, and a five gallon container of solvent in the paint room adjacent to the deck has no label identifying its contents or hazards.

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

During the morning walk-down of the north bridge deck the perimeter guardrail was removed for a concrete pour and never reinstalled, leaving roughly forty feet of open edge at a fall height of about twenty-six feet with laborers working within two feet of the edge and no personal fall arrest anchored anywhere on that span; at the same location the scaffold erected against the pier had no guardrail on the open side of the platform above ten feet and the planking was not fully decked, and the extension cord powering the chop saw at the deck level has exposed copper conductors and remains energized while laborers are working around it, and a five gallon container of solvent in the paint room adjacent to the deck has no label identifying its contents or hazards.

Risk: **Critical**

Severity 5 · Likelihood 4 · Risk score 20

APPLICABLE STANDARD

29 CFR 1926.416(a)(1) — Electrical safety-related work practices - General requirements: protection of employees from contact with electric power circuits

HazLenz standard summary: No employer may permit an employee to work in such proximity to any part of an electric power circuit that the employee could contact the circuit in the course of work, unless the employee is protected against electric shock by deenergizing the circuit and grounding it, or by guarding it effectively by insulation or other means (29 CFR 1926.416(a)(1)). HazLenz basis: Supported by submitted evidence for OSHA Construction electric power circuit contact protection; qualified review remains required.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 2

Immediate: Immediate hazard control required to prevent contact/exposure to Hazard Communication hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 3 — Fall Protection

WHAT WAS OBSERVED

leaving roughly forty feet of open edge at a fall height of about twenty-six feet with laborers working within two feet of the edge

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

During the morning walk-down of the north bridge deck the perimeter guardrail was removed for a concrete pour and never reinstalled, leaving roughly forty feet of open edge at a fall height of about twenty-six feet with laborers working within two feet of the edge and no personal fall arrest anchored anywhere on that span; at the same location the scaffold erected against the pier had no guardrail on the open side of the platform above ten feet and the planking was not fully decked, and the extension cord powering the chop saw at the deck level has exposed copper conductors and remains energized while laborers are working around it, and a five gallon container of solvent in the paint room adjacent to the deck has no label identifying its contents or hazards.

Risk:

Critical

Severity 5 · Likelihood 4 · Risk score 20

APPLICABLE STANDARD

29 CFR 1926.501 — Duty to have fall protection

HazLenz standard summary: Candidate only, qualified review required: Construction employers must provide fall protection where employees are exposed to fall hazards at applicable elevations or conditions. HazLenz basis: Candidate only; missing: worker exposure.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 3

Immediate: Restrict access to the elevated exposure and stop the task until compliant fall protection is verified.

Permanent: Provide and maintain a compliant guardrail, personal fall-arrest system, or other approved fall control for the work area.

Verification: Verify the fall-control system and access route before resuming work.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 4 — Excavation Trenching

WHAT WAS OBSERVED

no shoring

Finding 4 — Excavation Trenching (continued)

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

In the excavation on the east approach the trench is approximately eight feet deep in previously disturbed clay soil with vertical sides, no shoring, shielding or sloping in place, spoil piled directly at the edge, and two pipefitters were working at the bottom; the ladder that was being used as the means of egress from the trench extends only to the top of the excavation and is not secured, and the same crew reported that the atmosphere at the bottom has not been tested since the excavation was opened three days ago even though a sanitary sewer line was encountered.

Risk: **High**

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

29 CFR 1926.652(a)(1) — OSHA Construction excavation protective systems

HazLenz standard summary: Candidate only, qualified review required: Candidate only; missing: worker cave-in exposure.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 4

Immediate: Immediate hazard control required to prevent contact/exposure to Excavation Trenching hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 5 — Excavation Trenching

WHAT WAS OBSERVED

the same crew reported that the atmosphere at the bottom has not been tested since the excavation was opened three days ago even though a sanitary sewer line was encountered

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

In the excavation on the east approach the trench is approximately eight feet deep in previously disturbed clay soil with vertical sides, no shoring, shielding or sloping in place, spoil piled directly at the edge, and two pipefitters were working at the bottom; the ladder that was being used as the means of egress from the trench extends only to the top of the excavation and is not secured, and the same crew reported that the atmosphere at the bottom has not been tested since the excavation was opened three days ago even though a sanitary sewer line was encountered.

Risk: **High**

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

29 CFR 1926.652(a)(1) — OSHA Construction excavation protective systems

Finding 5 — Excavation Trenching (continued)

HazLenz standard summary: Candidate only, qualified review required: Candidate only; missing: worker cave-in exposure, protective system absent.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 5

Immediate: Immediate hazard control required to prevent contact/exposure to Excavation Trenching hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 6 — Excavation

WHAT WAS OBSERVED

the ladder that was being used as the means of egress from the trench extends only to the top of the excavation

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

In the excavation on the east approach the trench is approximately eight feet deep in previously disturbed clay soil with vertical sides, no shoring, shielding or sloping in place, spoil piled directly at the edge, and two pipefitters were working at the bottom; the ladder that was being used as the means of egress from the trench extends only to the top of the excavation and is not secured, and the same crew reported that the atmosphere at the bottom has not been tested since the excavation was opened three days ago even though a sanitary sewer line was encountered.

Risk: **Moderate**

Severity 2 · Likelihood 3 · Risk score 6

APPLICABLE STANDARD

29 CFR 1926.652(a)(1) — OSHA Construction excavation protective systems

HazLenz standard summary: Candidate only, qualified review required: Candidate only; missing: worker cave-in exposure, protective system absent.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 6

Immediate: Immediate hazard control required to prevent contact/exposure to Excavation hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Finding 6 — Excavation (continued)

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 7 — Pressure

WHAT WAS OBSERVED

two pipefitters were working at the bottom

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

In the excavation on the east approach the trench is approximately eight feet deep in previously disturbed clay soil with vertical sides, no shoring, shielding or sloping in place, spoil piled directly at the edge, and two pipefitters were working at the bottom; the ladder that was being used as the means of egress from the trench extends only to the top of the excavation and is not secured, and the same crew reported that the atmosphere at the bottom has not been tested since the excavation was opened three days ago even though a sanitary sewer line was encountered.

Risk:

Moderate

Severity 2 · Likelihood 3 · Risk score 6

APPLICABLE STANDARD

Not established for this specific finding.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 7

Immediate: Immediate hazard control required to prevent contact/exposure to Pressure hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 8 — Excavation Trenching

WHAT WAS OBSERVED

in the excavation on the east approach the trench is approximately eight feet deep in previously disturbed clay soil with vertical sides

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

In the excavation on the east approach the trench is approximately eight feet deep in previously disturbed clay soil with vertical sides, no shoring, shielding or sloping in place, spoil piled directly at the edge, and two pipefitters were working at the bottom; the ladder that was being used as the means of egress from the trench extends only to the top of the excavation and is not secured, and the same crew reported that the atmosphere at the bottom has not been tested since the excavation was opened three days ago even though a sanitary sewer line was encountered.

Risk:

High

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

29 CFR 1926.652(a)(1) — OSHA Construction excavation protective systems

HazLenz standard summary: Candidate only, qualified review required: Candidate only; missing: worker cave-in exposure, protective system absent.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 8

Immediate: Immediate hazard control required to prevent contact/exposure to Excavation Trenching hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 9 — Excavation Trenching

WHAT WAS OBSERVED

shielding or sloping in place

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

In the excavation on the east approach the trench is approximately eight feet deep in previously disturbed clay soil with vertical sides, no shoring, shielding or sloping in place, spoil piled directly at the edge, and two pipefitters were working at the bottom; the ladder that was being used as the means of egress from the trench extends only to the top of the excavation and is not secured, and the same crew reported that the atmosphere at the bottom has not been tested since the excavation was opened three days ago even though a sanitary sewer line was encountered.

Finding 9 — Excavation Trenching (continued)

Risk: **High**

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

29 CFR 1926.652(a)(1) — OSHA Construction excavation protective systems

HazLenz standard summary: Candidate only, qualified review required: Candidate only; missing: worker cave-in exposure, protective system absent.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 9

Immediate: Immediate hazard control required to prevent contact/exposure to Excavation Trenching hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 10 — Noise

WHAT WAS OBSERVED

noise survey at the concrete cutting station recorded ninety-two dba sustained for the full eight hour shift with two operators stationed at the saw

Risk: **Moderate**

Severity 2 · Likelihood 3 · Risk score 6

APPLICABLE STANDARD

Not established for this specific finding.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 10

Immediate: Immediate hazard control required to prevent contact/exposure to Noise hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Medium

Finding 10 — Noise (continued)

Assigned To: Riley Okafor

NOTES

Finding 11 — Walking Working Surfaces

WHAT WAS OBSERVED

twelve workers are on shift on that floor

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The ground floor exit door on the occupied side of the building under renovation is chained shut while twelve workers are on shift on that floor, and the illuminated exit sign above the second stairwell is not functioning.

Risk: **Moderate**

Severity 2 · Likelihood 3 · Risk score 6

APPLICABLE STANDARD

Not established for this specific finding.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 11

Immediate: Restrict access to the elevated exposure and stop the task until compliant fall protection is verified.

Permanent: Provide and maintain a compliant guardrail, personal fall-arrest system, or other approved fall control for the work area.

Verification: Verify the fall-control system and access route before resuming work.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 12 — Fall Protection

WHAT WAS OBSERVED

the illuminated exit sign above the second stairwell is not functioning

Finding 12 — Fall Protection (continued)

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The ground floor exit door on the occupied side of the building under renovation is chained shut while twelve workers are on shift on that floor, and the illuminated exit sign above the second stairwell is not functioning.

Risk: **High**

Severity 4 · Likelihood 3 · Risk score 12

APPLICABLE STANDARD

Not established for this specific finding.

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 12

Immediate: Restrict access to the elevated exposure and stop the task until compliant fall protection is verified.

Permanent: Provide and maintain a compliant guardrail, personal fall-arrest system, or other approved fall control for the work area.

Verification: Verify the fall-control system and access route before resuming work.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Finding 13 — Egress

WHAT WAS OBSERVED

the ground floor exit door on the occupied side of the building under renovation is chained shut

FULL SOURCE OBSERVATION (SHARED ACROSS THIS INSPECTION'S FINDINGS)

The ground floor exit door on the occupied side of the building under renovation is chained shut while twelve workers are on shift on that floor, and the illuminated exit sign above the second stairwell is not functioning.

Risk: **Moderate**

Severity 2 · Likelihood 3 · Risk score 6

APPLICABLE STANDARD

29 CFR 1926.34(a) — Means of egress - General

HazLenz standard summary: In every building or structure on a construction site, exits must be so arranged and maintained as to provide free and unobstructed egress from all parts of the building or structure at all times when it is occupied (29 CFR 1926.34(a)); means of egress must be continually maintained free of all obstructions or impediments to full instant use in case of fire or other emergency (1926.34(c)). HazLenz basis: Supported by submitted evidence for OSHA Construction means of egress; qualified review remains required.

Finding 13 — Egress (continued)

QUALIFIED-PERSON REVIEW

Accepted — Reviewed against the observed facts; accepted as an advisory conclusion.

RECOMMENDED CORRECTIVE ACTION

Verify and correct reviewed condition 13

Immediate: Immediate hazard control required to prevent contact/exposure to Egress hazard.

Permanent: Address systemic factors to prevent recurrence.

Verification: Confirm the hazard control effectively removes the exposure.

Status: Open · Priority: Medium

Assigned To: Riley Okafor

NOTES

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#2	Immediate hazard control required to prevent contact/exposure to Hazard Communication hazard.	Riley Okafor	—	Open
#4	Immediate hazard control required to prevent contact/exposure to Excavation Trenching hazard.	Riley Okafor	—	Open
#5	Immediate hazard control required to prevent contact/exposure to Excavation Trenching hazard.	Riley Okafor	—	Open
#6	Immediate hazard control required to prevent contact/exposure to Excavation hazard.	Riley Okafor	—	Open
#7	Immediate hazard control required to prevent contact/exposure to Pressure hazard.	Riley Okafor	—	Open
#8	Immediate hazard control required to prevent contact/exposure to Excavation Trenching hazard.	Riley Okafor	—	Open
#10	Immediate hazard control required to prevent contact/exposure to Noise hazard.	Riley Okafor	—	Open
#11	Restrict access to the elevated exposure and stop the task until compliant fall protection is verified.	Riley Okafor	—	Open
#12	Restrict access to the elevated exposure and stop the task until compliant fall protection is verified.	Riley Okafor	—	Open
#1	Place the affected electrical equipment in a safe state and restrict access pending qualified electrical verification.	Riley Okafor	—	Open
#3	Restrict access to the elevated exposure and stop the task until compliant fall protection is verified.	Riley Okafor	—	Open
#9	Immediate hazard control required to prevent contact/exposure to Excavation Trenching hazard.	Riley Okafor	—	Open
#13	Immediate hazard control required to prevent contact/exposure to Egress hazard.	Riley Okafor	—	Open