

INSITE

Inspection Report

Field Safety Inspection Record

Northgate Manufacturing Plant (mswc92jx)

ReportB — Northgate Manufacturing Plant

Inspection date: August 16, 2026

Inspector: Report P2 Tester

Findings documented: 4

Report generated: August 16, 2026

Executive Summary

METRIC	VALUE
Total findings	4
Critical / High risk findings	3
Open corrective actions	3
Inspection status	Completed

Risk Distribution

Critical		2
High		1
Moderate		1
Low		0

Summary

This inspection identified findings requiring prioritized corrective action. Critical and High findings should be assigned an owner and closure date without delay.

Inspection Information

FIELD	DETAIL
Site / facility	Northgate Manufacturing Plant (mswc92jx)
Inspection	ReportB — Northgate Manufacturing Plant
Inspection date	August 16, 2026
Inspector	Report P2 Tester
Status	Completed

Findings Summary

Concise reference of every finding documented in this inspection.

#	HAZARD	RISK	STATUS	ACTION STATUS
1	Machine Guarding	Critical	Finalized	Open
2	Fall Protection	Critical	Finalized	Open
3	Lockout Tagout	High	Finalized	Open
4	Loto	Moderate	Finalized	No action logged

Detailed Findings

Finding 1 — Machine Guarding

WHAT WAS OBSERVED

Machine operator working next to an unguarded rotating drive belt on the packaging line conveyor, point of operation fully exposed.

FINDING

The packaging line conveyor drive belt lacks a fixed guard at the point of operation, exposing workers passing nearby to entanglement.

RISK

CRITICAL

Severity 4 · Likelihood 4 · Score 16

APPLICABLE STANDARD

29 CFR 1910.212(a)(3)(ii)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ANSI (American National Standards Institute) - ANSI B11.19)

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

RECOMMENDED CORRECTIVE ACTION

Install fixed guard on conveyor drive belt

Fabricate and install a fixed guard enclosing the conveyor drive belt point of operation; verify with a qualified technician before returning the line to service.

Owner: Line Maintenance · Due: 08/20/2026 · Status: Open · Priority: High

Finding 2 — Fall Protection

WHAT WAS OBSERVED

Worker on elevated mezzanine platform approximately 12 feet above the warehouse floor with no guardrail or fall-arrest system in use along the open edge.

FINDING

The mezzanine platform edge has no guardrail system and workers were observed without personal fall-arrest equipment while working near the unprotected edge.

RISK

CRITICAL

Severity 5 · Likelihood 4 · Score 20

APPLICABLE STANDARD

29 CFR 1910.28(b)(1)

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ANSI/ASSP (American Society of Safety Professionals) - ANSI/ASSP Z359.1 Fall Protection Code)

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

RECOMMENDED CORRECTIVE ACTION

Install guardrail system on mezzanine edge

Install a compliant guardrail system along the open mezzanine edge; until installed, require fall-arrest harnesses tied off to an approved anchor point for any work within 6 feet of the edge.

Owner: Facilities Manager · Due: 08/17/2026 · Status: Open · Priority: Urgent

Finding 3 — Lockout Tagout

WHAT WAS OBSERVED

Electrician observed servicing a 480V motor control center panel without applying lockout/tagout, panel energized with cover removed.

FINDING

Energized 480V motor control center was serviced with the panel cover removed and no lockout/tagout applied, exposing the technician to arc flash and shock hazards.

RISK

HIGH

Severity 4 · Likelihood 3 · Score 12

APPLICABLE STANDARD

29 CFR 1910.147 — Control of hazardous energy

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ANSI/ASSP (American Society of Safety Professionals) - ANSI/ASSP Z244.1)

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

RECOMMENDED CORRECTIVE ACTION

Enforce lockout/tagout before MCC panel servicing

Retrain electrical staff on the site LOTO procedure for motor control centers; verify a lock/tag and zero-energy check is completed and documented before any panel cover is removed.

Owner: Electrical Safety Lead · Due: 08/16/2026 · Status: Open · Priority: Urgent

Finding 4 — Loto

WHAT WAS OBSERVED

Electrician observed servicing a 480V motor control center panel without applying lockout/tagout, panel energized with cover removed.

FINDING

Additional hazard identified during decomposition: lockout.

RISK

MODERATE

Severity 2 · Likelihood 3 · Score 6

APPLICABLE STANDARD

29 CFR 1910.147 — Control of hazardous energy

HazLenz standard summary: Standard matched using hazard classification, operational context, exposure pathways, and contextual risk indicators. (Supported by high-authority consensus standard: ANSI/ASSP (American Society of Safety Professionals) - ANSI/ASSP Z244.1)

QUALIFIED-PERSON REVIEW

Accepted — Reviewed and confirmed by qualified inspector.

Corrective Action Summary

Consolidated view of all corrective actions from this inspection for management follow-up.

FINDING	ACTION	OWNER	DUE	STATUS
#1	Install fixed guard on conveyor drive belt	Line Maintenance	08/20/2026	Open
#2	Install guardrail system on mezzanine edge	Facilities Manager	08/17/2026	Open
#3	Enforce lockout/tagout before MCC panel servicing	Electrical Safety Lead	08/16/2026	Open

HazLenz AI output is advisory and requires qualified human review. This report reflects findings as reviewed at the time of generation.