

VEHICLE INSPECTION REPORT

Date: 18 Mar 2026 Report No: CK-2024-001 Inspector: Authorised Technician

Vehicle	Maruti Suzuki Baleno RS	Year	2018
Odometer	80,000+ km	Fuel Type	Petrol (Turbo)
Transmission	Manual	Inspection Type	Comprehensive

🔧 BODY & VISUAL INSPECTION

- Front bumper — inspected
- Right headlight — inspected
- Right and left front fenders — inspected
- Driver's door, left rear door, right rear door — inspected
- Bonnet — inspected
- Rear dicky / boot door — repainted, minor cosmetic touch-up done
- Left rear fender and right rear door — inspected
- Bumpers and some body parts repainted

Overall body is in good shape and condition. Repaint noted on boot door and select panels — minor cosmetic correction only, no structural or safety impact observed.

🔧 ENGINE BAY

- No oil spills detected
- No accidental damage found
- All hoses and pipes in good condition
- Aprons in good shape

■ **Minor tampering observed in wiring — recommend further inspection by electrician.**

Belt condition — OK.

🔧 FLUIDS

Fluid	Status	Action Required
Engine Oil	Needs Service	Replace / Top-up
Coolant	Needs Service	Replace / Top-up
Brake Oil	Needs Service	Replace / Top-up

🔧 BATTERY & CHARGING SYSTEM

Test	Reading	Status
Ignition Voltage	12.50 V	Normal
Cranking Voltage	10.4 V	Acceptable
Charging Voltage	14.4 V	Good
Load Voltage Range	13.8 V – 14.2 V	Good

- Battery and alternator charging system working properly at the time of inspection.

🪑 INTERIOR INSPECTION

- Seats — good condition
- Steering wheel — functional
- Infotainment system — functional
- Instrument cluster — functional
- Air conditioning system — see critical note below
- Seat belts — good condition
- Rear seats and flooring — good condition

- **AC COMPRESSOR NOT WORKING — requires replacement/repair before use. Rear boot space plastic trim components need to be refixed.**

🧠 OBD DIAGNOSTIC SCAN

- Minor fault codes present — all healed / non-active
- No active faults found in ECM (Engine Control Module)
- System appears stable at time of inspection

🚗 TEST DRIVE OBSERVATIONS

Component	Observation	Rating
Overall Driving Performance	Acceptable	OK
Braking	Responsive and stable	OK
Suspension	No unusual behaviour	OK
Clutch	Slightly hard / stiff	Monitor
Turbo	Core noise noted	Attention

Drive Shaft	Noisy — inspect / replace	Attention
-------------	---------------------------	-----------

OVERALL VERDICT & RECOMMENDATION

 Mechanically Sound Engine & structure OK	 Items Needing Attention AC Drive Shaft Turbo	 Purchase Recommendation Negotiate before buying
---	---	--

PRECAUTIONS & SERVICE RECOMMENDATIONS

Precautions:

- Vehicle has covered **80,000+ km** — age and wear factors apply; treat with care (TLC).
- Early comprehensive service strongly recommended.
- AC compressor replacement/repair needed before use.
- Drive shaft inspection and replacement recommended.
- Turbo inspection — clean or replace as required.
- Wiring anomaly — have inspected by qualified auto-electrician.
- Boot trim panels to be refixed.

Recommended Service Items:

- Throttle body cleaning
- Inlet valve cleaning
- Turbo cleaning / inspection
- Radiator and intercooler cleaning
- Spark plug inspection and replacement
- Full fluid service (engine oil, coolant, brake oil)

Inspected By	Inspection Centre	Signature
Authorised Technician	CaRya.krama	_____
18 March 2026	Professional Vehicle Inspection	_____

This report reflects the condition of the vehicle at the time of inspection. CaRya.krama accepts no liability for changes in vehicle condition after the inspection date.