Part Number	85-3309-SK	**Document No.**	WI-0851
Part Name	Seal and Gasket Service Kit	**Revision**	A
Operation	Op 20: Kitting, Inspection, and Pack-Out	**Effective Date**	2026-10-05
Work Center	Kitting Bench 1	**Takt / Cycle Time**	4.0 min
Prepared By	Manufacturing Engineering	**Approved By**	Quality Manager

1. Purpose and Scope

This work instruction defines component verification, visual inspection, bagging, labeling, and carton pack-out of the seal and gasket service kit 85-3309-SK for the aftermarket channel.

2. Safety Requirements and PPE

Requirement	Detail
PPE	Safety glasses. Thin nitrile gloves, seals must be handled with clean gloves at all times.
Heat sealer	The sealer bar reaches 180 C. Keep fingers behind the guard line. Report any damaged guard immediately.
Box cutter	Self-retracting cutter only for carton work.
Housekeeping	Keep the bench clear. Loose desiccant packs on the floor are a slip hazard.

3. Tools, Equipment, and Materials

Item	Description	Spec / Calibration
Heat bag sealer	Impulse sealer, 300 mm bar	Seal temp verified at shift start
Barcode scanner	Station scanner tied to kitting screen	Scan test pass
Count scale	0.1 g resolution	Calibrated, tare verified
Light table	Backlit inspection surface	All lamps working
Label printer	Thermal transfer	Print test legible

4. Components / Materials Required

Component	Part / Spec No.	Qty
O-ring, 45 mm, FKM	OR-4530-V	2
O-ring, 22 mm, FKM	OR-2225-V	2
Flat gasket, die cut	GK-8560	1
Shaft seal, 25 x 40 x 7	SS-2540-7	1
Desiccant pack, 1 g	DP-0100	1
Poly bag, 150 x 200 mm	PB-1520	1
Kit label	LB-8533 (printed at station)	1

5. Work Steps

Step	Instruction	Key Point / Specification
1	Open the kitting screen and scan the work order barcode. The screen lists the six components and lot numbers for this kit run.	Work order on screen
2	Scan the lot label on each component bin. The screen must show a green check for all six before kitting may start.	6 green checks
3	Verify all component lots are within shelf life on the screen. FKM parts have a 5 year cure date limit.	No expired lots
4	Place one flat gasket on the light table. Inspect for tears, thin spots, and incomplete die cuts.	No light visible through defects
5	Inspect the shaft seal lip under the bench light. The lip must be continuous with no nicks or flat spots.	Seal lip continuous
6	Inspect all four O-rings by running them gently between gloved fingers. Check for flash, nicks, and flow lines.	No surface defects
7	Stack components into the poly bag in this order: gasket first (flat against the bag), then shaft seal, then O-rings.	Gasket flat at back
8	Add one desiccant pack on top of the stack.	1 desiccant pack
9	Weigh the filled bag on the count scale as a completeness check.	38.5 +/- 1.5 g
10	Seal the bag with the impulse sealer, one continuous seal, 10 mm from the bag edge.	Seal continuous, no wrinkles
11	Pull-check the seal by hand with light tension.	No separation
12	Print the kit label (prints only after the weight check passes), apply it to the bag face, and scan it to close the kit on screen.	Label scan closes kit
13	Pack sealed kits upright in the shipping carton with a divider every 12 kits.	24 kits per carton
14	When the carton is full, apply the carton label, record the carton on the kitting screen, and move it to the FIFO lane.	FIFO lane, oldest first

6. Quality Checks

Characteristic	Specification	Method	Frequency
Component lot scan	6 of 6 green	Barcode scan	Every kit run
Kit weight	38.5 +/- 1.5 g	Count scale	Every kit
Bag seal integrity	Continuous, no separation	Visual + pull check	Every kit
Seal lip condition	No nicks or flats	Visual, bench light	Every kit
Carton count audit	24 kits per carton	Recount	1 carton per shift

7. Nonconforming Material

If any check fails or a defect is observed, STOP the operation. Tag the part with a red NONCONFORMING tag, record the part number, lot, and defect on the tag, and move the part to the quarantine rack. Notify the line lead and Quality immediately. Do not rework or scrap without an approved disposition.

8. Revision History

Rev	Date	Description	Approved
A	2026-10-05	Initial release	QM

Operator Signature: _____ Date: _____

Supervisor Verification: _____ Date: _____