

Zephyr ZX-9000 Hydraulic Press Controller

Service & Troubleshooting Manual - Rev C - Doc MIRACUSTOMERTEST-7731

Section 7 - Fault Codes

Fault ZX-451 - Hydraulic Pressure Sensor Drift

Cause: The PT-7 pressure transducer has drifted outside the 4-20 mA calibration band, usually after a cold-start or following a manifold reseal.

Corrective action for Fault ZX-451:

1. Recalibrate the PT-7 transducer so the zero point reads exactly 4.2 mA.
2. Torque the four manifold bolts to 38 Nm in a cross pattern.
3. Cycle the E-stop twice to clear the latched ZX-451 fault.
4. Confirm DECK pressure holds 210 bar for 60 seconds before returning to AUTO.

Fault ZX-452 - Ram Overtravel

Cause: Linear encoder LE-3 lost reference. Re-home the ram from the HMI service page.

(c) Zephyr Industrial. Internal marker: MIRACUSTOMERTEST-7731. Not a real product.