GAINWELL CAT	Minutes of Meeting	Issue: 1.0 Date: 07/01/2020 Page: 1/4

Subject:	Joint Inspection & Finalisation of scope for Refurbishment of 953 Track type Loader SL no-LBP00980
Venue:	CRC Asansol
Minutes taken by:	Mr Akshaya Pattanaik

Attendee Details	Attendee Details	Attendee Details
Mr. Bhupendra Kumar (RWP - Bela)	Mr. Surajit Singha (GCPL)	Mr.Koushik Kundu (GCPL)
Mr. Akshaya Pattanaik (GCPL)	Mr. Anup Ghoshal (GCPL)	

Sl No	Issues discussed	DY. CME-3 PLANT BELA (Comment)	GCPL (Comments)
1	The 953 Track type loader (LBP00980) has come to GCPL work shop as burn condition. Scope of work has to be finalized.	Dismantle only that portion which has affected by fire and below mention points as agreed jointly.	Agreed
2	Component: Under Carriage—Track chain, Both Idler, Both Sprocket, Track Rollers, Carrier Rollers.Track Tensioning Cylinders and Recoil springs	Repair of the these items not required as Overhauling job carried out few hours (SMU) ago.	Agreed
3	**Compartment** : Cabin As The Cabin as has totally burnt. All glasses are cracked/ broken. All seals, Harness & other Electrical accessories are also affected by fire. Most of the parts have replace with new.	Agreed but Some Electrical items put into functional test which has no direct burn impression if possible.	Agreed

Sl No	Issues discussed	DY. CME-3 PLANT BELA (Comment)	GCPL (Comments)
4	**Compartment** : Engine Engine Have to dismantle completely and preparation of parts list.	Left side & Top portion of the engine has directly burn affected. Agreed for overhauling as per condition	Heat may affect all around the unit. Dismantle is require to conclude. Complete Overhauling of engine recommended
5	**Compartment** : Implement Pump and control valve And pilot pump. Both are burnt. Have to Replace.	Agreed	Agreed
6	**Compartment** : Hyd. Static Pump : 2 Nos (LH & RH) Burning impression is there. Have to Replace.	Agreed	Agreed
7	**Compartment** : Lift Cylinder : 2 Nos (LH & RH) & Tilt Cylinder (01 No) Oil leakage from Cylinder from all above mention cylinders. Cylinder needs to repair by Machining and replacing the necessary parts. Burning impression not found.	Agreed	Agreed
8	**Component** : Track Motor : 2 Nos (LH & RH) No burning impression found. These units are put into functional test. The same will be tested during machine testing. If found any problem/abnormality Customer have to pay extra as per requirement at that point of time for repairing the same.	Agreed	Agreed
9	**Component** : Radiators : 3 part(After Cooler, Radiator, Hyd oil Cooler) Heavy Molten materials are deposited on radiator cores. Cleaning may not possible. GCPL will try to clean the same But if not possible the new replace will be done.	Agreed	Agreed

Sl No	Issues discussed	DY. CME-3 PLANT BELA (Comment)	GCPL (Comments)
10	**Compartment** : Hoses & Seals All hoses and seals have to replace with new as all are burnt.	Agreed	Agreed
11	**Compartment** : Machine frame Accessories Fuel Tank: Totally burnt. Have to install new. All filters & valves are burnt. Have to replace with new. Water Tank: Burnt. Have to install new. Air pre-cleaner AS : burnt. Have to install new. Radiator & Fan Pump : Have to Put into functional test.	Agreed	Agreed
12	**Compartment** : Loader arm, all tilt linkage & bucket with pin bushes. Out of scope, no repair work will be carried out.	Agreed	Agreed
13	**Component** : Final Drive : 2 Nos (LH & RH) No burning impression found. These units are put into functional test. The same will be tested during machine testing. If found any problem/abnormality Customer have to pay extra as per requirement at that point of time for repairing the same.	Agreed	Agreed
14	**Component** : AC Unit Ac Unit completely burn, have to replace with new one.	Agreed	Agreed

07/01/2020
Mr. Bhupendra Kumar (RWP - Bela)

Mr. Akshaya Pattanaik (GCPL)

07/01/2020
Mr. Surajit Singha (GCPL)

07/01/2020
Mr. Anup Ghoshal (GCPL)

7.1.2020
Mr.Koushik Kundu (GCPL)