Pre Plane Assembly Summary

| Panel No     | Plane No   | Cleaned/<br>Prepped | Blocked<br>straws | Missing wires | Missing wires confirmed | PFN & stnd. off epoxy | Ear<br>install  | Ear leak<br>test | Prep<br>Finished | gos luci   |
|--------------|--|---------------------|-------------------|---------------|-------------------------|-----------------------|-----------------|------------------|------------------|--|
| Mn 168       | 169  | . /                 | B                 | 29,33,88      |                         | 3                     | grey /<br>Clear |                  | 3/               | V.   |
| Repairs      | ear fl   |                     | 9-95 ml           | HS 76-95      | Ta Rus                  |                       |                 |                  |                  | or memory and a second and a se |
|              | PIR flooded 78-95 on LHS, 76-95 on RHS   |                     |                   |               |                         |                       |                 |                  |                  |  |
| HV<br>issues | ottV: missing 4 anagu pieces, straws 6/7 and 23/29 disconnect straws 34, 54 due to high aments           |                     |                   |               |                         |                       |                 |                  |                  |  |
|              | e gow  | n fest              | -V                |               |                         |                       |                 |                  |                  |  |
| 4            | Air tested for straw blockages - i<br>Aished as for as et could go<br>een sticks out / most in why wards |                     |                   |               |                         |                       |                 |                  |                  |  |
|              | Air tested & 5 mil Kapton 2 DMB comes - good - eargoes in parturily will epon V = good                   |                     |                   |               |                         |                       |                 |                  |                  | Monkel   |

MN168 (02/24/2025)High current wises! 34,54 Kapten dots: 94,95 Kapten washers at all pins Wire # 29, 33, 88 -> History serys these are missing wires But I bopt all 3 connected, couldn't see HV on other side (when applied 50V).

# 29, 33 -> No signal

# 88 -> Signal is there when roumped up to 1450 V (Slightly)
HV test Confusing)
Gain test Fess test v