Pre Plane Assembly Summary Panel Ear leak Prep PFN & stnd. Ear 1012 assy. Panel No Plane No Cleaned/ Blocked Missing Missing wires Finished gas loak + install test wires confirmed off epoxy Prepped straws #95 128 mn 271 none LT POST PA Repairs o added epoxy under omB on left side epoxy removed from Ch45,47 on cal side edrilled (30/31) = 54 th blocked Anned to drull again + redrilled (30) -) Still blocked thepa cleared backside PFN #8 AMB threed on LHS closest to St. O cleared p=) wine 95 broken; gas leah -> fise -> OK now wine 95 NO HV at Calside HV Ramode - anode I to blockeds traws: 30, 42 | cal side, ornega piece ch 46 touch cha issues Realmost - amode HVSide 5.65 => cress toth crosstolk to Withe 95 broken =) need to nemore except in ch 46. Fesstest-0 to wife 15 internal spark 1.+ Pan actest but need to repen Air test for blocked strawsblocked straw and dean the Notes DMB gaptest w/5mil Kapten tain-1 exposey in ch 45,47 - calside Backside pfn check-V elar flooding-