

Tallowick Auto Service

88 Millrace Street, Halden Cross. Phone 555-0163. Open Monday to Friday 7:30 am to 5:30 pm, Saturday 8:00 am to noon.

Repair Estimate E-4471

- Date: Wednesday 30 September 2026
- Customer: Jorrit Aldemere
- Vehicle: 2019 Sorrel Kestrel 1.6 hatchback
- Odometer: 61,840 miles
- Service advisor: Bexley Thorncastle
- Technician: R. Okafor-Lindqvist

Customer concern: a squeal from the front when braking at low speed. The customer asked for a brake check before a longer trip later in the month.

Inspection findings

Front brake pads. 2 mm of friction material remaining on both sides. Our replacement threshold is 3 mm. Replacement is needed now.

Front brake rotors. Thickness measured at 26.4 mm. The manufacturer's minimum thickness is 25.0 mm, and new rotors are 28.0 mm. Lateral runout is 0.03 mm against a limit of 0.05 mm. No scoring and no heat spots. The rotors are within specification and do not need to be replaced with this set of pads. Measure them again at the next pad change.

Rear brake pads. 6 mm remaining. No action needed. Check again in about 10,000 miles.

Brake fluid. Moisture content 2.4%. We recommend a flush at 3.0%. Not needed today.

Tires. Tread depth 5/32 in at the front and 6/32 in at the rear. Legal and wearing evenly. Rotate at the next service.

Cabin air filter. Dirty. Replacement is optional, \$38.00 fitted.

Wiper blades. Streaking on the driver's side. Replacement is optional, \$31.00 for the pair.

Battery. 12.5 V at rest. Passed the load check.

Option 1: front pads only (recommended)

- Parts: ceramic front pad set, \$94.00.
- Labor: 1.2 hours at \$128.00 per hour, \$153.60.
- Shop supplies: \$12.50.
- Sales tax, 7% on parts: \$6.58.
- Total for Option 1: \$266.68.

Option 2: front pads and front rotors

- Parts: ceramic front pad set at \$94.00 and a pair of front rotors at \$178.00, together \$272.00.
- Labor: 1.7 hours at \$128.00 per hour, \$217.60.
- Shop supplies: \$12.50.

- Sales tax, 7% on parts: \$19.04.
- Total for Option 2: \$521.14.

Notes

Option 2 is shown because some owners prefer to renew pads and rotors together. On the measurements above it is not required.

Either option takes about an hour and a half once the car is on the lift. You are welcome to wait, the waiting room has coffee and wi-fi, or we can phone you when the car is ready.

Appointment held: Tuesday 6 October 2026, drop-off at 8:00 am.

This estimate is valid for 14 days from the date above. Parts prices may change after that.

Parts and labor on brake work are warranted for 12 months or 12,000 miles, whichever comes first.

Old parts are returned on request. Payment is due on collection by card, cash or bank transfer. There is no surcharge on cards.

Customer authorization: _____ Date: _____