Synthetic sample document - fictional data for demos and evaluation only.

LOCKOUT/TAGOUT (LOTO) PROCEDURE
Document ID: SOP-LOTO-001
Purpose: Control hazardous energy while equipment is serviced or maintained.

1. Preparation:
- Notify all affected employees that the equipment will be locked out and why.
- Identify every energy source (electrical, pneumatic, hydraulic, stored mechanical, thermal) using the equipment energy isolation list.
- Collect a personal padlock and a danger tag from the LOTO station.
- Each padlock has a single key, kept by the person who applies it.

2. Isolation Steps:
- Shut down the equipment with its normal stop control.
- Isolate each energy source at its isolation point: open the MCC breaker, close and chain valves.
- Apply your personal padlock and danger tag to every isolation device.
- Release stored energy: bleed pneumatic lines, block or lower suspended loads, discharge capacitors.
- Verify zero energy: press the local start button (try-step) and test conductors with a voltage tester.

3. Group Lockout and Lock Removal:
- Use a group lockout box when more than three workers service the same equipment; every worker attaches their own lock to the box.
- A lock may only be removed by the person who applied it.
- If that person has left site, the supervisor follows the abandoned lock procedure, which requires Plant Manager approval.
- Before re-energizing, account for all workers and notify affected employees.
- This procedure is audited annually.