Bulletin no. / Nr.	Issue date / Ausgabedatum	Revision
SB-2025-018	**2025-11-04**	**0**
Product / Produkt	Supersedes / Ersetzt	Compliance / Umsetzung
HCP-350 centrifugal pump	**-**	**For information**

Kategorie / Category: ☐ Safety ☐ Reliability ☒ **Information**

HCP-350 mechanical seal kit 18-0355 superseded by 18-0356 (silicon carbide faces)

HCP-350 Gleitringdichtungssatz 18-0355 ersetzt durch 18-0356 (Gleitflächen Siliziumkarbid)

1 Summary / Zusammenfassung

With effect from 2025-11-04, mechanical seal kit 18-0356 replaces kit 18-0355 for all HCP-350 pumps. The new kit has silicon carbide against silicon carbide seal faces instead of carbon against silicon carbide. Dimensions and installation are unchanged. The kits are fully interchangeable.

This is an information bulletin. No field action is required on pumps in service. Installed 18-0355 seals stay in service until their next scheduled replacement, and existing stock of 18-0355 may be used until exhausted.

2 Applicability / Geltungsbereich

Model	Serial number range	Old kit	New kit	Remark
HCP-350	HCP350-210001 and later (casing Version 1 and 2)	18-0355	18-0356	Interchangeable
HCP-200	all	18-0201	18-0201	Not affected
HCP-500	all	18-0502	18-0502	Not affected

3 Background / Hintergrund

Field data collected by Halden service partners in 2024 and 2025 show that on HCP-350 pumps in water-glycol circuits with suspended solids, and on pumps with frequent start-stop duty (more than 20 starts per day), the carbon face of kit 18-0355 wears faster than expected. Typical findings are grooving of the carbon face and blistering after repeated thermal shock. The result is seal leakage (fault P-04) well before the 4,000 h inspection interval (IOM task M-03).

Silicon carbide against silicon carbide is more resistant to abrasive particles and does not blister. Bench tests at Aalen with 30% propylene glycol and 50 mg/l of test dust gave a mean face wear of less than one third of the carbon face. In the same tests the SiC/SiC pairing was more sensitive to dry running. The instruction never to start the pump unless the casing is completely filled and vented (IOM chapters 2.3 and 6) therefore becomes more important, not less.

4 Kit comparison / Vergleich der Sätze

Item	18-0355 (old)	18-0356 (new)
Rotating face	Carbon, resin impregnated	Silicon carbide, sintered (SSiC)
Stationary face	Silicon carbide (SSiC)	Silicon carbide (SSiC)
Secondary seals (O-rings)	EPDM, peroxide cured	EPDM, peroxide cured (unchanged)
Spring and metal parts	Stainless steel 1.4571	Stainless steel 1.4571 (unchanged)
Cartridge length / shaft diameter	Unchanged	Unchanged
Kit contents	Seal cartridge, O-rings, gland gasket	Seal cartridge, O-rings, gland gasket
Box label	White label	Blue label, cartridge laser marked "SIC/SIC"

The casing gasket is not part of either kit. It is ordered separately according to the casing version of the pump. For pumps with the revised casing cover, see SB-2025-009 for the gasket and the casing bolt torque.

5 Interchangeability and stock / Austauschbarkeit und Lagerbestand

- 18-0356 can be fitted to any HCP-350 from serial HCP350-210001 in place of 18-0355, and the reverse. Installation per IOM section 8.4 is unchanged.
- Do not combine faces from an 18-0355 kit with faces from an 18-0356 kit. Always fit a complete kit.
- Existing stock of 18-0355 at service partners and end users may be used until exhausted. It is not necessary to replace an installed 18-0355 seal before its next scheduled replacement.
- Halden Spare Parts Service will deliver 18-0356 against open and new orders for 18-0355 once Halden stock of 18-0355 is sold. The order confirmation will show the substitution. No return of 18-0355 stock is offered.
- For installations with abrasive media or frequent starts where a P-04 seal leak has occurred within the last 4,000 h, Halden recommends using 18-0356 at the next seal replacement even if 18-0355 is still in stock.

6 Running-in / Einlaufverhalten

SiC/SiC faces can show slight weeping during the first hours after installation, up to approximately 2 drops per minute, while the faces bed in. This is normal and stops within 24 hours. The leak sensor delay of the PC-3 (60 s) is not affected by such quantities. Leakage above 10 drops per minute after running-in is to be treated as fault P-04.

7 Documentation affected / Betroffene Dokumentation

HDN-IOM-350 Rev D lists 18-0355 in section 4.3 (Technical data), section 8.4 (Replacing the mechanical seal) and section 10 (Spare parts, item 433). Read these references as 18-0356. The correction will be included in IOM Rev E.

8 Labour allowance and warranty / Arbeitszeit und Gewährleistung

Not applicable. This bulletin requires no field action and no claim code is assigned. Seal replacements carried out as warranty repairs follow the normal warranty procedure (IOM 1.4). Mechanical seals are wear parts.

9 Distribution / Verteiler

- Halden authorised service partners, North America and Europe
- Halden Spare Parts Service and regional parts warehouses
- Halden Sales, regional offices
- Halden Product Engineering, Centrifugal Pumps

10 Revision record / Änderungsstand

Rev.	Date	Change	Prepared	Approved
0	2025-11-04	First issue	C. Riedel	M. Kessler

Erstellt / Prepared

Claudia Riedel
Product Management, Spare Parts

Freigegeben / Approved

Dipl.-Ing. M. Kessler
Head of Engineering

Released electronically in Halden PLM. Valid without handwritten signature.

Parts availability: Halden Spare Parts Service, parts@halden-pumpen.de. Technical questions: Stefan Wirth, Technical Support, s.wirth@halden-pumpen.de, +49 7361 555 0140.