Tom Becker

From: Tom Becker <t.becker@corvane.com>
Sent: Wednesday, June 3, 2026 10:42 AM
To: Stefan Wirth <s.wirth@halden-pumpen.de>
Cc: Maria Okafor <m.okafor@corvane.com>
Subject: HCP-350 casing joint leaking after seal change - FRS-P-0031 / HCP350-241187
Attachments: IMG_3051.jpg; IMG_3052.jpg; IMG_3054.jpg

Hello Stefan,

Maria Okafor gave me your address. She says you helped her with a PC-3 controller question last year.

We service Halden pumps at Sierra Springs Beverage in Fresno, California. I'm writing about FRS-P-0031, an HCP-350, serial HCP350-241187, commissioned August 2024. It's the process water supply pump for the syrup room and runs as duty pump with FRS-P-0012 as standby.

Yesterday (June 2) I replaced the mechanical seal, which had started weeping at the faces. I used seal kit 18-0356 and followed your IOM HDN-IOM-350 Rev D, section 8.4: withdrew the back pull-out assembly, fitted the new seal, new casing gasket, and torqued the casing bolts to 45 N-m in a cross pattern, two passes, threads lightly oiled as section 8.7 says. The torque wrench is in calibration (certificate from March).

Pump went back in service at 06:30 this morning. The seal is dry. But after about two hours the casing-to-cover joint started weeping at roughly the 4 o'clock position, looking from the motor end. A drop every few seconds at about 5.5 bar discharge. I stopped the pump and switched the duty to 0012. I checked the bolts at 45 N-m and none of them moved. I have not gone above 45 N-m and didn't want to before asking you.

Photos attached: the joint, the old gasket, and the nameplate.

Questions:
1. Is there a different gasket for this serial? The one in the kit looked the same as the one I took out.
2. Should the torque be higher?
3. Anything else you want me to check before I open it up again?

Our reference is case 00041988.

Thanks,
Tom

Tom Becker
Field Technician | Pumps & Conveyors
Corvane Field Services | Fresno Branch
M +1 559 555 0182
t.becker@corvane.com

CONFIDENTIALITY NOTICE: This e-mail message and any attachments are intended only for the named recipient(s) and may contain confidential or proprietary information of Corvane Field Services, Inc. If you are not the intended recipient, please notify the sender by reply e-mail and delete this message. Any other use, disclosure, copying or distribution is prohibited.

From: Stefan Wirth <s.wirth@halden-pumpen.de>
Sent: Wednesday, June 3, 2026 11:08 PM
To: Tom Becker <t.becker@corvane.com>
Cc: Maria Okafor <m.okafor@corvane.com>
Subject: AW: HCP-350 casing joint leaking after seal change - FRS-P-0031 / HCP350-241187
Attachments: Halden_SB-2025-009_HCP-350_Casing_Torque.pdf

CAUTION: This email originated from outside of Corvane Field Services. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Mr. Becker,

thank you for the clear description and the photos.

Your pump has serial HCP350-241187. For HCP-350 pumps from serial HCP350-240001 the casing was revised, with a lighter casing and a changed gasket seat, and the casing bolt torque for these units is 38 N-m, not 45 N-m. This is in our Service Bulletin SB-2025-009 from June 2025. I attach it again to this email.

From your photos I think it is likely that the gasket seat is cracked. The pattern you describe, a joint that is tight at assembly and then weeps at one position after some hours at temperature and pressure, is what we have seen on the other over-torque cases. That the bolts did not move at 45 N-m fits as well.

Please:
- do not tighten further, and do not run the pump again with this casing,
- when you open it, clean the gasket seat and check it with dye penetrant, especially around the bolt holes near the leak,
- send me photos of the seat after the dye test.

If there is a crack, the casing cannot be repaired. Welding or sealing compound is not permitted on this casing. You would need a new casing, which I can supply.

To your question 1: the gasket is the same part, there is no different gasket. Question 2: no, lower, see above.

Please note also section 1.1 of the IOM: service bulletins take precedence over the manual for the serial ranges they name.

Mit freundlichen Grüßen / Best regards

Stefan Wirth
Technischer Support / Technical Support

Halden Pumpen GmbH
Industriestraße 14 | 73430 Aalen | Germany
Tel. +49 7361 555 0147 | s.wirth@halden-pumpen.de
www.halden-pumpen.de

Halden Pumpen GmbH | Sitz der Gesellschaft: Aalen | Registergericht: Amtsgericht Ulm, HRB 701245 | USt-IdNr. DE 147 552 806
Diese E-Mail enthält vertrauliche Informationen. Wenn Sie nicht der richtige Adressat sind oder diese E-Mail irrtümlich erhalten haben, informieren Sie bitte sofort den Absender und vernichten Sie diese E-Mail. This e-mail contains confidential information. If you are not the intended recipient, please notify the sender immediately and destroy this e-mail.

From: Maria Okafor <m.okafor@corvane.com>
Sent: Thursday, June 4, 2026 8:17 AM
To: Stefan Wirth <s.wirth@halden-pumpen.de>
Cc: Tom Becker <t.becker@corvane.com>; Kenji Watanabe <k.watanabe@corvane.com>
Subject: RE: AW: HCP-350 casing joint leaking after seal change - FRS-P-0031 / HCP350-241187

Stefan,

Thanks for the quick answer. I'm the senior pump technician on the Fresno contract, and I'm copying Kenji Watanabe, our team lead.

I have to push back on the last line, though. Tom did exactly what the manual says. Rev D is the IOM on HaldenNet. I downloaded it again this morning to be sure: it still says 45 N-m in 4.3, 8.4 and 8.7, with no mention of serial numbers and no mention of the bulletin. Rev D is from 2023. The bulletin is from June 2025. So for a

year there has been a torque that cracks the casing on the newer pumps, and the manual every technician opens still has the old number.

Two questions:
1. Why was the IOM never updated? If the torque depends on the serial, that belongs in the manual, in the torque table, not in a separate PDF that someone has to know exists.
2. Why didn't the bulletin reach us? I've checked our manual library, which is what the technicians open on their tablets on site, and SB-2025-009 isn't in it. Nobody on the NA pump team remembers receiving it. If it was sent to Corvane, tell me where it went and we'll fix our side.

I know section 1.1 says bulletins take precedence. That only works if the bulletin is somewhere the technician will see it.

Separately, I've gone through our fleet register for the other HCP-350s we look after. FRS-P-0012 (HCP350-221034) and TAC-P-0045 (HCP350-231650) are older serials, so 45 N-m is still right for those if I read the bulletin correctly. GDN-P-0070 in Gdansk, HCP350-250877, is in the new range. That one belongs to our EU team and I'll make sure they know, because they'll be working from the same Rev D.

Maria

Maria Okafor
Field Technician II | Pumps
Corvane Field Services | Fresno Branch
M +1 559 555 0164

CONFIDENTIALITY NOTICE: This e-mail message and any attachments are intended only for the named recipient(s) and may contain confidential or proprietary information of Corvane Field Services, Inc. If you are not the intended recipient, please notify the sender by reply e-mail and delete this message. Any other use, disclosure, copying or distribution is prohibited.

From: Kenji Watanabe <k.watanabe@corvane.com>
Sent: Thursday, June 4, 2026 9:02 AM
To: Maria Okafor <m.okafor@corvane.com>; Tom Becker <t.becker@corvane.com>
Subject: RE: AW: HCP-350 casing joint leaking after seal change - FRS-P-0031 / HCP350-241187

Taking Stefan off this one.

Good email Maria. Tom, 0031 stays down until the casing has been checked, even if the plant pushes. If the seat is cracked it only gets worse, and 0012 can carry the syrup room for a week.

I'll take the bulletin question to Rachel. I'd bet this isn't only a Halden problem. Right now nobody on our side owns making sure OEM bulletins end up next to the manuals, they come in to whoever happens to be on the list.

K

From: Stefan Wirth <s.wirth@halden-pumpen.de>
Sent: Thursday, June 4, 2026 11:52 PM
To: Maria Okafor <m.okafor@corvane.com>
Cc: Tom Becker <t.becker@corvane.com>; Kenji Watanabe <k.watanabe@corvane.com>
Subject: AW: HCP-350 casing joint leaking after seal change - FRS-P-0031 / HCP350-241187

CAUTION: This email originated from outside of Corvane Field Services. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Ms. Okafor,

I understand the frustration and I won't argue with the main point.

Rev E of the HCP-350 IOM is in preparation. It will include the serial-dependent torque from SB-2025-009 in sections 4.3, 8.4 and 8.7, and the seal kit change from SB-2025-018. I do not have a release date I can give you. It is with our technical documentation department, and the translations are part of the delay, because we release all languages together.

About distribution: bulletins are sent by email to the contacts registered for each service partner, and they are posted on HaldenNet under Service > Bulletins. Manuals and bulletins are on different pages of HaldenNet, which I know is not ideal. I have checked our distribution record. SB-2025-009 was sent on 18 June 2025 to the one address we have registered for Corvane, which is a shared mailbox in Sacramento. I cannot see whether someone opened it. If you send me the names and addresses of the people who should receive pump bulletins, I will add them.

Your reading of the serial ranges is correct: 45 N-m for FRS-P-0012 and TAC-P-0045, 38 N-m for GDN-P-0070.

For FRS-P-0031: I have reserved a revised casing in Aalen. As soon as Mr. Becker confirms the dye penetrant result and we have your order, it goes by air freight, normally three working days to California. The pump is outside the warranty period, so the casing would normally be charged. Given the situation with the manual, I have asked my manager to supply it at no charge. I expect an answer on Monday.

Mit freundlichen Grüßen / Best regards

Stefan Wirth
Technischer Support / Technical Support

Halden Pumpen GmbH
Industriestraße 14 | 73430 Aalen | Germany
Tel. +49 7361 555 0147 | s.wirth@halden-pumpen.de
www.halden-pumpen.de

Halden Pumpen GmbH | Sitz der Gesellschaft: Aalen | Registergericht: Amtsgericht Ulm, HRB 701245 | USt-IdNr. DE 147 552 806
Diese E-Mail enthält vertrauliche Informationen. Wenn Sie nicht der richtige Adressat sind oder diese E-Mail irrtümlich erhalten haben, informieren Sie bitte sofort den Absender und vernichten Sie diese E-Mail. This e-mail contains confidential information. If you are not the intended recipient, please notify the sender immediately and destroy this e-mail.

From: Tom Becker <t.becker@corvane.com>
Sent: Friday, June 5, 2026 9:26 AM
To: Stefan Wirth <s.wirth@halden-pumpen.de>
Cc: Maria Okafor <m.okafor@corvane.com>; Kenji Watanabe <k.watanabe@corvane.com>
Subject: RE: AW: HCP-350 casing joint leaking after seal change - FRS-P-0031 / HCP350-241187
Attachments: IMG_3088.jpg; IMG_3090.jpg; IMG_3091.jpg

Stefan (Tom is fine, by the way),

Opened it up first thing this morning. The dye penetrant shows a crack in the gasket seat starting at the bolt hole at 4 o'clock and running about 15 mm inward. That's exactly where it was weeping. There's a second, shorter indication at the next bolt hole clockwise, maybe 5 mm. Photos attached, the red lines are clear enough.

So please go ahead with the casing. Our purchasing will send the order today with case 00041988 as the reference. Ship to Corvane Field Services, c/o Sierra Springs Beverage, Fresno plant, receiving dock 2, attention Tom Becker.

The line is running on FRS-P-0012 for now. The plant can live with that for a week, but they don't like having no standby on the syrup room water, so the sooner the better.

The seal stays in the back pull-out assembly, so I won't disturb it again. Is the gasket that comes with the casing the same one as before?

Tom

Tom Becker
Field Technician | Pumps & Conveyors
Corvane Field Services | Fresno Branch
M +1 559 555 0182
t.becker@corvane.com

CONFIDENTIALITY NOTICE: This e-mail message and any attachments are intended only for the named recipient(s) and may contain confidential or proprietary information of Corvane Field Services, Inc. If you are not the intended recipient, please notify the sender by reply e-mail and delete this message. Any other use, disclosure, copying or distribution is prohibited.

From: Stefan Wirth <s.wirth@halden-pumpen.de>
Sent: Sunday, June 7, 2026 11:31 PM
To: Tom Becker <t.becker@corvane.com>
Cc: Maria Okafor <m.okafor@corvane.com>; Kenji Watanabe <k.watanabe@corvane.com>
Subject: AW: HCP-350 casing joint leaking after seal change - FRS-P-0031 / HCP350-241187

CAUTION: This email originated from outside of Corvane Field Services. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Tom,

thank you for the photos. That is the typical crack from over-torque. I have added your case to our internal report on this casing.

Your order arrived on Friday evening. The casing leaves Aalen today by air freight and delivery in Fresno is planned for Wednesday 10 June. A new casing gasket is in the box, and yes, it is the same gasket as before.

My manager has approved the casing at no charge. Freight is also on us. Labour is not covered, I am sorry I could not do more there.

For the assembly:
- clean the gasket face on the cover side and check that it is flat and undamaged before you fit the new casing,
- new gasket, threads lightly oiled,
- 38 N-m in a cross pattern, two passes, and not more,
- if you see moisture at the joint after start-up, do not re-tighten it, contact me first.

Ms. Okafor, I have added your address and Mr. Watanabe's to the distribution for pump bulletins from today.

Mit freundlichen Grüßen / Best regards

Stefan Wirth
Technischer Support / Technical Support

Halden Pumpen GmbH
Industriestraße 14 | 73430 Aalen | Germany
Tel. +49 7361 555 0147 | s.wirth@halden-pumpen.de
www.halden-pumpen.de

Halden Pumpen GmbH | Sitz der Gesellschaft: Aalen | Registergericht: Amtsgericht Ulm, HRB 701245 | USt-IdNr. DE 147 552 806
Diese E-Mail enthält vertrauliche Informationen. Wenn Sie nicht der richtige Adressat sind oder diese E-Mail irrtümlich erhalten haben, informieren Sie bitte sofort den Absender und vernichten Sie diese E-Mail. This e-mail contains confidential information. If you are not the intended recipient, please notify the sender immediately and destroy this e-mail.

From: Tom Becker <t.becker@corvane.com>
Sent: Friday, June 12, 2026 2:47 PM
To: Stefan Wirth <s.wirth@halden-pumpen.de>
Cc: Maria Okafor <m.okafor@corvane.com>; Kenji Watanabe <k.watanabe@corvane.com>
Subject: RE: AW: HCP-350 casing joint leaking after seal change - FRS-P-0031 / HCP350-241187

Stefan,

Closing this out from our side. The casing arrived Wednesday afternoon as planned. I replaced the casing half yesterday (June 11): gasket face on the cover side checked flat with no damage, new gasket, bolts torqued to 38 N-m in a cross pattern in two passes. Back in service at 13:10. It has now run 24 hours as duty pump, joint and seal both dry, discharge 5.6 bar, bearing temperatures normal. FRS-P-0012 is back on standby.

Case 00041988 is closed with the bulletin reference in the resolution. Maria has put SB-2025-009 in our manual library.

The cracked casing is on the shelf in the Fresno shop if Halden wants it back for the report. Let me know and I'll ship it.

Thanks for the help, and for the casing.

Tom

Tom Becker
Field Technician | Pumps & Conveyors
Corvane Field Services | Fresno Branch
M +1 559 555 0182
t.becker@corvane.com

CONFIDENTIALITY NOTICE: This e-mail message and any attachments are intended only for the named recipient(s) and may contain confidential or proprietary information of Corvane Field Services, Inc. If you are not the intended recipient, please notify the sender by reply e-mail and delete this message. Any other use, disclosure, copying or distribution is prohibited.