

Maintenance Activity Log — Q1 2029

Maintenance Log

Date	Tag	Activity	Findings	Technician
2029-01-14	P-101A	Vibration survey	7.1 mm/s RMS — above 4.5 alert	R. Krishnan
2029-02-02	P-101B	Vibration survey	2.8 mm/s RMS — normal	R. Krishnan
2029-02-18	E-2405	Tube bundle inspection	12 tubes plugged, 4% of total	S. Nair
2029-03-06	V-1201	UT thickness survey	CML-04 at 9.20 mm, approaching t-min	S. Nair
2029-03-22	PSV-1207	Bench test	Set 18.5 barg, popped 18.9 barg — reset	M. Devadiga

Notes

P-101A vibration exceeded the 4.5 mm/s alert threshold and remains under watch. A bearing change is planned during the turnaround.