		EVEN	IT ANALYSIS R	EPO	RT			
UNIT NO: 01	TPS: Khaperkheda TPS Unit Capacity: 210 MW						V	
1. *HO Code: Station Code: TO		03	3 Time - Date -		Date -	No. of days from last sync.:		
			05:21 Hrs	2	9/06/2015		1 days	
2. Operating conditions at the time of Event :-								
Load		Coal Cycles in service				Oil Support		
160 MW		A,B,C,D,E				Nil		
3. Nature of Event: T.A. Set tripped on "Drum Level Very Low".								
4. Name of First Up	, Main Protections &	& Protect	tion on which (GCB	tripped :			
Drum Level V. Low (First Up), Turbine Trip, Turbine trip gear operated, Gen. Prot. Operated, GCB opened on RPP								
5A) Observations :- At 03:48 hrs, various controls including Hot well / FST control & Drum level failed. Hot well / FST								
level & Drum level controls were maintained manually. Suddenly Unit No. 1 server got bad. As checked by I & C, Drum								
Level processor was not working hence removed & cleaned. After cleaning the processor again placed in position but								
same problem persisting. Hence again Drum level processor removed. At that time No Drum level signal was available								
anywhere. Subsequently, I & C Staff inserted another drum level processor but at the same time T.A. set tripped on								
Boiler Drum level very Low protection.								
5 B) Remedial Action/work done: TIC: Drum level controller i.e. processor failed, replaced with repaired one.								
System checked found satisfactorily working.								
6. Root Cause Analysis: - Drum level controller i.e. Processor failed								
7. Preventive action suggested (Short Term):-								
8. Preventive action suggested (Long Term) :-								
9. Similar event occurred last time:-		Unit	Unit No # 1, 210MW		Time: 10:32 Hrs		Date: 07/12/2013	
Event: - : T.A. Set tripped on "Drum Level Very Low Protection".								
Remedial Actions: No Work done.								
9A. Implementation Status of Long Term/Short Term measures stated at Sr No 7 & 8:-								
10. Boiler lighted up			Time - 12:20 H				ate- 29/06/2015	
11. T-A Set Synchronised			Time - 14:17 Hrs		Date	- 29/06/2015		
12. Remark :-							1	
						Chief	Engineer	
13. Recommendation	ons of Works Section	:						
1. Procurement/Rep	placement Plan:							
2. Operational Error	r:							
3. Delay in Maintena	ance:							
4. Delay in bringing	back the Unit:							
5. Training of Staff:								
6. Whether remedial action is completed satisfactory & point is closed:								
C E/Dy C E (Works)							C E (Works)	