EVENT ANALYSIS REPORT						
UNIT NO: 03	TPS: Khaperk	heda TP:	Unit Capacity : 210 MW			
	Station Code: T003		Time -	Date -		No. of Days from last sync. :
1. *HO Code :			14:40 Hrs	17/02/20	016	9 days
2. Operating conditions at the time of Event :-						
Load			Coal Cycles in service		Oil Support	
160 MW			A, B, C & E		Nil	
3. Nature of Event: T.A. Set forced withdra		thdrawn	drawn due to air pre heater problem.			•
4. Name of First Up, Main Protections & Protection on which GCB tripped: Turbine Hand Tripped (First Up) Turbine Trip, Boiler MFT Operated, Gen Protection Operated.						
5A) Observations : At 14:40 hrs on date 17/02/16 set was on load at 160 MW with coal cycle A, B, C & E in service but withdrawn due to jamming of APH-3A. Bracing pipe found entrapped between sector plate and rotor of APH-3A, which was fallen due to its detachment from bracing pipe support. Hence set withdrawn at 14:40 Hrs on date 17/02/16 for removing the entrapped bracing pipe from APH-3A.						
5B) Remedial Action/work done:						
(1) Entrapped bracing pipe between sector plate & rotor of APH-3A removed.(2) Visual inspection of bracing support of APH-3A carried out and found ok.(3) APH-3A main drive assembly checked for smooth running.						
6. Root Cause Analysis : Due to flue gas erosion the bracing pipe detached from its support and entrapped between sector plate & rotor of APH-3A which resulted in jamming of APH-3A.						
7. Preventive action suggested (Short Term):-						
8. Preventive action suggested (Long Term): Replacement of APH bracing pipes and strengthening of structure						
including scaffolding erection and allied repairs during forthcoming annual overhaul tentatively scheduled to be commenced in April-2016.						
9. Similar event occurred last time:-		3	U - 3, 210 MW Time- Hrs			Date:
No similar event found.		5-3,210 MW Time- 1113			Date.	
Event:						
Remedial Action/work done:						
9A. Implementation Status of Long Term/Short Term measures stated at Sr. No 7 & 8: The above preventive action will be Implemented by April-2016.						
10. Boiler lighted up		Time - 01:10 Hrs		Dat	Date - 18/02/2016	
11. T-A Set Synchronized		Time - 04:24 H	Time - 04:24 Hrs		Date - 18/02/2016	
12. Remark: -						
Chief Engineer						
13. Recommendations of Works Section:						
1. Procurement/Replacement Plan:						
2. Operational Error:						
3. Delay in Maintenance:						
4. Delay in bringing back the Unit: 5. Training of Staff:						
6. Whether remedial action is completed satisfactory & point is closed:						
C E/Dy C E (Works)						