

Motor Failure	Cause	Inspection Method	Corrective Actions
	Output phase loss, current fluctuation or imbalanced	1. Check whether the wiring is securely locked, or if the connection is poor 2. Check if the AC motor drive parameters are properly set 3. Use hi-pot to check if there is obvious difference or corona in the insulation attenuation waveforms between the three phases	1. Adjust the AC motor drive parameters 2. Contact the manufacturer
	Carrier frequency is too low, causing vibration and excessive electromagnetic noise	Check whether the motor output carrier frequency is larger than 4 kHz	Adjust the AC motor drive carrier frequency
	The motor is not installed securely, or the foundation rigidity is insufficient	1. Check if the screwing force of the mounting bolts meets the specification	Lock the bolts according to the specified screwing force
		2. Check whether the foundation vibration is too large	Enhance the foundation rigidity
	Bearing failure or insufficient lubrication	Check whether the bearing rotates smoothly and whether the lubricating grease is sufficient	1. Add lubricating grease 2. Contact the manufacturer to replace the bearing
	Fan broken	Check if the fan is damaged	Contact the manufacturer to replace the fan
The temperature of the motor and the cover is too high	The motor installed environment does not meet the specification	Verify if the installed environment meets the specification: Temperature: -15–40°C Altitude: 1000m and below	Install and use the motor in an environment that meets the specification
	Poor heat dissipation and ventilation environment	1. Check if the fan works normally 2. Check whether the fan is damaged 3. Check whether the motor cooling air duct is blocked	1. Clean the cooling air duct 2. Contact the manufacturer to replace the fan
	The AC motor drive outputs abnormally	Check the drive output current and adjust the drive parameters	1. Adjust the drive parameters 2. Contact the manufacturer
	The load is too large	1. Check if the load is too large	Adjust the load to the motor specified operating range
		2. Check whether the motor centering is accurate	Adjust the centering
	Poor contact of the wire	Check if the wiring resistance is too large	Re-wire the motor
	The motor is demagnetized and causing the input current to be too large	Check the motor magnetic flux linkage	Contact the manufacturer to confirm the reason of demagnetization