

Chapter 7 : Troubleshooting

Q1. How to set up an SNTP server on my workstation for the Mini SNMP to synchronize?

To enable SNTP services in Windows XP, go to **Start → Control Panel → Add/ Remove Programs → Add/ Remove Windows Components → Networking Services** → check **Simple TCP/ IP Services** → **OK**. To enable time synchronization, you need to set SNTP time server addresses in **Time Server**. Please refer to **Chapter 4: System Configurations**.

Q2. How to make sure the connection between the Mini SNMP and the UPS is established?

If the connection between the Mini SNMP and the UPS is correctly established, the yellow LED indicator should flash rapidly. If not, confirm that the device ID settings on the Mini SNMP and that on the UPS are consistent.

```
C:\>ping 172.16.186.230

Pinging 172.16.186.230 with 32 bytes of data:
Reply from 172.16.186.230: bytes=32 time=2ms TTL=64
Reply from 172.16.186.230: bytes=32 time=2ms TTL=64
Reply from 172.16.186.230: bytes=32 time=2ms TTL=64
Reply from 172.16.186.230: bytes=32 time=4ms TTL=64

Ping statistics for 172.16.186.230:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 2ms, Maximum = 4ms, Average = 2ms

C:\>
```

Q3. I can access the InsightPower G3 Mini SNMP Web, but I cannot log in.

Please check the IP addresses of the Mini SNMP and your workstation. By default, they must be within the same LAN so you can connect via the web interface. You can enable external connections to solve this issue. To do this, launch EzSetting and change User Limitation to **Allow Any**, as shown below.