

Chapter 7 : Troubleshooting

If any fault message or abnormality is found, please refer to the table below for the corresponding solution.

Item	Fault Message	Possible Cause	Solution
1	SYS 485 Comm Loss	1. The communication wire is not well-connected. 2. The APF modules have repeated IDs.	1. Check if the communication wire is firmly connected. 2. Check the DIP switches of individual modules.
2	Fuse Blowout	The input fuse is broken.	Please contact service personnel.
3	Ambient OTP	1. The air vents are blocked. 2. The fans do not work.	Please contact service personnel.
4	BUS OVP/ UVP	BUS capacitor failure.	Please contact service personnel.
5	Fan Fail	Fan failure.	Please contact service personnel.
6	No Current Compensation/ Bad Current Compensation	The CT is not well connected.	Check if the CT wiring is correct.