

OPERATOR TRAINING PROGRAM
JOB PERFORMANCE MEASURE

STATION:	SALEM		
SYSTEM:	AC Electrical Distribution		
TASK:	Transfer A 4 KV Group Bus To The Alternate Power Supply (SPT to APT)		
TASK NUMBER:	N0620110101		
JPM NUMBER:	14-01 NRC Sim e		
ALTERNATE PATH:	☒	K/A NUMBER:	062 A4.01
APPLICABILITY:		IMPORTANCE FACTOR:	3.3 3.1
EO ☐	RO ☒	STA ☐	SRO ☒
EVALUATION SETTING/METHOD:	Simulator - Perform		
REFERENCES:	S2.OP-IO.ZZ-0003, Rev. 40, Hot Standby to Minimum Load (All checked 8-20-15) S2.OP-SO.4KV-0008, Rev. 12, 4KV Group Buses Power Supply Transfer		
TOOLS AND EQUIPMENT:	None		
VALIDATED JPM COMPLETION TIME:	15 min		
TIME PERIOD IDENTIFIED FOR TIME CRITICAL STEPS:	N/A		
Developed By:	G Gauding Instructor	Date:	8-20-15
Validated By:	S Bickhart / J Militti SME or Instructor	Date:	9-23-15
Approved By:	 Training Department	Date:	10/2/15
Approved By:	 Operations Department	Date:	10/9/15
ACTUAL JPM COMPLETION TIME:			
ACTUAL TIME CRITICAL COMPLETION TIME:			
PERFORMED BY:			
GRADE:	SAT	UNSAT	
REASON, IF UNSATISFACTORY:			
EVALUATOR'S SIGNATURE:			DATE:

OPERATOR TRAINING PROGRAM
JOB PERFORMANCE MEASURE

NAME: _____

DATE: _____

SYSTEM: AC Electrical Distribution

TASK: Transfer the 4KV Group Buses To The Alternate Power Supply (SPT to APT)

TASK NUMBER: N0620110101

SIMULATOR SETUP IC-253 19.2% power BOL.

MALFS: EL0257 4KV BREAKER 22FSD FAILURE
RP0058 Failure of Automatic Reactor Trip

Check APT voltage the same as the Group bus voltage pre-req 2.3.3

Note: The breaker failure MALF will cause a loss of 2 Group Buses

INITIAL CONDITIONS:

19.2% power, BOL.
The Main Turbine was synchronized 10 minutes ago.
Steam Dumps are in MS Pressure Mode-Auto set at 970 psig.
Rod Control is in Manual until Group Buses are transferred.
Group Buses are powered from the Station Power Transformers.

INITIATING CUE: The CRS directs you to transfer all 4KV Group buses from their respective Station Power Transformers to the Aux Power Transformers IAW S2.OP-SO.4KV-0008, 4KV Group Buses Power Supply Transfer. All pre-requisites are complete SAT. Perform Sections 5.1-5.4 in order.

Successful Completion Criteria:

1. All critical steps completed.
2. All sequential steps completed in order.
3. All time-critical steps completed within allotted time.
4. JPM completed within validated time. Completion time may exceed the validated time if satisfactory progress is being made.

Task Standard for Successful Completion:

1. Transfer 2E 4KV Group bus from SPT to APT.
2. Trip Rx upon ATWT while transferring 2F 4KV Group bus from SPT to APT

OPERATOR TRAINING PROGRAM
JOB PERFORMANCE MEASURE

NAME: _____
DATE: _____

SYSTEM: Electrical

TASK: Transfer the 4KV Group Buses To The Alternate Power Supply (SPT to APT)

*	STEP NO.	STEP (*Denotes a Critical Step)	STANDARD	EVAL S/U	COMMENTS (Required for UNSAT evaluation)
			Reviews Precautions and Limitations.		
	5.1.1	ENSURE all Overhead Annunciators for 2 APT are clear.	Checks OHA Windows and determines all Overhead Annunciators for 2 APT are clear.		
	5.1.2	ENSURE 2B APT voltage is 4.22 - 4.36KV.	Checks 2B APT reading on 2CC3 and ensures 2B APT voltage is 4.22 - 4.36KV.		
	5.1.3	<u>IF</u> Auxiliary Power Unit Isolation Transfer is tripped, <u>THEN RESET</u> Auxiliary Power Unit Isolation Transfer (UIT).	Determines Auxiliary Power Unit Isolation Transfer is not tripped from control console indication.		
*	5.1.4	PRESS the Mimic Bus 2E GROUP BUS INFEED 2AEGD BREAKER pushbutton, AND ENSURE console bezel 2AEGD MIMIC BUS INTLK CLOSE SELECTION illuminates.	Depresses Mimic Bus 2E GROUP BUS INFEED 2AEGD BREAKER pushbutton and checks console bezel 2AEGD MIMIC BUS INTLK CLOSE SELECTION Illuminates.		

OPERATOR TRAINING PROGRAM
JOB PERFORMANCE MEASURE

NAME: _____
DATE: _____

SYSTEM: Electrical

TASK: Transfer the 4KV Group Buses To The Alternate Power Supply (SPT to APT)

*	STEP NO.	STEP (*Denotes a Critical Step)	STANDARD	EVAL S/U	COMMENTS (Required for UNSAT evaluation)
*	5.1.5	PRESS control console 2AEGD CLOSE pushbutton, AND ENSURE the following: A. 21ESD is OPEN. B. 2AEGD is CLOSED. C. 2E 4KV Group Bus voltage is from 4.22 - 4.36KV. D. Console bezel 2AEGD MIMIC BUS INTLK CLOSE SELECTION is extinguished.	Depresses control console 2AHGD CLOSE pushbutton, and checks the following: A. 21ESD is OPEN. B. 2AEGD is CLOSED. C. 2E 4KV Group Bus voltage is from 4.22 - 4.36KV. D. Console bezel 2AEGD MIMIC BUS INTLK CLOSE SELECTION is extinguished.		
	5.2.1	ENSURE all Overhead Annunciators for 2 APT are clear.	Checks OHA Windows and determines all Overhead Annunciators for 2 APT are clear.		
	5.2.2	ENSURE 2A APT voltage is 4.22 - 4.36KV.	Checks 2A APT reading on 2CC3 and ensures 2A APT voltage is 4.22 - 4.36KV.		
	5.2.3	<u>IF</u> Auxiliary Power Unit Isolation Transfer is tripped, <u>THEN</u> RESET Auxiliary Power Unit Isolation Transfer (UIT).	Determines Auxiliary Power Unit Isolation Transfer is not tripped from control console indication.		
*	5.2.4	PRESS Mimic Bus 2F GROUP BUS INFEED 2BFGD BREAKER pushbutton, AND ENSURE console bezel 2BFGD MIMIC BUS INTLK CLOSE SELECTION illuminates.	Depresses Mimic Bus 2F GROUP BUS INFEED 2BFGD BREAKER pushbutton, AND checks console bezel 2BFGD MIMIC BUS INTLK CLOSE SELECTION illuminates.		

OPERATOR TRAINING PROGRAM
JOB PERFORMANCE MEASURE

NAME: _____
DATE: _____

SYSTEM: Electrical

TASK: Transfer the 4KV Group Buses To The Alternate Power Supply (SPT to APT)

*	STEP NO.	STEP (*Denotes a Critical Step)	STANDARD	EVAL S/U	COMMENTS (Required for UNSAT evaluation)
* * *	5.2.5	PRESS control console 2BFGD CLOSE pushbutton, AND ENSURE the following: A. 21FSD is OPEN. B. 2BFGD is CLOSED. C. 2F 4KV Group Bus voltage is 4.22 - 4.36KV. D. Console bezel 2BFGD MIMIC BUS INTLK CLOSE SELECTION is extinguished.	Depresses control console 2BFGD CLOSE pushbutton. Determines 2F Group bus did not transfer and recognizes a Rx trip demand signal is present by First Out Annunciator F-10, RC LO FLO OR RCP BKR OPEN & P-7. Recognizes the Rx did not trip. Announces ATWT. Note: Identification of the ATWT is not a critical action, tripping the Rx is. Trips the Rx using either trip handle. Confirms the Rx trip.		
			Terminate the JPM when a Rx trip has been initiated and confirmed.		

JOB PERFORMANCE MEASURE VALIDATION CHECKLIST

NOTE: All steps of this checklist should be performed upon initial validation. Prior to JPM usage, revalidate JPM using steps 8 and 11 below.

- 59 1. Task description and number, JPM description and number are identified.
- 59 2. Knowledge and Abilities (K/A) references are included.
- 59 3. Performance location specified. (in-plant, control room, or simulator)
- 59 4. Initial setup conditions are identified.
- 59 5. Initiating and terminating Cues are properly identified.
- 59 6. Task standards identified and verified by SME review.
- 59 7. Critical steps meet the criteria for critical steps and are identified with an asterisk (*).
- 59 8. Verify the procedure referenced by this JPM matches the most current revision of that procedure: Procedure Rev. 12 Date 1-20-11
- 59 9. Pilot test the JPM:
a. verify Cues both verbal and visual are free of conflict, and
b. ensure performance time is accurate.
- _____ 10. If the JPM cannot be performed as written with proper responses, then revise the JPM.
- _____ 11. When JPM is revalidated, SME or Instructor sign and date JPM cover page.

SME/Instructor: Joe M. Little M.L.H.

Date: 9-23-15

SME/Instructor: [Signature] BICKNART

Date: 9/23/15

SME/Instructor: _____

Date: _____

INITIAL CONDITIONS:

19.2% power, BOL.

The Main Turbine was synchronized 10 minutes ago.

Steam Dumps are in MS Pressure Mode-Auto set at 970 psig.

Rod Control is in Manual until Group Buses are transferred.

Group Buses are powered from the Station Power Transformers.

INITIATING CUE:

The CRS directs you to transfer all 4KV Group buses from their respective Station Power Transformers to the Aux Power Transformers IAW S2.OP-SO.4KV-0008, 4KV Group Buses Power Supply Transfer. All pre-requisites are complete SAT. Perform Sections 5.1-5.4 in order.