Service bulletin SB-250-07

Bramwell Hydraulics BH-250 hydraulic press

1 Scope

This bulletin applies to every BH-250 press in service, among them the press HP-01 on line 3. It covers pressure loss in the main cylinder and the seal kit that cures it.

2 Alarm E-217

The controller raises E-217, main cylinder pressure loss, when the main cylinder cannot hold pressure during the stroke. The usual cause is wear of the cylinder rod seals. Check for oil under the press before anything else.

3 Replacing the seals

Lock out the main isolator and release the stored pressure first. Drain the cylinder, withdraw the rod and fit the main cylinder seal kit SEAL-KIT-50. Replace the rod wiper WIPER-CYL-50 at the same time, since a worn wiper brings dirt back to the new seals.

4 Parts

SEAL-KIT-50 Main cylinder seal kit, 50 mm rod, one kit

WIPER-CYL-50 Cylinder rod wiper 50 mm, one

OIL-HLP46-20L Hydraulic oil HLP 46, 20 litre pail, to top up