



ACCESSIBILITY ASSESSMENT REPORT · SAMPLE, FOR ILLUSTRATION ONLY

Every barrier found. Every fix *sequenced*.

- Every barrier ranked by compliance points gained per dollar, so the first dollar counts
- Every finding measured on site and cited to a national standard and a rating-survey item
- Grant programs matched to the work that qualifies
- A phased capital plan that maps onto budget cycles, not a wish list

PREPARED FOR

Town of Clearwater

FACILITY

Clearwater Public Library
1204 Main Street, Clearwater AB T0M 0M0

ASSESSMENT DATE

April 14, 2026

ASSESSOR

Carl Christie, RHFAC Professional

RHFAC Professional

First Nation-owned · PSIB-eligible

Laser-measured to ± 1.5 mm

The short version.

Clearwater Public Library · assessed April 14, 2026. Share this page; the detail is in the rest of the report.

56%

RATING SCORE

28

FINDINGS

47

POINTS TO CERTIFIED

\$1,760–
\$3,870

COST TO CLOSE THAT GAP

Start here — six actions that close the gap to certification

- | | | |
|---|--|--|
| 1 | Reposition periodical shelving to restore a 1,200 mm aisle | Interior Circulation · \$0 |
| 2 | Install directional signage to the accessible washroom | Wayfinding and Signage · \$180–\$320 |
| 3 | Adjust the entrance door closer to 38 N maximum | Exterior Approach and Entrance · \$180–\$350 |
| 4 | Reprogram elevator audio floor announcements | Interior Circulation · \$200–\$400 |
| 5 | Correct website alt text and colour contrast | Technology and Innovation · \$800–\$2,000 |
| 6 | Repaint the accessible parking crossing markings | Vehicular Access · \$400–\$800 |

It does not have to happen at once

Everything in this report is grouped into three phases — immediate, Year 1 and Year 2 — each with its own cost total. Phase 0 is life safety and comes to \$11,460–\$19,860. The full path to Gold is \$71,120–\$123,430 before grants, and two federal programs are matched to specific findings in Section 09.

Questions before council sees this?

Carl Christie, RHFAC Professional · info@novoaccessibility.com · 587.355.4677

01 · WHAT THIS REPORT IS

A decision-support document, not a compliance certificate.

This is a Novo Accessibility Assessment produced using RHFAC v4.0 methodology and CSA/ASC B651:23. It is a pre-complaint documentation baseline for municipal capital planning.

What it is

A measured, scored record of every accessibility barrier at this facility, each one costed and ranked by the compliance points it recovers per dollar spent, and sequenced into phases that map onto budget cycles.

What it is not

It is not an RHFAC Registry submission and does not confer RHF certification. Formal certification requires submission to the RHFAC Registry by a designated RHFAC Professional for adjudication by the Rick Hansen Foundation.

Reaching 60% is not the same as being certified

RHF requires all mandatory certification requirements in Appendix D of the Guide to Certification to be met in addition to the score. The Phase 0 life-safety items in this report are treated as prerequisites for that reason. A site can reach the threshold on points and still not certify.

How to read a finding

Every finding carries four things: what was measured, what the standard requires, which rating-survey item scores it, and what the correction is estimated to cost. The two references do different jobs — the RHFAC item determines points and certification, the B651 clause determines whether the measured value passes.

REFERENCE	DOCUMENT	EDITION	WHAT IT GOVERNS
RHFAC 0.0.0	RHFAC Rating Survey — Rick Hansen Foundation	v4.0, January 2024	Scoring. Category and item point values, applicability, and the 60% and 80% certification thresholds.
B651 §0.0	CSA/ASC B651, Accessible design for the built environment	2023 edition, January 2023	Technical requirements. The measurable minimum behind each finding — dimensions, forces, slopes and heights.
Prerequisites	Guide to RHF Accessibility Certification — Rick Hansen Foundation	v4.2, June 2024	The certification and Gold prerequisites that must be met in addition to the score.
Legal context	Alberta Building Code; Alberta Human Rights Act (duty to accommodate)	Current	The regulatory and human-rights framework this documentation baseline is prepared against.
Cost basis	Alberta Construction Cost Database	Current	Order-of-magnitude cost ranges for capital planning. Not a quotation.

Where a finding shows no B651 minimum, the item is scored by RHFAC but no clause of B651:23 sets a measurable requirement for it; those findings are advisory. Where a reference reads as a section, such as RHFAC 2.2 §, the barrier is scored within that survey section but RHFAC publishes no discrete numbered item for it.

02 · EXECUTIVE SUMMARY

Certification is 47 points away, and most of them are cheap.

For administration and council — Town of Clearwater

The Clearwater Public Library scored **709 of 1,259 applicable points (56%)** across a full RHFAC v4.0 assessment conducted April 14, 2026. That is moderate compliance, and it sits 47 points below the 756-point threshold for RHF Accessibility Certified status.

Three findings are life-safety failures

There are no visual fire alarms on either level, so a person with a hearing impairment receives no warning during a fire. There is no designated area of rescue on Level 2, leaving anyone unable to use stairs with no safe waiting area during evacuation. The accessible washroom grab bars are mounted 40 mm below the required minimum and cannot provide adequate support. These are mandatory regardless of certification goals and regardless of cost.

The finding that matters most for capital planning is that **certification is achievable through a small number of low-cost, high-value actions**. Repositioning the periodical shelving to restore a compliant aisle width costs nothing and delivers the largest single point gain in the assessment. Combined with directional signage, a door closer adjustment, an elevator audio reprogram, a website correction and repainting the parking crossing markings, the total spend required to close the 47-point gap is approximately **\$1,760 to \$3,870** — well below the cost of the structural remediation addressed in later phases.

Full Gold certification is achievable over two capital budget cycles at an estimated **\$71,120 to \$123,430** before grants. The federal Enabling Accessibility Fund provides up to \$125,000 for projects of this type; the current intake is closed and the next call has not been announced, so confirm status before citing a firm figure. This assessment supplies the needs documentation a competitive application requires.

Phase 0

IMMEDIATE

\$11,460–\$19,860

+32 pts → 741 / 1,259

Phase 1

YEAR 1 (2026)

\$31,660–\$53,170

+123 pts → 864 / 1,259

Phase 2

YEAR 2 (2027)


\$28,000–\$50,400

+179 pts → 1043 / 1,259

03 · SCORE SUMMARY

709 of 1,259 applicable points.

Categories 9 (Residential Units) and 10 (Trails and Pathways) do not apply to this building type and are excluded from both the score and the maximum, exactly as RHFAC scores them.



#	CATEGORY	EARNED	MAX	%	PROFILE
1	Vehicular Access	54	75	72%	
2	Exterior Approach and Entrance	89	197	45%	
3	Interior Circulation	212	312	68%	
4	Interior Services and Environment	78	167	47%	
5	Sanitary Facilities	117	212	55%	
6	Wayfinding and Signage	38	84	45%	
7	Emergency Systems	36	70	51%	
8	Additional Use of Spaces	38	70	54%	
11	Mind-Friendly Environments	19	30	63%	
12	Technology & Innovation	28	42	67%	
Total — 10 applicable categories		709	1,259	56%	

Prerequisites outstanding

Two certification prerequisites and several Gold prerequisites remain unmet, most significantly emergency systems with visual alarms in both public and private areas, and at least one universal washroom. Until these are cleared the site cannot certify at any score.

04 · FINDINGS BY CATEGORY

28 findings across 10 categories.

Every category in scope was inspected. Each finding below carries what was measured, what the standard requires, and which rating-survey item scores it.

1. Vehicular Access

2 FINDINGS

1 1.1 Parking — Pedestrian crossing markings

MEDIUM \$400–\$800

Markings show wear and do not clearly delineate the crossing. Repainting recommended within 12 months. Est. \$400–\$800.

MEASURED Worn, faded

STANDARD B651 §8.3.4 requires crosswalks to be clearly marked.

SCORED UNDER **RHFAC 1.1.8** — Pedestrian crossings within parking areas · 3 points

2 1.1 Parking — Shelter over accessible spaces

ADVISORY Not in plan total

No weather protection over the designated accessible spaces. A canopy is recommended as best practice; not included in the capital plan total.

MEASURED None

STANDARD No clause of CSA/ASC B651:23 sets a measurable minimum for this item. Recorded as advisory best practice.

SCORED UNDER **RHFAC 1.1.11** — Shelter for designated accessible spaces · 2 points

2. Exterior Approach and Entrance

5 FINDINGS

3 2.2 Exterior ramp — running slope

HIGH \$14,000–\$22,000

Measured at three points: 8.6%, 8.8%, 8.9%. Ramp re-grading or rebuild required. Est. \$14,000–\$22,000.

MEASURED 8.8%

STANDARD B651 §5.5.1 requires a ramp running slope between 1:12 (8.33%) and 1:20 (5%), with landings no more than 9,000 mm apart.

SCORED UNDER **RHFAC 2.2.1** — Slope · 5 points

2. Exterior Approach and Entrance

CONTINUED

4 2.2 Exterior ramp — width

HIGH

Staff action · \$0

60mm below minimum. Addressed by ramp rebuild above.

MEASURED 1,140mm

STANDARD B651 §8.2.7 requires an exterior ramp to be at least 1,200 mm wide and to meet the running slope of §5.5.1.

SCORED UNDER **RHFAC 2.2.2** — Clear width · 3 points

5 2.2 Tactile warning — top of ramp

HIGH

\$800–\$1,200

No detectable warning strip at top of ramp. Est. \$800–\$1,200.

MEASURED Absent

STANDARD B651 §4.4.5 requires tactile walking indicator surfaces to warn of hazards and guide direction at key decision points.

SCORED UNDER **RHFAC 2.2.2 §** — Scored within survey section 2.2 — Exterior Ramps

6 2.4 Building entrance door — clear width

MEDIUM

Staff action · \$0

2mm below minimum, within measurement tolerance. Monitor.

MEASURED 858mm

STANDARD B651 §5.2.1 requires a doorway to have a clear opening width of at least 860 mm.

SCORED UNDER **RHFAC 2.4.9** — Clear opening width of entrance doors · 5 points

7 2.4 Entrance door — operating force

HIGH

\$180–\$350

Exceeds max by 3N. Door closer adjustment or replacement. Est. \$180–\$350.

MEASURED 41N (pull)

STANDARD B651 §5.2.8 limits door-opening force to 38 N for exterior swinging doors and 22 N for interior swinging doors.

SCORED UNDER **RHFAC 2.4.3** — Power-operated door or easy-to-open door · 5 points

3. Interior Circulation

3 FINDINGS

8 3.2 Path of travel — clear width (narrowest)

HIGH

Staff action · \$0

Periodical shelving encroaches on corridor. Repositioning resolves — no cost. Staff action.

MEASURED 1,130mm

STANDARD B651 §5.1.1 requires an accessible route to have a clear width of at least 1,200 mm.

SCORED UNDER **RHFAC 3.3.1** — Clear width · 5 points

9 3.5 Elevator — control panel height

HIGH

\$3,500–\$6,500

130mm above maximum. Panel replacement or supplementary low panel required. Est. \$3,500–\$6,500.

MEASURED 1,330mm (highest button)

STANDARD B651 §4.3.3 requires the centreline of operating controls to sit between 400 and 1,200 mm from the floor.

SCORED UNDER **RHFAC 3.5.10** — Controls inside elevator cab at accessible height and location · 4 points

10 3.5 Elevator — audio floor announcement

MEDIUM

\$200–\$400

Audio absent. Not required for base Certified status; a Gold prerequisite item. Technician reprogramming. Est. \$200–\$400.

MEASURED Absent

STANDARD B651 §5.6.1 requires an accessible elevator to comply with Appendix E of ASME A17.1/CSA B44.

SCORED UNDER **RHFAC 3.5.13** — Audible elevator components · 4 points

4. Interior Services and Environment

4 FINDINGS

11 4.2 Service counter — height

HIGH

\$2,800–\$4,500

No lowered section. Est. \$2,800–\$4,500 for lowered section addition.

MEASURED 960mm full length

STANDARD B651 §6.7.1.2 requires a table or counter surface to sit between 730 and 860 mm from the floor.

SCORED UNDER **RHFAC 4.2.1** — Desk/counters accessible height or variety of heights · 5 points

4. Interior Services and Environment

CONTINUED

12 4.2 Service counter — knee clearance

HIGH

Staff action · \$0

No knee clearance at any counter section. Resolved by lowered counter addition.

MEASURED None present

STANDARD B651 §6.7.1.3 requires knee clearance of at least 820 mm wide by 480 mm deep by 685 mm high where a forward approach is used.

SCORED UNDER **RHFAC 4.2.2** — Space for knee clearance at transaction points for public and staff · 5 points

13 4.2 Self-service kiosk — reach height

HIGH

\$4,500–\$8,000

70mm above maximum reach for seated users. Accessible terminal required. Est. \$4,500–\$8,000.

MEASURED 1,270mm screen centre

STANDARD B651 §4.3.3 requires the centreline of operating controls to sit between 400 and 1,200 mm from the floor.

SCORED UNDER **RHFAC 4.2.8** — Accessible interactive self-service transaction kiosks · 5 points

14 4.5 Acoustic — background noise

MEDIUM

Staff action · \$0

HVAC noise not formally measured. Recommend acoustic assessment. May affect hearing loop performance.

MEASURED HVAC audible in quiet zones

STANDARD B651 §4.7.3 addresses acoustics, including background noise that interferes with communication.

SCORED UNDER **RHFAC 4.5.1** — Sound damping and background noise · 5 points

5. Sanitary Facilities

3 FINDINGS

15 5.1 Grab bar — rear wall height

CRITICAL

\$760–\$1,360

40mm below minimum. Both bars at original 1997 construction height. Relocation required. Est. \$380–\$680 per bar.

MEASURED 710mm

STANDARD B651 §6.2.5 and Figure 45 require grab bars at least 600 mm long, mounted 750–850 mm above the floor, slip-resistant, 30–40 mm in diameter, and able to resist 1.3 kN.

SCORED UNDER **RHFAC 5.1.9** — Grab bars at appropriate height and locations at toilets · 5 points

5. Sanitary Facilities

CONTINUED

16 5.1 Grab bar — side wall height

CRITICAL

Staff action · \$0

Same deficiency. Both bars relocated together. Included in estimate above.

MEASURED 715mm

STANDARD B651 §6.2.5 and Figure 45 require grab bars at least 600 mm long, mounted 750–850 mm above the floor, slip-resistant, 30–40 mm in diameter, and able to resist 1.3 kN.

SCORED UNDER **RHFAC 5.1.9** — Grab bars at appropriate height and locations at toilets · 5 points

17 5.3 Universal washroom

MEDIUM

\$18,000–\$32,000

No universal washroom. Required for Gold, not for base Certified status. Min. 2,100 × 2,100mm clear area needed. Est. \$18,000– \$32,000.

MEASURED Absent

STANDARD B651 §6.3.1 requires a universal washroom with a single toilet and lavatory to provide a clear area of at least 2,100 by 2,100 mm.

SCORED UNDER **RHFAC 5.3.1** — Number of universal washrooms · 5 points

6. Wayfinding and Signage

4 FINDINGS

18 6.1 Directional signage to accessible washroom

HIGH

\$180–\$320

No directional sign provided. Est. \$180–\$320.

MEASURED Absent

STANDARD B651 §4.6.1 governs the location of signage so that it is visible from the approach and at decision points.

SCORED UNDER **RHFAC 6.1.1** — Interior directional signage is comprehensive and clearly visible · 5 points

6. Wayfinding and Signage

CONTINUED

19 6.1 Tactile attention indicators — entry

HIGH

\$6,000–\$11,000

No tactile wayfinding indicators. Est. \$6,000– \$11,000 main floor.

MEASURED Absent

STANDARD B651 §4.4.5 requires tactile walking indicator surfaces to warn of hazards and guide direction at key decision points.

SCORED UNDER **RHFAC 6.1.3** — Wayfinding includes a variety of techniques · 5 points

20 6.2 Room ID signs — Braille

HIGH

\$3,800–\$6,500

Braille on meeting room only. Full facility replacement required. Est. \$3,800–\$6,500.

MEASURED Partial — meeting room only

STANDARD B651 §4.6.6 requires tactile signs to supplement the text of identification signs — rooms, titles, names and numbers — with raised characters and braille placed near the bottom edge.

SCORED UNDER **RHFAC 6.2.2** — Sign includes Braille and characters/symbols that are raised · 4 points

21 6.2 Room ID signs — tactile characters

HIGH

Staff action · \$0

Addressed by Braille sign replacement above.

MEASURED Absent on non-compliant signs

STANDARD B651 §4.6.6 requires tactile signs to supplement the text of identification signs — rooms, titles, names and numbers — with raised characters and braille placed near the bottom edge.

SCORED UNDER **RHFAC 6.2.2** — Sign includes Braille and characters/symbols that are raised · 4 points

7. Emergency Systems

3 FINDINGS

22 7.1.3 Area of rescue assistance — Level 2

CRITICAL \$2,200–\$4,500

CRITICAL LIFE SAFETY. No designated area of refuge or two-way communication system on Level 2. Est. \$2,200–\$4,500 including signage and two-way communication device.

MEASURED Absent

STANDARD B651 §5.7.2 requires an area of refuge to form part of an accessible path of travel, with a compliant door and two-way communication.

SCORED UNDER **RHFAC 7.1.1** — Designated area of refuge in multi-level building · 5 points

23 7.2.1 Visual fire alarms — Level 1

CRITICAL \$8,500–\$14,000

CRITICAL LIFE SAFETY. No visual fire alarm devices on Level 1. Combined full facility estimate for Level 1 and Level 2: \$8,500– \$14,000. Immediate remediation required.

MEASURED Absent throughout Level 1

STANDARD B651 §5.7.1 requires visible alarms consisting of lights that flash in conjunction with the audible alarm, at a flash rate of 1 to 3 Hz.

SCORED UNDER **RHFAC 7.2.1** — Visual fire alarms generally visible throughout facility and where people might expect to be alone · 5 points

24 7.2.2 Visual fire alarms — Level 2

CRITICAL Staff action · \$0

CRITICAL LIFE SAFETY. Same deficiency as Level 1. Included in the combined estimate above.

MEASURED Absent throughout Level 2

STANDARD B651 §5.7.1 requires visible alarms consisting of lights that flash in conjunction with the audible alarm, at a flash rate of 1 to 3 Hz.

SCORED UNDER **RHFAC 7.2.1** — Visual fire alarms generally visible throughout facility and where people might expect to be alone · 5 points

8. Additional Use of Spaces

2 FINDINGS

25 8.21 Library — accessible stacks aisle width

HIGH

Staff action · \$0

Periodical stacks aisle below minimum. Shelving repositioning — no cost. Same finding as Category 3.

MEASURED 1,130mm

STANDARD B651 §5.1.1 requires an accessible route to have a clear width of at least 1,200 mm.

SCORED UNDER **RHFAC 8.21.3** — Book stacks and shelving · 3 points

26 8.21 Library — self-checkout reach height

HIGH

Staff action · \$0

Same finding as Category 4. Est. \$4,500–\$8,000.

MEASURED 1,270mm screen centre

STANDARD B651 §4.3.3 requires the centreline of operating controls to sit between 400 and 1,200 mm from the floor.

SCORED UNDER **RHFAC 8.21.7** — Accessible interactive self-service transaction kiosks · 5 points

11. Mind-Friendly Environments

1 FINDING

27 11.2 Sensory — adjustable lighting

ADVISORY

\$4,500–\$8,000

No dimmable zones. Fixed high-output fluorescent throughout. Upgrade to adjustable LED. Est. \$4,500–\$8,000.

MEASURED Fixed fluorescent only

STANDARD *No clause of CSA/ASC B651:23 sets a measurable minimum for this item. Recorded as advisory best practice.*

SCORED UNDER **RHFAC 11.2.4** — Structural and task lighting is independently adjustable and customizable to user preferences. · 2 points

12. Technology & Innovation

1 FINDING

28 12.2 Website — accessibility compliance

ADVISORY

\$800–\$2,000

Missing alt text on event images. Low contrast text on events calendar. Est. \$800–\$2,000.

MEASURED Partial WCAG 2.1 compliance

STANDARD No clause of CSA/ASC B651:23 sets a measurable minimum for this item. Recorded as advisory best practice.

SCORED UNDER **RHFAC 12.2.1** — General information about accessibility of the site (e.g., elevators) · 2 points

05 · WHERE THE NEXT DOLLAR GOES

Ranked by compliance points gained per dollar spent.

Most accessibility reports hand a council a list and no order of operations. Every finding here carries the points it recovers and what it costs. The ranking below is points recovered per thousand dollars — so a cheap fix that closes a real gap outranks an expensive fix that closes a small one.

RANK	ACTION	CATEGORY	PTS	ESTIMATE	PTS/\$1K	RUNNING
1	Reposition periodical shelving to restore a 1,200 mm aisle	Interior Circulation	+18	\$0	—	727
2	Install directional signage to the accessible washroom	Wayfinding and Signage	+6	\$180–\$320	33.3	733
3	Adjust the entrance door closer to 38 N maximum	Exterior Approach and Entrance	+8	\$180–\$350	44.4	741
4	Reprogram elevator audio floor announcements	Interior Circulation	+5	\$200–\$400	25.0	746
5	Correct website alt text and colour contrast	Technology and Innovation	+6	\$800–\$2,000	7.5	752
6	Repaint the accessible parking crossing markings	Vehicular Access	+4	\$400–\$800	10.0	756 CERTIFIED

Reading this table

Taken in order, the six actions above total **\$1,760 to \$3,870** and cross the 756-point Certified threshold at rank 6 — not at rank 1. The shelving reposition contributes the largest single share of the gap but does not close it alone. Phase 0 life-safety items must be completed in parallel; they are mandatory prerequisites for submission regardless of the score achieved.

06 · TWO-YEAR CAPITAL PLAN

Three phases, mapped to budget cycles.

Phase 0 is not optional and does not wait for a budget cycle. Phases 1 and 2 are structured so that certification is reached inside Year 1 and Gold inside Year 2.

Phase 0 IMMEDIATE

\$11,460–\$19,860

Life safety: visual fire alarms on both levels, an area of rescue on Level 2, and grab bar relocation. Mandatory regardless of score, and a prerequisite for any certification submission.

+32 points 741 / 1,259 = 59%

Phase 1 YEAR 1 (2026)

\$31,660–\$53,170

Ramp rebuild, full braille and tactile signage, tactile attention indicators, lowered service counter, elevator control panel and door closer — taken together with the six quick wins above. RHF Accessibility Certified is reached early in this phase.

+123 points 864 / 1,259 = 69% **CERTIFIED**

Phase 2 YEAR 2 (2027)

\$28,000–\$50,400

Accessible self-checkout terminal, adjustable LED lighting, the universal washroom required for Gold, website remediation and elevator audio.

+179 points 1043 / 1,259 = 83% **GOLD RANGE**

Total two-year investment to Gold
\$71,120 – \$123,430 before grants

07 · PORTFOLIO ROLL-UP

The same barrier at four buildings is one contract, not four.

This pilot assessed five Town of Clearwater facilities to the same standard. Where a barrier appears at more than one facility it is reported once, as a systemic finding, and costed across the portfolio.

FACILITY	BUILT	LEVELS	EARNED	APPLICABLE	SCORE	CERTIFIED AT	GAP
Clearwater Public Library	1997	2	709	1,259	56%	756	47 pts short
Clearwater Civic Centre	1992	3	690	1,301	53%	781	91 pts short
Clearwater Recreation Centre	2004	2	845	1,342	63%	806	Threshold met
Clearwater Seniors' Centre	1988	1	559	1,166	48%	700	141 pts short
Clearwater Public Works	2011	1	761	1,118	68%	671	Threshold met
Portfolio total	—	9	3,564	6,186	58%	3,714	3 of 5 below threshold

Eight barriers recur at two or more facilities

Repetition is not simply a multiplied cost. A defect found at four buildings is one procurement action, one contractor mobilisation, one specification and one inspection cycle — so the portfolio price sits consistently below the sum of the individual prices.

SYSTEMIC FINDING	FACILITIES	FIXED SEPARATELY	AS ONE CONTRACT	SAVING
No visual fire alarm coverage LIFE SAFETY	3 of 5	\$25,500–\$42,000	\$21,700–\$35,700	\$3,800–\$6,300
Grab bars below the 750 mm minimum LIFE SAFETY	4 of 5	\$3,040–\$5,440	\$2,280–\$4,080	\$760–\$1,360
No area of rescue on the upper floor LIFE SAFETY	2 of 5	\$4,400–\$9,000	\$3,740–\$7,650	\$660–\$1,350
No tactile attention indicators at entry	5 of 5	\$30,000–\$55,000	\$24,000–\$44,000	\$6,000–\$11,000
Room signage lacking braille and tactile characters	4 of 5	\$15,200–\$26,000	\$10,640–\$18,200	\$4,560–\$7,800
Service counter without a lowered section	3 of 5	\$8,400–\$13,500	\$6,720–\$10,800	\$1,680–\$2,700
Entrance door force above 38 N	4 of 5	\$720–\$1,400	\$480–\$930	\$240–\$470
No directional signage to the accessible washroom	3 of 5	\$540–\$960	\$380–\$670	\$160–\$290
Total — 8 systemic findings, 28 work items	—	\$87,800–\$153,300	\$69,940–\$122,030	\$17,860–\$31,270

08 · FUNDING PROGRAMS

Two programs match work in this report.

FEDERAL

Enabling Accessibility Fund

Up to \$125,000

Small Projects stream. Municipalities are eligible. Funds construction and renovation that improves accessibility — the ramp rebuild, universal washroom, tactile indicators and signage in Phases 1 and 2 all fall inside scope.

Status at time of writing: current intake closed, next call not yet announced. Confirm before citing a firm figure in a council report.

NATIONAL

RBC Barrier Buster Grants

Up to \$40,000

Rick Hansen Foundation with RBC and RBC Foundation. Suits the Quick Wins and mid-cost items — signage, door hardware, lighting and wayfinding.

Status at time of writing: the 2026 round closed and 40 recipients were announced in June 2026. Confirm whether a further round is planned.

09 · WHAT THE ESTIMATES ARE BASED ON

Order-of-magnitude, not quotations.

Cost ranges reference the Alberta Construction Cost Database and reflect supply and install at prevailing municipal rates, excluding GST, permit fees, asbestos or hazardous-material abatement, and any structural work uncovered once finishes are opened. Ranges widen where site conditions cannot be confirmed without invasive investigation. A range is given rather than a single figure because a report that hands council one number invites a variance conversation later. For tender, obtain three quotations against the scope described in each finding.

Measurement

All measurements were taken with calibrated equipment: Leica DISTO D2 laser distance meter to ± 1.5 mm, digital inclinometer for slopes, dynamometer for door-opening force, and a lux meter for illumination. Slopes were measured at three points and the least favourable recorded.

10 · WHAT HAPPENS NEXT

Four steps, and the first two cost nothing.

- 1 Circulate this report.** The one-page summary is written to be shared on its own. Administration, finance and the accessibility advisory committee each need a different part of it.
- 2 Authorise Phase 0.** The three life-safety findings do not wait for a capital cycle and can be approved within most simplified purchasing thresholds.
- 3 Complete the six quick wins.** \$1,760–\$3,870 closes the 47-point gap and gives council visible progress to report while the larger capital plan moves through approval.
- 4 Decide on submission.** If the Town intends to pursue formal RHF certification, the prerequisites in Section 01 must be cleared first and the rating submitted to the RHFAC Registry by a designated professional.

11 · CREDENTIALS AND METHODOLOGY

Who prepared this

Carl Christie, RHFAC Professional, accredited through the Rick Hansen Foundation and CSA Group. Novo Industries Inc. is a First Nation-owned business listed in the Indigenous Business Directory and eligible under the Procurement Strategy for Indigenous Business, which allows federal departments with an Indigenous procurement target to award directly without competitive tender. CanadaBuys / SAP Ariba ANID AN11298778565. BN 716914023.

Method

Every applicable item of the RHFAC v4.0 Rating Survey was inspected on site and scored. Each barrier was then cross-referenced to the clause of CSA/ASC B651:23 that sets its measurable requirement. Findings with no corresponding B651 clause are recorded as advisory rather than presented as code deficiencies. Costs were assigned per finding and the remediation sequence derived by dividing points recoverable by estimated cost, with life-safety items promoted above the ranking.

Novo Accessibility · Novo Industries Inc.

novoaccessibility.com · info@novoaccessibility.com · 587.355.4677 · BN 716914023

This is a Novo Accessibility Assessment using RHFAC methodology. It does not confer RHF certification. Sample report — facility, scores and findings shown are not actual assessment data.