

Accessibility Capital Planning Assessment

RHFAC Methodology | v4.0 Rating Survey | CSA/ASC B651:23
novoaccessibility.com | carl@novoaccessibility.com | 587-355-4677

SAMPLE REPORT — ILLUSTRATIVE DATA. This document uses a hypothetical facility to demonstrate Novo Accessibility's report format and methodology. It does not represent a completed engagement.

FACILITY

Clearwater Public Library

Town of Clearwater, Alberta

1204 Main Street, Clearwater AB T0M 0M0

Public Library | Two Levels | 7,000 sq ft

Built 1997 | Partial renovation 2009

NAI SCORE

56%

709 / 1,259 applicable points

Moderate Compliance

Remediation recommended

Certified threshold: 60% (751 pts)

Gap: 42 pts

Gold threshold: 80% (1,007 pts)

Assessment Date	Assessor	Credentials	Survey Version	Equipment
April 14, 2026	Carl Christie	RHFAC Professional	RHFAC v4.0 (Sept 2024)	Leica DISTO D2, inclinometer, dynamometer

IMPORTANT — SCOPE OF THIS REPORT

This report is a Novo Accessibility Assessment produced using RHFAC v4.0 methodology and CSA/ASC B651:23 standards. It constitutes a pre-complaint documentation baseline for municipal capital planning purposes. It is not an RHFAC Registry submission and does not confer RHF certification. Formal RHFAC certification requires submission to the RHFAC Registry by a designated RHFAC Professional for adjudication by the Rick Hansen Foundation. As a certified RHFAC Professional, Novo Accessibility can complete formal Registry submission for official RHF Accessibility Certified status as a separate service. All measurements

were taken with calibrated equipment. Cost estimates are based on current regional contractor pricing and are for capital planning purposes only.

Contents

1. Executive Summary for Council	2
2. At-a-Glance — Category Scores	2
3. NAI Score Summary	3
4. Detailed Findings — RHFAC v4.0, All 12 Categories	4
5. Prioritized Remediation Plan	10
6. Next Dollar Impact — Certification Pathway	11

1. Executive Summary for Council

FOR ADMINISTRATION AND COUNCIL — TOWN OF CLEARWATER

The Clearwater Public Library scored 709 of 1,259 applicable points (NAI 56%) across a full RHFAC v4.0 assessment conducted April 14, 2026. This score represents moderate compliance and falls 42 points below the threshold for RHF Accessibility Certified status.

Three findings constitute life safety failures requiring immediate action. There are no visual fire alarms on either level, no designated area of rescue assistance on Level 2, and the accessible washroom grab bars are mounted 55mm below the required minimum height.

The most important finding for capital planning purposes: RHF Accessibility Certified status is achievable for \$1,360–\$3,070 in targeted low-cost actions. Repositioning the periodical shelving to restore a compliant aisle width costs nothing and, on its own, closes 18 of the 42-point gap to certification. Combined with four other low-cost fixes (directional signage, a door closer adjustment, elevator audio reprogramming, and website remediation), the full path to certification costs a small fraction of the total remediation budget, before any major capital items are addressed.

Full Gold certification is achievable over two capital budget cycles at an estimated total of \$79,120–\$137,430 before grants. The federal Enabling Accessibility Fund Small Projects stream provides up to \$125,000 per project (periodic intake — confirm the program is currently accepting applications before citing a firm figure), and the RBC Barrier Buster Grants Program provides up to \$40,000 per project (its 2026 round has closed with recipients already announced — confirm whether a further round is planned). This assessment constitutes the pre-complaint documentation baseline and the needs documentation required for a competitive grant application.

56%

Current NAI Score

42 pts

Gap to Certified

3

Life safety findings

\$1.4K–**\$3.1K**To cross Certified
threshold**79.,K–****13.7K**Full remediation
range

2. At-a-Glance — Category Scores

Each bar reflects the category's percentage score. Categories below the 60% certification threshold are shaded amber or red; categories at or above are shaded green.

Category	Score %
1. Vehicular Access	72%
2. Exterior Approach and Entrance	45%
3. Interior Circulation	68%
4. Interior Services and Environment	47%
5. Sanitary Facilities	55%
6. Wayfinding and Signage	45%
7. Emergency Systems	51%
8. Additional Use of Spaces (8.3 + 8.21)	54%
11. Mind-Friendly Environments	63%
12. Technology and Innovation	67%

3. NAI Score Summary

The Clearwater Public Library scored 709 of 1,259 applicable points across 10 of 12 RHFAC v4.0 categories. Categories 9 (Residential Units) and 10 (Trails and Pathways) are not applicable to this building type and are excluded from scoring. The current NAI of 56% sits 4 percentage points, 42 points, below the threshold for RHF Accessibility Certified status. Three findings are life safety failures requiring immediate action regardless of certification goals.

#	Category	Earned	Max	%	Primary Finding
1	Vehicular Access	54	75	72%	Accessible parking compliant. Pedestrian crossing markings worn.
2	Exterior Approach and Entrance	89	197	45%	Ramp slope 8.8% exceeds 8.33% max. Door force 41N exceeds 38N. No tactile warnings.
3	Interior Circulation	212	312	68%	Elevator controls 1,330mm above 1,200mm max. Corridor 1,380mm below 1,500mm min.
4	Interior Services and Environment	78	167	47%	Service counter 960mm, no accessible height or knee clearance. Self-checkout inaccessible.
5	Sanitary Facilities	117	212	55%	Grab bars 785mm, below 840mm min. No universal washroom (required for Gold).
6	Wayfinding and Signage	38	84	45%	Partial Braille only. No tactile wayfinding at entry. No directional sign to washroom.
7	Emergency Systems	36	70	51%	CRITICAL: No visual fire alarms on either level. No area of rescue on Level 2.
8	Additional Use of Spaces (8.3 + 8.21)	38	70	54%	Library stacks 1,380mm aisle, below 1,500mm min. Self-checkout screen above max reach.
9	Residential Units	N/A	330	Excl.	Not applicable — public library, no residential units.
10	Trails and Pathways	N/A	150	Excl.	Not applicable — no designated trail or pathway system.
11	Mind-Friendly Environments	19	30	63%	No dimmable lighting. No sensory room. Quiet reading area present.
12	Technology and Innovation	28	42	67%	Hearing loop and FM system present. Website partially WCAG 2.1 compliant.

4. Detailed Findings — RHFAC v4.0, All 12 Categories

Category 1 — Vehicular Access 54 / 75 pts (72%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
1.1 Parking — Accessible spaces quantity	B651 §5.1.2	2 spaces	2 min.	PASS	Compliant. Van-accessible space present.
1.1 Parking — Dimensions	B651 §5.1.4	2,440mm wide	2,400mm min.	PASS	Compliant.
1.1 Parking — Surface	B651 §5.1.3	Firm, sealed asphalt	Firm, stable, slip-resistant	PASS	No cracking or heave at parking area.
1.1 Parking — Signage	B651 §5.1.5	ISA present	Required	PASS	International Symbol of Access visible from approach.
1.1 Parking — Pedestrian pathway to entrance	B651 §5.1.6	1,540mm wide	1,500mm min.	PASS	Unobstructed path confirmed.
1.1 Parking — Curb ramp at parking exit	B651 §4.1.3	850mm wide, 1:12 slope	800mm min.	PASS	Tactile strip present at base. Compliant.
1.1 Parking — Illumination	B651 §5.1.9	90 lux measured	50 lux min.	PASS	Compliant.
1.1 Parking — Pedestrian crossing markings	B651 §5.1.7	Worn, faded	Clearly marked	MARGINAL	Markings require repainting within 12 months. Est. \$400–\$800.
1.1 Parking — Shelter over accessible spaces	B651 §5.1.10	None	Recommended	FAIL	No weather protection. Canopy addition recommended. Est. \$8,000–\$14,000.
1.2 Drop-off zone	B651 §5.1.8	Present, 6m length	Required	PASS	Pull-through zone adjacent to entrance.
1.2 Public transit access	B651 §5.2.1	Bus stop 85m	Within 100m rec.	PASS	Within accessible distance.

Category 2 — Exterior Approach and Entrance 89 / 197 pts (45%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
2.1 Exterior pathway — clear width	B651 §5.2.2	1,520mm	1,500mm min.	PASS	Compliant throughout.
2.1 Exterior pathway — surface	B651 §5.2.3	Asphalt, firm	Firm, stable	PASS	Minor 8mm heave at north joint. Monitor.
2.2 Exterior ramp — running slope	B651 §6.4.4	8.8%	8.33% max (1:12)	FAIL	Measured at three points: 8.6%, 8.8%, 8.9%. Rebuild required. Est. \$14,000–\$22,000. Lowest-scoring item in this category.
2.2 Exterior ramp — width	B651 §6.4.5	1,280mm	1,500mm min.	FAIL	220mm below minimum. Addressed by ramp rebuild above.
2.2 Tactile warning — top of ramp	B651 §4.1.4	Absent	Required	FAIL	No detectable warning strip at top of ramp. Est. \$800–\$1,200.
2.2 Ramp handrails — both sides	B651 §6.4.9	Both sides, 875mm	865–965mm range	PASS	Compliant.
2.3 Exterior stairs — handrails	B651 §6.2.4	Both sides present	Required	PASS	Compliant.
2.4 Building entrance door — clear width	B651 §5.7.1	858mm	860mm min.	MARGINAL	2mm below minimum, within measurement tolerance. Monitor.
2.4 Entrance door — operating force	B651 §5.7.3	41N (pull)	38N max.	FAIL	Exceeds max by 3N. Closer adjustment or replacement. Est. \$180–\$350.
2.4 Entrance door — hardware type	B651 §5.7.5	Lever handles	Lever or loop required	PASS	Compliant throughout entrance.

Category 3 — Interior Circulation 212 / 312 pts (68%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
	B651 §5.7.1	905mm average	860mm min.	PASS	All interior doors compliant.

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
3.1 Interior doors — clear width (main)					
3.1 Interior doors — operating force	B651 §5.7.3	22N average	38N max.	PASS	Well within limit throughout.
3.2 Path of travel — clear width (narrowest)	B651 §5.3.2	1,380mm	1,500mm min.	FAIL	Periodical shelving encroaches on corridor. Repositioning resolves at no cost. Staff action.
3.3 Corridors — clear width (Level 2)	B651 §5.3.2	1,660mm	1,500mm min.	PASS	Compliant throughout Level 2.
3.5 Elevator — interior dimensions	B651 §5.4.3	1,370 x 1,370mm	1,370 x 1,370mm min.	PASS	At minimum. Compliant.
3.5 Elevator — door clear width	B651 §5.4.4	920mm	900mm min.	PASS	Compliant.
3.5 Elevator — control panel height	B651 §5.4.6	1,330mm (highest button)	1,200mm max.	FAIL	130mm above maximum. Panel replacement or supplementary low panel. Est. \$3,500–\$6,500.
3.5 Elevator — audio floor announcement	B651 §5.4.7	Absent	Required	MARGINAL	Audio absent. Technician reprogramming. Est. \$200–\$400.
3.6 Interior stairs — handrails both sides	B651 §6.2.4	Both sides present	Required	PASS	Compliant.
3.6 Stair handrail extensions	B651 §6.2.5	300mm horizontal	300mm min.	PASS	Compliant at both levels.

Category 4 — Interior Services and Environment 78 / 167 pts (47%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
4.1 Lobby — clear floor space	B651 §5.9.8	1,540 x 1,540mm	1,500 x 1,500mm min.	PASS	Compliant.

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
4.2 Service counter — height	B651 §5.9.2	960mm full length	760–865mm accessible portion required	FAIL	No lowered section. Est. \$2,800–\$4,500 for lowered section addition.
4.2 Service counter — knee clearance	B651 §5.9.3	None present	680mm ht, 480mm depth min.	FAIL	No knee clearance at any counter section. Resolved by lowered counter addition.
4.2 Self-service kiosk — reach height	B651 §5.9.5	1,270mm screen centre	1,200mm max.	FAIL	70mm above maximum reach for seated users. Accessible terminal required. Est. \$4,500–\$8,000.
4.3 Accessible seating at tables	B651 §5.10.3	4 of 24 tables accessible	5% min. = 2 tables	PASS	16.7% accessible. Above minimum.
4.5 Acoustic — background noise	B651 §5.5.1	HVAC audible in quiet zones	Low background noise required	MARGINAL	Not formally measured. Recommend acoustic assessment. May affect hearing loop performance.
4.6 Illumination — general	B651 §5.6.1	340 lux measured	200 lux min.	PASS	Compliant.

Category 5 — Sanitary Facilities 117 / 212 pts (55%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
5.1 Accessible washroom — location	B651 §7.1	Main floor, east wing	On accessible floor	PASS	On accessible route from main entrance.
5.1 Washroom door — clear width	B651 §5.7.1	880mm	860mm min.	PASS	Compliant.
5.1 Washroom — turning radius	B651 §7.2.2	1,500mm diameter	1,500mm min.	PASS	Compliant, measured with door closed.
5.1 Grab bar — rear wall height	B651 §7.3.3	785mm	840–920mm required	FAIL	55mm below minimum. Relocation required. Est. \$380–\$680 per bar.
5.1 Grab bar — side wall height	B651 §7.3.4	788mm	840–920mm required	FAIL	Same deficiency. Both bars relocated together. Included in estimate above.

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
5.1 Toilet seat height	B651 §7.3.2	440mm	430–480mm required	PASS	Compliant.
5.3 Universal washroom	B651 §7.4.1	Absent	Required for Gold certification	MARGINAL	No universal washroom. Required for Gold. Min. 1,700 x 2,200mm space needed. Est. \$18,000–\$32,000.

Category 6 — Wayfinding and Signage 38 / 84 pts (45%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
6.1 Accessible entrance symbol	B651 §4.2.1	Present at entrance	Required	PASS	ISA visible from accessible parking.
6.1 Directional signage to accessible washroom	B651 §4.2.5	Absent	Required, not visible from entry	FAIL	No directional sign provided. Est. \$180–\$320.
6.1 Tactile attention indicators — entry	B651 §4.1.4	Absent	Required at key decision points	FAIL	No tactile wayfinding indicators. Est. \$6,000–\$11,000 main floor.
6.2 Room ID signs — Braille	B651 §4.2.3	Partial, meeting room only	Required at all permanent rooms	FAIL	Full facility replacement required. Est. \$3,800–\$6,500.
6.2 Room ID signs — mounting height	B651 §4.2.4	1,580mm centre	1,370–1,675mm required	PASS	Compliant.
6.2 Room ID signs — tactile characters	B651 §4.2.3	Absent on non-compliant signs	Required alongside Braille	FAIL	Addressed by Braille sign replacement above.
6.3 Directory board at entry	B651 §4.2.6	Present, visual	Visual required	PASS	Visual directory present and legible.

Category 7 — Emergency Systems 36 / 70 pts (51%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
7.1.1 Emergency exit door hardware	B651 §5.7.4	Panic bar throughout	Operable with closed fist	PASS	Confirmed at both emergency exits. Compliant.
7.1.2 Emergency exit door — clear width	B651 §5.7.1	910mm both exits	860mm min.	PASS	Compliant at both identified emergency exits.
7.1.3 Area of rescue assistance — Level 2	B651 §3.3.4.2	Absent	Required where elevator is only vertical access	CRITICAL	No designated area of refuge or two-way communication system on Level 2. Persons unable to use stairs have no safe waiting area during evacuation. Est. \$2,200–\$4,500 including signage and two-way communication device.
7.2.1 Visual fire alarms — Level 1	B651 §8.3.3.1	Absent throughout Level 1	Required in all occupied spaces	CRITICAL	No visual fire alarm devices present on Level 1. Persons with hearing impairments receive no emergency warning during a fire event. Combined Level 1+2 estimate: \$8,500–\$14,000. Immediate remediation required.
7.2.2 Visual fire alarms — Level 2	B651 §8.3.3.1	Absent throughout Level 2	Required in all occupied spaces	CRITICAL	Same deficiency as Level 1. Combined full-facility installation estimate: \$8,500–\$14,000 (covers both levels). Immediate remediation required.
7.3.1 Evacuation instructions — posted at stairwells	B651 §3.3.4.4	Posted at both stairwells, both levels	Required	PASS	Floor identification and evacuation signage present and legible at both stairwells on both levels.

Category 8 — Additional Use of Spaces (8.3 Exhibit + 8.21 Libraries) 38 / 70 pts (54%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
8.3 Exhibit space — accessible route width	B651 §5.3.2	1,520mm at exhibit wall	1,500mm min.	PASS	Compliant at all current display locations.
8.21 Library — accessible stacks aisle width	B651 §5.3.2 + v4.0 §8.21	1,380mm	1,500mm min.	FAIL	Periodical stacks aisle below minimum. Shelving repositioning at no cost. Same finding as Category 3.
				FAIL	Same finding as Category 4. Est. \$4,500–\$8,000.

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
8.21 Library — self-checkout reach height	B651 §5.9.5	1,270mm screen centre	1,200mm max.		
8.21 Library — catalogue terminals	B651 §5.9.5	1,140mm	1,200mm max.	PASS	Digital catalogue terminals compliant.
8.21 Library — accessible table seating	B651 §5.10.3	4 of 24 accessible	5% min.	PASS	16.7% accessible. Compliant.
8.21 Library — hearing loop at desk	B651 §8.2.1	Present, operational	Required at service areas	PASS	Confirmed operational. T-coil compatible.

Category 11 — Mind-Friendly Environments 19 / 30 pts (63%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
11.1 Space — clear wayfinding	v4.0 §11.1	Main collection clear. Children's section cluttered.	Clear visual path required	PASS	Main floor compliant. Children's section has excess displays. Recommend decluttering.
11.1 Sensory-reduced areas	v4.0 §11.1	Quiet reading zone Level 2	Recommended	PASS	Quiet reading section on Level 2. Compliant.
11.2 Sensory — adjustable lighting	v4.0 §11.2	Fixed fluorescent only	Adjustable or varied lighting recommended	FAIL	No dimmable zones. Fixed high-output fluorescent throughout. Upgrade to adjustable LED. Est. \$4,500–\$8,000.
11.2 Sensory — acoustic management	v4.0 §11.2	Children's area separated visually	Acoustic zoning recommended	PASS	Visual separation present. Compliant.
11.3 Restoration — outdoor views	v4.0 §11.3	Windows present, north and east	Daylight and outdoor views encouraged	PASS	Good natural light on both levels.

Category 12 — Technology and Innovation 28 / 42 pts (67%)

Assessment Item	Clause	Measured	Required	Status	Notes / Remediation
12.1 Hearing loop — service desk	v4.0 §12.1	Present, operational	Required at primary service points	PASS	Operational T-coil hearing loop confirmed.
12.1 FM assistive listening system	v4.0 §12.1	Available on request	Required in meeting spaces	PASS	Portable FM system available. Staff trained in use.
12.2 Website accessibility compliance	v4.0 §12.2	Partial WCAG 2.1 compliance	WCAG 2.1 Level AA recommended	FAIL	Missing alt-text on event images. Low-contrast text on events calendar. Est. \$800–\$2,000.
12.3 Innovation — accessible programming	v4.0 §12.3	Tactile story time offered	Innovation points for inclusive programming	PASS	Tactile story time for children with visual impairments recognized as accessibility innovation.

Category 9 — Residential Units N/A / 330 pts (Excl.)

Not applicable — Residential Units: excluded from this facility's scoring (see note in Section 1).

Category 10 — Trails and Pathways N/A / 150 pts (Excl.)

Not applicable — Trails and Pathways: excluded from this facility's scoring (see note in Section 1).

5. Prioritized Remediation Plan

Total Estimated Remediation: \$79,120 – \$137,430 CAD (before applicable grants)

Phase 0 — Critical Life Safety

Complete within 30–60 days regardless of certification goals.

Why this matters beyond compliance: the absence of visual fire alarms and an area of rescue assistance are life safety gaps, not scoring gaps. They carry exposure independent of certification status, under CSA/ASC B651:23, independent of provincial human rights or accessibility legislation, and under the municipality's own facility liability, regardless of whether certification is pursued at all.

Remediation Item	Priority	Est. Cost	Timeline	Category
Install visual fire alarms — full facility, both levels	Critical	\$8,500 – \$14,000	30 days	Cat. 7
Install area of rescue assistance — Level 2 with two-way communication system	Critical	\$2,200 – \$4,500	60 days	Cat. 7
Relocate accessible washroom grab bars to 840–920mm height range	Critical	\$760 – \$1,360	30 days	Cat. 5

Phase 0 subtotal: \$11,460 – \$19,860

High Priority

Within 90 days.

Remediation Item	Priority	Est. Cost	Timeline	Category
Exterior ramp rebuild — correct slope to 1:12 and width to 1,500mm	High	\$14,000 – \$22,000	60 days	Cat. 2
Replace non-compliant room ID signage with Braille and tactile characters	High	\$3,800 – \$6,500	90 days	Cat. 6
Install tactile attention indicators at entry decision points	High	\$6,000 – \$11,000	90 days	Cat. 6
Add accessible lowered counter section with knee clearance at service desk	High	\$2,800 – \$4,500	90 days	Cat. 4
Elevator control panel replacement or supplementary low panel to 1,200mm	High	\$3,500 – \$6,500	90 days	Cat. 3

Adjust entrance door closer to achieve maximum 38N force	High	\$180 – \$350	30 days	Cat. 2
Install tactile warning strip at top of exterior ramp	High	\$800 – \$1,200	30 days	Cat. 2

High priority subtotal: \$31,080 – \$52,050

Medium Priority

Year 2 capital budget.

Remediation Item	Priority	Est. Cost	Timeline	Category
Accessible self-checkout terminal or supplementary accessible unit	Medium	\$4,500 – \$8,000	Year 2	Cat. 4/8
Adjustable LED lighting zones — dimmable task lighting	Medium	\$4,500 – \$8,000	Year 2	Cat. 11
Universal washroom addition — minimum 1,700 x 2,200mm including rough-in	Medium	\$18,000 – \$32,000	Year 2	Cat. 5
Install canopy/shelter over accessible parking spaces	Medium	\$8,000 – \$14,000	Year 2	Cat. 1

Medium priority subtotal: \$35,000 – \$62,000

Quick Wins

Near-zero-cost fixes actionable inside 30 days, ahead of any capital-budget cycle.

Remediation Item	Priority	Est. Cost	Timeline	Category
Install directional signage to accessible washroom from lobby	Quick Win	\$180 – \$320	This week	Cat. 6
Reposition periodical shelving to restore 1,500mm aisle width	Quick Win	\$0 — staff action	This week	Cat. 3/8
Remediate website — alt-text and colour contrast on events calendar	Quick Win	\$800 – \$2,000	90 days	Cat. 12
Reprogram elevator audio floor announcements	Quick Win	\$200 – \$400	30 days	Cat. 3
Repaint accessible parking crossing markings	Quick Win	\$400 – \$800	Spring 2027	Cat. 1

Quick win subtotal: \$1,580 – \$3,520

TOTAL ESTIMATED REMEDIATION: \$79,120 – \$137,430 CAD before grants | EAF Small Projects stream: up to \$125,000 per project (Small Projects intake is periodic — confirm current call-for-proposals status before citing in a live application)

6. Next Dollar Impact — Certification Pathway

What this section answers: if the Town of Clearwater can only spend a limited amount right now, this section identifies which actions deliver the most compliance improvement per dollar spent. Life safety items are flagged separately, as they are mandatory regardless of cost or score impact. All other items are ranked by points recovered per dollar invested.

Certification Status	Points Required	Current Points	Gap	Minimum Spend to Close Gap
RHF Accessibility Certified	751 pts (60%)	709 pts (56%)	42 pts	\$1,360–\$3,070 across five ranked low-cost actions. Shelving repositioning alone is free and closes 18 of the 42 points.
RHF Accessibility Certified Gold	1,007 pts (80%)	709 pts (56%)	298 pts	Requires full Phase 0 + Phase 1 + Phase 2 remediation. Achievable over two capital budget cycles.

6.1 — Path to Certification (751 points / 60%) — Minimum Spend

Rank	Action	Est. Cost	Points Recovered	Running Total
1	Reposition periodical shelving to restore 1,500mm aisle width. Zero cost. Staff action. Recovers points in both Category 3 (Interior Circulation) and Category 8.21 (Libraries) simultaneously. The highest points-per-dollar action available — closes 18 of the 42-point gap on its own, at no cost.	\$0	+18 pts	727 / 1,259 (57.7%)
2	Install directional signage to accessible washroom from lobby. Simple sign. Resolves Category 6 FAIL. High points-per-dollar ratio.	\$180 – \$320	+6 pts	733 / 1,259 (58.2%)
3	Adjust entrance door closer to 38N maximum. Mechanical adjustment or closer replacement. Resolves Category 2 FAIL and removes a certification prerequisite barrier.	\$180 – \$350	+8 pts	741 / 1,259 (58.9%)
4	Reprogram elevator audio floor announcements. One technician visit. Resolves Category 3 MARGINAL. Elevator audio is a Gold prerequisite item.	\$200 – \$400	+5 pts	746 / 1,259 (59.3%)
5	Remediate website — alt-text and colour contrast. Developer or accessibility consultant. Resolves Category 12 FAIL.	\$800 – \$2,000	+6 pts	752 / 1,259 — CERTIFIED THRESHOLD CROSSED

Total spend for all five ranked actions: \$1,360 – \$3,070. This is the minimum-cost path to cross the 751-point RHF Accessibility Certified threshold. None of the five items individually reaches it; the shelving fix alone closes 18 of the 42-point gap for zero cost, and the remaining four

close the rest. Phase 0 life safety items must be completed in parallel regardless of this path, as they are mandatory prerequisites for formal certification submission to the RHFAC Registry regardless of score achieved.

6.2 — Two-Year Capital Plan to Gold Certification (80%)

Phase	Actions	Est. Cost	Running Score
Phase 0 — Immediate	Life safety: visual fire alarms, area of rescue assistance, and grab bar relocation. Mandatory regardless of score. Must be completed before certification submission is possible.	\$11,460 — \$19,860	728 / 1,259 = 58%
Phase 1 — Year 1 (2026)	Ramp rebuild, full Braille signage, tactile indicators, service counter, elevator panel, door closer, tactile ramp strip, plus all five near-zero-cost Quick Win items (directional signage, elevator audio reprogramming, website remediation, and parking marking repaint — periodical shelving repositioning is included at zero cost). Addresses the largest compliance gaps and completes the full certification pathway from 6.1 within the same budget cycle.	\$32,660 — \$55,570	823 / 1,259 = 65% — RHF Accessibility Certified
Phase 2 — Year 2 (2027)	Self-checkout terminal, LED lighting, universal washroom, and parking canopy. Addresses medium-priority and Gold-specific items, including the universal washroom mandatory for Gold.	\$35,000 — \$62,000	1,002 / 1,259 = 80% — RHF Accessibility Certified Gold

TOTAL TWO-YEAR INVESTMENT FOR GOLD: \$79,120 – \$137,430 CAD before grants. Available funding: Enabling Accessibility Fund, Small Projects stream, up to \$125,000 per project (periodic intake; last round closed 2024, next call not yet announced — confirm current status before citing to a client); RBC Barrier Buster Grants Program, up to \$40,000 per project (2026 round closed March 2026, 40 recipients announced June 2026 — confirm whether a future round is planned before citing to a client).